E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept.	Manager	E&A- P2000	6.056.001				
Inspector: Avery Dresser					Stage		
Project Name:		Iron Horse NER110574					
For Week Ending:			/11/2020				
Project Location:	Hwy	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)					
Grading:	1009	×					
Sanitary Sewer:	100						
Storm Sewer:	100	%					
Paving:	100	%					
Seeding:	1009						
Utilities:	100						
Overall Development:	720	%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions				
Curreleur	0.45"				Week 1		
Sunday: Monday	0.15" 0.00"						
Tuesday	0.00"	+					
Wednesday	0.00"						
Thursday	0.00"	1					
Friday	0.00"						
Saturday	0.00"						
Oundaus	0.00"				Week 2		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"	_					
Wednesday	0.00"	-					
Thursday	0.00"				_		
Friday	0.06"	_					
Saturday	1.96"						
Sunday:	0.28"				Week 3		
Monday	0.00"						
Tuesday	0.00"	12/31/2019	Dorthy Cloudy 29/	24			
Wednesday	0.00	12/31/2019	Partly Cloudy 38/2	24			
Thursday	0.00"						
Friday	0.00						
	0.00"						
Saturday	0.00				Week 4		
Sunday:	0.00"				week 4		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"	+					
Thursday	0.00	1					
Friday	0.05						
Saturday	0.00"	+					
Jatuluay	0.00				Week 5		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday	N/A						
Friday	N/A						
Saturday	N/A						
	None						
Complaints:							
Construction Sequencing:	I	1	1	1			

Which portion(s) (i.e. drainage basins) of the	site have had a tempor	rary or permanent cessation	n of grading, earthwork, or groun	d disturbance in the l	ast 14 days?
Entire site; grading completed and stal	bilized prior to Sprin	g 2005.			
Which portion(s) (i.e. drainage basins) of the	site do not have gradir	ng, earthwork, or ground di	sturbance scheduled in the next	14 days? :	
Entire site; grading completed and stal					
What temporary or permanent stabilization m					
Dense Vegetation, seeding/sodding, m	natting, Re-seeding	5/2006, paving, and lar	idscaping.		
Summary Questions:					
Are approved entrances and adjacent streets	being maintained adec	juately?			
Yes					
Are receiving waters adjacent to the project	free of any significant s	signs of erosion or sedime	nt that would be associated with	the construction activ	ity?
Yes					
Checklist Questions:					
Are waste materials (concrete, construction r	material, hazardous, etc	.) being managed properly	?		
No, see BMP section	,	<u>,</u>			
Is dust associated with the construction activ	vity adequately controll	ed on the site?			
Yes					
Comments:					
Comments:					
Home construction is active on a few lo	ots.				
Findings / Corrective Actions (Date)					
Findings / Corrective Actions (Date)					
1) Some maintenance is required in th	e BMP section.				
2) There is disturbed ground on either					
waterbodies or the street therefore imr	mediate stabilization	or installation of BMPs	s is not necessary at this time	e. E&A inspector w	ill continue to monitor
the area for revegetation.					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
IF 1	Inlet	Lot 110	In Place	Active	No
Current Condition:	Active - This struct	ture was previously refe	erred to as a sediment basin	, but is actually fun	ctioning as a slope
			ction, silt fence is in place be	hind the structure	and straw wattles are
	located downhill fro	om the outlet pipe.			
Lot 2	Individual Lot	Lot 2		Removed	
Current Condition:	Removed - Pacese		he silt fence and sodded the	lot prior to the insp	pection on 11/06/19.
Lot 32	Individual Lot	Lot 32		Removed	
Current Condition: Lot 90		Homes removed the of Lot 90	concrete debris and sodded		ection on 7/23/19.
Current Condition:	Individual Lot		prior to inspection on 7/02/1	Removed	
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	No
Current Condition:		Boyer Young repaired t	he silt fence on the lot prior t		tion. Boyer Young
		U U	and repaired the runs left in		
			tation has filled in sufficiently	y to prevent erosio	n, therefore seeding is
	no longer required		1		1
Lot 126	Individual Lot			Removed	
Current Condition:			e silt fence and sodded the		on on 9/20/19.
Lot 130	Individual Lot	Lot 130		Removed	
Current Condition: Lot 137	Removed - The ho Individual Lot	be b	lot prior to inspection on 5/2	9/19. Removed	1
Current Condition:			I the lot and removed the silt t		ot prior to inspection on
	8/13/19.	company coudou			
Lot 138	Individual Lot	Lot 138		Removed	
Current Condition:	Removed - The Ho Silt Fence	ome Company removed Lot 155	the portable toilet and sodo 9/3/2018	ded the lot prior to Active	inspection on 8/13/19.
Lot 155 Current Condition:			es installed silt fence on the		
	inspection on 9/3/1				
Lot 163	Silt Fence	Lot 163	9/20/2019	Active	Yes
Current Condition:			d the lot and installed silt fer		
	inspection on 9/20	/19. Hubbell Homes rei	moved the dirt pile from the	ROW prior to the in	nspection on 11/06/19.
	1 The silt famous	ould be extended to b	order the back side of the lot		
		nould be extended to be			
		emoved from the golf co			
		end of the silt fence s			
			ete by 10/03/19. Not done a	is of the last inspe	ction. Hubbell Homes
		10/08/19, 11/06/19, 12/		of the last include	ation Hubboll Lawson
		was informed to compl 10/08/19, 11/06/19, 12/	ete by 10/03/19. Not done a 04/19 12/31/19	is of the last inspec	Cuon. Hubbell Homes
			ete by 10/14/19. Not done a	s of the last inspec	tion, Hubbell Homes
		11/06/19, 12/04/19 , 12/			
		s was informed to cor			

Current Condition:	Silt Fence	Lot 193	9/20/2019	Active	Yes								
Guiten Conulton.			ated the lot and installed s										
			wners (Danielson) are liste										
			issumed to be responsible										
	otherwise. The shifted wattle was restaked, and buried by additional dirt prior to the inspection on 12/04/19. The												
	wattle should be cleaned off, along with the other full wattles (See maintenance item #1). The homeowners (Danielson) cleaned the street, partially cleaned out the wattles on the east side of the lot, partially												
							staked down the new wattles, and replaced the damaged wattle to close the gap on the back side of the lot prior to the inspection on 12/31/19.						
	1. The homeowner	s (Danielson) were info	rmed to complete by 10/14	/19. Not done as of	f the last inspection. The								
	 The homeowners (Danielson) were informed to complete by 10/14/19. Not done as of the last inspection. The homeowners (Danielson) were reminded on 12/05/19. The homeowners (Danielson) were informed to complete by 12/10/19. Not done as of the last inspection. 												
		Permanent	41°02'43.47"N										
	PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No							
	Current Condition:		his is a pond as of 199	3.									
	SB 1	Sediment Basin	Lot 109		Removed								
	Current Condition:		•	ion, this structure is no long	0								
	have any sediment storage capacity and appears to be an area inlet/slope drain. See IF 1 for further information												
SF 3	Silt Fence	Lot 197		Removed									
Current Condition:	Removed- the insp	ector removed the silt f	ence during the inspection	on 3/22/17.	•								
SF 5	Silt Fence	South side of lake		Removed									
Current Condition:	Removed- the inst	bector removed the silt f	ence during the inspection	on 3/22/17.									
SF 8	Silt Fence	40' South of SF 5		Removed									
Current Condition:	Removed- the insp	ector removed the silt f	ence during the inspection	on 3/22/17.	•								
		East of Lots 119 and											
SF 9	Silt Fence	120	In Place	Active	Yes								
SF 9 Current Condition:													
	Fair Condition - Bo	over Young repaired and	In Place partially removed the silt f a and cart path prior to ins	ence prior to inspec	tion on 12/5/17. The								
	Fair Condition - Bo	over Young repaired and	partially removed the silt f	ence prior to inspec	tion on 12/5/17. The								
	Fair Condition - Bo sediment was rem	yer Young repaired and oved from the golf cours	partially removed the silt f	ence prior to inspection on 4/29/19.	tion on 12/5/17. The								
	Fair Condition - Bo sediment was rem	yer Young repaired and oved from the golf cours	partially removed the silt f se and cart path prior to ins	ence prior to inspection on 4/29/19.	tion on 12/5/17. The								
	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i	yer Young repaired and oved from the golf cours Il and needs to be clean nformed to complete by	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la	ence prior to inspec pection on 4/29/19. 5.	tion on 12/5/17. The								
	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i	yer Young repaired and oved from the golf cours Il and needs to be clean	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la	ence prior to inspec pection on 4/29/19. 5.	tion on 12/5/17. The								
Current Condition:	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/18	yer Young repaired and oved from the golf cours II and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la 5/19, 12/04/19	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer	tion on 12/5/17. The r Young was reminded								
Current Condition: SF 10	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/18 Silt Fence	yer Young repaired and oved from the golf cours Il and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la 5/19, 12/04/19 12/5/2018	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active	tion on 12/5/17. The r Young was reminded No								
Current Condition:	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/18 Silt Fence Good Condition - T	yer Young repaired and oved from the golf cours Il and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la 5/19, 12/04/19	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active	tion on 12/5/17. The r Young was reminded No								
Current Condition: SF 10	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/18 Silt Fence	yer Young repaired and oved from the golf cours Il and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor.	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la 5/19, 12/04/19 12/5/2018	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active	tion on 12/5/17. The r Young was reminded No								
Current Condition: SF 10 Current Condition:	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - T good condition. E8	yer Young repaired and oved from the golf cours Il and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la 5/19, 12/04/19 12/5/2018 kenly removed from the rep	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active port in July, howeve	tion on 12/5/17. The r Young was reminded No r it is still in place and ir								
Current Condition: SF 10 Current Condition: STR	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition. E8 Streets	Ver Young repaired and oved from the golf cours II and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96°20'36.35"W	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active oort in July, howeve Active	tion on 12/5/17. The r Young was reminded No								
Current Condition: SF 10 Current Condition: STR Current Condition:	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/1i Silt Fence Good Condition - 1 good condition. E8 Streets Good Condition - N	Vyer Young repaired and oved from the golf cours I and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active ort in July, howeve Active Active	tion on 12/5/17. The r Young was reminded No r it is still in place and ir No								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was on 6/28/18, 9/24/19 Silt Fence Good Condition - 1 good condition. E8 Streets Good Condition - N SWPPP Sign	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96°20'36.35"W No signs of trackout wer Two signs on site	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008	ence prior to inspec pection on 4/29/19. st inspection. Boyer Active Active Active Active Active	r Young was reminded No r it is still in place and ir No No No								
Current Condition: SF 10 Current Condition: STR Current Condition:	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition - T Streets Good Condition - N SWPPP Sign Good Condition - A	Vyer Young repaired and oved from the golf cours and needs to be clean nformed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installed	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H	ence prior to inspec pection on 4/29/19. 5. st inspection. Boyer Active ort in July, howeve Active inspection. Active wy 6. South Lakevi	tion on 12/5/17. The Young was reminded No r it is still in place and ir No ew Way & South Bend								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/16 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - N SWPPP Sign Good Condition - A Road entrance. Th	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96°20'36.35"W No signs of trackout wer Two signs on site A sign has been installed the sign at the South Lak	partially removed the silt f ea and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend	ence prior to inspec pection on 4/29/19. st inspection. Boyer Active A	tion on 12/5/17. The Young was reminded No r it is still in place and ir No No ew Way & South Bend as visible again due to								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior f	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend o inspection on 7/02/19. Th		r Young was reminded No r it is still in place and ir No No No Way & South Bend as visible again due to Hwy 6 and Iron Horse								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr Drive had been kn	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior to ocked over prior to insp	partially removed the silt f ea and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend		r Young was reminded No r it is still in place and ir No No No Way & South Bend as visible again due to Hwy 6 and Iron Horse								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior to ocked over prior to insp	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend o inspection on 7/02/19. Th		r Young was reminded No r it is still in place and ir No No No Way & South Bend as visible again due to Hwy 6 and Iron Horse								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr Drive had been kn	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior to ocked over prior to insp	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend o inspection on 7/02/19. Th		tion on 12/5/17. The Young was reminded No r it is still in place and ir No No ew Way & South Bend as visible again due to Hwy 6 and Iron Horse								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr Drive had been kn	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior to ocked over prior to insp	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend o inspection on 7/02/19. Th		tion on 12/5/17. The Young was reminded No r it is still in place and ir No Way & South Bend as visible again due to Hwy 6 and Iron Horse re downed SWPPP sign								
Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Fair Condition - Bo sediment was rem The silt fence is fu Boyer Young was i on 6/28/18, 9/24/13 Silt Fence Good Condition - T good condition. E8 Streets Good Condition - A SWPPP Sign Good Condition - A Road entrance. Th the surrounding gr Drive had been kn	yer Young repaired and oved from the golf cours and needs to be clean informed to complete by 3, 3/19/19, 6/06/19, 8/15 Behind Lot 190 The silt fence was mista A will monitor. 41°02'28.55"N 96'20'36.35"W No signs of trackout wer Two signs on site A sign has been installer e sign at the South Lak ass being mowed prior to ocked over prior to insp	partially removed the silt f se and cart path prior to ins ed behind lots 114 and 115 3/24/18. Not done as of la /19, 12/04/19 12/5/2018 kenly removed from the rep In Place e observed during the last 8/8/2008 d at Iron Horse Drive and H eview Way and South Bend o inspection on 7/02/19. Th		tion on 12/5/17. The Young was reminded No r it is still in place and in No No ew Way & South Bend as visible again due to Hwy 6 and Iron Horse								