E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Mai		E&A- P2006.0	56.001		
Inspector: Avery Dresser					Stage
Project Name:		3			
For Week Ending:		2/8	3/2020		
Project Location:	Hww	County)	68003		
Troject Location.	ilwy	Journey			
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	72%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
	2.1011				Week 1
Sunday:	0.13"				
Monday	0.00" 0.00"				
Tuesday Wednesday	0.00"				
Thursday	0.00"				
Friday	0.11"				
Saturday	0.01"				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.02"				
Wednesday	0.40"				
Thursday	0.26"	1/23/2020	Snow 36/32		
Friday	0.00"	1/20/2020			
Saturday	0.00"				
	0.00				Week 3
Sunday:	0.02"				
Monday	0.00"				
Tuesday	0.02"				
Wednesday	0.04"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
outur du j	0.00				Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.08"				
Saturday	0.00"				
					Week 5
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
	•				
Complaints:	None				
1					

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No, see BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Home construction is active on a few lots. Not all BMPs could be visually verified during the last inspection due to winter conditions.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) There is disturbed ground on either side of the newly-sodded Lot 32 as of inspection on 7/23/19. The lot is flat and doesn't have runoff potential to waterbodies or the street therefore immediate stabilization or installation of BMPs is not necessary at this time. E&A inspector will continue to monitor the area for revegetation.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
IF 1	Inlet	Lot 110	In Place	Active	No	
Current Condition:		of the 11/26/18 inspec	erred to as a sediment basin ction, silt fence is in place be			
Lot 2	Individual Lot	Lot 2		Removed		
Current Condition:	Removed - Pacese	etter Homes removed t	he silt fence and sodded the	lot prior to the insp	ection on 11/06/19.	
Lot 32	Individual Lot	Lot 32		Removed		
Current Condition:			concrete debris and sodded		ection on 7/23/19.	
Lot 90	Individual Lot	Lot 90		Removed		
Current Condition:			prior to inspection on 7/02/1			
Lot 113 Current Condition:	Silt Fence	Lot 113	8/17/2017 he silt fence on the lot prior t	Active	No No	
	the inspection on 7 no longer required	7/02/19, volunteer vege at this time.	and repaired the runs left in tation has filled in sufficiently	y to prevent erosion		
Lot 126	Individual Lot	Lot 126	L	Removed		
Current Condition:	Removed - The Ho		ne silt fence and sodded the	lot prior to inspection	on on 9/20/19.	
Lot 130	Individual Lot	Lot 130		Removed		
Current Condition:			lot prior to inspection on 5/2			
Lot 137	Individual Lot	Lot 137		Removed		
Current Condition:	8/13/19.	. ,	the lot and removed the silt	•	or prior to inspection o	
Lot 138	Individual Lot	Lot 138		Removed		
Current Condition:			d the portable toilet and sodo			
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	No	
Current Condition:	inspection on 9/3/1	8.	es installed silt fence on the	-		
Lot 163	Silt Fence	Lot 163	9/20/2019 d the lot and installed silt fer	Active	Yes	
Current Condition:	 Inspection on 9/20/19. Hubbell Homes removed the dirt pile from the ROW prior to the inspection on 11/06/19. The silt fence should be extended to border the back side of the lot. The silt fence should be cleaned out where full. Silt should be removed from the golf course. The damaged end of the silt fence should be repaired. Hubbell Homes was informed to complete by 10/03/19. Not done as of the last inspection. Hubbell Homes was reminded on 10/08/19, 11/06/19, 12/04/19, 12/31/19 Hubbell Homes was informed to complete by 10/03/19. Not done as of the last inspection. Hubbell Homes was reminded on 10/08/19, 11/06/19, 12/04/19, 12/31/19 Hubbell Homes was informed to complete by 10/14/19. Not done as of the last inspection. Hubbell Homes was reminded on 11/06/19, 12/04/19, 12/31/19 Hubbell Homes was informed to complete by 10/14/19. Not done as of the last inspection. 					

Lot 193 Current Condition:		Lot 193	9/20/2019	Active	Yes				
Current Condition:	Silt Fence		vated the lot and installed st						
	-								
		prior to inspection on 9/20/19. The homeowners (Danielson) are listed as the lot owner on the Saunders County Assessor's website, and will therefore be assumed to be responsible for maintenance unless they communicate							
			d, and buried by additional d						
	wattle should be cleaned off, along with the other full wattles (See maintenance item #1). The homeowners								
	(Danielson) cleaned the street, partially cleaned out the wattles on the east side of the lot, partially staked down the new wattles, and replaced the damaged wattle to close the gap on the back side of the lot prior to the inspection on 12/31/19.								
	1. The wattles should be cleaned out where full on the north side of the lot.								
	2. The new wattles on the back side of the lot should be staked down.								
	3. The portable toilet should be secured. 1. The homeowners (Denisland) were informed to complete by 10/14/10. Not done as of the last inspection. The								
							1. The homeowners (Danielson) were informed to complete by 10/14/19. Not done as of the last inspection. The homeowners (Danielson) were reminded on 12/05/19, 1/24/20		
			2. The homeowners (Danielson) were informed to complete by 12/10/19. Not done as of the last inspection. The						
		homeowners (Da	nielson) were reminde	ed on 1/24/20.					
	3. The homeowne	3. The homeowners (Danielson) were informed to complete by 1/30/20.							
	Permanent	41°02'43.47"N							
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No				
Current Condition:		This is a pond as of 199							
SB 1	Sediment Basin	Lot 109	J	Removed					
Current Condition:			tion, this structure is no long		d a basin as it does not				
Current Condition.			appears to be an area inlet/s						
	nave any seumen	i Storage capacity and a	appears to be an area inlet/s	siope drain. See ir	i ioi iururei iirioimauon				
SF 3	Silt Fence	Lot 197		Removed					
Current Condition:	Removed- the insp	ector removed the silt f	ence during the inspection	on 3/22/17.					
SF 5	Silt Fence	South side of lake		Removed					
Current Condition:	Removed- the insp	ector removed the silt f	ence during the inspection	on 3/22/17.					
SF 8	Silt Fence	40' South of SF 5		Removed					
or ŏ				0/00//=					
Current Condition:	Removed- the insp	ector removed the silt f	ence during the inspection	on 3/22/17.					
	Removed- the insp	pector removed the silt f	ence during the inspection of	on 3/22/17.					
	Removed- the insp		ence during the inspection of In Place	on 3/22/17. Active	Yes				
Current Condition:	Silt Fence	East of Lots 119 and 120	In Place	Active					
Current Condition: SF 9	Silt Fence Fair Condition - Bo	East of Lots 119 and 120 yer Young repaired and	In Place partially removed the silt fe	Active ence prior to inspec	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bo	East of Lots 119 and 120 yer Young repaired and	In Place	Active ence prior to inspec	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bosediment was rem	East of Lots 119 and 120 over Young repaired and oved from the golf cour	In Place d partially removed the silt fesse and cart path prior to ins	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bosediment was rem	East of Lots 119 and 120 over Young repaired and oved from the golf cour	In Place partially removed the silt fe	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful	East of Lots 119 and 120 over Young repaired and oved from the golf count Il and needs to be clear	In Place d partially removed the silt fe se and cart path prior to ins	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bo sediment was rem The silt fence is ful Boyer Young was i	East of Lots 119 and 120 byer Young repaired and oved from the golf cours Il and needs to be clear informed to complete by	In Place dipartially removed the silt fease and cart path prior to instance behind lots 114 and 115 of 3/24/18. Not done as of last	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9 Current Condition:	Silt Fence Fair Condition - Bo sediment was rem The silt fence is ful Boyer Young was i	East of Lots 119 and 120 byer Young repaired and oved from the golf cours Il and needs to be clear informed to complete by 3, 3/19/19, 6/06/19, 8/18	In Place dipartially removed the silt fease and cart path prior to instance behind lots 114 and 115 of 3/24/18. Not done as of last	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9	Silt Fence Fair Condition - Bo sediment was rem The silt fence is ful Boyer Young was i	East of Lots 119 and 120 byer Young repaired and oved from the golf cours Il and needs to be clear informed to complete by	In Place dipartially removed the silt fease and cart path prior to instance behind lots 114 and 115 of 3/24/18. Not done as of last	Active ence prior to inspec pection on 4/29/19.	tion on 12/5/17. The				
Current Condition: SF 9 Current Condition:	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence	East of Lots 119 and 120 byer Young repaired and oved from the golf course and the gol	In Place dipartially removed the silt for see and cart path prior to inside the behind lots 114 and 115 and 148. Not done as of last 12/5/2018	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active	Young was reminded No				
Current Condition: SF 9 Current Condition: SF 10	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was in on 6/28/18, 9/24/18 Silt Fence Good Condition - 1	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the second seco	In Place d partially removed the silt for see and cart path prior to instance behind lots 114 and 115 of 3/24/18. Not done as of last 5/19, 12/04/19	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active	Young was reminded No				
Current Condition: SF 9 Current Condition: SF 10	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the second seco	In Place dipartially removed the silt for see and cart path prior to inside the behind lots 114 and 115 and 148. Not done as of last 12/5/2018	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active	Young was reminded No				
Current Condition: SF 9 Current Condition: SF 10 Current Condition:	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was in on 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition. E8	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the second seco	In Place dipartially removed the silt for see and cart path prior to instance behind lots 114 and 115 of 3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active ort in July, however	Young was reminded No r it is still in place and ir				
Current Condition: SF 9 Current Condition: SF 10 Current Condition:	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition. E8	East of Lots 119 and 120 over Young repaired and oved from the golf course oved from the golf course oved from the golf course over the	In Place In partially removed the silt for se and cart path prior to instance the second path prior to instance the second cart path pr	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active ort in July, however	Young was reminded No				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition:	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition - E8 Streets Good Condition - N	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the country of the	In Place In partially removed the silt for se and cart path prior to inspect behind lots 114 and 115 If 3/24/18. Not done as of last 5/19, 12/04/19 In Place In Place In Place In observed during the last in partial	Active ence prior to inspec pection on 4/29/19. st inspection. Boyer Active ort in July, however Active nspection.	Young was reminded No r it is still in place and ir				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition. E8 Streets Good Condition - N SWPPP Sign	East of Lots 119 and 120 over Young repaired and oved from the golf course. If and needs to be clear informed to complete by 3, 3/19/19, 6/06/19, 8/18 Behind Lot 190 The silt fence was mistar A will monitor. 41°02'28.55"N 96°20'36.35"W No signs of trackout wer Two signs on site	In Place In partially removed the silt for se and cart path prior to instance the second cart path prior to instance the silt for second cart path prior to instance the silt for second cart path prior to instance the silt for second cart path prior to instance the silt for second cart path prior to instance the silt for silt	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active Active Active	Young was reminded No r it is still in place and ir				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition:	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/19 Silt Fence Good Condition - Togood condition - Streets Good Condition - SWPPP Sign Good Condition - A	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the country of the	In Place d partially removed the silt for se and cart path prior to instance the second cart pat	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active spection. Active wy 6. South Lakevie	Young was reminded No r it is still in place and ir No No No No No No No No No N				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition - 8 Streets Good Condition - N SWPPP Sign Good Condition - A Road entrance. Th	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the country of the	In Place d partially removed the silt fesse and cart path prior to instance debenind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the reputable lin Place e observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Benders	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No Wo Way & South Bend s visible again due to				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was on 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition - 8 Streets Good Condition - N SWPPP Sign Good Condition - A Road entrance. Th	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the country of the	In Place d partially removed the silt for se and cart path prior to instance the second cart pat	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No Wo Way & South Bend s visible again due to				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition - 8 Streets Good Condition - N SWPPP Sign Good Condition - A Road entrance. Th	East of Lots 119 and 120 byer Young repaired and oved from the golf course of the country of the state of the country o	In Place d partially removed the silt fesse and cart path prior to instance debenind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the reputable lin Place e observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Benders	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No No www. South Bend s visible again due to Hwy 6 and Iron Horse				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - 1 good condition - 8 Streets Good Condition - N SWPPP Sign Good Condition - A Road entrance. Th	East of Lots 119 and 120 byer Young repaired and oved from the golf course over the golf cours	In Place d partially removed the silt fesse and cart path prior to instance behind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep In Place re observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Bencto inspection on 7/02/19. The	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No No www. South Bend s visible again due to Hwy 6 and Iron Horse				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition - Super Sign Good Condition - Area Road entrance. The Surrounding gr	East of Lots 119 and 120 byer Young repaired and oved from the golf course over the golf cours	In Place d partially removed the silt fesse and cart path prior to instance behind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep In Place re observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Bencto inspection on 7/02/19. The	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No No www. South Bend s visible again due to Hwy 6 and Iron Horse				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition - Super Sign Good Condition - Area Road entrance. The Surrounding gr	East of Lots 119 and 120 byer Young repaired and oved from the golf course over the golf cours	In Place d partially removed the silt fesse and cart path prior to instance behind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep In Place re observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Bencto inspection on 7/02/19. The	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No No www. South Bend s visible again due to Hwy 6 and Iron Horse				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition - Super Sign Good Condition - Area Road entrance. The Surrounding gr	East of Lots 119 and 120 byer Young repaired and oved from the golf course over the golf cours	In Place d partially removed the silt fesse and cart path prior to instance behind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep In Place re observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Bencto inspection on 7/02/19. The	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No ew Way & South Bend s visible again due to Hwy 6 and Iron Horse e downed SWPPP sign				
SF 9 Current Condition: SF 9 Current Condition: SF 10 Current Condition: STR Current Condition: SWPPP Sign	Silt Fence Fair Condition - Bosediment was rem The silt fence is ful Boyer Young was ion 6/28/18, 9/24/18 Silt Fence Good Condition - Tagood condition - Super Sign Good Condition - Area Road entrance. The Surrounding gr	East of Lots 119 and 120 byer Young repaired and oved from the golf course over the golf cours	In Place d partially removed the silt fesse and cart path prior to instance behind lots 114 and 115 (3/24/18. Not done as of last 5/19, 12/04/19 12/5/2018 kenly removed from the rep In Place re observed during the last in 8/8/2008 d at Iron Horse Drive and Heview Way and South Bencto inspection on 7/02/19. The	Active ence prior to inspect pection on 4/29/19. St inspection. Boyer Active ort in July, however Active nspection. Active wy 6. South Lakeviel Road entrance wa	Young was reminded No r it is still in place and in No No No Way & South Bend s visible again due to Hwy 6 and Iron Horse				