E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		E&A- P2006	0.056.001			
Inspector: Joe Manning			an Haraa		Stage	
Project Name:		Iron Horse NER110574				
For Week Ending:		9	/12/2020			
Project Location:	Hw	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
		. 1	1	-		
Grading:	1009					
Sanitary Sewer: Storm Sewer:	1009					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	72%	6				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
					Week	
Sunday:	0.10"					
Monday Tuesday	0.00"			+		
Wednesday	0.00"			+ +		
Thursday	0.03"	1		1 1		
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.43"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"	8/19/2020	Mostly Sunny 84/62	2:45 PM		
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.05"					
Wednesday	0.00"					
Thursday Friday	0.00"			+		
Friday	0.00"			+		
Saturday	0.00"				Week	
Sunday:	0.00"				vveek :	
Monday	0.00			+ +		
Tuesday	1.04"					
Wednesday	0.36"	1				
Thursday	0.38"	9/10/2020	Thunderstorms 56/47	11:00 AM		
Friday	0.04"					
Saturday	0.00"					
Complaints:	None			/		
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a tempo	rary or permanent cessat	ion of grading, earthwork, or ground	d disturbance in the last 1	l4 days?	
Construction Sequencing: Which portion(s) (i.e. drainage basins Entire site; grading completed an Which portion(s) (i.e. drainage basins	nd stabilized prior to Sprin	g 2005.			l4 days?	

Entire site; grading completed and stabilized prior to Spring 2005.						
What temporary or permanent stabilization measures listed in this section are being implemented?						
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.						
Checklist Questions:						
Are receiving waters adjacent to the project fro	ee of any significant sig	ns of erosion or sediment t	nat would be associated with the	construction activity?		
Yes						
Create Corrective Action?						
N/A						
Have disturbed areas been seeded or otherwis	se stabilized as required	1? List inactive portions of t	he project and if stabilization mea	asure are adequate or	needed to prevent erosion.	
Yes Create Corrective Action?						
N/A						
Are waste materials (concrete, construction m	aterial, hazardous, etc.) being managed properly?				
No						
Create Corrective Action?						
No, See BMP Section						
Are construction entrances and adjacent stree	ts being maintained ad	equately?				
No						
Create Corrective Action?						
No - See BMP Section						
Is dust associated with the construction activi	ty adequately controlle	d on the site?				
Yes	iy adequately controlle					
Create Corrective Action?						
N/A						
Comments:						
Comments:						
Home construction is active on a few lot	S.					
Findings / Corrective Actions (Date):						
Findings / Corrective Actions (Date):						
1) Some maintenance is required in the	RMP section					
2) There is disturbed ground on either s		ded Lot 32 as of inspect	ion on 7/23/19 The lot is fla	t and doesn't have	runoff potential to	
waterbodies or the street therefore imme						
area for revegetation.			,			
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
IF 1	Inlet	Lot 110	In Place	Active	No	
Current Condition:	Active - This struct	ure was previously refer	ed to as a sediment basin, b	out is actually functi	oning as a slope	
			on, silt fence is in place behi			
	located downhill fro		, I			
Lot 2		Lot 2		Domovod		
	Individual Lot		silt fence and sodded the lo	Removed	tion on 11/06/10	
Current Condition:						
Lot 5	Silt Fence	Lot 5	5/18/2020	Active	Yes	
Current Condition:		U	onstruction and installed silt	tence along the so	utheast side of the lot	
	prior to the inspecti	on on 5/18/20.				
	The street in front of the lot should be cleaned and silt fence should be installed along the front of the lot.					
	Trademark Homes was informed to complete by 7/08/20. Not done as of the last inspection. Trademark Homes					
	was reminded on	9/11/20				
Lot 32	Individual Lot	Lot 32		Removed		
Current Condition:			ncrete debris and sodded the			
Lot 53	Silt Fence	Lot 53	5/18/2020	Active	No	
Current Condition:	Current Condition: Active - An unknown builder began construction on the lot prior to the inspection on 5/18/20. E&A inspector will					
monitor the need for BMPs.						
Lot 57	Silt Fence	Lot 57	6/1/2020	Active	No	
Current Condition:	Active - An unknow	vn builder began constru	iction on the lot prior to the i	nspection on 6/01/2	20. E&A inspector will	
	monitor the need for	r BMPs.				

Individual Lot

Lot 90 Current Condition: Lot 113 Lot 90

 Removed - Grace Homes sodded the lot prior to inspection on 7/02/19.

 Silt Fence
 Lot 113
 8/17/2017

Removed

Active

Yes

Current Condition:			silt fence on the lot prior to th				
	some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no						
	Inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seed longer required at this time.						
	1. The silt fence sh	ould be retied to 2 t-pos	ts near the northeast corner	of the lot.			
	 The silt fence should be retied to 2 t-posts near the northeast corner of the lot. The eastern edge of the upstream-most run of silt fence should be repaired. 						
	 The second upstream-most run of silt fence should be patched where torn on a t-post. The silt fence should be retied on the north end of the lot. 						
	 Boyer Young was informed to complete by 4/23/20. Not done as of the last inspection. Boyer Young was reminded on 6/02/20, 7/31/20 Boyer Young was informed to complete by 4/23/20. Not done as of the last inspection. Boyer Young was reminded on 6/02/20, 7/31/20 Boyer Young was informed to complete by 4/23/20. Not done as of the last inspection. Boyer Young was reminded on 6/02/20, 7/31/20 Boyer Young was informed to complete by 4/23/20. Not done as of the last inspection. Boyer Young was reminded on 6/02/20, 7/31/20 Boyer Young was informed to complete by 4/23/20. Not done as of the last inspection. Boyer Young was reminded on 6/02/20, 7/31/20 						
	reminded on 6/02/2			le last inspection. E	boyer roung was		
			by 8/6/20. Not done as of the				
Lot 116 Current Condition:	Silt Fence	Lot 116	4/28/2020 ed silt fence along the back a	Active	Yes		
ourient oonunion.			d the dirt pile from the ROW				
	1) The silt fence a	long the back of the lot s	should be cleaned out				
	2.) The street in fro	ont of the lot should be cl					
		ilet should be secured. In the side of the lot shou	uld be transhed in				
	· ·		own and should be repaired/r	einstalled.			
		l la mara a consta india mara di ta					
	was reminded on 7		complete by 7/08/20. Not do	one as of the last in	spection. Al Beil Homes		
	2.) Al Belt Custom	Homes was informed to	complete by 7/08/20. Not do	one as of the last in	spection. Al Belt Homes		
	was reminded on 7		complete by 7/08/20. Not do	ne as of the last in	spection Al Belt Homes		
	was reminded on 7				spection. Ai ben nomes		
			complete by 8/6/20. Not do	ne as of the last ir	spection. Al Belt		
		vas reminded on 9/11/2 Homes was informed to	complete by 8/6/20. Not do	ne as of the last ir	spection Al Belt		
		vas reminded on 9/11/2					
Lot 126	Individual Lot	Lot 126		Removed			
Current Condition: Lot 130	Individual Lot	Lot 130	silt fence and sodded the lo	Removed	on 9/20/19.		
Current Condition:			t prior to inspection on 5/29/				
Lot 137	Individual Lot	Lot 137	le lot and removed the silt fro	Removed	niente increation en		
Current Condition:	8/13/19.	Sine Company souded in					
Lot 138	Individual Lot	Lot 138	1	Removed			
Current Condition:			I the portable toilet and sodde		pection on 8/13/19.		
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	No		
Current Condition:	Good Condition - V on 9/3/18.	Vidhalm Custom Homes	installed silt fence on the lot	to protect sodded			
Lot 163					Iot 154 prior to inspection		
Current Condition: Lot 193	Silt Fence	Lot 163		Removed			
Current Condition:	Removed - Hubbel	II Home sodded the lot pi	rior to the inspection on 6/20	/20.			
PDP A	Removed - Hubbel Silt Fence	Il Home sodded the lot p Lot 193 Custom Homes sodded	rior to the inspection on 6/20 [/20. Removed			
	Removed - Hubbel Silt Fence Removed - Murray Permanent	Il Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N	the lot prior to the inspection	/20. Removed n on 6/11/20.			
Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond	Il Home sodded the lot p Lot 193 Custom Homes sodded	the lot prior to the inspection	/20. Removed	No		
Current Condition: SB 1	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin	II Home sodded the lot pr Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109	the lot prior to the inspection In Place	/20. Removed n on 6/11/20. Active Removed	No		
Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi	II Home sodded the lot p Lot 193 / Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspectio	the lot prior to the inspection	/20. Removed n on 6/11/20. Active Removed r being considered	No a basin as it does not		
Current Condition: SB 1 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment	II Home sodded the lot p Lot 193 (Custom Homes sodded 41°02'43.47"N 96°20'36.65"W (his is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap	the lot prior to the inspection In Place	/20. Removed n on 6/11/20. Active Removed r being considered	No a basin as it does not		
Current Condition: SB 1 Current Condition: SF 3	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment	II Home sodded the lot p Lot 193 (Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspectit t storage capacity and ap Lot 197	In Place In Place In Place on, this structure is no longe opears to be an area inlet/slo	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed	No a basin as it does not		
Current Condition: SB 1 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence Silt Fence	Il Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W Fhis is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake	In Place In Place In Place on, this structure is no longe opears to be an area inlet/slo	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed n 3/22/17. Removed	No a basin as it does not		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence Removed- the insp	II Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake Dector removed the silt fe	In Place In Place In Place on, this structure is no longe opears to be an area inlet/slo	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed 3/22/17. Removed 3/22/17.	No a basin as it does not		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence	I Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96'20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake Dector removed the silt fe 40' South of SF 5	In Place In Place In Place on, this structure is no longe opears to be an area inlet/slo	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed o 3/22/17. Removed o 3/22/17. Removed	No a basin as it does not		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp	II Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 South side of lake bector removed the silt fe 40' South of SF 5 sector removed the silt fe East of Lots 119 and	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed of 3/22/17. Removed of 3/22/17. Removed of 3/22/17.	No No a basin as it does not for further information.		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence	II Home sodded the lot p Lot 193 (Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspectiv t storage capacity and ap Lot 197 bector removed the silt fe South side of lake bector removed the silt fe 40' South of SF 5 bector removed the silt fe East of Lots 119 and 120	In Place In Place In Place In Place In Place In this structure is no longe popears to be an area inlet/slo Ince during the inspection or Ince during the inspection or	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed n 3/22/17. Removed n 3/22/17. Removed n 3/22/17. Active	No No a basin as it does not for further information.		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence Fair Condition - Bo	II Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 bector removed the silt fe South side of lake 900 south of SF 5 100 bector removed the silt fe 40' South of SF 5 bector removed the silt fe East of Lots 119 and 120 byer Young repaired and	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered pe drain. See IF 1 Removed n 3/22/17. Removed n 3/22/17. Active Active ce prior to inspectio	No No a basin as it does not for further information.		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence Fair Condition - Bo sediment was removed	II Home sodded the lot p Lot 193 Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake Dector removed the silt fe 40' South of SF 5 Dector removed the silt fe East of Lots 119 and 120 Dyer Young repaired and oved from the golf course	In Place In Place In Place In Place In Place In Place In this structure is no longe opears to be an area inlet/slo In ce during the inspection or In Place Partially removed the silt fer e and cart path prior to inspection	/20. Removed n on 6/11/20. Active Removed r being considered pe drain. See IF 1 Removed n 3/22/17. Removed n 3/22/17. Active Active ce prior to inspectio	No No a basin as it does not for further information.		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - 1 Sediment Basin Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence The silt fence is ful	II Home sodded the lot p Lot 193 'Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 South side of lake South side of lake South side of lake South of SF 5 Sector removed the silt fe 40' South of SF 5 Sector removed the silt fe East of Lots 119 and 120 Syer Young repaired and oved from the golf course II and needs to be cleaned	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed n 3/22/17. Removed n 3/22/17. Removed n 3/22/17. Ce prior to inspection ce prior to inspection ce prior to inspection	No No No A basin as it does not for further information. Yes on on 12/5/17. The		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment Silt Fence Removed - Followi have any sediment Silt Fence Removed- the insp Silt Fence The silt fence is ful Boyer Young was it	II Home sodded the lot p Lot 193 (Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 bector removed the silt fe South side of lake bector removed the silt fe 40' South of SF 5 bector removed the silt fe East of Lots 119 and 120 byer Young repaired and oved from the golf course II and needs to be cleane informed to complete by	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed of 3/22/17. Removed of 3/22/17. Removed of 3/22/17. Active ce prior to inspectioned construction on 4/29/19.	No No No A basin as it does not for further information. Yes on on 12/5/17. The		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment Silt Fence Removed - the insp Silt Fence Removed- the insp Silt Fence The silt fence is ful Boyer Young was i 6/28/18, 9/24/18, 3	II Home sodded the lot p Lot 193 (Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake bector removed the silt fe 40' South of SF 5 Dector removed the silt fe East of Lots 119 and 120 Dyer Young repaired and oved from the golf course II and needs to be cleaned informed to complete by 8/19/19, 6/06/19, 8/15/19	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Removed 13/22/17. Removed 13/22/17. Removed 13/22/17. Active cce prior to inspection active inspection. Boyer 1 7/31/20	No No A basin as it does not for further information. Yes on on 12/5/17. The Young was reminded on		
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9	Removed - Hubbel Silt Fence Removed - Murray Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followi have any sediment Silt Fence Removed - the insp Silt Fence Removed- the insp Silt Fence The silt fence is ful Boyer Young was i 6/28/18, 9/24/18, 3 Silt Fence	II Home sodded the lot p Lot 193 'Custom Homes sodded 41°02'43.47"N 96°20'36.65"W This is a pond as of 1993 Lot 109 ing the 11/26/18 inspection t storage capacity and ap Lot 197 Dector removed the silt fe South side of lake ector removed the silt fe 40' South of SF 5 Dector removed the silt fe East of Lots 119 and 120 Dyer Young repaired and oved from the golf course II and needs to be cleaned informed to complete by 3/19/19, 6/06/19, 8/15/19 Behind Lot 190	In Place In	/20. Removed n on 6/11/20. Active Removed r being considered ope drain. See IF 1 Removed n 3/22/17. Removed n 3/22/17. Removed n 3/22/17. Ce prior to inspection ce prior to inspection control on 4/29/19. inspection. Boyer N 7/31/20 Active	No No No No No Yes on on 12/5/17. The Young was reminded on No		

STR	Streets	41°02'28.55"N 96°20'36.35"W	In Place	Active	No	
Current Condition:	Good Condition - No signs of trackout were observed during the last inspection.					
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No	
Current Condition:	Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due to the surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Horse Drive had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP sign during inspection on 7/23/19.					
Inspector Signature:	ling			Reviewed By:	Cate Sur	