E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A Jilek CPESC, CISEC

| nvironmental Services Dept. I | Manager | E&A- P2006 | 056 001 | | |
|--|---------------------|----------------|---------------------|---------|-------|
| nspector: Joe Manning | | E&A- P2006 | 050.001 | | Stage |
| Project Name: | | | Stage 3 | | |
| or Week Ending: | | 2. | /13/2021 | | |
| Project Location: | Hwy 6 | 68003 | | | |
| | | | | | |
| Grading: | 100% | | | | |
| Sanitary Sewer: Storm Sewer: | 100% | | | | |
| Paving: | 100% | | | | |
| Beeding: | 100% | | | | |
| Jtilities: | 100% | | | | |
| Overall Development: | 72% | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time | |
| July 17 MEE 7 MIC CHITC | 7 and and an estate | Bute inspected | Wedner Conditions | Time | We |
| Sunday: | 0.00" | | | | |
| Monday | 0.00" | | | | |
| Tuesday | 0.00" | | | | |
| Vednesday Thursday | 0.00" 0.04" | | | | |
| riday | 0.04 | | | | |
| Saturday | 0.00" | | | | |
| | | | | | We |
| Sunday: | 0.00" | | | | |
| Monday | 0.00" | | | | |
| uesday | 0.00" | | | | |
| Vednesday | 0.00" | | | | |
| - Thursday | 0.00" | | | | |
| Friday | 0.00" | | | | |
| Saturday | 0.00" | | | | |
| | | | | | We |
| Sunday: | 0.00" | | | | |
| Monday | 0.46" | | | | |
| Tuesday | 0.03" | | | | |
| Vednesday | 0.03" | | | | |
| Thursday | 0.00" | | | | |
| riday | 0.01" | | | | |
| Saturday | 0.00" | | | | |
| | | | | | We |
| Sunday: | 0.00" | | | | |
| Monday | 0.00" | 2/2/2021 | Partly Cloudy 31/23 | 1:45 PM | |
| Tuesday | 0.00" | | | | |
| Vednesday | 0.00" | | | | |
| Thursday | 0.00" | | | | |
| riday | 0.00" | | | | |
| Saturday | 0.02" | | | | |
| Name of the control o | 0.000 | | | | We |
| Sunday: | 0.03" | | | + | |
| Monday | 0.00" | | | | |
| uesday | 0.00" | | | | |
| Vednesday | 0.00" | | | | |
| hursday Fiday | 0.00" | | | + | |
| Friday Saturday | 0.03" | | | | |
| ususuuy | U.UL | | l | | |
| | None | | | | |
| Complaints: | | | | | |
| | 1 | | | | |

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; grading completed and stabilized prior to Spring 2005. What temporary or permanent stabilization measures listed in this section are being implemented? Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping. **Checklist Questions:** N/A Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes reate Corrective Action? N/A Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes reate Corrective Action? N/A Are construction entrances and adjacent streets being maintained adequately? No No - See BMP Section s dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: Home construction is active on a few lots. Due to snow-covered conditions, not all BMPs could be observed during the most recent inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section. 2) There is disturbed ground on either side of the newly-sodded Lot 32 as of inspection on 7/23/19. The lot is flat and doesn't have runoff potential to waterbodies or the street therefore immediate stabilization or installation of BMPs is not necessary at this time. E&A inspector will continue to monitor the area for revegetation. **Unique Name** Type Location Projected Install Date Status Maintenance

| IF 1 | Inlet | Lot 110 | In Place | Active | No | | | |
|--------------------|--|--|----------------------------------|---------------------|---------|--|--|--|
| Current Condition: | drain/area inlet. As | Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe. | | | | | | |
| Lot 5 | Silt Fence | Lot 5 | 5/18/2020 | Active | Yes | | | |
| Current Condition: | prior to the inspecting 11/02/20. 1.) The silt fence of 2.) Silt fence should 1.) Trademark Hon Homes was remind | Fair Condition - Trademark Homes began construction and installed silt fence along the southeast side of the lot prior to the inspection on 5/18/20. Trademark Homes cleaned the street in front of the lot prior to the inspection on 11/02/20. 1.) The silt fence on the east side of the lot should be repaired where down. 2.) Silt fence should be installed along the front of the lot. 1.) Trademark Homes was informed to complete by 10/12/20. Not done as of the last inspection. Trademark Homes was reminded on 11/13/20 2.) Trademark Homes was informed to complete by 11/18/20. Not done as of the last inspection. | | | | | | |
| Lot 53 | Silt Fence | Lot 53 | | Removed | | | | |
| Current Condition: | Removed - Dougla | s Stagemeyer (homeow | ner) sodded the lot prior to the | he inspection on 12 | /07/20. | | | |
| Lot 57 | Silt Fence | Lot 57 | 6/1/2020 | Active | No | | | |
| Current Condition: | | Active - An unknown builder began construction on the lot prior to the inspection on 6/01/20. The lot has vegetated as of 10/05/20. The lot is currently vacant. | | | | | | |
| Lot 113 | Silt Fence | Lot 113 | 8/17/2017 | Active | No | | | |
| Current Condition: | removed some of the inspection on 7/02/ longer required at the second control of the sec | Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time. Boyer Young removed the damaged runs of silt fence from the lot prior to the inspection on 11/11/20. | | | | | | |
| Lot 116 | Silt Fence | Lot 116 | | Removed | | | | |
| Current Condition: | Removed - Al Belt | Custom Homes sodded | the lot prior to the inspection | n on 11/02/20. | | | | |
| Lot 153 | Silt Fence | Lot 153 | 10/5/2020 | Active | Yes | | | |

| Current Condition: | Fair Condition - Hubbell Homes began construction on the lot prior to the inspection on 10/05/20. A dirt pile v observed in the ROW during the inspection on 10/05/20; however Hubbell Homes was in the process of except the lot. Hubbell Homes removed the dirt pile from the ROW and installed silt fence on the north and south side the lot prior to the inspection on 11/02/20. Silt fence on the north and south sides of the lot should be repaired. Hubbell Homes was informed to complete by 12/14/20. Not done as of the last inspection. | | | | | |
|----------------------------|--|--|--|--|--|--|
| | | · | • | | | |
| Lot 155 Current Condition: | on 9/3/18. | Lot 155 dhalm Custom Homes in | 9/3/2018 stalled silt fence on the lot to ed from the lot. | Active to protect sodded lot | Yes t 154 prior to inspection | |
| | | | omplete by 12/14/20. Not d | one as of the last in | spection. | |
| Lot 163 | Silt Fence | Lot 163 | | Removed | | |
| Current Condition: | | | ior to the inspection on 6/20 | | | |
| Lot 186 | Individual Lot | Lot 186 | 2/2/2021 | Active | No | |
| Current Condition: | Active - An unkno | wn builder began exca | vation on the lot prior to | the inspection on: | 2/02/2021. E&A | |
| | inspector will mo | nitor and recommend I | BMPs and dirt removal as | necessary. | | |
| Lot 193 | Silt Fence | Lot 193 | | Removed | | |
| Current Condition: | | | the lot prior to the inspection | n on 6/11/20. | | |
| | Permanent | 41°02'43.47"N | . = | | | |
| PDP A | Detention Pond | 96°20'36.65"W | In Place | Active | No | |
| Current Condition: | Good Condition - T Sediment Basin | his is a pond as of 1993 | | Removed | I | |
| SB 1 | | Lot 109 | on, this structure is no longe | | - | |
| Current Condition: | | | pears to be an area inlet/slo | | | |
| SF 3 | Silt Fence | Lot 197 | | Removed | | |
| Current Condition: | Removed- the insp | ector removed the silt fe | nce during the inspection or | n 3/22/17. | • | |
| SF 5 | Silt Fence | South side of lake | | Removed | | |
| Current Condition: | | | nce during the inspection or | | | |
| SF 8 | Silt Fence | 40' South of SF 5 | | Removed | | |
| Current Condition: | Removed- the insp | | nce during the inspection or | n 3/22/17. | | |
| 05.0 | 0:14 = | East of Lots 119 and | la Diam | A . 45 | V . | |
| SF 9 Current Condition: | Silt Fence | 120 | In Place partially removed the silt fer | Active | Yes | |
| | The silt fence is ful Boyer Young was i 6/28/18, 9/24/18, 3 | oved from the golf course I and needs to be cleane Informed to complete by 1/19/19, 6/06/19, 8/15/19, | e and cart path prior to inspend d behind lots 114 and 115. 3/24/18. Not done as of last 12/04/19, 4/17/20, 6/02/20 | ection on 4/29/19. t inspection. Boyer Y , 7/31/20, 10/06/20 | oung was reminded on | |
| SF 10 | Silt Fence | Behind Lot 190 | 12/5/2018 | Active | No | |
| Current Condition: | | | enly removed from the repo | ιτ in July, however i | t is still in place and in | |
| | good condition. E& | | | 1 | | |
| STR | Strooto | 41°02'28.55"N | In Diago | Activo | Yes | |
| Current Condition: | Streets Fair Condition - | 96°20'36.35"W | In Place | Active | res | |
| | 1.) The street in fro 2.) The street in fro 1.) Trademark Hon 2.) Hubbell Homes | was informed to comple | cleaned. plete by 11/12/20. Not done te by 12/08/20. Not done as | · · | | |
| SWPPP Sign | SWPPP Sign | Two signs on site | 8/8/2008 | Active | No | |
| Current Condition: | Road entrance. The surrounding grass | e sign at the South Lake being mowed prior to ins over prior to inspection o | at Iron Horse Drive and Hw view Way and South Bend pection on 7/02/19. The SW on 7/23/19. E&A inspector r | , Road entrance was VPPP sign by Hwy 6 | visible again due to the and Iron Horse Drive | |
| Inspector Signature: | Min | | | Reviewed By: | Hattes Van | |