E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. N	Manager Manager	Ger Engineering Answers					
	Hariago	E&A- P2000	6.056.001				
Inspector: Joe Manning							
Project Name:		Stage 3 68003					
For Week Ending:							
Project Location:	Hw						
Project Location:	ПМ						
Grading:	1009	%l					
Sanitary Sewer:	1009						
Storm Sewer:	1009						
Paving:	1009	%					
Seeding:	1009						
Utilities:	1009						
Overall Development:	729	%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
NAIN I ALL AMOUNTS	Amount in tentils	Date inspected	Weather Conditions	Time	Wee		
Sunday:	0.00"						
Monday	0.00"	3/14/2022	Partly Cloudy 60/36	1:40 PM			
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.11"				<u> </u>		
Friday	0.66"						
Saturday	0.00"						
Ourselland	0.00"				Wee		
Sunday: Monday	0.00" 0.25"						
Tuesday	0.39"						
Wednesday	0.01"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
					Wee		
Sunday:	0.00"						
Monday	0.01"						
Tuesday	0.00"						
Wednesday	0.01"						
Thursday	0.00"						
Friday	0.05"						
Saturday	0.00"						
Juliu uuy	0.00				Wee		
Sunday:	0.00"				1100		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.04"						
Friday	0.01"						
Saturday	0.00"						
					We		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
	N/A						
Wednesday							
Wednesday Thursday	N/A						
Wednesday Thursday	N/A N/A						
Wednesday Thursday Friday Saturday	N/A						
Wednesday Thursday Friday	N/A N/A N/A						
Wednesday Thursday Friday Saturday	N/A N/A						
Wednesday Thursday Friday	N/A N/A N/A						
Nednesday Fhursday Friday Saturday	N/A N/A N/A						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; grading completed and stabilized prior to Spring 2005.

Vhat temporary or permanent stabilization measures listed in this section are being implemented? Dense Vegetation, seeding/sodding, matting, re-seeding 5/2006, paving, and landscaping Checklist Questions: Yes N/A ave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. N/A are waste materials (concrete, construction material, hazardous, etc.) being managed properly? No - See BMP Section. Are construction entrances and adjacent streets being maintained adequately? No No - See BMP Section. s dust associated with the construction activity adequately controlled on the site Yes reate Corrective Action? N/A Comments: Comments: Home construction is active on a few lots. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. Projected Install Date Unique Name Status Location Maintenance Type IF 1 Inlet Lot 110 In Place Active No Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope **Current Condition:** drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe. Lot 4 R IV Lot 4 R IV Removed Silt Fence **Current Condition:** Removed - Trademark Homes sodded the lot prior to the inspection on 5/11/21. The street in front of the lot was cleaned by rain prior to the inspection on 7/15/21. The disturbed area west of the lot has vegetated as of 7/15/21. Lot 6 R II Lot 6 R II Removed Removed - Hubbell Homes sodded the lot and removed the concrete waste prior to the inspection on 6/24/21. **Current Condition:** Silt Fence Lot 57 Lot 57 6/1/2020 Active Nο Active - An unknown builder began construction on the lot prior to the inspection on 6/01/20. The lot has vegetated **Current Condition:** as of 10/05/20. The lot is currently vacant. 9/28/2021 Lot 61 Silt Fence Lot 61 Active **Current Condition:** Active - The Home Company began construction on the lot prior to the inspection on 9/28/21. A dirt pile was observed in the ROW; however, The Home Company was actively excavating the lot during the 9/28/21 inspection. The Home Company removed the dirt pile from the ROW and secured a portable toilet on the lot prior to the inspection on 10/28/21. The street in front of the lot should be cleaned. The Home Company was informed to complete by 3/15/22. Lot 82 Lot 82 5/28/2021 Active **Current Condition:** Fair Condition - Paradise Homes began construction on the lot prior to the inspection on 5/28/21. Paradise Homes installed silt fence along the back side of the lot prior to the inspection on 5/28/21. Paradise Homes installed a run of silt fence along the front of the lot prior to the inspection on 8/25/21. Paradise Homes extended the silt fence along the front of the lot prior to the inspection on 9/28/21. Paradise Homes removed the dirt pile from the ROW and from Lot 47 prior to the inspection on 10/14/21. Paradise Homes removed the concrete waste from the lot and from Lot 47 prior to the inspection on 1/17/22. 1.) The silt fence needs to be trenched in and repaired along the back and sides of the lot and reinstalled where removed 2.) The street in front of the lot should be cleaned. 3.) The silt fence along the front of the lot should be repaired/reinstalled. 1.) Paradise Homes was informed to complete by 6/04/21. Not done as of the last inspection. Paradise Homes was reminded on 6/25/21, 7/16/21, 8/27/21, 10/15/21, 12/22/21, 3/15/22 2.) Paradise Homes was informed to complete by 7/22/21. Not done as of the last inspection. Paradise Homes was reminded on 8/27/21, 10/15/21, 12/22/21, 3/15/22 3.) Paradise Homes was informed to complete by 9/01/21. Not done as of the last inspection. Paradise Homes was

reminded on 10/15/21, 12/22/21, 3/15/22

Lot 1 R VI	C:IA Farras	1-44 D \/I	0/47/0047	Λ -4:	NI-			
Current Condition:	Silt Fence	Lot 1 R VI	8/17/2017 silt fence on the lot prior to the	Active	No Rover Young removed			
ourrent condition.			ed the runs left in place prior					
		•	n has filled in sufficiently to pr	•				
	longer required at t	his time. Boyer Young re	emoved the damaged runs o	f silt fence from the	lot prior to the			
			lentified as Lot 113. Some po					
	ļ'	•	A inspector retied a portion of		0 1			
	becomes active.	ctor will make recomme	endations for the remainder o	the loose portion	of slit fence once the lot			
Lot 152	Individual Lot	Lot 152	11/23/2021	Active	Yes			
Current Condition:			struction on the lot and install					
	to the inspection on 11/23/21. A dirt pile was observed in the ROW during the current inspection; however, Citadel Homes was actively excavating the lot during the inspection. E&A inspector will monitor and make							
		,	inspector retied portions of the					
	12/20/21.							
	i ne siit tence snou	d be repaired/retied who	ere loose along its length.					
	Citadel Homes was	informed to complete h	by 2/21/22. Not done as of the	he last inspection				
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	Yes			
Current Condition:			nstalled silt fence on the lot to					
	on 9/3/18.							
	The silt fence shou	ld be repaired or remove	ed from the lot.					
	Midbalm Codens							
			complete by 12/14/20. Not do 6/25/21, 10/15/21 , 3/15/22	one as or the last in	spection, widnaim			
Lot 156	Silt Fence	Lot 155	9/3/2018	Active	Yes			
Current Condition:			ion on the lot prior to the insp					
Current Condition.				DECUION ON 9/20/21.	Wedadi Homes Temoved			
	the dirt pile from the ROW prior to the inspection on 10/14/21.							
	Silt fence should be	installed along the bac	k and east sides of the lot.					
			by 10/05/21. Not done as of t	the last inspection.	McCaul Homes was			
	reminded on 12/22		1.440040004					
Lot 184	Individual Lot	Lot 184	11/23/2021	Active	Yes			
Current Condition:			struction on the lot prior to the					
	installed silt fence along the back of the lot prior to the inspection on 12/20/21. The dirt piles were removed from the ROW of the lot prior to the inspection on 1/17/22.							
	1.) The dirt pile should be removed from the ROW of Lot 185.							
	2.) The portable toilet should be secured.							
	1.) E&A will attempt to identify the builder. Not done as of the last inspection. Hubbell Homes was reminded on							
	2/15/22	t to identify the builder. I	Not done as of the last hispe	clion. Hubbell Holl	les was reminded on			
		was informed to comple	ete by 2/21/22. Not done as	of the last inspec	tion.			
L at 196	-	· ·	1					
Lot 186 Current Condition:	Individual Lot	Lot 186	I ot and removed the portable	Removed	spection on 11/23/21			
Lot 194	Individual Lot	Lot 194	1/17/2022					
Current Condition:				i Pendind				
			ction on the lot prior to the ins	Pending spection on 1/17/22	Yes			
			ction on the lot prior to the ins		Yes			
		ıld be installed along t	he back of the lot.		Yes			
		· ·	he back of the lot.		Yes			
	2.) The street in fr	old be installed along to	the back of the lot. be cleaned.		Yes			
	2.) The street in fr 1.) Empire Homes	uld be installed along to ont of the lot should but was informed to com	the back of the lot. be cleaned. plete by 3/21/22.		Yes			
	2.) The street in fr 1.) Empire Homes 2.) Empire Homes	uld be installed along to ont of the lot should be was informed to comwas informed to com	the back of the lot. be cleaned. plete by 3/21/22.		Yes			
DUD V	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent	uld be installed along to ont of the lot should be was informed to comwas informed to com41°02'43.47"N	the back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22.	pection on 1/17/22	Yes			
PDP A Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond	was informed to com was informed to com 41°02'43.47"N 96°20'36.65"W	che back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22.		Yes			
PDP A Current Condition: SB 1	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond	uld be installed along to ont of the lot should be was informed to comwas informed to com41°02'43.47"N	che back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22.	pection on 1/17/22	Yes			
Current Condition:	2.) The street in from the stree	uld be installed along to ont of the lot should be was informed to come was informed to come 41°02'43.47"N 96°20'36.65"W his is a pond as of 1993 Lot 109	che back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22.	Active Removed	Yes			
Current Condition: SB 1	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin	was informed to com was informed to com 41°02'43.47"N 96°20'36.65"W his is a pond as of 1993 Lot 109 ng the 11/26/18 inspection	plete by 3/21/22. plete by 3/15/22. In Place	Active Removed r being considered	No No a basin as it does not			
Current Condition: SB 1 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment	was informed to comwas informed	che back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22. In Place 3. on, this structure is no longe	Active Removed r being considered ope drain. See IF 1	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence	was informed to comwas informed	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place and the place by 3/15/22. In place by 3/15/22.	Active Removed r being considered pe drain. See IF 1 Removed	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp	was informed to comwas informed	che back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22. In Place 3. on, this structure is no longe	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17.	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence	was informed to comwas informed to 20'43.47"N 96'20'36.65"W his is a pond as of 1993 Lot 109 high the 11/26/18 inspections storage capacity and approximately compared to 197 ector removed the silt ferosouth side of lake	plete by 3/21/22. plete by 3/15/22. In Place In place on, this structure is no longe oppears to be an area inlet/slo	Active Removed r being considered ope drain. See IF 1 Removed 3/22/17. Removed	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence	was informed to comwas informed to 20'43.47"N 96'20'36.65"W his is a pond as of 1993 Lot 109 high the 11/26/18 inspections storage capacity and approximately compared to 197 ector removed the silt ferosouth side of lake	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place and the place by 3/15/22. In place by 3/15/22.	Active Removed r being considered ope drain. See IF 1 Removed 3/22/17. Removed	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence	was informed to com was informed to com was informed to com 41°02'43.47"N 96°20'36.65"W his is a pond as of 1993 Lot 109 ng the 11/26/18 inspecti storage capacity and ap Lot 197 ector removed the silt fe 40' South of SF 5 ector removed the silt fe	plete by 3/21/22. plete by 3/15/22. In Place In place on, this structure is no longe oppears to be an area inlet/slo	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Removed	No No a basin as it does not			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	2.) The street in from the stree	was informed to comwas informed	the back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22. In Place and this structure is no longe opears to be an area inlet/slopence during the inspection on the longence during the longe	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17.	No No a basin as it does not for further information.			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	2.) The street in from the stree	was informed to commas informed the silt feactor removed the	the back of the lot. be cleaned. plete by 3/21/22. plete by 3/15/22. In Place and this structure is no longe opears to be an area inlet/slopears to be an area inlet/slopears during the inspection on lence during the lence during th	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active	No No a basin as it does not for further information.			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	2.) The street in from the stree	was informed to commas informed the silt feactor removed the	plete by 3/21/22. plete by 3/15/22. In Place and the structure is no longe opears to be an area inlet/slc ence during the inspection on lence during the inspection of lence during the inspection of lence during the inspection of lence during the lence during	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspec	No No a basin as it does not for further information. No No tion on 12/5/17. The			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence Good Condition - B sediment was removed-	was informed to come was informed to come was informed to come was informed to come 41°02′43.47″N 96°20′36.65″W his is a pond as of 1993 Lot 109 and the 11/26/18 inspective storage capacity and appropriate to the sit feed of the sit feed	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place on, this structure is no longe opears to be an area inlet/slopence during the inspection on lence during the lence during	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspec	No No a basin as it does not for further information. No No tion on 12/5/17. The			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Following have any sediment Silt Fence Removed- the insp Silt Fence Good Condition - B sediment was removed out prior to	was informed to commas informed to command informed informed to command informed informed to command informed inf	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place on, this structure is no longe opears to be an area inlet/slopence during the inspection on lence during the lence during	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspec ction on 4/29/19. T	No No a basin as it does not for further information. No No tion on 12/5/17. The			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence Good Condition - B sediment was removed out prior to Silt Fence	was informed to come was informed to come was informed to come was informed to come 41°02'43.47"N 96°20'36.65"W his is a pond as of 1993 Lot 109 and the 11/26/18 inspective storage capacity and again to the sit feed of the	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place and a rea inlet/slo pence during the inspection on ence during the inspection on In Place d partially removed the silt fee and cart path prior to inspec	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspectation on 4/29/19. T	No No a basin as it does not for further information. No No tion on 12/5/17. The			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence Good Condition - B sediment was removed out prior to Silt Fence	was informed to come was informed to come was informed to come was informed to come 41°02'43.47"N 96°20'36.65"W his is a pond as of 1993 Lot 109 and the 11/26/18 inspective storage capacity and again to the sit feed of the	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place on, this structure is no longe opears to be an area inlet/slopence during the inspection on lence during the lence during	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspectation on 4/29/19. T	No No a basin as it does not for further information. No No tion on 12/5/17. The			
Current Condition: SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	2.) The street in from 1.) Empire Homes 2.) Empire Homes Permanent Detention Pond Good Condition - T Sediment Basin Removed - Followin have any sediment Silt Fence Removed- the insp Silt Fence Good Condition - B sediment was removed out prior to Silt Fence	was informed to come was informed to come was informed to come was informed to come at 1°02′43.47″N 96°20′36.65″W his is a pond as of 1993 Lot 109 and the 11/26/18 inspective storage capacity and appear to the silt feromoved from the golf course the inspection on 8/10/190 genice was removed price on the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the inspection on 8/10/190 fence was removed price of the silt feromoved from the golf course the silt feromoved from the golf cour	plete by 3/21/22. plete by 3/15/22. plete by 3/15/22. In Place and a rea inlet/slo pence during the inspection on ence during the inspection on In Place d partially removed the silt fee and cart path prior to inspec	Active Removed r being considered pe drain. See IF 1 Removed 3/22/17. Removed 3/22/17. Removed 3/22/17. Active ence prior to inspectation on 4/29/19. T	No No a basin as it does not for further information. No No tion on 12/5/17. The			

Current Condition:	Good Condition - Trademark Homes cleaned the street in front of Lot 5 prior to the inspection on 3/01/21. Hubbell Homes cleaned the streets at lot 153 prior to the inspection on 3/23/21.					
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No	
Current Condition:	Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due to the surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Horse Drive had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP sign during inspection on 7/23/19.					
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.					
Inspector Signature:	ling			Reviewed By:	Site Sol	