E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept. M		E&A - P2019.032.0	000				
Inenester: Bruce Wright	E	-&A - P2019.032.0	100		Store		
Inspector: Bryce Wright					Stage		
	Kempten Creek 2						
Project Name:	CSW-202106167						
For Week Ending:		2/4/2	023				
Project Location:	North 168th Stroot	2/4/2023 North 168th Street and Bennington Road - Bennington, NE (Douglas County)					
	North Tooth Sheet	and bernington Koa	iu - Bernnigton, NE (Douţ	jias county)	68007		
Grading:	5%	1					
Sanitary Sewer:	0%						
Storm Sewer:	0%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	0%						
Overall Development.	0%						
	Amount in tenths	Data in an estad		Time	1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
Sunday:	0.00"				Week 1		
Monday	0.00"	+					
Tuesday	0.00"	1/31/2023	Sunny 12	10:00 AM			
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
Grading Began (11/29/22).	pasins) of the site do not have gr stabilization measures listed in th			duled in the next 14	days?		
Checklist Questions: Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?							
Yes Create Corrective Action?							
N/A							
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes Create Corrective Action? N/A							
Are waste materials (concrete, constru	ction material. hazardous. etc.) being m	anaged properly?					
No		and property .					
Create Corrective Action?							
No, see BMP section							
Are construction or transported and all	nt atracta baing maintained adapts to t	2					
Are construction entrances and adjace	nt streets being maintained adequately?	ſ					
Create Corrective Action?							
No, See BMP section							
	Is dust associated with the construction activity adequately controlled on the site?						
Yes Create Corrective Action?							

N/A

Comments:

Comments:

The site was inactive during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes	
Current Condition:	Pending -			. enanig		
	A construction entrance should be installed.					
	Ruff Grading and HRC Devel	opment were informed t	o complete by 12/20/22. No	ot done as of the la	st inspection.	
D1	Diversion	D-8 to K-8	11/4/2022	Pending	No	
Current Condition:	Pending - Diversion will be in	stalled when the area is	near the final grade.			
D2	Diversion	East of SB B	11/4/2022	Pending	No	
Current Condition:	Pending - Diversion will be in	stalled when the area is	near the final grade.	Ū	•	
D3	Diversion	Southeast of SB A	11/4/2022	Pending	No	
Current Condition:	Pending - Diversion will be in			rending	110	
			11/4/2022	Davralinan	Ne	
ET 1 Current Condition:	Erosion Control Terraces Pending - The erosion contro	B-9 to G-10		Pending	No	
					1	
ET 2	Erosion Control Terraces	B-9 to I-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro					
ET 3	Erosion Control Terraces	B-7 to K-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro			, , , , , , , , , , , , , , , , , , ,	1	
ET 4	Erosion Control Terraces	I-7 to M-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	I terraces will be installe	d when the area is near the	final grade.		
ET 5	Erosion Control Terraces	Q-10 to Q-8	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	d when the area is near the	final grade.	•	
ET 6	Erosion Control Terraces	R-10 to R-7	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro		d when the area is near the	final grade.		
ET 7	Erosion Control Terraces	S-7 to U-10	11/4/2022	Pending	No	
Current Condition:	Pending - The erosion contro	l terraces will be installe	d when the area is near the	final grade.		
FT 1	Fuel Tank	On site	12/6/2022	Active	Yes	
Current Condition:						
San Sin Sonahon.	Fair Condition - Ruff Grading	brought a fuel tank on s	ite prior to the inspection or	n 12/6/22.		
	, in the second s	, , , , , , , , , , , , , , , , , , ,		12/6/22.		
	A secondary containment be	, , , , , , , , , , , , , , , , , , ,		ו 12/6/22.		
	A secondary containment ber	m should be installed a	ound the fuel tank.		not increation. Buff	
	A secondary containment ber Ruff Grading and HRC Devel	m should be installed a	o complete by 12/13/22. No		ist inspection. Ruff	
	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm	m should be installed an opment were informed t ent were reminded on 1:	ound the fuel tank. o complete by 12/13/22. No 2/15/22.	ot done as of the la	-	
MS 1	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area	m should be installed a opment were informed t ent were reminded on 1: On site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022	ot done as of the la Active	No	
MS 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and	m should be installed at opment were informed t ent were reminded on 1: On site vehicle staging area oc	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t	ot done as of the la Active anker as of 12/26/	No /22	
MS 1 Current Condition: SB A	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin	m should be installed at opment were informed t ent were reminded on 1: On site vehicle staging area oc Z-9	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022	ot done as of the la Active	No	
MS 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and	m should be installed at opment were informed t ent were reminded on 1: On site vehicle staging area oc Z-9	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022	ot done as of the la Active anker as of 12/26/	No /22	
MS 1 Current Condition: SB A Current Condition: SB B	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin	m should be installed at opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7	round the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022	ot done as of the la Active anker as of 12/26/	No /22	
MS 1 Current Condition: SB A Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install	m should be installed at opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7	round the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022	ot done as of the la Active anker as of 12/26/ Pending	No /22 No	
MS 1 Current Condition: SB A Current Condition: SB B	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin	m should be installed at opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7	round the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022	ot done as of the la Active anker as of 12/26/ Pending	No /22 No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 area starts. 11/4/2022 11/4/2022	ot done as of the la Active anker as of 12/26/ Pending Pending Active	No 22 No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1	A secondary containment ber Ruff Grading and HRC Developm Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 area starts. 11/4/2022 11/4/2022	ot done as of the la Active anker as of 12/26/ Pending Pending Active	No 22 No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Devel Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Good Condition - HRC Devel Silt fence	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 area starts. 11/29/2022 fence prior to the inspection 11/29/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active	No 22 No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Seliment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel	m should be installed at opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 area starts. 11/29/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22.	No 22 No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 area starts. 11/29/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active	No 22 No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout	m should be installed at opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site of	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/29/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/2/2022 fence prior to the inspection 11/4/2022 vhen paving begins.	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22. Pending	No 22 No No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WO 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area	m should be installed an opment were informed a ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site w	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22. Pending Pending	No 22 No No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently r	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site will On site	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22. Pending Pending	No 22 No No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WO 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area	m should be installed an opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site will On site on sete the E&A inspector will co	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22. Pending Pending	No 22 No No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently r generated or stored on-site; t	m should be installed an opment were informed to ent were reminded on 1: On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site will on site on need for a designated he E&A inspector will co Bennington Road, N.	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022 waste storage area on-site intinue to monitor.	Active Active anker as of 12/26/ Pending Pending Active non 11/29/22. Active non 11/29/22. Pending Pending e due to no waste n	No V22 No No No No No No No No No Mo materials being	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently r generated or stored on-site; t Streets	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site v On site on need for a designated he E&A inspector will co Bennington Road, N. 168th Street	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022	Active Active anker as of 12/26/ Pending Pending Active n on 11/29/22. Active n on 11/29/22. Pending Pending	No 22 No No No No	
MS 1 Current Condition: SB A Current Condition: SB B Current Condition: SF 1 Current Condition: SF 2 Current Condition: WO 1 Current Condition: WS 1 Current Condition:	A secondary containment ber Ruff Grading and HRC Developm Material Storage Area Good Condition-Material and Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Sediment Basin Pending - Basin will be install Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Silt fence Good Condition - HRC Devel Concrete Washout Pending - Concrete washout Waste Storage Area Pending - There is currently r generated or stored on-site; t	m should be installed at opment were informed to ent were reminded on 12 On site vehicle staging area oc Z-9 ed when grading in the L-7 ed when grading in the West edge of site opment installed the silt West edge of site opment installed the silt On site will be installed on site v On site on need for a designated he E&A inspector will co Bennington Road, N. 168th Street	ound the fuel tank. o complete by 12/13/22. No 2/15/22. 11/4/2022 curring on-site by Ruff fuel t 11/4/2022 area starts. 11/4/2022 fence prior to the inspection 11/29/2022 fence prior to the inspection 11/4/2022 vhen paving begins. 11/4/2022 waste storage area on-site intinue to monitor.	Active Active anker as of 12/26/ Pending Pending Active non 11/29/22. Active non 11/29/22. Pending Pending e due to no waste n	No V22 No No No No No No No No No Mo materials being	

Certification Statement:	direction or supervision in acc properly gathered and evalua persons who manage the sys the information submitted is, t	r, that this document and all attachments were prep cordance with a system designed to assure that qua ted the information submitted. Based on my inquiry stem or those persons directly responsible for gathe to the best of my knowledge and belief, true, accura ficant penalties for submitting false information inclu- knowing violations."	alified personnel of the person or ring the information, ate, and complete. I
Inspector Signature:	Breya M Winght		Reviewed By: