E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary & .lilek. CPESC, CISEC

Zachary A. Jilek, CPESC, CISE Environmental Services Dept.		Engineering Answers						
Environmental Services Dept.		E&A - P2019.032.0	000					
Inspector: Bryce Wright								
Project Name:		Kempten Creek 2 CSW-202106167						
For Week Ending:		3/4/2023						
Project Location:	North 169th Street							
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County) 68007							
Grading:	5%	<u>, </u>		T	T			
Sanitary Sewer:	0%							
Storm Sewer:	0%							
Paving:	0%	_						
Seeding:	0%							
Utilities:	0%							
Overall Development:	0%							
		<u> </u>						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time			
Sunday:	0.72"				Week			
Monday	0.72	+		+				
Tuesday	0.00"	2/28/2023	Partly Cloudy 39	12:00 PM				
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
last 14 days? Grading Began (11/29/22). Grad	basins) of the site do not have g							
What temporary or permanent Existing Vegetation (11/29/22).	stabilization measures listed in t	his section are being	implemented?					
Checklist Questions:								
Are receiving waters adjacent to the p Yes Create Corrective Action?	project free of any significant signs of ero	osion or sediment that wo	uld be associated with the const	ruction activity?				
N/A								
Yes	otherwise stabilized as required? List in	active portions of the pro	ject and if stabilization measure	are adequate or neede	ed to prevent erosion.			
Create Corrective Action? N/A								
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? No								
Create Corrective Action? No, see BMP section								
Are construction entrances and adjacent streets being maintained adequately?								
No Create Corrective Action?								
No, See BMP section Is dust associated with the construction activity adequately controlled on the site?								
Yes Create Corrective Action?	on activity adequately controlled on the	Site (
Negle Outstate Activiti								

N/A

Comments:

Comments:

The site was inactive during the last inspection.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is required in the BMP section at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	X-11	11/4/2022	Pending	Yes		
Current Condition:	Pending -						
	A construction entrance should be installed.						
	Technique de la companya de la compa						
	Ruff Grading and HRC Development were informed to complete by 12/20/22. Not done as of the last inspection. Ruff						
	Grading and HRC Developm	ent were reminded on 2	2/8/23 , 3/3/23				
D1	Diversion	D-8 to K-8	11/4/2022	Pending	No		
Current Condition:	Pending - Diversion will be in	stalled when the area is	near the final grade.				
D2	Diversion	East of SB B	11/4/2022	Pending	No		
Current Condition:	Pending - Diversion will be installed when the area is near the final grade.						
D3	Diversion	Southeast of SB A	11/4/2022	Pending	No		
Current Condition:	Pending - Diversion will be in	stalled when the area is	near the final grade.				
ET 1	Erosion Control Terraces	B-9 to G-10	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro	ol terraces will be installe	ed when the area is near the	final grade.			
ET 2	Erosion Control Terraces	B-9 to I-10	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion control						
ET 3	Erosion Control Terraces	B-7 to K-10	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro	1	ı		1		
ET 4	Erosion Control Terraces	I-7 to M-10	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro	of terraces will be installe	1	final grade.			
ET 5	Erosion Control Terraces	Q-10 to Q-8	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro	ol terraces will be installe	1				
ET 6	Erosion Control Terraces	R-10 to R-7	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro						
ET 7	Erosion Control Terraces	S-7 to U-10	11/4/2022	Pending	No		
Current Condition:	Pending - The erosion contro	1	1		.,		
FT 1 Current Condition:	Fuel Tank Fair Condition - Ruff Grading	On site	12/6/2022	Active	Yes		
	A secondary containment berm should be installed around the fuel tank. Ruff Grading and HRC Development were informed to complete by 12/13/22. Not done as of the last inspection. Ruff Grading and HRC Development were reminded on 12/15/22, 2/8/23, 3/3/23						
MS 1	Material Storage Area	On site	11/4/2022	Active	No		
Current Condition:	Good Condition-Material and	vehicle staging area oc	curring on-site by Ruff fuel t	tanker as of 12/26/	22		
SB A	Sediment Basin	Z-9	11/4/2022	Pending	No		
Current Condition:	Pending - Basin will be instal	led when grading in the	area starts.	· ·	•		
SB B	Sediment Basin	L-7	11/4/2022	Pending	No		
Current Condition:	Pending - Basin will be instal	led when grading in the	area starts.	, , ,	•		
SF 1	Silt fence	West edge of site	11/29/2022	Active	Yes		
Current Condition:	Fair Condition - HRC Develo		ence prior to the inspection	on 11/29/22.			
	2.) Additional silt fence che 1.) Ruff Grading and HRC D	1.) Silt fence should be cleaned out in multiple locations where full. 2.) Additional silt fence checks should be installed in multiple high flow areas. 1.) Ruff Grading and HRC Development were informed to complete by 3/7/23. 2.) Ruff Grading and HRC Development were informed to complete by 3/7/23.					
SF 2	Silt fence	West edge of site	11/29/2022	Active	Yes		
Current Condition:	Fair Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. Silt fence should be trenched in where undermined.						
	Ruff Grading and HRC Development were informed to complete by 3/7/23.						
SF 3	Silt fence	East edge of site	3/7/2023	Pending	Yes		
	•		•				

Current Condition:	Pending -	Pending -					
	Silt fence should be installed along the east edge of the site near Cora Street. Ruff Grading and HRC Development were informed to complete by 2/14/23 or as weather allows. Not done as of the last inspection. Ruff Grading and HRC Development were reminded on 3/3/23						
WO 1	Concrete Washout	On site	11/4/2022	Pending	No		
Current Condition:	Pending - Concrete washout will be installed on site when paving begins.						
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No		
Current Condition:	Pending - There is currently no need for a designated waste storage area on-site due to no waste materials being generated or stored on-site; the E&A inspector will continue to monitor.						
		Bennington Road, N.					
STR	Streets	168th Street	11/4/2022	Active	No		
Current Condition:	Good Condition - No trackout was observed.						
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Active	No		
Current Condition:	Good Condition - SWPPP inspector installed the sign during the inspection on 12/20/22.						
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Brya M Wazht			Reviewed By:	Site Site		