

## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

E&A - P2019.032.000								
Inspector: Bryce Wright					Stage			
Project Name:		1						
For Week Ending:	CSW-202106167 10/14/2023							
Project Location:	North 168th Street a	68007						
		and Demnigton Roat		as county)	00001			
Grading:	100%							
Sanitary Sewer:	100%							
Storm Sewer:	<b>30%</b>							
Paving:	0%							
Seeding:	40%							
Utilities:	0%							
	15%							
Overall Development:	15%	1						
	Ann ann t in tan tha	Data in an estad	Marthan Ornalitiana	<b>T</b> :				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time			
Oran daya	0.00				Week 1			
Sunday: Monday	0.00"	10/9/2023	Suppy 50	12:20 PM				
Tuesday	0.00"	10/9/2023	Sunny 59	12:20 PW				
Wednesday	0.00"							
Thursday	1.04"							
Friday	0.08"	10/13/2023	Overcast 50	9:30 AM				
Saturday	0.00"							
Complaints:								
Construction Sequencing:								
Which portion(s) (i.e. drainage basir last 14 days?	ns) of the site have had a ten	nporary or permanen	t cessation of grading, ea	rthwork, or ground	disturbance in the			
Grading Began (11/29/22). Grading ce and grading ceased across the entire s								
Which portion(s) (i.e. drainage basi								
Grading Began (11/29/22). Grading ce and grading ceased across the entire s	ased (12/20/23). Grading resu	med on site (3/14/23).	Spreading top soil across e	entire site (5/16/23).	Final grade reached			
What temporary or permanent stabi								
Existing Vegetation (11/29/22).		ins section are being						
Checklist Questions:								
Checklist Questions:								
Are receiving waters adjacent to the project fi	ree of any significant signs of erosic	on or sediment that would	be associated with the construct	tion activity?				
Yes Create Corrective Action?								
N/A								
Have disturbed areas been seeded or otherwi	se stabilized as required? List inact	tive portions of the project	and if stabilization measure are	adequate or needed to	prevent erosion.			
Yes								
Create Corrective Action?								
N/A								
Are waste materials (concrete, construction n	naterial, hazardous, etc.) being man	aged properly?						
Yes								

## Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately? Yes

Create Corrective Action?

N/A

## Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action? N/A

## Comments:

Comments:

The site was active for storm sewer installation during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section at this time.

2.) Second inspection was completed for scheduling.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	X-11	11/4/2022	Pending	No		
Current Condition:	Pending - Site is being accessed through Morgan Ridge as of 6/27/23. No construction entrance is needed at this time						
D1	Diversion	D-8 to K-8	5/23/2023	Active	No		
Current Condition:	Good Condition - HRC Devel	opment installed the div	ersion prior to the inspectio	n on 5/23/23.			
D2	Diversion	East of SB B	5/23/2023	Active	Yes		
Current Condition:	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23. Diversion should be reinstalled where removed for sanitary installation. K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection.						
D3	Diversion	Southeast of SB A	5/23/2023	Active	No		
Current Condition:	Good Condition - HRC Devel				110		
D4	Diversion	South of SB A	5/23/2023	Active	Yes		
Current Condition:	Fair Condition - HRC Develo						
	K2 Construction was informe	d to complete by 9/19/2	3. Not done as of the last in	spection.			
ET 1	Erosion Control Terraces	B-9 to G-10	6/6/2023	Active	No		
ET 1 Current Condition:		B-9 to G-10	6/6/2023	Active			
Current Condition: ET 2	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10	6/6/2023 osion control terrace prior to 6/6/2023	Active the inspection on Active	6/6/23.		
Current Condition:	Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10	6/6/2023 osion control terrace prior to 6/6/2023	Active the inspection on Active	6/6/23.		
Current Condition: ET 2 Current Condition: ET 3	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. No 6/6/23. No 6/6/23.		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. No 6/6/23. No 6/6/23.		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. No 6/6/23. No 6/6/23.		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7	6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7 opment installed the erc S-7 to U-10	6/6/2023         psion control terrace prior to         6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6 Current Condition: ET 7	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7 opment installed the erc S-7 to U-10	6/6/2023         psion control terrace prior to         6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6 Current Condition: ET 7 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7 opment installed the erc S-7 to U-10 opment installed the erc On site ght a fuel tank on site pr n on 3/28/23. Ruff Grad	6/6/2023         psion control terrace prior to $6/6/2023$ psion control terrace prior to $12/6/2023$ psion control terrace prior to $12/6/2022$ psion control terrace prior to $12/6/2022$ psion to the inspection on $12/6$ psi pstalled a fuel tank and	Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 000000000000000000000000000000000000		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6 Current Condition: ET 7 Current Condition: ET 7	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Fuel Tank Pending - Ruff Grading broug from site during the inspectio inspection on 4/11/23. Ruff G 5/2/23.	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7 opment installed the erc S-7 to U-10 opment installed the erc On site ght a fuel tank on site pr n on 3/28/23. Ruff Grad	6/6/2023         psion control terrace prior to $6/6/2023$ psion control terrace prior to $12/6/2023$ psion control terrace prior to $12/6/2022$ psion control terrace prior to $12/6/2022$ psion to the inspection on $12/6$ psi pstalled a fuel tank and	Active the inspection on Active the inspection on Active	6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. 6/6/23. No 7/7 No 7		
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 6 Current Condition: ET 7 Current Condition: FT 1 Current Condition:	Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Fuel Tank Pending - Ruff Grading broug from site during the inspection inspection on 4/11/23. Ruff G	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc Q-10 to Q-8 opment installed the erc R-10 to R-7 opment installed the erc S-7 to U-10 opment installed the erc S-7 to U-10 opment installed the erc On site ght a fuel tank on site pr n on 3/28/23. Ruff Grad crading moved the fuel ta	6/6/2023psion control terrace prior to $6/6/2023$ psion control terrace prior to $12/6/2022$ ior to the inspection on $12/6$ ing installed a fuel tank andank to the Morgan Ridge su $11/4/2022$	Active the inspection on Active the inspection on Pending 5/22. Ruff Grading secondary contai bdivision prior to t	6/6/23. No 8/6/23. No 8/6/23. No		

Current Condition:	Good Condition - Ruff Grad Grading secured the portab Morgan Ridge subdivision p site prior to the inspection o	ble toilet during the inspectorior to the inspector	tion on 4/18/23. Ruff Gra	ding moved the portab	le toilet to the portable toilet on		
SB A	Sediment Basin	Z-9	3/21/2023	Pending	Yes		
Current Condition:	Pending - HRC Developmen Basin should be installed per HRC Development was info reminded on 5/4/23, 6/21/23	er plan. ormed to complete by 3/28 3, 8/22/23	3/23. Not done as of the I				
SB B	Sediment Basin	L-7	3/21/2023	Pending	Yes		
Current Condition:	Pending - HRC Development began shaping the basin prior to the inspection on 3/21/23. Basin should be installed per plan. HRC Development was informed to complete by 3/28/23. Not done as of the last inspection. HRC Development was reminded on 5/4/23, 6/21/23, 8/22/23						
SF 1	Silt fence	West edge of site	11/29/2022	Active	No		
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development installed additional silt fence checks in multiple high flow areas prior to the inspection on 3/14/23.						
SF 2	Silt fence	West edge of site	11/29/2022	Active	Yes		
	Silt fence should be repaired K2 Construction was inform	ned to complete by 9/19/2	3. Not done as of the last				
SF 3	Silt fence	East edge of site	3/14/2023	Active	No		
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 3/14/23. Due to the grade silt fence along the edge of the site near Daniel Street is no longer necessary as of 5/23/23.						
WO 1	Concrete Washout	On site	11/4/2022	Pending	No		
Current Condition:	Pending - Concrete washou	it will be installed on site	when paving begins.				
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No		
Current Condition:	Pending - There is currently generated or stored on-site;	; the E&A inspector will co		site due to no waste m	aterials being		
STR	Streets	Bennington Road, N. 168th Street	11/4/2022	Active	No		
Current Condition:	Good Condition - No tracko		11/4/2022		110		
SWPPP Sign	SWPPP Notification Sign		11/4/2022	Active	No		
Current Condition:	Good Condition - SWPPP in	nspector installed the sign	during the inspection or				
Certification Statement:	"I certify, under penalty of la direction or supervision in a	accordance with a system		qualified personnel			
	persons who manage the sy the information submitted is am aware that there are sig of fines and imprisonment for	ystem or those persons d s, to the best of my knowle inificant penalties for subr	irectly responsible for gated and belief, true, acc	thering the information curate, and complete. I			