E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Environmental Services Dept. Manager** 

**Engineering Answers** 

100% 100% 80% <b>70%</b> 40%		106167	glas County)	Stage 1 68007
100% 100% 80% <b>70%</b> 40%	CSW-202 <sup>2</sup> 12/9/2 and Bennington Road	106167 023	glas County)	68007
100% 100% 80% <b>70%</b> 40%	and Bennington Road		las County)	68007
100% 100% 80% <b>70%</b> 40%		d - Bennington, NE (Doug	las County)	68007
100% 80% <b>70%</b> 40%				
80% 70% 40% 0%				
<b>70%</b> 40% 0%				
40% 0%				
0%				1
	1			
30%				
Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
	·			Weel
0.00"				
0.00"				
0.00"	12/5/2023	Partly Cloudy 36	10:00 AM	
0.00"				
	0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00"	0.00" 0.00" 0.00" 0.00" 12/5/2023 0.00" 0.00" 0.00"	0.00" 0.00" 0.00" 12/5/2023 Partly Cloudy 36 0.00" 0.00" 0.00" 0.00"	0.00" 0.00" 0.00" 12/5/2023 Partly Cloudy 36 10:00 AM 0.00" 0.00" 0.00" 0.00" 0.00"

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). **Paving began** (11/14/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). **Paving began** (11/14/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (11/29/22).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See findings section

Are waste materials (concrete, construction m	naterial, hazardous, etc.) being mana	aged properly?				
Yes						
Create Corrective Action?						
N/A						
Are construction entrances and adjacent stree	ets being maintained adequately?					
No						
Create Corrective Action?						
No, See BMP section						
Is dust associated with the construction activ	ity adequately controlled on the site	.?				
Yes	ny adoquately controlled on the old	··				
Create Corrective Action?						
N/A						
Comments:						
Comments:						
The site was active for paving during t	he last inspection.					
Findings / Corrective Actions (Date)						
Findings / Corrective Actions (Date)						
1.) Some maintenance is required in th	ne BMP section at this time.					
3.) All bare areas on-site that have been		be seeded. HRC Develo	pment was informed to con	nplete by 11/21/23.	Not done as of the	
last inspection.	•		•			
Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley pav	ed all entrances prior	to the inspection on 12/5/	23.		
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Develo	opment installed the div	ersion prior to the inspection	n on 5/23/23.		
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develop	ment installed the dive	rsion prior to the inspection	on 5/23/23. K2 Co	nstruction removed	
	sections of the diversion for s					
			•			
	Diversion should be reinstalled where removed for sanitary installation.					

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	X-11		Removed	
Current Condition:	Removed - Echo Valley pav	ed all entrances prior	to the inspection on 12/5/	23.	
D1	Diversion	D-8 to K-8	5/23/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the div	ersion prior to the inspection	n on 5/23/23.	•
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop sections of the diversion for some diversion for some diversion should be reinstalled.	anitary sewer installatio	on prior to the inspection on		nstruction removed
	K2 Construction was informer reminded on 10/18/23, 11/16		9/23. Not done as of the last inspection. K2 Construction was		
D3	Diversion Fair Condition - HRC Develop	Southeast of SB A	5/23/2023	Active	Yes
	Diversion should be extended  K2 Construction was informed bevelopment was reminded of	d to complete by 10/24/		·	
D4	Diversion	South of SB A	5/23/2023	Active	Yes
	sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23.  Diversion should be reinstalled where removed for sanitary installation.  K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was informed to complete by 9/19/23.				
	K2 Construction was informe	d to complete by 9/19/2	·	spection. K2 Cons	truction was
ET 1		d to complete by 9/19/2	·	spection. K2 Cons	truction was
ET 1 Current Condition:	K2 Construction was informe reminded on 10/18/23, 11/16.	d to complete by 9/19/2 /23 B-9 to G-10	3. Not done as of the last in 6/6/2023	Active	No
	K2 Construction was informereminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2 /23  B-9 to G-10 opment installed the ero B-9 to I-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.
Current Condition:	K2 Construction was informereminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2 /23  B-9 to G-10 opment installed the ero B-9 to I-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3	K2 Construction was informe reminded on 10/18/23, 11/16/ Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	d to complete by 9/19/2  B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active	No 6/6/23. No 6/6/23. No
Current Condition: ET 2 Current Condition:	K2 Construction was informereminded on 10/18/23, 11/16 Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	d to complete by 9/19/2  B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active	No 6/6/23. No 6/6/23. No
Current Condition:  ET 2  Current Condition:  ET 3  Current Condition:  ET 4	K2 Construction was informe reminded on 10/18/23, 11/16  Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active	No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No
Current Condition:  ET 2  Current Condition:  ET 3  Current Condition:	K2 Construction was informe reminded on 10/18/23, 11/16  Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active the inspection on Active the inspection on Active	No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No
Current Condition:  ET 2  Current Condition:  ET 3  Current Condition:  ET 4	K2 Construction was informe reminded on 10/18/23, 11/16.  Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc I-7 to M-2 Q-10 to Q-8	3. Not done as of the last in 6/6/2023 sion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	K2 Construction was informe reminded on 10/18/23, 11/16.  Erosion Control Terraces Good Condition - HRC Devel	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc I-7 to M-2 Q-10 to Q-8	3. Not done as of the last in 6/6/2023 sion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5	K2 Construction was informe reminded on 10/18/23, 11/16.  Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	B-9 to G-10 opment installed the erc B-9 to I-10 opment installed the erc B-7 to K-10 opment installed the erc I-7 to M-10 opment installed the erc I-7 to M-2 Q-10 to Q-8	3. Not done as of the last in 6/6/2023 sion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	K2 Construction was informer reminded on 10/18/23, 11/16.  Erosion Control Terraces Good Condition - HRC Develerosion Control Terraces	B-9 to G-10 opment installed the ero B-7 to K-10 opment installed the ero B-7 to K-10 opment installed the ero I-7 to M-10 opment installed the ero I-0 to Q-8 opment installed the ero R-10 to R-7	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.  No 6/6/23.
Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition: ET 5	K2 Construction was informereminded on 10/18/23, 11/16.  Erosion Control Terraces Good Condition - HRC Develerosion Control Terraces	B-9 to G-10 opment installed the ero B-7 to K-10 opment installed the ero B-7 to K-10 opment installed the ero I-7 to M-10 opment installed the ero I-0 to Q-8 opment installed the ero R-10 to R-7	3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active the inspection on Active	No 6/6/23.   No 6/6/23.   No 6/6/23.   No 6/6/23.   No 6/6/23.

FT 1 Current Condition:	Fire! Table	On site	10/0/000	Dandina	NI-
	Fuel Tank Pending - Ruff Grading bro	On site	rior to the inspection on 12/	Pending /6/22 Ruff Grading (	No removed the fuel t
	from site during the inspect inspection on 4/11/23. Ruff 5/2/23.	tion on 3/28/23. Ruff Grad	ding installed a fuel tank an	id secondary contair	nment prior to the
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material ar	nd vehicle staging area or	ccurring on-site by Ruff fue	tanker as of 12/26/	22
PB 1	Portable toilet	On site	4/11/2023	Active	No
Current Condition:	Good Condition - Ruff Grad Grading secured the portab Morgan Ridge subdivision p site prior to the inspection on 10/24/23. Echo Valley in	ole toilet during the inspec prior to the inspection on on 8/29/23. K2 Constructi	ction on 4/18/23. Ruff Grad 5/2/23. K2 Construction ins ion removed the portable to	ing moved the porta stalled and secured oilet from the site pri	ble toilet to the a portable toilet or or to the inspectio
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes
Current Condition:	Fair Condition - HRC Devel in the process of installing triser prior to the inspection inspection on 11/28/23.  Dewatering holes should be	the riser and outfall pipe of on 11/14/23. <b>E&amp;A inspe</b>		<mark>/7/23. HRC Develop</mark>	ment installed the
	HRC Development was info		/21/23 Not done as of the I	ast inspection	
SB B	Sediment Basin	L-7	3/21/2023	Pending	Yes
Current Condition:	Pending - HRC Developme				162
	1.) HRC Development was reminded on 5/4/23, 6/21/2 2.) HRC Development was		16/23		RC Development v
SF 1	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Dev cleaned out the silt fence ir silt fence checks in multiple	n multiple locations prior t	to the inspection on 3/6/23.		
SF 2	Silt fence	West edge of site	11/29/2022	Active	Yes
Current Condition:	Fair Condition - HRC Devel trenched in the silt fence who prior to the inspection on 3/1.) Silt fence should be rep 2.) Silt fence should be rein	here undermined prior to /28/23.  aired where damage on t	the inspection on 3/6/23. He the north side of the site.		
	1.) K2 Construction was inf		19/23. Not done as of the la	ast inspection. K2 Co	onstruction was
	1.) K2 Construction was infreminded on 10/18/23, 11/2.) HRC Development was	16/23			onstruction was
SF 3	reminded on 10/18/23, 11/2 2.) HRC Development was	16/23			onstruction was
SF 3 Current Condition:	reminded on 10/18/23, 11/1	informed to complete by  East edge of site velopment installed the sil	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspection	he last inspection.  Active on on 3/14/23. Due	No
Current Condition: WO 1	reminded on 10/18/23, 11/2 2.) HRC Development was  Silt fence Good Condition - HRC Development was along the edge of the site in Concrete Washout	informed to complete by East edge of site relopment installed the sil hear Daniel Street is no lo	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspectionger necessary as of 5/23/	he last inspection.  Active on on 3/14/23. Due /23.  Active	No to the grade silt fe
Current Condition:	reminded on 10/18/23, 11/7 2.) HRC Development was  Silt fence  Good Condition - HRC Develong the edge of the site	informed to complete by East edge of site relopment installed the sil near Daniel Street is no lo On site ley installed a concrete w	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspectionger necessary as of 5/23/ 11/21/2023 vashout on site prior to the inspections.	he last inspection.  Active on on 3/14/23. Due /23.  Active inspection on 11/21/	No to the grade silt fe
Current Condition:  WO 1  Current Condition:	reminded on 10/18/23, 11/7 2.) HRC Development was  Silt fence  Good Condition - HRC Development was along the edge of the site in Concrete Washout  Good Condition - Echo Valled	informed to complete by East edge of site relopment installed the sil near Daniel Street is no lo On site ley installed a concrete w	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspectionger necessary as of 5/23/ 11/21/2023 vashout on site prior to the inspections.	he last inspection.  Active on on 3/14/23. Due /23.  Active inspection on 11/21/	No to the grade silt fe
Current Condition: WO 1	reminded on 10/18/23, 11/2 2.) HRC Development was Silt fence Good Condition - HRC Devalong the edge of the site n Concrete Washout Good Condition - Echo Vall installed a second concrete	informed to complete by East edge of site relopment installed the sil near Daniel Street is no lo On site ley installed a concrete wete washout pit with line On site y no need for a designate; the E&A inspector will or	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspection or necessary as of 5/23/ 11/21/2023 Vashout on site prior to the inspection of the i	he last inspection.  Active on on 3/14/23. Due /23.  Active inspection on 11/21/ on 12/5/23.  Pending	No to the grade silt fe  No 23. Echo Valley
WO 1 Current Condition:  WS 1 Current Condition:	reminded on 10/18/23, 11/2.) HRC Development was  Silt fence Good Condition - HRC Development was along the edge of the site in Concrete Washout Good Condition - Echo Valletinstalled a second concrete Waste Storage Area Pending - There is currently generated or stored on-site	informed to complete by East edge of site relopment installed the sil near Daniel Street is no lo On site ley installed a concrete wete washout pit with line On site y no need for a designate to the teach inspector will concern to the silvert of	11/21/23. Not done as of the 3/14/2023 It fence prior to the inspection onger necessary as of 5/23/ 11/21/2023 //ashout on site prior to the inspection 11/4/2022 ed waste storage area on-sicontinue to monitor.	he last inspection.  Active on on 3/14/23. Due 23.  Active inspection on 11/21/ on 12/5/23.  Pending ite due to no waste r	No to the grade silt fe  No 23. Echo Valley  No materials being
Current Condition:  WO 1 Current Condition:  WS 1	reminded on 10/18/23, 11/2.) HRC Development was  Silt fence Good Condition - HRC Development was along the edge of the site in Concrete Washout Good Condition - Echo Valletinstalled a second concrete Waste Storage Area Pending - There is currently	informed to complete by East edge of site relopment installed the sil near Daniel Street is no lo On site ley installed a concrete wete washout pit with line On site y no need for a designate to the test of the silver of the s	11/21/23. Not done as of the 3/14/2023  It fence prior to the inspection or necessary as of 5/23/ 11/21/2023  vashout on site prior to the inspection of the	he last inspection.  Active on on 3/14/23. Due /23.  Active inspection on 11/21/ on 12/5/23.  Pending	No to the grade silt fe  No 23. Echo Valley
WO 1 Current Condition:  WS 1 Current Condition:  STR	reminded on 10/18/23, 11/2.) HRC Development was  Silt fence Good Condition - HRC Development was along the edge of the site in Concrete Washout Good Condition - Echo Valletinstalled a second concrete Waste Storage Area Pending - There is currently generated or stored on-site Streets  Fair Condition -	informed to complete by East edge of site relopment installed the sil hear Daniel Street is no lo On site ley installed a concrete wete washout pit with line On site y no need for a designate to the E&A inspector will on the ley installed a concrete wete washout pit with line And the concrete wete washout pit with line Sensington Road, N. 168th Street  Cleaned daily or as neededed to complete by 10/18.	3/14/2023 It fence prior to the inspection or necessary as of 5/23/ 11/21/2023 Vashout on site prior to the inspection or to the inspec	Active on on 3/14/23. Due //23.  Active inspection on 11/21/ on 12/5/23.  Pending ite due to no waste r  Active	No to the grade silt fe  No 23. Echo Valley  No naterials being

Current Condition:	Good Condition - SWPPP inspecto	r installed the sign during the inspection on 12/20/22.	
Certification Statement:	direction or supervision in accordar properly gathered and evaluated th persons who manage the system o the information submitted is, to the	this document and all attachments were prepared under my note with a system designed to assure that qualified personnel in information submitted. Based on my inquiry of the person or introse persons directly responsible for gathering the information, best of my knowledge and belief, true, accurate, and complete. I penalties for submitting false information including the possibility ing violations."	
Inspector Signature:	Breya M Zlaght	Reviewed By:	