

## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

E&A - P2019.032.000					
Inspector: Bryce Wright				Stage	
	Kempten Creek 2			0	
Ducia et Nove e	CSW-202106167			1	
Project Name:					
For Week Ending:	1/13/2024				
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)			68007	
Ourse alline and	4000/				
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	90%				
Seeding:	40%				
Utilities:	0%				
Overall Development:	30%				
				1	1
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
Sunday	0.00"				Week 1
Sunday: Monday:	0.00" 0.26"				
Tuesday:	0.05"	1/9/2024	Overcast 19	11:35 AM	
Wednesday:	0.05	1/9/2024	Overcast 19	11.35 AW	
	0.00"				
Friday:	0.00"				
	0.00"				
	0.00				
	[				
Complaints:					
Construction Sequencing:					
Which portion(s) (i.e. drainage basin last 14 days?	is) of the site have had a ten	nporary or permane	nt cessation of grading, e	arthwork, or ground	d disturbance in the
Grading Began (11/29/22). Grading cea	ased (12/20/23). Grading resu	med on site (3/14/23	). Spreading top soil across	entire site (5/16/23).	Final grade reached
Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began					
(11/14/23). Paving and construction ceased on site (1/2/24).					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?					
Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached					
and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began					
(11/14/23). Paving and construction ceased on site (1/2/24).					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Existing Vegetation (11/29/22).			<b></b>		
3 3 ( 2 4 7					
Checklist Questions:					
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?					
Yes					
Create Corrective Action?					
N/A					
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.					
No					
Create Corrective Action?					
No, See findings section					

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
The site was inactive during the last inspection.
Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	X-11		Removed	
Current Condition:	Removed - Echo Valley pave	d all entrances prior to	the inspection on 12/5/23.		
D1	Diversion	D-8 to K-8	5/23/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the div	version prior to the inspection	n on 5/23/23.	
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	anitary sewer installation ad where removed for sind d to complete by 9/19/2	on prior to the inspection on anitary installation.	8/29/23.	
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop				103
	K2 Construction was informe Development was reminded of	on 11/16/23			
D4 Current Condition:		on 11/16/23 South of SB A oment installed the dive	5/23/2023 rsion prior to the inspection	Active on 5/23/23. K2 Co	Yes
	Development was reminded of Diversion Fair Condition - HRC Develop	on 11/16/23 South of SB A Soment installed the dive canitary sewer installation of where removed for sa d to complete by 9/19/2	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation.	Active on 5/23/23. K2 Cc 8/29/23.	Yes nstruction remov
	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe	on 11/16/23 South of SB A Soment installed the dive canitary sewer installation of where removed for sa d to complete by 9/19/2	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation.	Active on 5/23/23. K2 Cc 8/29/23.	Yes nstruction remov
Current Condition:	Development was reminded of Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	Yes Instruction remov struction was
Current Condition: ET 1	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for sections     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Develop     Erosion Control Terraces	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	Yes Instruction remov
Current Condition: ET 1 Current Condition:	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Develop	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	Yes Instruction remov
ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Develop     Erosion Control Terraces	on 11/16/23 South of SB A coment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the ero B-9 to I-10 opment installed the ero B-7 to K-10	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   3. Not done as of the last in 6/6/2023   osion control terrace prior to 6/6/2023   osion control terrace prior to 6/6/2023   osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	Yes Instruction remov
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Develop     Erosion Control Terraces     Good Condition - HRC Develop     Erosion Control Terraces     Good Condition - HRC Develop	on 11/16/23 South of SB A coment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the ero B-9 to I-10 opment installed the ero B-7 to K-10	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   3. Not done as of the last in 6/6/2023   osion control terrace prior to 6/6/2023   osion control terrace prior to 6/6/2023   osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	Yes Instruction removes Struction was No 6/6/23. No 6/6/23. No
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for se d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   3. Not done as of the last in 6/6/2023   osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction removes     Struction was     No     6/6/23.     6/6/23.     No
ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informe     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for se d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   3. Not done as of the last in 6/6/2023   osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction removes     Struction was     No     6/6/23.     6/6/23.     No
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for se d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   3. Not done as of the last in 6/6/2023   osion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction removes     Struction was     No     6/6/23.     6/6/23.     No
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for sections of the diversion for sections     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for se d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   anitary installation.   3. Not done as of the last in 6/6/2023   psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction removes     struction was     No     6/6/23.     No
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for s     Diversion should be reinstalled     K2 Construction was informe     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A coment installed the dive canitary sewer installation ad where removed for se d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   anitary installation.   3. Not done as of the last in 6/6/2023   psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction remove     struction was     No     6/6/23.     No
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Development was reminded of     Diversion     Fair Condition - HRC Develop     sections of the diversion for sections of the diversion for sections     Diversion should be reinstalled     K2 Construction was informered     reminded on 10/18/23, 11/16     Erosion Control Terraces     Good Condition - HRC Devel	on 11/16/23 South of SB A South of SB A coment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error I-7 to K-10 opment installed the error Q-10 to Q-8 opment installed the error Q-10 to Q-8 opment installed the error R-10 to R-7	5/23/2023   rsion prior to the inspection on prior to the inspection on anitary installation.   anitary installation.   3. Not done as of the last in 6/6/2023   psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Cc 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Yes     Instruction remove     Instruction was     No     6/6/23.     No     6/6/23.

Current Condition:	Good Condition - HRC Deve	lopment installed the ero	psion control terrace prior t	o the inspection on	6/6/23.
FT 1	Fuel Tank	On site	12/6/2022	Pending	No
Current Condition:	Pending - Ruff Grading broug from site during the inspection inspection on 4/11/23. Ruff C 5/2/23.	on on 3/28/23. Ruff Grad	ing installed a fuel tank an ank to the Morgan Ridge s	d secondary contair	nment prior to the
MS 1	Material Storage Area	On site	11/4/2022	Active	No
Current Condition:	Good Condition-Material and	l vehicle staging area oc	curring on-site by Ruff fuel		22
PB 1	Portable toilet	On site	4/11/2023	Pending	No
Current Condition:	<b>Pending</b> - Ruff Grading insta secured the portable toilet du subdivision prior to the inspe inspection on 8/29/23. K2 Co Echo Valley installed and sec portable toilet from the site	uring the inspection on 4 ction on 5/2/23. K2 Con onstruction removed the cured a portable toilet or	/18/23. Ruff Grading move struction installed and secu portable toilet from the site a site prior to the inspection	d the portable toilet ured a portable toile prior to the inspect	to the Morgan Rid t on site prior to the tion on 10/24/23.
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develo in the process of installing th riser prior to the inspection o 11/28/23. Dewatering holes should be HRC Development was infor	e riser and outfall pipe on 11/14/23. E&A inspection in the riser.	uring the inspection on 11, tor painted the cleanout ma	/7/23. HRC Develop ark on the riser durin	ment installed the
SB B	Sediment Basin	L-7	3/21/2023	Pendina	Yes
	the erosion on the outerbank Basin should be installed per HRC Development was infor reminded on 5/4/23, 6/21/23,	r plan. med to complete by 3/20	3/23. Not done as of the la	st inspection. HRC	Development was
SF 1	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Deve cleaned out the silt fence in r silt fence checks in multiple l	multiple locations prior to	the inspection on 3/6/23.		
SF 2	Silt fence	West edge of site	11/29/2022	Active	No
Current Condition:	Good Condition - HRC Devel trenched in the silt fence whe prior to the inspection on 3/2 12/12/23.	ere undermined prior to	the inspection on 3/6/23. H	RC Development re	epaired the silt fend
SF 3	Silt fence	East edge of site	3/14/2023	Active	No
Current Condition:	Good Condition - HRC Deve along the edge of the site ne				to the grade silt fer
WO 1	Concrete Washout	On site	11/21/2023	Pending	No
Current Condition:	Pending - Echo Valley install second concrete washout pit on site and pile up concrete	with liner prior to the ins	spection on 12/5/23. Echo	Valley removed the	
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No
Current Condition:	Pending - There is currently generated or stored on-site;	the E&A inspector will c		te due to no waste r	materials being
стр	Straata	Bennington Road, N.	11///2022	Active	No
STR Current Condition:	Streets Good Condition - HRC Devel	168th Street	11/4/2022	Active	No tion on 12/19/23
				- ·	1
SWPPP Sign	SWPPP Notification Sign	Adjacent to CE 1	11/4/2022	Active	No
Current Condition: Certification Statement:	Good Condition - SWPPP in: "I certify, under penalty of law direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is, am aware that there are sign of fines and imprisonment fo	w, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	d all attachments were pre designed to assure that qu mitted. Based on my inquin irectly responsible for gath edge and belief, true, accu	pared under my ualified personnel y of the person or ering the informatio rate, and complete.	I

Inspector Signature:	
----------------------	--

Broger M Wayht

	Cate Sales
Reviewed By:	