

## Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

	E	&A - P2019.032.00	10				
Inspector: Bryce Wright					Stage		
		Kempten C	Creek 2				
Ducie of Nove of		CSW-2021			1		
Project Name:		1/20/20					
For Week Ending:							
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)         68007						
	1	I					
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	90%						
Seeding:	40%						
Utilities:	0%						
Overall Development:	30%						
	<b>I.</b>						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
Sunday:	0.00"				Week 1		
Monday:	0.00"						
Tuesday:	0.00"	1/16/2024	Sunny 2	12:05 PM			
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
Complaints:							
•							
Construction Sequencing:							
Which portion(s) (i.e. drainage basir last 14 days?	ns) of the site have had a ter	mporary or permanent	t cessation of grading, ea	arthwork, or ground	disturbance in the		
Grading Began (11/29/22). Grading ce	ased (12/20/23). Grading resu	med on site (3/14/23).	Spreading top soil across	entire site (5/16/23).	Final grade reached		
and grading ceased across the entire s							
(11/14/23). Paving and construction ce		<b>U</b> (	,	υ ( )	0 0		
Which portion(s) (i.e. drainage basir	as) of the site do not have a	rading earthwork or	around disturbance sch	duled in the next 1	4 days?		
Grading Began (11/29/22). Grading ce							
and grading ceased across the entire s							
(11/14/23). Paving and construction ce		instantion began (6/20		ion began (10/0/20).	r aving bogan		
What temporary or permanent stabi		his section are being i	implemented?				
Existing Vegetation (11/29/22).							
Checklist Questions:							
Are receiving waters adjacent to the project fr	ree of any significant signs of erosi	on or sediment that would b	be associated with the construct	tion activity?			
Yes							
Create Corrective Action?							
N/A							
Have disturbed areas been seeded or otherwi	se stabilized as required? List inset	tive portions of the project	and if stabilization measure are	adequate or needed to r	revent erosion		
No	ee etaemizee ae requiree : List maci	and portions of the project	and in orabilization measure are	anoquate of fielded to			
Create Corrective Action?							
No, See findings section							

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
The site was inactive during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section at this time. 2.) All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection.

## 3.) Due to snow cover not all BMPs could be observed during the most recent inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley pave	d all entrances prior to	the inspection on 12/5/23.			
D1	Diversion	D-8 to K-8	5/23/2023	Active	No	
Current Condition:	Good Condition - HRC Devel	opment installed the div	version prior to the inspectio	n on 5/23/23.		
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	<ul> <li>Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23.</li> <li>Diversion should be reinstalled where removed for sanitary installation.</li> <li>K2 Construction was informed to complete by 9/19/23. Not done as of the last inspection. K2 Construction was reminded on 10/18/23, 11/16/23</li> </ul>					
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. Diversion should be extended east across Kempten Creek Drive to prevent sediment from washing onto the street. K2 Construction was informed to complete by 10/24/23. Not done as of the last inspection. K2 Construction and HRC					
		44/40/00		· · · · · · · · · · · · · · · · · · ·		
D4 Current Condition:	Development was reminded Diversion	South of SB A	5/23/2023	Active	Yes	
D4 Current Condition:	Development was reminded Diversion Fair Condition - HRC Develo sections of the diversion for s Diversion should be reinstalle K2 Construction was informe	South of SB A pment installed the dive canitary sewer installation ad where removed for sa d to complete by 9/19/2	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation.	Active on 5/23/23. K2 Co 8/29/23.	nstruction removed	
Current Condition:	Development was reminded Diversion Fair Condition - HRC Develop sections of the diversion for s Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. (3. Not done as of the last in	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons	nstruction removed	
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop           sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. (3. Not done as of the last in 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active	nstruction removed	
Current Condition: ET 1 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develop           sections of the diversion for s           Diversion should be reinstalled           K2 Construction was informed           reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develop	South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the ered	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on	struction removed	
Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces           Good Condition - HRC Developsector	South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the ere B-9 to I-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	struction removed truction was No 6/6/23.	
Current Condition: ET 1 Current Condition: ET 2	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces           Good Condition - HRC Developsector	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active	struction removed truction was No 6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces	South of SB A pment installed the dive sanitary sewer installation ad where removed for sa d to complete by 9/19/2 /23 B-9 to G-10 opment installed the ered B-9 to I-10 opment installed the ered B-7 to K-10	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	struction removed truction was No 6/6/23. No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces           Good Condition - HRC Developsector           Erosion Control Terraces           Good Condition - HRC Developsector	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error	5/23/2023 rsion prior to the inspection on prior to the inspection on anitary installation. 3. Not done as of the last in 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active	struction removed truction was No 6/6/23. No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informereminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsector	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	No           6/6/23.           6/6/23.           No           6/6/23.           No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections and the diversion for sections should be reinstalled           Diversion should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Develoption	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	No           6/6/23.           6/6/23.           No           6/6/23.           No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for the divers	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Instruction removed Instruction was No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23.	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: ET 5	Development was reminded           Diversion           Fair Condition - HRC Developsections of the diversion for sections of the diversion for sections and the diversion of the diversion for sections should be reinstalled           K2 Construction was informed reminded on 10/18/23, 11/16           Erosion Control Terraces           Good Condition - HRC Developsection	South of SB A pment installed the dive sanitary sewer installation ad where removed for said d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023         rsion prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Instruction removed Instruction was No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No	
Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Development was reminded           Diversion           Fair Condition - HRC Develops           sections of the diversion for sections (Section Control Terraces)           Good Condition - HRC Developed           Erosion Control Terraces           Good Condition - HRC Developed	South of SB A pment installed the dive sanitary sewer installation and where removed for since d to complete by 9/19/2 /23 B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8 opment installed the error R-10 to R-7	5/23/2023         rsion prior to the inspection on prior to the inspection on prior to the inspection on anitary installation.         3. Not done as of the last in 6/6/2023         psion control terrace prior to 6/6/2023	Active on 5/23/23. K2 Co 8/29/23. spection. K2 Cons Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Instruction removed Instruction was No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23.	

Current Condition:	Good Condition - HRC Devel	1			1	
FT 1	Fuel Tank	On site	12/6/2022	Pending	No	
Current Condition:	Pending - Ruff Grading broug from site during the inspection inspection on 4/11/23. Ruff G 5/2/23.	on on 3/28/23. Ruff Grad	ing installed a fuel tank and	d secondary contair	nment prior to the	
MS 1	Material Storage Area	On site	11/4/2022	Active	No	
Current Condition:	Good Condition-Material and	vehicle staging area oc	curring on-site by Ruff fuel	tanker as of 12/26/	22	
PB 1	Portable toilet	On site	4/11/2023	Pending	No	
Current Condition:	Pending - Ruff Grading insta secured the portable toilet du subdivision prior to the inspe inspection on 8/29/23. K2 Co Echo Valley installed and sec portable toilet from the site p	uring the inspection on 4 ction on 5/2/23. K2 Con onstruction removed the cured a portable toilet or	/18/23. Ruff Grading move struction installed and secu portable toilet from the site n site prior to the inspectior	d the portable toilet ured a portable toile prior to the inspec	to the Morgan Ric t on site prior to th tion on 10/24/23.	
SB A	Sediment Basin	Z-9	11/14/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develo in the process of installing th riser prior to the inspection o 11/28/23. Dewatering holes should be HRC Development was infor	e riser and outfall pipe on n 11/14/23. E&A inspection installed in the riser.	uring the inspection on 11/ tor painted the cleanout ma	7/23. HRC Develop ark on the riser durin	ment installed the	
SB B		L-7	3/21/2023	1	Yes	
Current Condition:	Sediment Basin       L-7       3/21/2023       Pending       Yes         Pending - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC Development repaired the erosion on the outerbank of the basin prior to the inspection on 12/12/23.       Basin should be installed per plan.					
	HRC Development was infor reminded on 5/4/23, 6/21/23,	, 8/22/23, 10/18/23, 11/1	6/23	-	1	
SF 1	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Devel cleaned out the silt fence in r silt fence checks in multiple I	nultiple locations prior to	the inspection on 3/6/23.			
SF 2	Silt fence	West edge of site	11/29/2022	Active	No	
Current Condition:	Good Condition - HRC Devel trenched in the silt fence whe prior to the inspection on 3/2 12/12/23.	ere undermined prior to	he inspection on 3/6/23. H	RC Development re	epaired the silt fend	
SF 3	Silt fence	East edge of site	3/14/2023	Active	No	
Current Condition:	Good Condition - HRC Deve along the edge of the site ne	lopment installed the sill	fence prior to the inspection		to the grade silt fe	
WO 1	Concrete Washout	On site	11/21/2023	Pending	No	
Current Condition:	Pending - Echo Valley installed a concrete washout on site prior to the inspection on 11/21/23. Echo Valley installed a second concrete washout pit with liner prior to the inspection on 12/5/23. Echo Valley removed the concrete washout on site and pile up concrete rubble in preparation for removal prior to the inspection on 12/1/23.					
WS 1	Waste Storage Area	On site	11/4/2022	Pending	No	
Current Condition:	Pending - There is currently generated or stored on-site;	no need for a designate the E&A inspector will c	d waste storage area on-sit	te due to no waste r	materials being	
STR	Straata	Bennington Road, N. 168th Street	11///2022	Activo	No	
Current Condition:	Streets Good Condition - HRC Devel		11/4/2022 I interior and exterior street	Active	No tion on 12/19/23.	
		1	I	1	1	
SWPPP Sign Current Condition:	SWPPP Notification Sign Good Condition - SWPPP in:	Adjacent to CE 1	11/4/2022	Active	No	
ertification Statement:	"I certify, under penalty of law direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is, am aware that there are sign of fines and imprisonment fo	w, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	d all attachments were pre designed to assure that qu mitted. Based on my inquir irectly responsible for gath edge and belief, true, accu	pared under my Jalified personnel y of the person or ering the informatio rate, and complete.	I	

Inspector Signature:

Broga M Wayht

Parto Sul Reviewed By: