E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599



Zachary A. Jilek, CPESC, CISEC

www.eacg.com

Engineering Answers

	. Manager E	&A - P2019.032.0	000			
Inspector: Bryce Wright					Stage	
Project Name:		1				
For Week Ending:						
Project Location:	North 168th Street	3/30/2024 North 168th Street and Bennington Road - Bennington, NE (Douglas County)				
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	90%					
Seeding:	40%					
Utilities:	0%					
Overall Development:	30%					
·						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
					Week	
Sunday:	0.55"					
Monday:	0.12"					
Tuesday:	0.00"	3/26/2024	Overcast 25	12:45 PM		
Wednesday:	0.00"					
Wednesday: Thursday:	0.00" 0.00"					
Tuesday: Wednesday: Thursday: Friday:	0.00"					

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading Began (11/29/22). Grading ceased (12/20/23). Grading resumed on site (3/14/23). Spreading top soil across entire site (5/16/23). Final grade reached and grading ceased across the entire site (5/23/23). Sanitary sewer installation began (8/29/23). Storm sewer installation began (10/9/23). Paving began (11/14/23). Paving and construction ceased on site (1/2/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (11/29/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See findings section

Are waste materials (concrete, construction n	naterial, hazardous, etc.) being man	aged properly?			
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and adjacent stre	ote hoing maintained adequately?				
Yes	ets being maintained adequatery:				
Create Corrective Action?					
N/A					
Is dust associated with the construction activ	ity adequately controlled on the site	e?			
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments: The site was inactive during the last in	spection.				
Findings / Corrective Actions (Date)	:				
Findings / Corrective Actions (Date)					
1.) Some maintenance is required in the	ne BMP section at this time.				
2.) All bare areas on-site that have bee		be seeded. HRC Develo	opment was informed to co	mplete by 11/21/23	. Not done as of the
last inspection. K2 Construction was re	eminded on 2/15/24, 3/21/24				
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	X-11		Removed	
Current Condition:	Removed - Echo Valley pave	ed all entrances prior to t	the inspection on 12/5/23.	!	!
D1	Diversion	D-8 to K-8	5/23/2023	Active	No
Current Condition:	Good Condition - HRC Devel				
D2	Diversion	East of SB B	5/23/2023	Active	Yes
Current Condition:					
Current Condition.	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23. K2 Construction removed sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23.				
		January Cowor motamatic	in prior to are inopedadir on	0/20/20.	
	Diversion should be reinstalled	ed where removed for sa	anitary installation.		
			,		
	K2 Construction was informe	d to complete by 9/19/2	<mark>3. Not done as of the last ir</mark>	nspection. K2 Cons	truction was
	reminded on 10/18/23, 11/16	/23, 2/15/24, 3/21/24			
D3	Diversion	Southeast of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop	pment installed the dive	rsion prior to the inspection	on 5/23/23.	
	Diversion should be extended	d east across Kempten	Creek Drive to prevent sed	<mark>iment from washing</mark>	onto the street.
	K2 Construction was informe			inspection. K2 Con	struction and HRC
	Development was reminded	on 11/16/23, 2/15/24, 3/	21/24		
D4	Diversion	South of SB A	5/23/2023	Active	Yes
Current Condition:	Fair Condition - HRC Develop	pment installed the dive	rsion prior to the inspection	on 5/23/23. K2 Co	nstruction removed
	sections of the diversion for sanitary sewer installation prior to the inspection on 8/29/23.				
Diversion should be reinstalled where removed for sanitary installation.					
	reminded on 10/18/23, 11/16			1	1 .
ET 1	Erosion Control Terraces	B-9 to G-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	T .			6/6/23.
ET 2	Erosion Control Terraces	B-9 to I-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	opment installed the ero	osion control terrace prior to	the inspection on	6/6/23.
ET 3	Erosion Control Terraces	B-7 to K-10	6/6/2023	Active	No
Current Condition:	Good Condition - HRC Devel	anmont installed the are	sion control terrace prior to	the increation on	6/6/23

I-7 to M-10

Q-10 to Q-8

R-10 to R-7

Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.

Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.

Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.

6/6/2023

6/6/2023

6/6/2023

No

No

No

Active

Active

Active

ET 4

Current Condition:

ET 5

Current Condition:

ET 6

Current Condition:

Erosion Control Terraces

Erosion Control Terraces

Erosion Control Terraces

ET 7	Erosion Control Terraces S-7 to U-10 6/6/2023 Active No
Current Condition:	Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.
FT 1	Fuel Tank On site 12/6/2022 Pending No
Current Condition:	Pending - Ruff Grading brought a fuel tank on site prior to the inspection on 12/6/22. Ruff Grading removed the fuel from site during the inspection on 3/28/23. Ruff Grading installed a fuel tank and secondary containment prior to the inspection on 4/11/23. Ruff Grading moved the fuel tank to the Morgan Ridge subdivision prior to the inspection on 5/2/23.
MS 1	Material Storage Area On site 11/4/2022 Active No
Current Condition:	Good Condition-Material and vehicle staging area occurring on-site by Ruff fuel tanker as of 12/26/22
PB 1	Portable toilet On site 4/11/2023 Pending No
Current Condition:	Pending - Ruff Grading installed and secured a portable toilet on site prior to the inspection on 4/11/23. Ruff Grading secured the portable toilet during the inspection on 4/18/23. Ruff Grading moved the portable toilet to the Morgan R subdivision prior to the inspection on 5/2/23. K2 Construction installed and secured a portable toilet on site prior to t inspection on 8/29/23. K2 Construction removed the portable toilet from the site prior to the inspection on 10/24/23. Echo Valley installed and secured a portable toilet on site prior to the inspection on 11/28/23. Echo Valley removed portable toilet from the site prior to the inspection on 1/9/24.
SB A	Sediment Basin Z-9 11/14/2023 Active Yes Fair Condition - 20% filled - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC
	Development was in the process of installing the riser and outfall pipe during the inspection on 11/7/23. HRC Development installed the riser prior to the inspection on 11/14/23. E&A inspector painted the cleanout mark on the during the inspection on 11/28/23. Dewatering holes should be installed in the riser. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. HRC Development was reminded on 2/15/24, 3/21/24
SB B	Sediment Basin L-7 3/21/2023 Active No
Current Condition:	Good Condition - 5% filled - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC Development repaired the erosion on the outerbank of the basin prior to the inspection on 12/12/23. HRC Development installed the riser prior to the inspection on 2/13/24. E&A inspector painted the cleanout mark during the 2/20/24 inspection.
SF 1	Silt fence West edge of site 11/29/2022 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development cleaned out the silt fence in multiple locations prior to the inspection on 3/6/23. HRC Development installed addition silt fence checks in multiple high flow areas prior to the inspection on 3/14/23.
SF 2	Silt fence West edge of site 11/29/2022 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development trenched in the silt fence where undermined prior to the inspection on 3/6/23. HRC Development repaired the silt fer prior to the inspection on 3/28/23. HRC Development repaired the entire run of silt fence prior to the inspection on 12/12/23.
SF 3	Silt fence East edge of site 3/14/2023 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 3/14/23. Due to the grade silt f along the edge of the site near Daniel Street is no longer necessary as of 5/23/23.
WO 1	Concrete Washout On site 11/21/2023 Pending No
Current Condition:	Pending - Echo Valley installed a concrete washout on site prior to the inspection on 11/21/23. Echo Valley installed second concrete washout pit with liner prior to the inspection on 12/5/23. Echo Valley removed the concrete washout on site and pile up concrete rubble in preparation for removal prior to the inspection on 12/12/23.
WS 1	Waste Storage Area On site 11/4/2022 Pending No
Current Condition:	Pending - There is currently no need for a designated waste storage area on-site due to no waste materials being generated or stored on-site; the E&A inspector will continue to monitor.
STR	Bennington Road, N. Streets 168th Street 11/4/2022 Active No
STR Current Condition:	Bennington Road, N.
	Bennington Road, N. Streets 168th Street 11/4/2022 Active No

Certification Statement:	direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is,	w, that this document and all attachments were preportion of the information submitted. Based on my inquirestem or those persons directly responsible for gathe to the best of my knowledge and belief, true, accurificant penalties for submitting false information incoming violations."	ualified personnel y of the person or ering the informati rate, and complete	e. l [°]
Inspector Signature:	Brya M Waght		Reviewed Bv:	Post Sul