

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Mana		&A - P2019.032.0	00				
Inspector: Bryce Wright					Stage		
Project Name:		1					
For Week Ending:	CSW-202106167 9/7/2024						
Project Location:	North 168th Street and Bennington Road - Bennington, NE (Douglas County)				68007		
	North Tooth Street a	and Demnigton Roa		jias county)			
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	90%						
Seeding:	40%						
Utilities:	35%						
Overall Development:	30%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
					Week 1		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"	9/3/2024	Sunny 74	10:10 AM			
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
	•			•	•		
Complaints:							
Construction Sequencing:							
Which portion(s) (i.e. drainage basir last 14 days?	·			· · ·			
Grading Began (11/29/22). Grading cea and grading ceased across the entire s (11/14/23). Paving and construction ce	site (5/23/23). Sanitary sewer i	nstallation began (8/2	9/23). Storm sewer installa				
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?							
Grading Began (11/29/22). Grading cea and grading ceased across the entire s (11/14/23). Paving and construction ce	site (5/23/23). Śanitary sewer i	nstallation began (8/2	9/23). Storm sewer installa				
What temporary or permanent stabilization measures listed in this section are being implemented?							
Existing Vegetation (11/29/22).							
Checklist Questions:							
Are receiving waters adjacent to the project fr	ree of any significant signs of erosid	on or sediment that would	be associated with the constru	ction activity?			
Yes							
Create Corrective Action? N/A							
Have disturbed areas been seeded or otherwis	se stabilized as required? List inact	ive portions of the project	t and if stabilization measure are	adequate or needed to	prevent erosion.		
No Create Corrective Action?							

No, See findings section
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:

Comments:

The site was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

 Some maintenance is required in the BMP section at this time.
 All bare areas on-site that have been inactive for 14 days should be seeded. HRC Development was informed to complete by 11/21/23. Not done as of the last inspection. K2 Construction was reminded on 2/15/24, 3/21/24, 5/2/24, 5/22/24, Cedar Construction was reminded on 5/30/24. HRC Development was reminded on 7/10/24, 8/7/24

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	X-11		Removed		
Current Condition:	Removed - Echo Valley paved all entrances prior to the inspection on 12/5/23.					
D1	Diversion	D-8 to K-8	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develo	Fair Condition - HRC Development installed the diversion prior to the inspection on 5/23/23.				
	Diversion should be redefined HRC Development and Ceda Cedar Construction was remi	r Construction was info				
D2	Diversion	East of SB B	5/23/2023	Active	Yes	
Current Condition:	Fair Condition - HRC Develo		rsion prior to the inspection		onstruction removed	
	Diversion should be reinstalle K2 Construction was informe reminded on 10/18/23, 11/16	d to complete by 9/19/2	3. Not done as of the last in			
	Development was reminded	on 7/10/24, 8/7/24				
D3	Development was reminded of Diversion	on 7/10/24, 8/7/24 Southeast of SB A		Removed		
D3 Current Condition:		Southeast of SB A	necessary as of the 4/16/24			
Current Condition: D4	Diversion Removed - Due to paving the Diversion	Southeast of SB A diversion is no longer r South of SB A	5/23/2023	inspection. Active	No	
Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2	5/23/2023 ersion prior to the inspection on prior to the inspection on	inspection. Active n on 5/23/23. K2 8/29/23. K2 Cons	Construction remov	
Current Condition: D4	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2	5/23/2023 ersion prior to the inspection on prior to the inspection on	inspection. Active n on 5/23/23. K2 8/29/23. K2 Cons	Construction remov	
Current Condition: D4 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sections of the diversion prior cleanout prior to the inspection	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10	5/23/2023 rersion prior to the inspectio on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023	inspection. Active n on 5/23/23. K2 (8/29/23. K2 Cons ed the diversion d Active	Construction remov truction partially luring the basin No	
Current Condition: D4 Current Condition: ET 1	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sreinstalled the diversion prior cleanout prior to the inspectio Erosion Control Terraces	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10	5/23/2023 rersion prior to the inspectio on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023	inspection. Active n on 5/23/23. K2 (8/29/23. K2 Cons ed the diversion d Active	Construction remov truction partially luring the basin No	
Current Condition: D4 Current Condition: ET 1 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sreinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installatio to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the ere B-9 to I-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active	Construction remov truction partially luring the basin No 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sreinstalled the diversion prior cleanout prior to the inspectio Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin 6/6/23. 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin 6/6/23. 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sreinstalled the diversion prior cleanout prior to the inspectio Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin 6/6/23. 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for sreinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin No 6/6/23. 6/6/23. No 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition: ET 4	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023 psion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 0 8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin No 6/6/23. 6/6/23. No 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error B-7 to K-10 opment installed the error I-7 to M-10 opment installed the error Q-10 to Q-8	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 (8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin 0 6/6/23. 0 6/6/23. 0 6/6/23. 0 6/6/23. 0 6/6/23. 0 6/6/23. 0 0 6/6/23. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4 Current Condition: ET 5	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior cleanout prior to the inspection Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error I-7 to K-10 opment installed the error Q-10 to Q-8 opment installed the error Q-10 to Q-8 opment installed the error R-10 to R-7	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 (8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No	
Current Condition: D4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Diversion Removed - Due to paving the Diversion Good Condition - HRC Devel sections of the diversion for s reinstalled the diversion prior cleanout prior to the inspector Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel Erosion Control Terraces Good Condition - HRC Devel	Southeast of SB A diversion is no longer n South of SB A opment installed the div sanitary sewer installation to the inspection on 5/2 on on 7/9/24. B-9 to G-10 opment installed the error B-9 to I-10 opment installed the error I-7 to K-10 opment installed the error Q-10 to Q-8 opment installed the error Q-10 to Q-8 opment installed the error R-10 to R-7	5/23/2023 rersion prior to the inspection on prior to the inspection on 28/24. Ruff Grading reinstall 6/6/2023 osion control terrace prior to 6/6/2023 osion control terrace prior to 6/6/2023	inspection. Active n on 5/23/23. K2 (8/29/23. K2 Cons ed the diversion d Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active the inspection on Active	Construction remov truction partially luring the basin No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No 6/6/23. No	

Current Condition:	Good Condition - HRC Development installed the erosion control terrace prior to the inspection on 6/6/23.
FT 1	Fuel Tank On site 12/6/2022 Pending No
Current Condition:	Pending - Ruff Grading brought a fuel tank on site prior to the inspection on 12/6/22. Ruff Grading removed the fuel tai
	from site during the inspection on 3/28/23. Ruff Grading installed a fuel tank and secondary containment prior to the inspection on 4/11/23. Ruff Grading moved the fuel tank to the Morgan Ridge subdivision prior to the inspection on 5/2/23. Cedar Construction installed a single walled fuel tank on site prior to the inspection on 4/23/24. Cedar Construction removed the fuel tank from the site prior to the inspection on 5/28/24.
IF 1-4	Inlet Filter Street A 5/28/2024 Active No
Current Condition:	Good Condition - HRC Development installed inlet filters 1-3 prior to the inspection on 5/28/24.
MS 1	Material Storage Area On site 11/4/2022 Active No
Current Condition:	Good Condition-Material and vehicle staging area occurring on-site by Ruff fuel tanker as of 12/26/22
PB 1	Portable toilet On site 4/11/2023 Pending No
Current Condition:	Pending - Ruff Grading installed and secured a portable toilet on site prior to the inspection on 4/11/23. Ruff Grading secured the portable toilet during the inspection on 4/18/23. Ruff Grading moved the portable toilet to the Morgan Ridg subdivision prior to the inspection on 5/2/23. K2 Construction installed and secured a portable toilet on site prior to the inspection on 8/29/23. K2 Construction removed the portable toilet from the site prior to the inspection on 10/24/23. Echo Valley installed and secured a portable toilet on site prior to the inspection on 11/28/23. Echo Valley removed the portable toilet from the site prior to the inspection on 1/9/24.
SB A	Sediment Basin Z-9 11/14/2023 Active No
Current Condition:	Good Condition - 15% filled - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC
	Development was in the process of installing the riser and outfall pipe during the inspection on 11/7/23. HRC
	Development installed the riser prior to the inspection on 11/14/23. E&A inspector painted the cleanout mark on the ris during the inspection on 11/28/23. HRC Development installed the dewatering hole prior to the inspection on 5/7/24. Ruff Grading was in the process of cleaning out the basin during the 7/9/24 inspection. An unknown contractor was
	cleaning out the basin prior to the inspection on 9/3/24. E&A inspector will continue to monitor.
SB B	Sediment Basin L-7 3/21/2023 Active No
Current Condition:	Good Condition - 5% filled - HRC Development began shaping the basin prior to the inspection on 3/21/23. HRC Development repaired the erosion on the outer bank of the basin prior to the inspection on 12/12/23. HRC Developme installed the riser prior to the inspection on 2/13/24. E&A inspector painted the cleanout mark during the 2/20/24 inspection.
SF 1	Silt fence West edge of site 11/29/2022 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development cleaned out the silt fence in multiple locations prior to the inspection on 3/6/23. HRC Development installed additional silt fence checks in multiple high flow areas prior to the inspection on 3/14/23.
SF 2	Silt fence West edge of site 11/29/2022 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 11/29/22. HRC Development trenched in the silt fence where undermined prior to the inspection on 3/6/23. HRC Development repaired the silt fence prior to the inspection on 3/28/23. HRC Development repaired the entire run of silt fence prior to the inspection on 12/12/23.
SF 3	Silt fence East edge of site 3/14/2023 Active No
Current Condition:	Good Condition - HRC Development installed the silt fence prior to the inspection on 3/14/23. Due to the grade silt fen along the edge of the site near Daniel Street is no longer necessary as of 5/23/23.
WO 1	Concrete Washout On site 11/21/2023 Pending No
Current Condition:	Pending - Echo Valley installed a concrete washout on site prior to the inspection on 11/21/23. Echo Valley installed a second concrete washout pit with liner prior to the inspection on 12/5/23. Echo Valley removed the concrete washouts on site and pile up concrete rubble in preparation for removal prior to the inspection on 12/12/23.
WS 1	Waste Storage Area On site 11/4/2022 Pending No
Current Condition:	Pending - There is currently no need for a designated waste storage area on-site due to no waste materials being generated or stored on-site; the E&A inspector will continue to monitor.
	Bennington Road, N.
CTD	
STR Current Condition:	Streets 168th Street 11/4/2022 Active No
STR Current Condition:	Streets 168th Street 11/4/2022 Active No Good Condition - HRC Development was cleaning all interior and exterior streets during the inspection on 12/19/23. HRC Development cleaned all interior streets prior to the inspection on 5/28/24. Ruff Grading was in the process of
	Streets 168th Street 11/4/2022 Active No Good Condition - HRC Development was cleaning all interior and exterior streets during the inspection on 12/19/23.

Certification Statement:	direction or supervision in acc properly gathered and evaluat persons who manage the syst the information submitted is,	v, that this document and all attachments were prep cordance with a system designed to assure that qu ited the information submitted. Based on my inquiry stem or those persons directly responsible for gather to the best of my knowledge and belief, true, accur ificant penalties for submitting false information incl r knowing violations."	alified personnel y of the person or ering the information, rate, and complete. I
Inspector Signature:	Brya M Zhanght		Reviewed By: