	E&A - P200	6.135.000	
Inspector: Mike Jacobson			Stage
Project Name:	Kenned	2	
For Week Ending:	6		
Grading:	100%		
Sanitary Sewer:	100%		
Storm Sewer:	100%		
Paving:	100%		
Seeding:	100%		
Utilities:	100%		
Overall Development:	24%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	
	•		Week
Sunday:	0.00"		
Monday	0.05"		
Tuesday	0.03"		
Wednesday	0.00"	06/17/09	
Thursday	0.00"		
Friday	0.33"		
Saturday	0.00"		
			Week 2/
Sunday:	0.79"	06/21/09	
Monday	0.00"		
Tuesday	0.00"	06/23/09	
Wednesday	0.01"		
Thursday	0.00"		
Friday	0.00"		
Saturday	0.00"		
	None		
Complaints:	None.		

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, Grading was completed and entire site was seeded Fall 2006.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site, Grading was completed and entire site was seeded Fall 2006.

What temporary or permanent stabilization measures listed in this section are being implemented?

Seeding (Fall 2006), stabilized entrance, Paved streets (10/2007), Paved entrance (11/2007); Re-seed part of the lot to west of SB B(4/2009); Re-seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009)

Comments:

Comments:

Site is stabilized with vegetative cover. Home construction is active in the south west corner of the site.

Rain event on 6/19/09 per ACCUWEATHER.COM for zip code 68154 which is the location of E&A Consulting Group had 0.33". If you check the zip code of various projects located in surrounding areas they range from 0.33" – 0.81". The 0.81" is from two separate rain events of less than a $\frac{1}{2}$ " an AM shower of .40 and lunch time shower of 0.20 - 0.40" depending on zip code. This is why there isn't a rain inspection on 6/19/09 on the following report.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) A few areas of lot level silt fence is damaged and needs to be repaired. On 6/25/09 Developer Mike Kucera gave E&A inspector Mike Jacobson permission to have Commercial Seeding complete maintenance. Commercial Seeding was informed to complete maintenance by 7/2/09.
- 2) Some maintenance is required in the BMP section.

	1		Projected	I	1	Description of	
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity:	
omquo ramo	.,,,,,	Location	motan Bato	Otatao	Mantonario	•	
		N41d00m00s				Repairs	
CE A	Construction Entrance	W96d00m00s		Removed	No	Needed/Planned:	
Current Condition:	Removed paved entrance	_					
DD 1	Swale	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - Partially re			Active	INU	-	
Guirent Gonation.	Diversion ditch was redefine						
			1			1	
		N41d00m00s					
DD 2	Swale	W96d00m00s		Removed			
Current Condition:	Removed due to paving of s						
OD 4	O di di di Dania	N41d00m00s		Aution	N.		
SB A Current Condition:	Sediment Basin Good Condition - 19% filled	W96d00m00s	In Place	Active	No	-	
Current Condition:	Cleaned out 10/2007 by Da		n maintenance w	as completed pri	or to inspection		
	on 4/8/09 by M.E. Collins.	ve Hausman. Liusioi	i mantenance we	as completed pin	or to mapection		
	011 1/0/00 by 1111 <u>2</u> 1 001111101		1	ī	1		
CD D	Coding out Doois	N41d00m00s	40/0/0007	A ati a	N-		
SB B Current Condition:	Sediment Basin Good Condition - 9% filled	W96d00m00s	10/6/2007	Active	No		
Current Condition.	Cleanout and riser maintena	nce was completed	on 4/1/09 by M.E	. Collins.			
		N41d00m00s	1	<u> </u>	I		
SF A	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- Partially re						
	Maintenance was completed						
		N41d00m00s					
SF B	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition						
	Maintenance was completed		on 3/7/09 by CS.	T	1		
		N41d00m00s					
SF C	Silt Fence	W96d00m00s	9/25/2006	Active	Yes		
Current Condition:	Fair Condition						
	One area is down/damaged	and needs to be ren	noved as it is no l	onger needed			
	end area is demily damaged			ongo noodod			
	On 6/25/09 Developer Mike	Kucera gave E&A in	spector Mike Jac	obson permissio	n to have		
	Commercial Seeding complete maintenance. Commercial Seeding was informed to complete						
	maintenance by 7/2/09.		T	1	ı		
05.5	074.5	N41d00m00s					
SF D	Silt Fence	W96d00m00s	in this area	Removed			
Current Condition: Silt Fence removed and diversion ditch installed in this area.							
STR	Street Cleaning	N41d00m00s W96d00m00s		Active	No		
Current Condition:	Good Condition- No major s			7.0076	140		
24	The state of the s			l e			
CWDDD C:	CWDDD C:	Two signs are all	0/0/0000	A 04:	N-		
SWPPP Sign Current Condition:	SWPPP Sign Good Condition	Two signs on site.	8/8/2008	Active	No	4	
Current Condition:	r Road						
A SWPPP sign has been installed at 19th & Chandler Road and 22nd & Chandler Road entrances.							
	11000						
Inspector Signature:	Spaled Jawson		Reviewed By:	Zachany k	. Jilek		