E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

	E	&A - P2008.194.	000		
Inspector: Mike Jacobson, CISEC		Stage			
		Kiltera Villas @ Waterford			
Project Name:		NER111205 12/10/2011			
For Week Ending:					
Project Location:	144	68007			
- "	1 4000/	1			
Grading:	100%				
Sanitary Sewer: Storm Sewer:	100% 100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	40%				
•	•	•			
RAIN FALL AMOUNTS	Amount in inches	Date inspected			
	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Week	
Sunday:	0.00"			HCCK	
Monday	0.00"	1			
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	Trace				
				Week	
Sunday:	0.00"				
Monday	0.00"	11/21/11			
Tuesday	0.00"				
Wednesday Thursday	0.00"				
Friday	Trace				
Saturday	0.00"				
Catarday	0.00			Week	
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	Trace				
Friday	Trace				
Saturday	1.04"				
				Week	
Sunday:	0.00"	40/05/44			
Monday Tuesday	Trace 0.00"	12/05/11			
Tuesday Wednesday	0.00"	+	+		
Thursday	0.16"				
Friday	0.01"				
Saturday	Trace	1			
				Week	
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			
Saturday	N/A	N/A			
	INT.				
Commissinto	None				
Complaints:					
		T	T T		
Construction Sequencing:		L	ı		

Entire Site, grading was completed prior to taking this project over on 8/28/2008.							
Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.							
Which portion(s) (i.e. drainage basins) of the site do not l	have grading, earth	 work, or ground disturbance	e scheduled in the next 14	days?:			
Entire Site, grading was completed prior to taking this project over on 8/28/2008.							
Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.							
What temporary or permanent stabilization measures list	ed in this section a	re being implemented?					
Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011)							
Comments:							
Comments: Home construction is active on lot 12.							
An inspection was not conducted on Sunday 12/- place on 12/5/11.	4/11 due to winte	er conditions. An inspect	ion will be conducted a	s conditions allow.	This inspection took		
Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP sections.	on.						
			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
CE 1	Construction Entrance	N41d11m25s W96d12m40s		Removed	No		
Current Condition:		ntrance paved prior to fir	rst inspection on 8/28/0				
IF	Inlet Filters	9 inlet filters		Removed	No		
Current Condition:	Removed by Commercial Seeding prior to inspection on 04/01/10. These inlet filters might need to be re-installed on construction is active in this area again.						
Lot 10	Silt Fence	Lot 10		Removed			
Current Condition:		prior to inspection on 1	1/3/11 by Steve Faller	w/ Landmark Hom	es.		
Lot 11	Silt Fence	Lot 11		Removed			
Current Condition:	Lot has been sodded prior to inspection on 5/12/11 by Landmark Homes.  The straw wattle behind the lot in the outlot was removed prior to inspection on 8/7/11 by Steve Faller w/ Landmark Homes.						
S.B. B	Sediment Basin	N41D11M27 w96D12M23S		Removed	No		
Current Condition:	Basin removed	by MJA Trucking, comp	leted as of 12-12-08				
SF A Current Condition:	Silt Fence Fair Condition-	Behind lots 12 through 18 Active home construction	4/16/2011	Active	Yes		
	As of inspection on 11/21/11 dirt was piled in the R.O.W. of lot 12						
	On 11/21/11 Steve Fowler with Landmark Homes was informed to remove dirt or place silt fence around piles by 11/30/11. Two extra days were given due to the holiday weekend. Maintenance not completed as of last inspection.						
S.F. B	Silt Fence around A.I.	N41d11m34s W96d12m23s		Removed			
Current Condition:		vas removed prior to ins	pection on 07/07/10 du		tion.		
		N41d11m34s					
ST 1	Sediment Trap	W96d12m23s	8/26/2008	Removed	No		
Current Condition:	Permanent water	erfall and pond N41d11m34s					
STR	Streets	W96d12m23s	8/28/2008	Active	No		
Current Condition:	Good Condition	- No major signs of trac	k off.				
SWPPP signs	signs	1 sign	10/27/2008	Active	No		
Current Condition:	Good Condition						
, , 0/							
Inspector Signature: Jacket Jawlon Reviewed By:				ا المالية	yuu-		
mapecion arginature. #		1	nevieweu by:				