E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Joe Manning					Stage
			edar Hollow Mall		2
Project Name:		CSI	N-201904209		
For Week Ending:		68069			
Project Location:	2:				
	1		all - Waterloo, NE (Dougla	1	
Grading:	10	0%			
Sanitary Sewer:	10	0%			
Storm Sewer:		<mark>0%</mark>			
Paving:		0%			
Seeding:		<mark>0%</mark>			
Jtilities: Overall Development:		<mark>0%</mark> 0%			
-		0 /0			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	
Sunday:	0.00"				Weel
Monday	0.00"				
luesday	0.00"	12/15/2020	Partly Sunny 27/19	11:30 AM	
		12/13/2020		TT.50 AIM	
Vednesday	0.00"				
Thursday					
Friday	0.00"				
Saturday	0.00"				Week
Sunday:	0.00"				Weer
Monday	0.00"				
ruesday	0.00"				
Vednesday	0.00"				
Fhursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Weel
Sunday:	N/A				
fonday	N/A				
luesday	N/A				
Nednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
Complaints:					
Construction Sequencing:	1				
		emporary or permanent ce	essation of grading, earthwork, o	r ground disturbance in the las	t 14 days?
(12/07/20).			oughout site (8/24/20). Down		east side of the site
			ound disturbance scheduled in th oughout site (8/24/20). Down	-	east side of the sit

E&A - P2019.247.003

(12/07/20). What temporary or permanent stabilization measures listed in this section are being implemented? Existing perimeter vegetation (5/21/20). Seeding and matting installed north of the building, at the stub road on the west side, and at the curb cut on the south side (9/09/20). Seeding in the west and southeast portion of the site (9/23/20). **Eastern and southern portion of the site sodded** (12/15/20).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Yes

Yes

Yes

Yes

N/A

Create Corrective Action? No - See BMP Section (PT 1).

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

Comments:

The site was active for building construction during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1. See BMP section for required maintenance.

2. Due to stabilization of site and removal of BMPs, the NOT was sent to the applicant on 12/16/20 and signed by the applicant on 12/17/20.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	Cedar Hollow Mall		Removed	
Current Condition:	Removed - Nelson Hill C	contracting paved the	construction entrance prio	r to the inspection on 8/10/2	Э.
		Southeast side of			
CW 1	Concrete Washout	lot		Removed	
Current Condition:	Removed - Nelson Hill 12/15/20.	Contracting remove	d the concrete washout f	rom the site prior to the in	spection on
ECM 1	Erosion Control Matting	North side of the lot	9/9/2020	Active	No
Current Condition:	Good Condition - Nelson on 9/09/20.	Hill Contracting insta	Illed erosion control matting	g north of the building prior t	o the inspection
ECM 2	Erosion Control Matting	West side of the lot	9/9/2020	Active	No
Current Condition:	Good Condition - Nelson the inspection on 9/09/20	•	illed erosion control matting	g west of the building at the	stub road prior to
		Southwest side of			
ECM 3	Erosion Control Matting	the lot	9/9/2020	Active	No
Current Condition:	Good Condition - Nelson	Hill Contracting insta	Illed erosion control matting	g along the pavement on the	south side of
	the lot prior to the inspec	tion on 9/09/20.			
ECM 4	Erosion Control Matting			Active	No
Current Condition:	Good Condition - Nelson prior to the inspection or	•	lled erosion control mattin	g at the curb cut on the sout	h side of the lot
PT	Portable Toilet	East of CE1	6/10/2020	Active	Yes

Current Condition:		n Hill Contracting installed	d and secured a portable t	toilet on the site prior to th	ne inspection on	
	<mark>6/10/20.</mark>					
	.					
	The portable toilet should be resecured.					
	Nelson Hill Contracting	g was informed to comple	ete by 12/14/20. Not done	as of the last inspectio	n.	
SF #1	Silt Fence	Southeast corner		Removed		
Current Condition:	Removed - Nelson H	ill Contracting removed	the silt fence and sodde	ed the remainder of the	site prior to the	
	inspection on 12/15/2	20.				
SF #2	Silt Fence	South of CE 1		Removed		
Current Condition:	Removed - Nelson Hil	I Contracting removed the	e silt fence prior to the ins	pection on 9/23/20. Due t	o stabilization in	
	the area, the silt fence	will no longer be recomn	nended.			
SF #3	Silt Fence	South side of the lot		Removed		
Current Condition:			silt fence will no longer be			
SF #4	Silt Fence	Southwest corner	ent forfice will no forfiger be	Removed		
Current Condition:			the silt fence on 12/16/2			
SF #5	Silt Fence	North side of the lot		Removed		
Current Condition:	Removed - Due to sit	e stabilization, silt fenc	e will not be recommend	ded.		
SF #6	Silt Fence	North side of the lot		Removed		
Current Condition:	Removed - Due to sit	e stabilization, silt fenc	e will not be recommend	ded.		
Current Condition: SF #7	Removed - Due to sit	te stabilization, silt fenc Northeast corner		ded. Removed		
Current Condition: SF #7 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit	e stabilization, silt fenc Northeast corner e stabilization, silt fenc	e will not be recommend	ded. Removed ded.	No	
Current Condition: SF #7 Current Condition: STR	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning	e stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site	e will not be recommend In Place	ded. Removed ded. Active	No No	
Current Condition: SF #7 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel	e stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site	e will not be recommend	ded. Removed ded. Active		
Current Condition: SF #7 Current Condition: STR	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear	e will not be recommend In Place	ded. Removed ded. Active		
Current Condition: SF #7 Current Condition: STR	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20.	e will not be recommend In Place	ded. Removed ded. Active		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site Ison Hill Contracting clear nspection on 12/15/20. Northeast side of the lot	e will not be recommend In Place	ded. Removed ded. Active inspection on 9/04/20. Th Removed		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w East side of the lot	e will not be recommend In Place ned the street prior to the attles will not be recomm	ded. Removed ded. Active inspection on 9/04/20. Th Removed nended. Removed		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle Straw Wattle	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w East side of the lot te stabilization, straw w	e will not be recommend In Place ned the street prior to the	ded. Removed ded. Active inspection on 9/04/20. Th Removed nended. Removed		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle Removed - Due to sit Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w East side of the lot te stabilization, straw w Southeast corner of	e will not be recommend In Place ned the street prior to the attles will not be recomm	ded. Removed ded. Active inspection on 9/04/20. Th Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed ded. Active inspection on 9/04/20. Th nended. Removed nended. Removed		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recomm	ded. Removed ded. Active inspection on 9/04/20. Th nended. Removed nended. Removed		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Nel cleaned prior to the i Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner te stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w.	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed ded. Active inspection on 9/04/20. The Removed mended. Removed mended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the in Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the in Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the in Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. West side of the lot te stabilization, straw w. West side of the lot te stabilization, straw w.	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Straw Wattle	te stabilization, silt fenc Northeast corner e stabilization, silt fenc Off-Site son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. West side of the lot te stabilization, straw w. West side of the lot te stabilization, straw w.	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend attles will not be recommend attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended. Removed nended.		
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition: SW #5 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner Son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot E stabilization, straw w Southeast corner of the lot West side of the lot te stabilization, straw w West side of the lot te stabilization, straw w South side of the lot te stabilization, straw w South side of the lot te stabilization, straw w	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended. Removed nended. Removed nended.	e streets were	
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition: SW #5 Current Condition:	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner Son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot E stabilization, straw w Southeast corner of the lot West side of the lot te stabilization, straw w West side of the lot te stabilization, straw w South side of the lot te stabilization, straw w South side of the lot te stabilization, straw w	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend attles will not be recommend attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended. Removed nended. Removed nended.	e streets were	
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition: SW #5 Current Condition: SW #5	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit Signs Removed - The E&A	te stabilization, silt fenc Northeast corner Son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot E stabilization, straw w Southeast corner of the lot West side of the lot te stabilization, straw w West side of the lot te stabilization, straw w South side of the lot te stabilization, straw w South side of the lot te stabilization, straw w	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed Removed nended. Removed nended.	e streets were	
Current Condition: SF #7 Current Condition: STR Current Condition: SW #1 Current Condition: SW #2 Current Condition: SW #3 Current Condition: SW #4 Current Condition: SW #5 Current Condition: SW #5	Removed - Due to sit Silt Fence Removed - Due to sit Street cleaning Good Condition - Net cleaned prior to the i Straw Wattle Removed - Due to sit	te stabilization, silt fenc Northeast corner Off-Site Son Hill Contracting clear nspection on 12/15/20. Northeast side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. West side of the lot te stabilization, straw w. Southeast corner of the lot te stabilization, straw w. South side of the lot te stabilization, straw w. South side of the lot te stabilization, straw w. South side of the lot te stabilization, straw w. Southeast corner of the lot	e will not be recommend In Place ned the street prior to the attles will not be recommend attles will not be recommend	ded. Removed inspection on 9/04/20. Th Removed nended. Removed nended. Removed nended. Removed nended. Removed nended. Removed nended.	e streets were	