## E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington			Stage
	1		
Project Name:	OMA-202010		
For Week Ending:		68007	
Project Location:	168th Street and		
	000/		1
Grading:	99%		
Sanitary Sewer:	100%		
Storm Sewer:	95%		
Paving:	98%		
Seeding:	35%		
Utilities:	80%		
Overall Development:	58%		

E&A - P2020.091.000

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
					Week 1
Sunday:	0.14"				
Monday	0.01"	9/11/2023	Partly Cloudy 71	1:10 PM	
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.01"				
Saturday	0.02"				
	•		•	•	•
	None				

Complaints:

## **Construction Sequencing:**

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

## What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021). Seeding along the N 170th Street crossing (9/28/2022). Matting along the N 170th Street crossing (10/05/2022).

Checklist Questions:

Yes

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

**Create Corrective Action?** 

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needer o prevent erosion?
Create Corrective Action?
lo - See Findings section
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
lo
Create Corrective Action?
lo - See Findings section
I.) Are construction entrances and adjacent streets being maintained adequately?
/es
Create Corrective Action?
I/A
i.) Is dust associated with the construction activity adequately controlled on the site?
/es
Create Corrective Action?
I/A
Comments:
Comments:

Site was active for home construction during the current inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP section. 2.) Waste concrete should be removed. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23. 3.) Inactive portions of the site should be stabilized. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23. on 7/18/23.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	V11		Removed		
Current Condition:	Removed - JC Excavation gr	aded out the site acces	s at this location as of the inspe	ection on 10/13/21.	•	
CE 2	Construction Entrance	S2	2/23/2021	Pending	No	
Current Condition:	Pending - Legacy Homes installed a construction entrance prior to 2/23/21. Majestic Pointe LLC and Legacy Homes blocked the construct entrance prior to the inspection on 6/08/21. JC Excavation blocked the construction entrance prior to the inspection on 10/13/21. E&A inspector will monitor and make recommendations if the entrances is used at a later date.					
CE 3	Construction Entrance	T27		Removed	No	
Current Condition:	Removed - TAB Construction	n removed the construct	tion entrance prior to the inspec	tion on 6/10/22.	•	
CE 4	Construction Entrance	14		Removed		
Current Condition:	Removed - The construction	entrance was paved pr	ior to the inspection on 9/21/22.		•	
CIP 1	Inlet Protection	S29	2/16/2022	Active	No	
	,	LC cleaned out the cur	b inlet protection prior to the ins	pection on 7/26/22. Majestic P	ointe LLC cleaned out the	
	inlet protection prior to the 8/					
CIP 2	inlet protection prior to the 8/	7/23 inspection. South end of North 169 Street		Removed		
CIP 2 Current Condition:		South end of North 169 Street	it as of 8/28/23.	Removed		
	Inlet Protection	South end of North 169 Street	5t as of 8/28/23. 8/28/2023	Removed	No	
Current Condition:	Inlet Protection Removed - This BMP is now Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St		Active	No	
Current Condition: CIP Craig St	Inlet Protection Removed - This BMP is now Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St	8/28/2023	Active	No No	
Current Condition: CIP Craig St Current Condition:	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curf	8/28/2023 inlet protections 1-8 prior to the	Active inspection on 8/28/23. Active	No	
Current Condition: CIP Craig St Current Condition: CIP N 169th St	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po	South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curf	8/28/2023 inlet protections 1-8 prior to the 8/28/2023	Active inspection on 8/28/23. Active	No	
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition:	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St binte LLC installed curb N 169th St binte LLC installed curf n this BMP. N 170th Ave	8/28/2023 inlet protections 1-8 prior to the 8/28/2023 o inlet protections 1-6 prior to the	Active inspection on 8/28/23. Active e inspection on 8/28/23. CIP 2 Active	No No was installed previously	
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St binte LLC installed curb N 169th St binte LLC installed curf n this BMP. N 170th Ave	8/28/2023 inlet protections 1-8 prior to the 8/28/2023 D inlet protections 1-6 prior to the 8/28/2023	Active inspection on 8/28/23. Active e inspection on 8/28/23. CIP 2 Active	No No was installed previously	
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave Current Condition:	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection Good Condition - Majestic Po Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb n this BMP. N 170th Ave Dinte LLC installed curb N 169th St	8/28/2023         inlet protections 1-8 prior to the         8/28/2023         o inlet protections 1-6 prior to the         8/28/2023         inlet protection prior to the insp	Active inspection on 8/28/23. Active e inspection on 8/28/23. CIP 2 Active ection on 8/28/23. Active	No No No No No No	
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave Current Condition: CIP N 170th St	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection Good Condition - Majestic Po Inlet Protection	South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb n this BMP. N 170th Ave Dinte LLC installed curb N 169th St	8/28/2023         inlet protections 1-8 prior to the         8/28/2023         o inlet protections 1-6 prior to the         8/28/2023         inlet protection prior to the insp         8/28/2023	Active inspection on 8/28/23. Active e inspection on 8/28/23. CIP 2 Active ection on 8/28/23. Active	No No No No No No	

CIP Reynolds St	Inlet Desta stice	Deumelale Ct	8/28/2022	A -40	l Nia
Current Condition:	Inlet Protection	Reynolds St	8/28/2023 o inlet protections 1-8 prior to the	Active	No
	-		· · · · ·		
CIP Sheffield St	Inlet Protection	Sheffield St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed curb	o inlet protections 1-4 prior to the	e inspection on 8/28/23.	
CIP Young St	Inlet Protection	Young Street	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed curb	inlet protections 1 & 2 prior to	the inspection on 8/28/23.	•
CW	Concrete Washout	On Site	8/28/2023	Active	No
Current Condition:	Good Condition - D R Hortor	n installed a portable co	ncrete washout prior to the insp	pection on 8/28/23.	
D 1	Diversion	O3 - U2	11/16/2021	Active	No
Current Condition:				for to the inspection on 11/16/21.	
current contaition.				artially removed by disking prior to	
			sion into the basin prior to the in		
D 2	Diversion	J18 - S27		Removed	1
Current Condition:			ion during conitory installation r	prior to the inspection on 12/02/21	Due te peving
Current Condition:	reinstallation will not be reco			biol to the hispection on 12/02/21	L Due to paving,
D 3	Diversion	J15 - N6	1	Removed	1
Current Condition:			ue to diaking on aits prior to the	inspection 12/02/21. Due to pavi	ng rejectallation will n
Current Condition:	be recommended as of 7/5/2		lue to disking on site prior to the	inspection 12/02/21. Due to pavi	ing, reinstallation will n
EM 1	Erosion Control Matting	E11 - S25	9/1/2021	Pending	No
	J. J			0	INO
Current Condition: EM 2	Erosion Control Matting	E6 - F12	is completed in the area and w 12/8/2021	Active	No
	0				INO
Current Condition:			erosion control matting prior to	1	
EM 3	Erosion Control Matting	M6 - Z6	9/1/2021	Pending	No
Current Condition:			is completed in the area and w	1	
EM 4	Erosion Control Matting	Z5 - Z24	12/8/2021	Active	No
Current Condition:			erosion control matting prior to t		
EM 5	Erosion Control Matting	V1 - V7	12/8/2021	Active	No
Current Condition:	-		rosion control matting prior to t		
ET 1	Erosion Control Terrace	V8 - O21	9/21/2021	Active	No
Current Condition:			on control terrace prior to the ins		
ET 2	Erosion Control Terrace	S2 - K14	9/21/2021	Active	No
Current Condition:			ity of the erosion control terrace	prior to the inspection on 9/21/21	1.
FT 1	Fuel Tank	On-site		Removed	
Current Condition:	Removed - JC Excavation a	nd Majestic Pointe LLC	removed the fuel tanker and cl	eaned up the spills prior to the ins	spection on 12/16/21.
FT 2	Fuel Tank	On-site		Removed	
Current Condition:	Removed - Valley Corp remo	oved the fuel tank prior	to the inspection on 11/23/21.		
FT 3	Evert Treats			<b>D</b> 1	
	Fuel Tank	On-site		Removed	
Current Condition:		-	lled fuel tank on site prior to the		
	Removed - Tab Constructior	n removed a double-wa	lled fuel tank on site prior to the	inspection on 7/19/22.	
FT 4	Removed - Tab Constructior Fuel Tank	n removed a double-wa On-site		inspection on 7/19/22. Removed	
FT 4 Current Condition:	Removed - Tab Construction Fuel Tank Removed - Tab Construction	n removed a double-wal On-site n removed the fuel tank	prior to the inspection on 12/29	inspection on 7/19/22. Removed /21.	
FT 4 Current Condition: Lot 166	Removed - Tab Construction Fuel Tank Removed - Tab Construction Individual Lot	n removed a double-wa On-site n removed the fuel tank Lot 166	prior to the inspection on 12/29 9/6/2023	inspection on 7/19/22. Removed /21. Active	No
FT 4 Current Condition:	Removed - Tab Construction Fuel Tank Removed - Tab Construction Individual Lot Good Condition - D R Hortor	n removed a double-wa On-site n removed the fuel tank Lot 166 n began excavating the	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspectio	inspection on 7/19/22. Removed /21.	
FT 4 Current Condition: Lot 166 Current Condition:	Removed - Tab Construction Fuel Tank Removed - Tab Construction Individual Lot Good Condition - D R Hortor inspection, the inspector will	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs.	inspection on 7/19/22. Removed //21. Active on. Dirt piles were observed in the	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition: Lot 167	Removed - Tab Construction Fuel Tank Removed - Tab Construction Individual Lot Good Condition - D R Hortor inspection, the inspector will Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023	inspection on 7/19/22.  Removed  //21. Active on. Dirt piles were observed in the Active	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition:	Removed - Tab Construction Fuel Tank Removed - Tab Construction Individual Lot Good Condition - D R Hortor inspection, the inspector will Individual Lot Good Condition - D R Hortor	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection	inspection on 7/19/22. Removed //21. Active on. Dirt piles were observed in the	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs.	inspection on 7/19/22.          Removed         //21.         Active         on. Dirt piles were observed in the         Active         On. Dirt piles were observed in the	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Individual Lot           Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the Active On. Dirt piles were observed in the Active Active Active Active Active	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           Individual Lot           Good Condition - D R Hortor	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection	inspection on 7/19/22.          Removed         //21.         Active         on. Dirt piles were observed in the         Active         On. Dirt piles were observed in the	ROW during the 9/6/2
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs.	inspection on 7/19/22.  Removed //21.  Active on. Dirt piles were observed in the Active on. Dirt piles were observed in the Active On. Dirt piles were observed in the	ROW during the 9/6/: ROW during the 9/6/: ROW during the 9/6/: ROW during the 9/6/:
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Individual Lot           Individual Lot           Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 168	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023	inspection on 7/19/22.  Removed //21.  Active	<ul> <li>ROW during the 9/6/2</li> <li>No</li> <li>ROW during the 9/6/2</li> <li>No</li> <li>ROW during the 9/6/2</li> <li>No</li> <li>No</li> </ul>
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           Individual Lot           Good Condition - D R Hortor	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, an	inspection on 7/19/22.  Removed //21.  Active	<ul> <li>ROW during the 9/6/2</li> <li>No</li> <li>ROW during the 9/6/2</li> <li>No</li> <li>ROW during the 9/6/2</li> <li>No</li> <li>No</li> </ul>
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the solution for removal an Lot 169 n began excavating the OW during the 8/26/23	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, are inspection, the inspector will m	inspection on 7/19/22.  Removed  //21.  Active  Active Acti	ROW during the 9/6/2     No     ROW during the 9/6/2     No     ROW during the 9/6/2     No     ROW during the 9/6/2     No the 8/2823 inspection.
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the OW during the 8/26/23 Lot 170	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, are inspection, the inspector will m 8/28/2023	inspection on 7/19/22.  Removed //21.  Active	ROW during the 9/6/2     No     ROW during the 9/6/2     No     ROW during the 9/6/2     No     No the 8/2823 inspection.     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the OW during the 8/26/23 Lot 170 n began excavating the	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, are inspection, the inspector will m 8/28/2023 lot and installed straw wattles p	inspection on 7/19/22.  Removed  //21.  Active  Active Acti	ROW during the 9/6/2           No           ROW during the 9/6/2           No           ROW during the 9/6/2           ROW during the 9/6/2           No           the 8/2823 inspection.           No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 inspector	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the 20W during the 8/26/23 Lot 170 n began excavating the pection, the inspector wa	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p rill monitor for removal.	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the Active In Active In installed straw wattles prior to to onitor for removal. Active rior to the 8/2823 inspection. Dirt	ROW during the 9/6/2     No     ROW during the 9/6/2     No     ROW during the 9/6/2     No     ROW during the 9/6/2     No the 8/2823 inspection.     No piles were observed in
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 170 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 insp           Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the OW during the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, are inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023	inspection on 7/19/22.  Removed  //21.  Active  Active Ac	ROW during the 9/6/2     No     the 8/2823 inspection.     No     piles were observed in     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 insp           Individual Lot           Active - D R Horton began e	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the OW during the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180 xcavating the lot prior to	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, are inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the Active In Active In installed straw wattles prior to to onitor for removal. Active rior to the 8/2823 inspection. Dirt	ROW during the 9/6/2     No     the 8/2823 inspection.     No     piles were observed in     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 180 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 insp           Individual Lot           Active - D R Horton began e           the inspector will monitor for	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the excavating the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180 xcavating the lot prior to removal.	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023 to the 8/2823 inspection. Dirt pile	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the  Active onitor for removal.  Active rior to the 8/2823 inspection. Dirt  Active swere observed in the ROW dur	ROW during the 9/6/2  No the 8/2823 inspection.  No piles were observed in  No ring the 8/26/23 inspec
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 170 Current Condition: Lot 180 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 inspector           Individual Lot           Active - D R Horton began e           the inspector will monitor for           Individual Lot	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180 xcavating the lot prior to removal. Lot 194	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023 to the 8/2823 inspection. Dirt pile 8/28/2023	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the  Active onitor for removal.  Active rior to the 8/2823 inspection. Dirt  Active swere observed in the ROW dur  Active	ROW during the 9/6/2     No     piles were observed ir     No     ring the 8/26/23 inspec     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 180 Current Condition:	Removed - Tab Construction         Fuel Tank         Removed - Tab Construction         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         piles were observed in the R         Individual Lot         Good Condition - D R Hortor         piles were observed in the R         Individual Lot         Good Condition - D R Hortor         ROW during the 8/26/23 insp         Individual Lot         Active - D R Horton began e         the inspector will monitor for         Individual Lot         Active - D R Horton began e         the inspector will monitor for	n removed a double-wall         On-site         n removed the fuel tank         Lot 166         n began excavating the monitor for removal an         Lot 167         n began excavating the monitor for removal an         Lot 168         n began excavating the monitor for removal an         Lot 168         n began excavating the monitor for removal an         Lot 168         n began excavating the monitor for removal an         Lot 169         n began excavating the monitor for removal an         Lot 169         n began excavating the social and the monitor for removal an         Lot 169         n began excavating the social and the social a	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023 to the 8/2823 inspection. Dirt pile 8/28/2023	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the  Active onitor for removal.  Active rior to the 8/2823 inspection. Dirt  Active swere observed in the ROW dur	ROW during the 9/6/2     No     piles were observed in     No ring the 8/26/23 inspec     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 180 Current Condition: Lot 180 Current Condition:	Removed - Tab Construction           Fuel Tank           Removed - Tab Construction           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           inspection, the inspector will           Individual Lot           Good Condition - D R Hortor           piles were observed in the R           Individual Lot           Good Condition - D R Hortor           ROW during the 8/26/23 insp           Individual Lot           Active - D R Horton began e           the inspector will monitor for           Individual Lot           Active - D R Horton began e           the inspector will monitor for	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the scow during the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180 xcavating the lot prior to removal. Lot 194 xcavating the lot prior to removal.	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023 to the 8/2823 inspection. Dirt pile 8/28/2023 to the 8/2823 inspection. Dirt pile	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the  Active onitor for removal.  Active rior to the 8/2823 inspection. Dirt  Active swere observed in the ROW dur  Active swere observed in the ROW dur  Active	ROW during the 9/6/2     No     piles were observed ir     No     ring the 8/26/23 inspec     No
FT 4 Current Condition: Lot 166 Current Condition: Lot 167 Current Condition: Lot 168 Current Condition: Lot 169 Current Condition: Lot 170 Current Condition: Lot 170 Current Condition: Lot 180 Current Condition:	Removed - Tab Construction         Fuel Tank         Removed - Tab Construction         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         inspection, the inspector will         Individual Lot         Good Condition - D R Hortor         piles were observed in the R         Individual Lot         Good Condition - D R Hortor         ROW during the 8/26/23 insp         Individual Lot         Active - D R Horton began e         the inspector will monitor for         Individual Lot         Active - D R Horton began e         the inspector will monitor for         Material Storage	n removed a double-wal On-site n removed the fuel tank Lot 166 n began excavating the monitor for removal an Lot 167 n began excavating the monitor for removal an Lot 168 n began excavating the monitor for removal an Lot 169 n began excavating the scow during the 8/26/23 Lot 170 n began excavating the pection, the inspector w Lot 180 xcavating the lot prior to removal. On Site	prior to the inspection on 12/29 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 9/6/2023 lot prior to the 8/28/23 inspection d the installation of BMPs. 8/28/2023 lot, secured a portable toilet, ar inspection, the inspector will m 8/28/2023 lot and installed straw wattles p ill monitor for removal. 8/28/2023 to the 8/2823 inspection. Dirt pile 8/28/2023	inspection on 7/19/22.  Removed  //21.  Active on. Dirt piles were observed in the  Active onitor for removal.  Active rior to the 8/2823 inspection. Dirt  Active swere observed in the ROW dur  Active Activ	ROW during the 9/6/2     No     piles were observed ir     No     ring the 8/26/23 inspec     No

PB 02		···· · · · · · · · · · · · · · · · · ·	et prior to the inspection on 11/	23/21.	
	Portable Bathroom	On Site		Removed	
Current Condition:	Removed - Tab Construction	removed the portable	toilet prior to the inspection on	1/12/22.	
PB X	Portable Bathroom	On Site	12/29/2021	Pending	No
Current Condition:	prior to the inspection on 3/16 up and resecured the portable secured a portable toilet on s	6/22. Tab Construction e toilet prior to the insp ite prior to the inspection the inspection on 4/26/	removed a portable toilet from ection on 4/22/22. Valley Corp on on 11/21/22. MUD removed /23. An unknown contractor ren	on 12/29/21. Valley Corp secured the site prior to the inspection on removed a toilet prior to the inspe- the portable toilet and an unknow noved the portable toilet on site p	n 3/29/22. Valley Corp s ection on 8/16/22. MUD vn contractor secured a
SB A	Sediment Basin	E9	7/14/2021	Active	No
Current Condition:	Good Condition - 9% full - JC JC Excavation repaired the e installing the riser during the inspector painted the cleanou inspection on 12/08/21. The r site's advanced development	rosion along the berm inspection on 11/23/21 It mark during the inspection ecommendation of incl . Minor erosion was ob	ping the basin prior to the insp of the basin prior to the inspect . JC Excavation installed the o ection on 12/08/21. Majestic Pc luding the emergency spillway served around the barrel during	Lection on 10/06/21. E&A inspecto ion on 11/03/21. JC Excavation v utfall pipe prior to the inspection o pinte LLC installed an inlet pipe in will no longer be recommended a g the 6/26/23 inspection; E&A ins he remained of the riser structure	was in the process of on 12/02/21. The E&A nto the basin prior to the as of 9/6/2022 due to the spector will continue to
SB B	Sediment Basin	O3	9/28/2021	Active	No
Current Condition:	berm of the basin prior to the 11/23/21. JC Excavation insta inspection on 12/08/21. JC E 12/16/21. JC Excavation fully riser during the inspection on inspection on 6/28/22. The Ed	inspection on 11/03/21 alled the outfall pipe pri- acavation and Gene Gi built up the berm prior 6/21/22. E&A inspector &A inspector painted the ager be recommended	<ol> <li>JC Excavation was in the pro- ior to the inspection on 12/02/2 raves partially built up the low s to the inspection on 12/21/21.</li> <li>br will monitor for completion. M the cleanout mark during the inspection on the second seco</li></ol>	on 10/25/21. JC Excavation reparates of installing the riser during 1. The E&A inspector painted the spot in the berm near the riser prior Majestic Pointe LLC was in the plajestic Pointe LLC reinstalled the pection on 6/28/22. The recommens advanced development. Hausm	the inspection on e cleanout mark during or to the inspection on process of reinstalling th e riser prior to the endation of including th
SF 1	Silt Fence	W27 - I20	4/27/2021	Active	No
	cleaned out the silt fence pric	i to the inspection on ?			
	inspection on 3/16/22. E&A ir inspection. Sudbeck reinstalled reinstalled the silt fence along backfilled the silt fence and ir Walvoord Excavating backfill 10/05/22. Minor spoils were c	spector will monitor fo ed the silt fence where g and over the south si istalled a J-hook north ed and repaired the silt bserved in the silt fence	on 10/25/21. Sudbeck Compar r completion. Sudbeck cleaned removed near the center of the de of Reynolds Street Culvert p of the crossing on the eastern t fence on the north side of the	ties was in the process of repairing out and repaired the silt fence pro- errun prior to the inspection on 3/2 prior to the inspection on 7/26/22. portion of the silt fence prior to the Reynolds Street crossing prior to the prior to the street crossing during the the prior to the transmission of the silt fence prior to the transmission of the t	ng the silt fence during t rior to the 3/22/22 29/22. Majestic Pointe L Majestic Pointe LLC le inspection on 8/30/22 the inspection on
SF 2	inspection on 3/16/22. E&A ir inspection. Sudbeck reinstalled reinstalled the silt fence along backfilled the silt fence and ir Walvoord Excavating backfill 10/05/22. Minor spoils were c	spector will monitor fo ed the silt fence where g and over the south si istalled a J-hook north ed and repaired the silt bserved in the silt fence	on 10/25/21. Sudbeck Compar r completion. Sudbeck cleaned removed near the center of the de of Reynolds Street Culvert p of the crossing on the eastern t fence on the north side of the ce along the south side of the R	ties was in the process of repairing out and repaired the silt fence pro- errun prior to the inspection on 3/2 prior to the inspection on 7/26/22. portion of the silt fence prior to the Reynolds Street crossing prior to the prior to the street crossing during the the prior to the transmission of the silt fence prior to the transmission of the t	ng the silt fence during t rior to the 3/22/22 29/22. Majestic Pointe L Majestic Pointe LLC le inspection on 8/30/22 the inspection on
SF 2 Current Condition:	inspection on 3/16/22. E&A ir inspection. Sudbeck reinstalled reinstalled the silt fence along backfilled the silt fence and ir Walvoord Excavating backfill. 10/05/22. Minor spoils were of The silt fence was cleaned of Silt Fence Good Condition - JC Excavat fence along the south side of 10/25/21. Tab Construction g inspection on 3/02/22. Sudbe the SB A outfall and reinstalle outfall was removed during the Majestic Pointe LLC reinstalle the inspection on 7/26/22. Th silt fence was removed along reinstalled prior to the 5/31/23 removal in this maintenance	spector will monitor fo ad the silt fence where and over the south si istalled a J-hook north ed and repaired the silt bserved in the silt fenc it south of the Reynold <u>117 - K7</u> ion installed the silt fer the N 170th Street cro raded the N 170th Street ck cleaned out and rep ed the silt fence where ee clearing observed d ed the silt fence along a e area of ground distur the north side of the R B inspection. Old portio as of 6/7/23. Majestic F	on 10/25/21. Sudbeck Compar r completion. Sudbeck cleaned removed near the center of the de of Reynolds Street Culvert p of the crossing on the eastern t fence on the north side of the R is Street crossing prior to the in <u>4/27/2021</u> and the north side of the executivert and removed the silt baired the silt fence prior to the removed near the center of the luring the inspection on 7/19/22 and over the north side of Reyn bance was stabilized by Dustin Reynolds Street crossing prior to the created the silt fence prior to the removed near the center of the luring the inspection on 7/19/22 and over the north side of Reyn bance was stabilized by Dustin Reynolds Street crossing prior to the solution of SF 2 west of the creek do Pointe LLC reinstalled the silt fer	nies was in the process of repairin out and repaired the silt fence pr e run prior to the inspection on 3/2 prior to the inspection on 7/26/22. portion of the silt fence prior to th Reynolds Street crossing prior to teynolds Street crossing during the spection on 5/17/23.	ng the silt fence during f rior to the 3/22/22 29/22. Majestic Pointe LL Majestic Pointe LLC the inspection on 8/30/22 the inspection on 10/26/2 the inspection on 10/26/2 No tic Pointe LLC installed the inspection on rocess prior to the aired the silt fence north 29/22. Silt fence around ecommend reinstallation Oth Street Culvert prior 9/21/22. A portion of th fence was partially ill not be recommended crossing and above the
	inspection on 3/16/22. E&A ir inspection. Sudbeck reinstalled reinstalled the silt fence along backfilled the silt fence and ir Walvoord Excavating backfill. 10/05/22. Minor spoils were of The silt fence was cleaned of Silt Fence Good Condition - JC Excavat fence along the south side of 10/25/21. Tab Construction g inspection on 3/02/22. Sudbe the SB A outfall and reinstalle outfall was removed during the Majestic Pointe LLC reinstalle the inspection on 7/26/22. Th silt fence was removed along reinstalled prior to the 5/31/23 removal in this maintenance	spector will monitor fo ad the silt fence where and over the south si istalled a J-hook north ed and repaired the silt bserved in the silt fenc it south of the Reynold <u>117 - K7</u> ion installed the silt fer the N 170th Street cro raded the N 170th Street ck cleaned out and rep ed the silt fence where ee clearing observed d ed the silt fence along a e area of ground distur the north side of the R B inspection. Old portio as of 6/7/23. Majestic F	on 10/25/21. Sudbeck Compar r completion. Sudbeck cleaned removed near the center of the de of Reynolds Street Culvert p of the crossing on the eastern t fence on the north side of the R is Street crossing prior to the in <u>4/27/2021</u> and the north side of the executivert and removed the silt baired the silt fence prior to the removed near the center of the luring the inspection on 7/19/22 and over the north side of Reyn bance was stabilized by Dustin Reynolds Street crossing prior to the created the silt fence prior to the removed near the center of the luring the inspection on 7/19/22 and over the north side of Reyn bance was stabilized by Dustin Reynolds Street crossing prior to the solution of SF 2 west of the creek do Pointe LLC reinstalled the silt fer	ies was in the process of repairir out and repaired the silt fence pro- prior to the inspection on 3/2 portior to the inspection on 7/26/22. portion of the silt fence prior to the Reynolds Street crossing prior to teynolds Street crossing during the spection on 5/17/23. Active 27/21. JC Excavation and Majest Reynolds Street crossing prior to fence around the culvert in the prior 3/22/22 inspection. Sudbeck repair run prior to the inspection on 3/2 E. &A inspector will monitor to re- iolds Street Culvert and the N 17(0 Wallis prior to the inspection on the inspection on 10/26/22. Silt on the belong to this project and with the north of the Reynolds Street	ng the sill fence during t rior to the 3/22/22 29/22. Majestic Pointe LC Majestic Pointe LLC the inspection on 8/30/22 the inspection on 10/26/2 mage inspec

SF 4	Silt Fence	M6 - R2		Removed		
Current Condition:				the inspection on 10/06/21. JC	Excavation removed the	
	remainder of the silt fence fabric prior to the inspection on 11/11/21.					
SF 5	Silt Fence	M6 - N3		Removed		
Current Condition:	Removed - Silt fence identifi		21.	-		
SF 6	Silt Fence	H19		Removed		
Current Condition:		emoved the silt fence or	n both sides of the creek prior t	o the inspection on 10/06/21.		
SF 7	Silt Fence	K6		Removed		
Current Condition:	Removed - JC Excavation re	emoved the silt fence or	n both sides of the creek prior t	o the inspection on 10/06/21.		
SF 8	Silt Fence	R2		Removed		
Current Condition:			ior to the inspection on 10/06/2		-	
SF 9	Silt Fence	W15	6/28/2022	Active	No	
Current Condition:		n; maintenance is not n		ection on 6/28/22. Damage was of Pointe LLC repaired the silt fence		
SF 10	Silt Fence	Along Streets	1/4/2023	Active	No	
Current Condition:	northern portion of the silt fe	nce prior to the 8/7/23 i pector will monitor for m	nspection. Damage was obser naintenance. Majestic Pointe Ll	e inspection on 5/31/23. Majesti ved to the northern portion of the .C extended the northern run of	e silt fence prior to the	
SF 11	Silt Fence	Terrace	7/24/2023	Active	No	
Current Condition:	Good Condition - Majestic P	ointe LLC installed the	silt fence prior to the 8/7/23 ins	pection.		
SF 12	Silt Fence	N 170th Ave & N 170th Terrace	8/28/2023	Active	No	
Current Condition:			silt fence prior to the 8/28/23		NU	
current condition.	Good Condition - Majestic P		· · · · · · · · · · · · · · · · · · ·			
<b>0-</b> 10	ow =	South of Young Street				
SF 13	Silt Fence	& N 170th St	8/28/2023	Active	No	
Current Condition:	Good Condition - Majestic P	ointe LLC installed the	silt fence prior to the 8/28/23 in	spection.		
SF 14	Silt Fence	South of N 169th St	8/28/2023	Active	No	
Current Condition:	Good Condition - Majestic P	ointe LLC installed the	silt fence prior to the 8/28/23 in	spection.	•	
SF 15	Silt Fence	South of Reynolds St and 169th St	8/28/2023	Active	No	
Current Condition:	Good Condition - Majestic P	ointe LLC installed the	silt fence prior to the 8/28/23 in	spection.		
			1	I	1	
SF 16	Silt Fence	South of Reynolds St and 170th St	8/28/2023	Active	No	
Current Condition:			silt fence prior to the 8/28/23 in		NO	
current condition.						
STR	Street Cleaning	Internal and Adjacent Streets	9/11/2023	Active	No	
	Good Condition -	Aujacent Streets	5/11/2023	Active		
Current Condition:						
WO 01	Concrete Washout	On Site		Removed		
Current Condition:			waste from the site prior to the	-	-	
WO 02	Concrete Washout	On Site		Removed		
Current Condition:			washout prior to the inspection		_	
WO 03	Concrete Washout	Southeast of SB B		Removed		
Current Condition:			washout prior to the inspection			
WO 04	Concrete Washout	West of SB B		Removed		
Current Condition:			washout prior to the inspection		-	
WS 01	Waste Storage Area	On Site		Removed		
Current Condition:	Removed - The waste storage	ge container was remov	ved from the site prior to the ins	pection on 7/26/22.		
Certification Statement:	system designed to assure to person or persons who man the best of my knowledge ar	hat qualified personnel age the system or those ad belief, true, accurate	properly gathered and evaluate e persons directly responsible f	ed under my direction or supervised ad the information submitted. Ba or gathering the information, the t there are significant penalties f ns.	sed on my inquiry of the information submitted is,	
spector Signature:	HE			Reviewed By:	to be	