E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A -	P2020.091.000				
Inspector: Josh Ellington					Stage		
Project Name:	0	1					
For Week Ending:		OMA-20201015-5644-GP1 / CSW-202005078 9/23/2023					
Project Location:	16	8th Street and State	Street - Omaha, NE (Douglas	s County)			
Grading:	99%						
Sanitary Sewer:	100%						
Storm Sewer:	95%						
Paving:	98%						
Seeding:	35%						
Utilities:	80%						
Overall Development:	58%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time Weel		
RAIN FALL AMOUNTS Sunday:	Amount in tenths 0.00"	Date inspected	Weather Conditions	Time			
Sunday:		Date inspected 9/18/2023	Weather Conditions Partly Cloudy 69	Time 10:50 AM			
Sunday: Monday Tuesday	0.00"						
Sunday: Monday Tuesday	0.00" 0.00"						
Sunday: Monday	0.00" 0.00" 0.00"						
Sunday: Monday Tuesday Wednesday	0.00" 0.00" 0.00" 0.00"						
Sunday: Monday Tuesday Wednesday Thursday	0.00" 0.00" 0.00" 0.00" 0.08"						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021). Seeding along the N 170th Street crossing (9/28/2022). Matting along the N 170th Street crossing (10/05/2022).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

_		_	_	_	_
ĸ	ı	1	۸		

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion?

Nο

Create Corrective Action?

No - See Findings section

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

NIO

Create Corrective Action?

No - See Findings section

4.) Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

5.) Is dust associated with the construction activity adequately controlled on the site?

Voc

Create Corrective Action?

N/A

Comments:

Comments:

Site was active for home construction during the current inspection.

Tree removal northwest of SB B was observed during the 9/18/23 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) Waste concrete should be removed. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23.
- 3.) Inactive portions of the site should be stabilized. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	V11		Removed			
Current Condition:	Removed - JC Excavation graded out the site access at this location as of the inspection on 10/13/21.						
CE 2	Construction Entrance	S2	2/23/2021	Pending	No		
Current Condition:	Pending - Legacy Homes installed a construction entrance prior to 2/23/21. Majestic Pointe LLC and Legacy Homes blocked the construct entrance prior to the inspection on 6/08/21. JC Excavation blocked the construction entrance prior to the inspection on 10/13/21. E&A inspector will monitor and make recommendations if the entrances is used at a later date.						
CE 3	Construction Entrance	T27		Removed	No		
Current Condition:	Removed - TAB Construction	n removed the construc	tion entrance prior to the inspec	ction on 6/10/22.			
CE 4	Construction Entrance	14		Removed			
Current Condition:	Removed - The construction	entrance was paved pr	ior to the inspection on 9/21/22		•		
CIP 1	Inlet Protection	S29	2/16/2022	Active	No		
			a mar protoction prior to the mi	opodion on megalical	onite LLO oleanea out ti		
CIP 2	inlet protection prior to the 8/		p	Removed	Since ELO Gicarioù out il		
CIP 2 Current Condition:	inlet protection prior to the 8/	7/23 inspection. South end of North 169 Street			ointe LLC cleaned out th		
<u> </u>	inlet protection prior to the 8/	7/23 inspection. South end of North 169 Street			No No		
Current Condition:	Inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St	t as of 8/28/23.	Removed			
Current Condition: CIP Craig St	Inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St	St as of 8/28/23. 8/28/2023	Removed			
Current Condition: CIP Craig St Current Condition:	Inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Poly Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb	St as of 8/28/23. 8/28/2023 inlet protections 1-8 prior to the	Removed Active e inspection on 8/28/23. Active	No No		
Current Condition: CIP Craig St Current Condition: CIP N 169th St	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Policy Inlet Protection Good Condition - Majestic Policy Good Condition - Majestic Policy Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb	8t as of 8/28/23. 8/28/2023 inlet protections 1-8 prior to the 8/28/2023	Removed Active e inspection on 8/28/23. Active	No No		
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition:	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Policy Inlet Protection Good Condition - Majestic Policy B/22/22 but is now included i	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb In this BMP. N 170th Ave	8t as of 8/28/23. 8/28/2023 inlet protections 1-8 prior to the 8/28/2023 o inlet protections 1-6 prior to the	Removed Active e inspection on 8/28/23. Active le inspection on 8/28/23. CIP 2 Active	No No was installed previously		
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave	Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Policy Inlet Protection Good Condition - Majestic Policy B/22/22 but is now included i	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St Dinte LLC installed curb In this BMP. N 170th Ave	8/28/2023 inlet protections 1-8 prior to the 8/28/2023 o inlet protections 1-6 prior to the 8/28/2023	Removed Active e inspection on 8/28/23. Active le inspection on 8/28/23. CIP 2 Active	No No was installed previously		
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave Current Condition:	Inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection Good Condition - Majestic Po Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St binte LLC installed curb N 169th St binte LLC installed curb n this BMP. N 170th Ave binte LLC installed curb N 169th St	8/28/2023 inlet protections 1-8 prior to the 8/28/2023 o inlet protections 1-6 prior to the 8/28/2023 inlet protection prior to the insp	Removed Active e inspection on 8/28/23. Active le inspection on 8/28/23. CIP 2 Active Decition on 8/28/23. Active Decition on 8/28/23.	No No was installed previously No		
Current Condition: CIP Craig St Current Condition: CIP N 169th St Current Condition: CIP N 170th Ave Current Condition: CIP N 170th St	Inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Po Inlet Protection Good Condition - Majestic Po 8/22/22 but is now included i Inlet Protection Good Condition - Majestic Po Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St binte LLC installed curb N 169th St binte LLC installed curb n this BMP. N 170th Ave binte LLC installed curb N 169th St	8/28/2023 inlet protections 1-8 prior to the 8/28/2023 o inlet protections 1-6 prior to the 8/28/2023 inlet protection prior to the inspection prior prior prior to the inspection prior p	Removed Active e inspection on 8/28/23. Active le inspection on 8/28/23. CIP 2 Active Decition on 8/28/23. Active Decition on 8/28/23.	No No was installed previously No		

CIP Reynolds St	Inlet Protection	Reynolds St	8/28/2023	Active	No		
Current Condition:	Good Condition - Majestic Pe	ointe LLC installed curb	inlet protections 1-8 prior to the	e inspection on 8/28/23.			
CIP Sheffield St	Inlet Protection	Sheffield St	8/28/2023	Active	No		
Current Condition:	Good Condition - Majestic P	ointe LLC installed curb	inlet protections 1-4 prior to the	e inspection on 8/28/23.			
CIP Young St	Inlet Protection	Young Street	8/28/2023	Active	No		
Current Condition:			inlet protections 1 & 2 prior to		INO		
	•		•		T		
CW	Concrete Washout	On Site	8/28/2023	Active	No		
Current Condition:	Good Condition - D R Horton installed a portable concrete washout prior to the inspection on 8/28/23.						
D 1	Diversion	O3 - U2	11/16/2021	Active	No		
Current Condition:	misidentified. As of 11/23/21 12/02/21. Walvoord Excavat	, diversion is located at ing redefined the divers		•			
D 2	Diversion	J18 - S27		Removed			
Current Condition:	reinstallation will not be reco	mmended as of 7/5/22.		orior to the inspection on 12/02/21	. Due to paving,		
D 3	Diversion	J15 - N6		Removed			
Current Condition:	Removed - The diversion was be recommended as of 7/5/2	22.		e inspection 12/02/21. Due to pavi	ng, reinstallation will not		
EM 1	Erosion Control Matting	E11 - S25	9/1/2021	Pending	No		
Current Condition:	Pending - The matting will be	e installed after grading	is completed in the area and w	eather conditions allow.			
EM 2	Erosion Control Matting	E6 - F12	12/8/2021	Active	No		
Current Condition:	Good Condition - Majestic Po	ointe LLC installed the	erosion control matting prior to	the inspection on 12/08/21.			
EM 3	Erosion Control Matting	M6 - Z6	9/1/2021	Pending	No		
Current Condition:	Pending - The matting will be	e installed after grading	is completed in the area and w	eather conditions allow.			
EM 4	Erosion Control Matting	Z5 - Z24	12/8/2021	Active	No		
Current Condition:	Good Condition- Majestic Po	inte LLC installed the e	rosion control matting prior to t	he inspection on 12/08/21.			
EM 5	Erosion Control Matting	V1 - V7	12/8/2021	Active	No		
Current Condition:	Good Condition- Majestic Po	inte LLC installed the e	rosion control matting prior to t	he inspection on 12/08/21.			
ET 1	Erosion Control Terrace	V8 - O21	9/21/2021	Active	No		
Current Condition:	Good Condition - JC Excava	ition installed the erosic	n control terrace prior to the ins	spection on 9/21/21.			
ET 2	Erosion Control Terrace	S2 - K14	9/21/2021	Active	No		
Current Condition:			tv of the erosion control terrace	prior to the inspection on 9/21/21	<u> </u> -		
FT 1	Fuel Tank	On-site	 	Removed			
Current Condition:			removed the fuel tanker and cla	eaned up the spills prior to the ins	Lection on 12/16/21		
FT 2	Fuel Tank			Removed	T		
		On-site	to the improvation on 14/02/04	Removed			
Current Condition:			to the inspection on 11/23/21.	D	T T		
FT 3	Fuel Tank	On-site	lad facilitarilaria de la constanta de la	Removed			
Current Condition:			led fuel tank on site prior to the				
FT 4	Fuel Tank	On-site		Removed			
Current Condition:	Removed - Tab Construction		prior to the inspection on 12/29	9/21.			
Lot 166	Individual Lot	Lot 166	9/6/2023	Active	No		
Current Condition:	Good Condition - D R Hortor inspection, the inspector will			on. Dirt piles were observed in the	ROW during the 9/6/23		
Lot 167	Individual Lot	Lot 167	9/6/2023	Active	No		
Current Condition:	Good Condition - D R Hortor inspection, the inspector will			on. Dirt piles were observed in the	ROW during the 9/6/23		
Lot 168	Individual Lot	Lot 168	9/6/2023	Active	No		
Current Condition:	Good Condition - D R Hortor inspection, the inspector will			on. Dirt piles were observed in the	ROW during the 9/6/23		
Lot 169	Individual Lot	Lot 169	8/28/2023	Active	No		
Current Condition:				nd installed straw wattles prior to t	he 8/2823 inspection. Dirt		
Lot 170	piles were observed in the R Individual Lot	OW during the 8/26/23 Lot 170	inspection, the inspector will m	onitor for removal. Active	No		
Current Condition:				prior to the 8/2823 inspection. Dirt	I .		
	ROW during the 8/26/23 insp	pection, the inspector w	ill monitor for removal.				
Lot 180	Individual Lot	Lot 180	8/28/2023	Active	No		
Current Condition:	the inspector will monitor for			es were observed in the ROW dur	ing the 8/26/23 inspection,		
Lot 194	Individual Lot	Lot 194	8/28/2023	Active	No		
Current Condition:	Active - D R Horton began exthe inspector will monitor for		the 8/2823 inspection. Dirt pile	es were observed in the ROW dur	ing the 8/26/23 inspection,		
MS 01	Material Storage	On Site	3/2/2022	Active	No		
Current Condition:	•		outh portion of the site as of the	inspection on 3/02/22.	1		
PB 01	Portable Bathroom	On Site		Removed			

Current Condition:	Removed - JC Excavation re	moved the portable toil	et prior to the inspection on 11/	23/21.		
PB 02	Portable Bathroom	On Site		Removed		
Current Condition:	Removed - Tab Construction	· · · · · · · · · · · · · · · · · · ·	toilet prior to the inspection on			
PB X	Portable Bathroom	On Site	12/29/2021	Pending	No	
Current Condition:	prior to the inspection on 3/1 up and resecured the portable secured a portable toilet on s	6/22. Tab Construction le toilet prior to the inspection to the inspection to the inspection on 4/26/	removed a portable toilet from ection on 4/22/22. Valley Corp on on 11/21/22. MUD removed '23. An unknown contractor rem	on 12/29/21. Valley Corp secured the site prior to the inspection on removed a toilet prior to the inspe the portable toilet and an unknow loved the portable toilet on site pr	3/29/22. Valley Corp stood ction on 8/16/22. MUD n contractor secured a	
SB A	Sediment Basin	E9	7/14/2021	Active	No	
Current Condition:	JC Excavation repaired the einstalling the riser during the inspector painted the cleanor inspection on 12/08/21. The site's advanced development	erosion along the berm inspection on 11/23/21 ut mark during the insper recommendation of incl t. Minor erosion was ob	of the basin prior to the inspecti JC Excavation installed the ou- ection on 12/08/21. Majestic Po- luding the emergency spillway was served around the barrel during	ection on 10/06/21. E&A inspecto on on 11/03/21. JC Excavation w tifall pipe prior to the inspection o inte LLC installed an inlet pipe int will no longer be recommended as g the 6/26/23 inspection; E&A inspection; the commended of the riser structure of the commended of the riser structure of the commended of the riser structure of the commended of the commended of the riser structure of the commended of the c	as in the process of n 12/02/21. The E&A to the basin prior to the s of 9/6/2022 due to the pector will continue to	
SB B	Sediment Basin	О3	9/28/2021	Active	No	
Current Condition:	berm of the basin prior to the 11/23/21. JC Excavation inst inspection on 12/08/21. JC E 12/16/21. JC Excavation fully riser during the inspection or inspection on 6/28/22. The E emergency spillway will no lo prior to the inspection on 9/1.	inspection on 11/03/21 alled the outfall pipe prince and Gene Given being the berm prior of 6/21/22. E&A inspector & inspector painted the proper be recommended 2/22.	I. JC Excavation was in the pro- ior to the inspection on 12/02/2- raves partially built up the low s to the inspection on 12/21/21. or will monitor for completion. M he cleanout mark during the insp as of 9/6/2022 due to the site's	on 10/25/21. JC Excavation repairess of installing the riser during to 1. The E&A inspector painted the pot in the berm near the riser priomagestic Pointe LLC was in the piection on 6/28/22. The recommendation advanced development. Hausman	the inspection on cleanout mark during the r to the inspection on occess of reinstalling the riser prior to the endation of including the an began basin cleanout	
SF 1 Current Condition:	Silt Fence	W27 - I20	4/27/2021	Active 27/21. JC Excavation and Majesti	No	
	cleaned out the silt fence prior to the inspection on 10/13/21. JC Excavation and Majestic Pointe LLC installed silt fence along the south side the Reynolds Street crossing prior to the inspection on 10/25/21. Sudbeck Companies was in the process of repairing the silt fence during the inspection on 3/16/22. E&A inspector will monitor for completion. Sudbeck cleaned out and repaired the silt fence prior to the 3/22/22 inspection. Sudbeck reinstalled the silt fence where removed near the center of the run prior to the inspection on 3/29/22. Majestic Pointe LLC reinstalled the silt fence along and over the south side of Reynolds Street Culvert prior to the inspection on 7/26/22. Majestic Pointe LLC backfilled the silt fence and installed a J-hook north of the crossing on the eastern portion of the silt fence prior to the inspection on 8/30/22. Walvoord Excavating backfilled and repaired the silt fence on the north side of the Reynolds Street crossing prior to the inspection on 10/26/22. The silt fence was cleaned out south of the Reynolds Street crossing prior to the inspection on 5/17/23.					
SF 2	Silt Fence	I17 - K7	4/27/2021	Active	No	
Current Condition:	fence along the south side of 10/25/21. Tab Construction of inspection on 3/02/22. Sudbethe SB A outfall and reinstall outfall was removed during tr Majestic Pointe LLC reinstall the inspection on 7/26/22. The silt fence was removed along reinstalled prior to the 5/31/2 removal in this maintenance	f the N 170th Street cro graded the N 170th Street eck cleaned out and reped the silt fence where ree clearing observed ded the silt fence along a ne area of ground distur g the north side of the R 3 inspection. Old portions of 6/7/23. Majestic F	ssing and the north side of the let culvert and removed the silt paired the silt fence prior to the removed near the center of the uring the inspection on 7/19/22 and over the north side of Reynbance was stabilized by Dustin teynolds Street crossing prior to ns of SF 2 west of the creek do Pointe LLC reinstalled the silt fe	27/21. JC Excavation and Majesti Reynolds Street crossing prior to fence around the culvert in the prior 3/22/22 inspection. Sudbeck reparun prior to the inspection on 3/29. E&A inspector will monitor to recolds Street Culvert and the N 170 Wallis prior to the inspection on 9 to the inspection on 10/26/22. Silt from the long to this project and will not provide the Reynolds Street west of the creek prior to the 8/8/	the inspection on occess prior to the ired the silt fence north of 2/22. Silt fence around the commend reinstallation. th Street Culvert prior to 2/21/22. A portion of the ence was partially I not be recommended for crossing and above the	
SF 3	Silt Fence	M6 - R2	4/27/2021	Active	No	
Current Condition:	repairing/reinstalling the silt finstalled silt fence along the reinstalled/extended the silt f Construction graded the N 1. Sudbeck cleaned out and tre of SB B, reinstalled silt fence 3/29/22. Graves Developmer 7/26/22. Graves Developmer repairing the silt fence south	ence during the inspect north side of the N 1701 ience south from the SE 70th Street culvert and nuched in the silt fence e along the north side of nt reinstalled the silt fen int installed silt fence ab of the crossing during t	tion on 4/21/21. Silt fence was fith Street crossing prior to the in 8 B outfall to the N 170th Street removed the silt fence around to prior to the 3/22/22 inspection. 5 the site, and installed two checked along and over the north side ove and below the outfall prior the inspection on 9/28/22. Walve	on on 2/23/21. JC Excavation was formerly identified as SF 5. JC Excavation on 10/25/21. JC Excavations on 10/25/21. JC Excavations on the culvert in the process prior to the Sudbeck reinstalled the silt fence cks along the north side of the site of the N 170th Street Culvert prior the inspection on 8/30/22. Graviord Excavating cleaned out the cort to the inspection on 10/05/22.	cavation and Gene Graves tion and Gene Graves in 12/08/21. Tab he inspection on 3/02/22. where removed northwest prior to the inspection on ior to the inspection on yes Development was	

SF 4	Silt Fence	M6 - R2		Removed	
Current Condition:	Removed - JC Excavation re remainder of the silt fence fa			the inspection on 10/06/21. JC E	xcavation removed the
SF 5	Silt Fence	M6 - N3		Removed	
Current Condition:	Removed - Silt fence identifi	ed as SF 3 as of 4/27/2	1.		
SF 6	Silt Fence	H19		Removed	
Current Condition:	Removed - JC Excavation re	moved the silt fence or	Loth sides of the creek prior to	the inspection on 10/06/21	
SF 7	Silt Fence	K6		Removed	Ī
Current Condition:		-	l both sides of the creek prior to		
SF 8	Silt Fence	R2	I both sides of the creek prior to	Removed	T
			I ior to the inspection on 10/06/2		
Current Condition: SF 9	Silt Fence	W15	6/28/2022	Active	No
Current Condition:		n; maintenance is not ne		ction on 6/28/22. Damage was ob Pointe LLC repaired the silt fence	
SF 10	Silt Fence	Along Streets	1/4/2023	Active	No
Current Condition:	northern portion of the silt fe	nce prior to the 8/7/23 in sector will monitor for m	nspection. Damage was observ aintenance. Majestic Pointe LL	inspection on 5/31/23. Majestic ed to the northern portion of the s C extended the northern run of th	silt fence prior to the
		N 170th St & N 170th			
SF 11	Silt Fence	Terrace	7/24/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the s	silt fence prior to the 8/7/23 insp	pection.	
		N 170th Ave & N			
SF 12	Silt Fence	170th Terrace	8/28/2023	Active	No
Current Condition:	Good Condition - Maiestic P	ointe LLC installed the s	silt fence prior to the 8/28/23 ins	spection.	1
			·		1
SF 13	Silt Fence	South of Young Street & N 170th St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the s	silt fence prior to the 8/28/23 ins	spection.	
SF 14	Silt Fence	South of N 169th St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	cinte LLC installed the s	silt fence prior to the 8/28/23 ins	spection.	
				·F	1
SF 15	Silt Fence	South of Reynolds St and 169th St	8/28/2023	Active	No
Current Condition:			silt fence prior to the 8/28/23 ins		INO
Current Condition.	Good Condition - Wajestic F		silt terice prior to the 0/20/25 ins	spection.	
		South of Reynolds St			
SF 16	Silt Fence	and 170th St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the s	silt fence prior to the 8/28/23 ins	spection.	
STR	Street Cleaning	Internal and Adjacent Streets	4/2/2021	Active	No
Current Condition:	· ·			r trackout was observed on N 170	
	inspection on 1/05/22. Majes cleaned 171th Street prior to cleaned the streets prior to the	tic Pointe LLC cleaned the inspection on 8/23/ ne inspection on 2/01/2	Potter Street south of the site p 22. The street was cleaned prior	orior to the inspection on 6/28/22. For to the inspection on 9/12/22. Method the streets prior to the 8/7/23 ins	Majestic Pointe LLC lajestic Pointe LLC partia
WO 01	Concrete Washout	On Site		Removed	
Current Condition:			waste from the site prior to the i	<u> </u>	
WO 02	Concrete Washout	On Site		Removed	
Current Condition:	Removed - Tab Construction	removed the concrete	washout prior to the inspection	on 8/16/22.	
WO 03	Concrete Washout	Southeast of SB B		Removed	
Current Condition:	Removed- Tab Construction		washout prior to the inspection	on 8/30/22.	
WO 04	Concrete Washout	West of SB B		Removed	
Current Condition:	Removed - Tab Construction	removed the concrete	washout prior to the inspection	on 8/9/22.	
WS 01	Waste Storage Area	On Site		Removed	
Current Condition:	Removed - The waste storage	ge container was remov	ed from the site prior to the insp	pection on 7/26/22.	•
Certification Statement:	system designed to assure to person or persons who manathe best of my knowledge and	hat qualified personnel age the system or those id belief, true, accurate,	properly gathered and evaluate persons directly responsible fo	d under my direction or supervision of the information submitted. Base or gathering the information, the inthere are significant penalties for s.	ed on my inquiry of the nformation submitted is,
	HE		-	Reviewed By:	t se