E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC					GROUP, INC. FIELD SERVICES
Erosion Control Specialist- Manage		2004.045.000	LIVOINTELINI	to or Extransion	TILLE GLITTIGLG
Inchester Mike Jacobson CISEC	EαA-F	2004.045.000			Stage
Inspector: Mike Jacobson, CISEC		Maridian D	- uls		Stage 2
Project Name:		Meridian Pa NER11069			2
For Week Ending:		6/9/2012			
Project Location:	168th & Giles	Street- Omaha, I		tv)	68136
			(-37	
Grading:	100%				
Sanitary Sewer:	90%				
Storm Sewer:	90%				
Paving:	90%				
Seeding: Utilities:	100%				
Overall Development:	20%				
Overan Development.	2070	l	1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			Wook
Sunday:	0.00"				Week
Monday	0.47"		 		
Tuesday	0.00"		†		
Wednesday	0.23"		1		
Thursday	0.01"				
Friday	0.02"				
Saturday	0.01"				
					Week
Sunday:	0.00"				
Monday	0.00"	06/04/12			
Tuesday Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
outu. uuy	0.00				Week
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday Saturday	N/A	N/A			
Saturday	N/A	N/A			
Complaints:	None				
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or perr	nanent cessation of g	rading, earthwork, o	or ground disturband	e in the last 14 days?
Entire Site, grading completed and si	te seeded Summer/Fall 2005.				
Entire Site, grading was completed in	Replat Three area Lots 1-54	prior to inspection	on 10/5/11 by Do	ouble D.	
Mich portions (i.e. delegan back)	alte de parthage con d'on o en d'	als an analysis district	nan askaduludu 11 - 11	- mant 44 days 2	
Which portion's) (i.e. drainage basins) of the			ance scheduled in th	ie next 14 days?	
Entire Site, grading completed and si					
Entire Site, grading was completed in	Replat Three area Lots 1-54	prior to inspection	on 10/5/11 by Do	ouble D.	
What temporary or permanent stabilization	neasures listed in this section are	being implemented?	I	<u> </u>	
Site seeded Fall 2005 & 5/2007, stab (9/2008); Areas around where handic Replat three lots 1-54 was seeded 10	ilized entrances installed Sum ap ramps were installed was i	nmer 2005, Re-See re-seeded (4/2009); Sediment basir		
Comments:			<u> </u>		

Comments:
A few homes are under construction in the site.

This is the last report as a stage two as it is being converted to a stage 3 as of next week.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No maintenance is required in the BMP section.

Unique Name	Type				
	. 950	Location	Install Date	Status	Maintenance
CE A	Construction Entrance	N41d00m00s W96d00m00s		Removed	
Current Condition:	Entrance Paved	VV30d00iii003		removed	
		Along 164th			
CW	Concrete Washout Pit	Street		Removed	
Current Condition:	Concrete washout was remo	oved prior to inspec	ction on 7/12/11 b	by Jeff w/ Hearths	stone Production.
		41 4054			
CW 1	Concrete Washout Pit	Along 165th Street	7/12/2011	Active	No
Current Condition:	Good Condition-				-
	Washout pit was replaced a by Jeff w/ Hearthstone Prod		debris was clea	ned up prior to in	spection on 10/19/11
POD B	Silt Fence	Lots 63-73		Removed	
Current Condition:	Silt fence is no longer neede	ed due to the all lot	s being sodded ir		inspection on 6/3/10
	by Chris w/ Hearthstone Pro	duction.			
POD C	Silt Fence	Lots 97-122		Removed	
Current Condition:	Silt fence is no longer neede	ed due to the all lot	s being sodded ir		inspection on 10/5/11
	by Jeff w/ Hearthstone Prod	uction.			
POD D Current Condition:	Silt Fence Silt fence is no longer neede	Lots 123-162	s being sodded ir	Removed	inspection on 10/5/11
Current Condition:	by Jeff w/ Hearthstone Prod		o bomig occacion ii	. timo pod prior to	
POD E	Silt Fence	Lots 163-199		Removed	
Current Condition:	Silt fence installed on the ba Hearthstone Production due				
	. Toda i i i i i i i i i i i i i i i i i i i	to the fet being co		pou	avo boon compreted.
DOD F	011 5	1 - 1 - 000 047	4/40/0044	A	N
POD F Current Condition:	Silt Fence Good Condition- Silt fence in	Lots 209-217	4/16/2011 k lots or the back	Active of the lots 209-2	No 212 and lot 217.
	Maintenance on lot 216 was	completed prior to	inspection on 6/	4/12 by Nic w/ Th	he Home Company.
		Lots 51-56 along			
POD E Current Condition:	Silt Fence Good Condition-	Meridian Street	5/2/2012	Active	No
Current Containent	Maintenance on lot 52 was o	completed prior to i	inspection on 6/4	/12 by Nic w/ The	e Home Company.
		N41d00m00s			
SB E	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Basin was removed due to l	ot development pri	or to inspection o	on 6/12/08 by Do	ouble D Excavating.
		N41d00m00s			
SB F	Sediment Basin	W96d00m00s	filled in his Davib	Removed	
Current Condition:	As of inspection on 5/12/11		i iiilea iii by Doub	ne D Excavating.	
SB G	Sediment Basin	N41d00m00s W96d00m00s	08/26/05	Active	No
Current Condition:	Good Condition- 15% Filled				
	Partially Cleaned out and ba		to inspection on 1	10/12/10 by Bob	Roth.
SF A	Silt Fence	N41d00m00s W96d00m00s	07/19/05	Removed	
Current Condition:	Removed	***************************************	01/13/00	Nomoveu	
		N41d00m00s			
SF B Current Condition:	Silt Fence Removed - Not needed due	W96d00m00s	etative cover in a	Removed	
Current Condition:	removed - Not needed due	N41d00m00s	eranive cover in a	uca.	
SF C	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed - Not needed due	to established veg	etative cover in a	irea.	

		Meridian Park				
SF 1	Silt Fence	Replat Lot 1	5/4/2010	Active	No	
Current Condition:	Good Condition- Silt fence Maintenance was comple				ne.	
		Meridian Park				
		Replat Lots 26,				
SF 2	Silt Fence	27	5/4/2010	Active	No	
Current Condition:	Good Condition- Silt fence Maintenance was comple				ne.	
		Meridian Park				
		Replat Lots 46,				
SF 3	Silt Fence	47	5/4/2010	Active	No	
Current Condition:	Good Condition- Silt fence Maintenance was comple				ne.	
		N41d00m00s				
ST A	Silt Trap	W96d00m00s		Removed		
Current Condition:	Trap Closed June 2006.	N41d00m00s	I	1	1	
ST B	Sediment Trap	W96d00m00s		Removed		
Current Condition:	Sediment trap was remov		on 10/5/11 due		he area by Doub	
		N41d00m00s	I		1	
ST C	Sediment Trap	W96d00m00s		Removed		
Current Condition:	Sediment trap was remov		on 10/5/11 due	to re-grading of t	he area by Doub	
		T	ī		1	
ST D	Sediment Trap	N41d00m00s W96d00m00s		Removed		
Current Condition:	Sediment trap was remov		on 10/5/11 due		he area by Doub	
		T.,	ı	1	1	
		North of Replat three Lots 1 and				
ST 1	Sediment Trap	2	10/5/2011	Active	No	
Current Condition:		Good Condition- 5% Filled				
	Sediment trap is installed			ble D.	T	
		Southeast corner of Replat three				
ST 2	Sediment Trap	lot 1	10/5/2011	Active	No	
Current Condition:	Good Condition- 6% Filled Sediment trap is installed prior to inspection on 10/5/11 by Double D.					
Current Condition:		prior to inspection or	า 10/5/11 by Dou	ble D.		
Current Condition:		Prior to inspection or Northeast corner	,	ble D.		
		· - ·	,	ble D.		
ST 3	Sediment trap is installed Sediment Trap	Northeast corner of Replat three lot 26	,	Active	No	
	Sediment trap is installed	Northeast corner of Replat three lot 26	10/5/2011	Active	No	
ST 3	Sediment trap is installed Sediment Trap Good Condition- 9% Fille	Northeast corner of Replat three lot 26 d	10/5/2011	Active	No	
ST 3	Sediment trap is installed Sediment Trap Good Condition- 9% Fille	Northeast corner of Replat three lot 26	10/5/2011 n 10/5/11 by Dou	Active	No	
ST 3 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28	10/5/2011 n 10/5/11 by Dou	Active	No No	
ST 3 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28 d	10/5/2011 10/5/11 by Dou 10/5/2011	Active Active		
ST 3 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28 d prior to inspection or	10/5/2011 n 10/5/11 by Dou 10/5/2011 n 10/5/11 by Dou	Active Active		
ST 3 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille	Northeast corner of Replat three lot 26 d I prior to inspection or North of Replat three Lots 27 and 28 d I prior to inspection or Southeast corner of Replat three	10/5/2011 n 10/5/11 by Dou 10/5/2011 n 10/5/11 by Dou	Active Active		
ST 3 Current Condition: ST 4 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Sediment Trap	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28 d prior to inspection or Southeast corner of Replat three lot 27	10/5/2011 n 10/5/11 by Dou 10/5/2011 n 10/5/11 by Dou	Active Active		
ST 3 Current Condition: ST 4 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28 d prior to inspection or Southeast corner of Replat three lot 27 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No	
ST 3 Current Condition: ST 4 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	Northeast corner of Replat three lot 26 d Prior to inspection or North of Replat three Lots 27 and 28 d Prior to inspection or Southeast corner of Replat three lot 27 d Prior to inspection or lot 27 d Prior to inspection or lot 27 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No	
ST 3 Current Condition: ST 4 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	Northeast corner of Replat three lot 26 d I prior to inspection or North of Replat three Lots 27 and 28 d I prior to inspection or Southeast corner of Replat three lot 27 d I prior to inspection or Northeast corner	10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No	
ST 3 Current Condition: ST 4 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	Northeast corner of Replat three lot 26 d Prior to inspection or North of Replat three Lots 27 and 28 d Prior to inspection or Southeast corner of Replat three lot 27 d Prior to inspection or lot 27 d Prior to inspection or lot 27 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment Trap Good Condition- 5% Fille	Northeast corner of Replat three lot 26 d I prior to inspection or North of Replat three Lots 27 and 28 d I prior to inspection or Southeast corner of Replat three lot 27 d I prior to inspection or Northeast corner of Replat three lot 27 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment trap is installed Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment Trap	Northeast corner of Replat three lot 26 d I prior to inspection or North of Replat three Lots 27 and 28 d I prior to inspection or Southeast corner of Replat three lot 27 d I prior to inspection or Northeast corner of Replat three lot 46 d I prior to inspection or Northeast corner of Replat three lot 46 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment Trap Good Condition- 5% Fille	Northeast corner of Replat three lot 26 d I prior to inspection or North of Replat three Lots 27 and 28 d I prior to inspection or Southeast corner of Replat three lot 27 d I prior to inspection or Northeast corner of Replat three lot 27 d	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active	No No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition: ST 6 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment Trap Good Condition- 5% Fille Sediment Trap Good Condition- 5% Fille Sediment Trap Good Condition- 5% Fille Sediment Trap is installed	Northeast corner of Replat three lot 26 d Prior to inspection or Replat three Lots 27 and 28 d Prior to inspection or Southeast corner of Replat three lot 27 d Prior to inspection or Replat three lot 27 d Prior to inspection or Replat three lot 46 d Prior to inspection or N41d14m44s W96d12m59s	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active ble D. Active	No No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition: ST 6 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 5% Fille Sediment Trap Good Condition- No majo	Northeast corner of Replat three lot 26 d prior to inspection or North of Replat three Lots 27 and 28 d prior to inspection or Southeast corner of Replat three lot 27 d prior to inspection or Northeast corner of Replat three lot 46 d prior to inspection or N41d14rm44s W96d12m59s or signs of track off.	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active ble D. Active	No No No	
ST 3 Current Condition: ST 4 Current Condition: ST 5 Current Condition: ST 6 Current Condition:	Sediment trap is installed Sediment Trap Good Condition- 9% Fille Sediment Trap Good Condition- 7% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap Good Condition- 5% Fille	Northeast corner of Replat three lot 26 d Prior to inspection or Replat three Lots 27 and 28 d Prior to inspection or Southeast corner of Replat three lot 27 d Prior to inspection or Replat three lot 27 d Prior to inspection or Replat three lot 46 d Prior to inspection or N41d14m44s W96d12m59s	10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011 10/5/2011	Active ble D. Active ble D. Active ble D. Active	No No	

Saluel Jawlon

Zachany L. gilde

Inspector Signature:

Reviewed By: