E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager **E&A CONSULTING GROUP, INC.** ENGINEERING • PLANNING • FIELD SERVICES

nspector: Mike Jacobson, CIS	EC			Stage
		Meridian Park		3
Project Name:		NER110696		
-				
For Week Ending:		11/10/2012		
Project Location:	168th & Gi	les Street- Omaha, NE (Sarpy County)	68136
One dia au	100	0/		
Grading: Sanitary Sewer:	100			
Storm Sewer:	90			
Paving:	90			
Seeding:	100			
Utilities:	65			
Overall Development:	20			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
				Wee
Sunday:	0.26"			
Monday	0.00"			
Fuesday Nadasa day	0.00"			
Wednesday	0.02"			
Thursday	0.14"			
Friday Saturday	0.07"			
Saturday	0.00"			Wee
Sunday	0.00"			VVee
Sunday: Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.03"			
Thursday	0.41"			
Friday	0.00"			
Saturday	0.00"			
				Wee
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"	10/30/12		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Prine design	0.05"			Wee
Sunday:	0.05"			
Monday	0.02"			
Tuesday Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.17"	+ +		1
				Wee
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		1
	Nono			
Complaints:	None			
oompianits.	—			
Construction Sequencing:	I		I	I
Which portion(s) (i.e. drainage basins)	of the site have had a temporary or p	ermanent cessation of gradir	g, earthwork, or ground distur	pance in the last 14 days?
· · · · · · · · · · · · · · · · · · ·			-	
	d site cooded Summer/Fall 200)5		
ntire Site, grading completed ar	iu sile seeueu Summei/Faii 200	JG.		

Which portion's) (i.e. drainage bas	ins) of the site do not I	nave grading, earthwo	ork, or ground disturba	nce scheduled in th	e next 14 days?	
Entire Site, grading complete	d and site seeded \$	Summer/Fall 2005.				
Entire Site, grading was com	pleted in Replat Th	ree area Lots 1-54	prior to inspection	on 10/5/11 by Do	ouble D.	
What temporary or permanent stat	bilization measures list	ed in this section are	being implemented?			•
Site seeded Fall 2005 & 5/20 (9/2008); Areas around where Replat three lots 1-54 was se	e handicap ramps v	vere installed was	re-seeded (4/2009)	; Sediment basir	,	
Comments:						

The rain event of .65" received on 10/13/12 was composed of multiple rain events throughout the day, therefore a rain inspection was not conducted on 10/14/12 for this rain event.
Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.

				-	r
Unimus Name	Toma	Leasting	Projected	Chatria	Maintananaa
Unique Name	Туре	Location	Install Date	Status	Maintenance
		N41d00m00s			
CE A	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance Paved	•			•
		Ale			
CW	Concrete Washout Pit	Along 164th Street		Removed	
Current Condition:	Concrete washout was remo		tion on 7/12/11 k		stone Production
		Along 165th			
CW 1	Concrete Washout Pit	Along 165th Street		Removed	
Current Condition:	Concrete washout was remo		ction on 10/8/12 b		
				,	
Lot 51	Silt Fence	Lot 51		Removed	
Current Condition:	Silt fence check on the vaca	int lot was removed	d prior to inspecti	on on 10/30/12 b	y Nic w/ The Home
	company.,				
Lot EE	Miss/Other	Lot EE		Domourad	
Lot 55 Current Condition:	Misc/Other Maintenance was completed	Lot 55	on 10/8/12 by (Removed	e
Current Condition.	Maintenance was completed		1011 10/0/12 by C	maneston nome	5.
Lot 309	Silt Fence	Lot 309		Removed	
Current Condition:	Silt fence check on the corn			irt piled in the R.	O.W. was removed
	prior to inspection on 10/30/	12 by Legacy Hom	e.		
		l l l l l l l l l l l l l l l l l l l			
Lot 310	Silt Fence	Lot 310		Removed	
Current Condition:	Lot was sodded prior to insp	Dection on 8/27/12	by NIC W/ The Ho	me Company.	
Lots 27 Replat 3	Silt Fence	Lots 27 Replat 3		Active	Yes
Current Condition:	Good Condition- Silt fence is	s installed on the E	ast side of the lo	t.	
	There is some construction	dobric on the lot fre	m when let 2 ag	roce the street w	as coddod opd it
	needs to be cleaned up.		om when lot 2 act	oss the street wa	
	house to be clounded up.				
	Lucas w/ Legacy Homes wa	is informed to com	olete maintenanc	e by 10/15/12. O	n 10/30/12 Legacy
	Homes was reminded that n	naintenance needs	to be completed	ASAP.	
POD B	Silt Fence	Lots 63-73		Removed	
Current Condition:	Silt fence is no longer neede		s being sodded i		inspection on 6/3/10
	by Chris w/ Hearthstone Pro		5		
POD C	Silt Fence	Lots 97-122		Removed	
Current Condition:	Silt fence is no longer neede		s being sodded i	n this pod prior to	inspection on 10/5/11
	by Jeff w/ Hearthstone Production.				
POD D	Silt Fence	Lots 123-162		Removed	

Current Condition:	Silt fence is no longer nee by Jeff w/ Hearthstone Pro		s being souded		
POD E	Silt Fence	Lots 163-199		Removed	
Current Condition:	Silt fence installed on the		emoved prior to		29/10 by Chris w/
	Hearthstone Production de	ue to the lot being so	dded. All the hor	mes in this pod h	ave been comple
POD F	Silt Fence	Lots 209-217	4/16/2011	Active	Yes
Current Condition:	Fair Condition-	LOIS 209-217	4/10/2011	Active	Tes
	Silt fence was installed on	the back of the lots 2	213 and 214 pric	or to inspection o	<mark>n 10/30/12 by Nic</mark>
	The Home Company.		Level and all the factor		
	The construction debris or prior to inspection on 10/3			e was replaced o	on the back of lot
			ome company.		
	1) One area of silt fence o			ed and it needs to	o be replaced. Th
	a portable toilet on lot 214 2) There is dirt piled in the			1E and they need	d to be remained a
	silt fence around them.	R.O.W. 011015 212,	213, 214 and 2	15 and they need	
	1) Nic w/ The Home Comp				
	2) Nic w/ The Home Comp	pany was informed to	complete maint	enance by 11/6/	12.
POD E	Silt Fence	Lots 51-56 along Meridian Street		Removed	
Current Condition:	This silt fence is being mo	ved to there on lot le	vel BMP as of 9	/14/12.	1
		N41d00m00s			
SB E	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Basin was removed due to	o lot development prie	or to inspection	on 6/12/08 by De	ouble D Excavati
		N41d00m00s			
SB F	Sediment Basin	W96d00m00s		Removed	
Current Condition:	As of inspection on 5/12/1		filled in by Dou		
		N41d00m00s			
SB G	Sediment Basin	W96d00m00s	08/26/05	Active	No
Current Condition:	Good Condition- 15% Fille		o increation on	10/12/10 by Dab	Dath
	Partially Cleaned out and		o inspection on	10/12/10 by Bob	Roth.
	Silt Fanas	N41d00m00s	07/10/05	Demoved	
SF A Current Condition:	Silt Fence Removed	W96d00m00s	07/19/05	Removed	
		N41d00m00s			
SF B	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed - Not needed du	-	etative cover in	area.	
05.0	0111 5	N41d00m00s		Description	
SF C Current Condition:	Silt Fence Removed - Not needed du	W96d00m00s	etative cover in	Removed	
current condition.	Tremoved Not needed de	ie to catabilatica veg			T
SE 1	Silt Econo	Meridian Park Replat 3 Lot 1	5/4/2010	Activo	No
Current Condition:	Silt Fence Good Condition- Silt fence		5/4/2010 outheast corner	Active of the lot.	No
	Maintenance was complet				ne.
		Meridian Park			
_		Replat 3 Lots 26,			
SF 2	Silt Fence	27	5/4/2010	Active	No
Current Condition:	Good Condition- Silt fence	s installed on the S	oumeast corner		
		Meridian Park			
05.0	0:4 5	Replat 3 Lots 46,	E/4/0010	A	K 1.
SF 3 Current Condition:	Silt Fence Good Condition- Silt fence	47 e is installed on the S	5/4/2010 outheast corner	Active of the lot.	No
Sarrent Sondition.	Maintenance was complet				ne.
		N41d00m00s	,		
ST A	Silt Trap	W96d00m00s		Removed	
Current Condition:	Trap Closed June 2006.				
		N41d00m00s			
ST B	Sediment Trap	W96d00m00s		Removed	
Current Condition:	Sediment trap was remove	ea prior to inspection	on 10/5/11 due	to re-grading of I	ine area by Doub
		N41d00m00s		-	
ST C	Sediment Trap	W96d00m00s		Removed	

ST D	Sediment Trap	N41d00m00s W96d00m00s		Removed		
Current Condition:	Sediment trap was remov	ed prior to inspection	on 10/5/11 due	to re-grading of th	e area by Double	
		North of Replat				
		three Lots 1 and				
ST 1	Sediment Trap	2	10/5/2011	Active	No	
Current Condition:	Good Condition- 20% Filled Sediment trap was installed prior to inspection on 10/5/11 by Double D.					
		Southeast corner				
		of Replat three				
ST 2 Current Condition:	Sediment Trap Good Condition- 30% Fill	lot 1	10/5/2011	Active	No	
Current Condition:	Sediment trap was installe		on 10/5/11 by D	ouble D.		
		Northeast corner				
		of Replat three				
ST 3	Sediment Trap	lot 26		Removed		
Current Condition:	This trap was installed pri					
	construction taking place built out.	in the area. The trap	will need to be r	einstalled prior to	Replat 3 Lot 26 b	
		Between Replat				
		three Lots 26 and				
ST 4	Sediment Trap	27	10/5/2011	Active	No	
Current Condition:	Good Condition- 9% Filled					
	Sediment trap was installe	ed prior to inspection	on 10/5/11 by D	ouble D.		
		Southeast corner				
0T 5		of Replat three		Descent		
ST 5 Current Condition:	Sediment Trap This trap was installed pri	lot 27	e has been filler	Removed	sower and street	
Current Condition.	construction taking place built out.					
		Northeast corner				
		of Doplet three				
		of Replat three				
ST 6	Sediment Trap	lot 46	a haa haan filla	Removed	awar and atract	
ST 6 Current Condition:	This trap was installed pri	lot 46 or to 10/5/11, but sind		I in by the storm s		
		lot 46 or to 10/5/11, but sind		I in by the storm s		
Current Condition:	This trap was installed pri construction taking place built out.	lot 46 or to 10/5/11, but sind in the area. The trap N41d14m44s	will need to be r	d in by the storm s einstalled prior to	Replat 3 Lot 46 b	
Current Condition:	This trap was installed pri construction taking place built out. Streets	lot 46 or to 10/5/11, but sind in the area. The trap		I in by the storm s		
Current Condition:	This trap was installed pri construction taking place built out.	lot 46 or to 10/5/11, but sind in the area. The trap N41d14m44s	will need to be r	d in by the storm s einstalled prior to	Replat 3 Lot 46 b	
Current Condition:	This trap was installed pri construction taking place built out. Streets	N41d14m44s	will need to be n 8/10/2007	d in by the storm s einstalled prior to Active	Replat 3 Lot 46 b	
Current Condition:	This trap was installed pri construction taking place is built out. Streets Good Condition- Minor signs of run off by lo	Iot 46 or to 10/5/11, but sind in the area. The trap N41d14m44s W96d12m59s void 12m59s ots 13 and 14 and it not sind	will need to be n 8/10/2007 eeds to be clear	d in by the storm s einstalled prior to Active	Replat 3 Lot 46 b	
Current Condition:	This trap was installed pri construction taking place i built out. Streets Good Condition-	Iot 48 or to 10/5/11, but sind in the area. The trap N41d14m44s W96d12m59s ots 13 and 14 and it n ny was informed to compare to c	will need to be n 8/10/2007 eeds to be clear omplete maintena	d in by the storm s einstalled prior to Active	Replat 3 Lot 46 b	
Current Condition: STR Current Condition:	This trap was installed pri construction taking place is built out. Streets Good Condition- Minor signs of run off by lo Nic w/ The Home Compar prior to inspection on 10/8	Iot 48 or to 10/5/11, but sind in the area. The trap N41d14m44s W96d12m59s void 12m59s ots 13 and 14 and it no ny was informed to coo /12 by Nic w/ The Ho	8/10/2007 8/10/2007 eeds to be clear omplete maintena me Company.	t in by the storm s einstalled prior to Active ed up. ance by 9/14/12. \$	Replat 3 Lot 46 b	
Current Condition: STR Current Condition: SWPPP Sign	This trap was installed pri construction taking place is built out. Streets Good Condition- Minor signs of run off by lo Nic w/ The Home Compar prior to inspection on 10/8 SWPPP Sign	Iot 48 or to 10/5/11, but sind in the area. The trap N41d14m44s W96d12m59s ots 13 and 14 and it n ny was informed to compare to c	will need to be n 8/10/2007 eeds to be clear omplete maintena	d in by the storm s einstalled prior to Active	Replat 3 Lot 46 b	
Current Condition: STR Current Condition:	This trap was installed pri construction taking place is built out. Streets Good Condition- Minor signs of run off by lo Nic w/ The Home Compar prior to inspection on 10/8	N41d14m44s W96d12m59s N41d14m44s W96d12m59s N41d14m44s W96d12m59s Nots 13 and 14 and it n Ny was informed to co V12 by Nic w/ The Ho Two signs on site	will need to be n 8/10/2007 eeds to be clear omplete maintena me Company. 3/28/2008	Active	Replat 3 Lot 46 b Yes Street was cleaned No	