E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dent Manager Engineering Answers

E&A - P2021.321.000 Inspector: Shaun McGuire Stage Morgan Ridge 1 CSW-202207264 Project Name: 7/15/2023 For Week Ending: Southwest corner of Kempten Creek Drive and 156th Street - Bennington, NE (Douglas 68007 Project Location: County) Grading: 5% 0% Sanitary Sewer: 0% Storm Sewer: 0% Paving: Seeding 0% Utilities: 0% 0% Overall Development: RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Time Week Sunday: 0.00' Monday 0.08 Tuesday 0.00' Wednesday 0.54 0.00" 7/13/2023 Overcast 85/67 9:05 AM Thursday Friday 0.27 Saturday 0.00' Complaints: **Construction Sequencing:** Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the la<u>st 14 days?</u> Grading the site (4/20/23). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading the site (4/20/23). ermanent stabilization measures listed in this section are being implemented? What temporary or p Existing vegetation (4/20/23). Checklist Questions vre receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes **Corrective Action?** N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion Yes N/A Are wa Yes N/A re c Yes N/A s dus Yes Creat N/A rective Actio Comments Comments: The site was active during the most recent inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): Some maintenance is needed in the BMP

Unique Norre	Time	Looction	Projected Install Data	Stature	Meintene
Unique Name	Type	Location	Projected Install Date	Status	Maintenanc
CE 1	Construction Entrance	00-23	4/20/2023	Active	No /15/00 in an action
Current Condition:	Good Condition - 95% Effect				
D 1	Diversion	BB-4	6/29/2023	Active	No
Current Condition:	Good Condition - Ruff Grad				
D 2	Diversion	R-5 to Z-4	4/20/2023	Pending	Yes
Current Condition:	Pending -				
	Diversion should be installed per SWPPP. Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on				
	6/1/23, 7/14/23		1/00/0000		
D 3	Diversion	R-5 to S-4	4/20/2023	Pending	Yes
Current Condition:	Pending - Diversion should be installe Ruff Grading was informed 6/1/23, 7/14/23		Not done as of the last in	spection. Ruff Gra	ding was reminded
D 4	Diversion	I-9 to R-3	4/20/2023	Pending	Yes
Current Condition:	Pending -			i oriding	
	Diversion should be installe Ruff Grading was informed 6/1/23, 7/14/23		Not done as of the last in	spection. Ruff Gra	ding was reminded
D 5	Diversion	I-8 to E-8	7/13/2023	Active	No
Current Condition:	Good Condition - Ruff Gra	ding installed the div	ersion prior to the 7/13/2	3 inspection.	
D 6	Diversion	C-8 to D-8	7/13/2023	Active	No
Current Condition:	Good Condition - Ruff Gra				
D 7	Diversion	BB-11 to BB-12	4/20/2023	Pending	No
Current Condition:	Pending - BMP will be insta				
D 8	Diversion	BB-18 to BB-20	4/20/2023	Pending	No
Current Condition:	Pending - BMP will be insta			-	tor.
D 9	Diversion	NN-23	4/20/2023	Pending	No
Current Condition:	Pending - BMP will be insta	lled when grading begin	ns/ends in the area. E&A i	nspector will monit	tor.
D 10	Diversion	AA-33	4/20/2023	Pending	No
Current Condition:	Pending - BMP will be insta			U	
D 11	Diversion	G-13 to H-13	4/20/2023	Pending	Yes
Current Condition:	Diversion Pending -	0-1310 11-13	4/20/2023	renaing	res
	Diversion should be installe	d per SWPPP.			
D 12 Current Condition:	Ruff Grading was informed 7/14/23. Diversion	to complete by 6/8/23. K-14 to H-14	Not done as of last inspec 4/20/2023	tion. Ruff Grading Pending	<mark>y was reminded on</mark> Yes
Current Condition: EM 1	7/14/23. Diversion Pending - Diversion should be installe Ruff Grading was informed 7/14/23. Erosion Matting	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023	Pending tion. Ruff Grading Pending	Yes ywas reminded on No
Current Condition:	7/14/23. Diversion Pending - Diversion should be installe Ruff Grading was informed 7/14/23.	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023	Pending tion. Ruff Grading Pending	Yes y was reminded on No
Current Condition: EM 1	7/14/23. Diversion Pending - Diversion should be installe Ruff Grading was informed 7/14/23. Erosion Matting	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023	Pending tion. Ruff Grading Pending	Yes y was reminded on No
Current Condition: EM 1 Current Condition:	7/14/23. Diversion Pending - Diversion should be installe Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending	ywas reminded on No No
EM 1 Current Condition: EM 2 Current Condition:	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor.	yes was reminded on No No
EM 1 Current Condition: EM 2 Current Condition: EM 3	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending	y was reminded on No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be installed	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp ends in the area. E&A insp	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor.	y was reminded on No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 3 Current Condition: EM 4	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending	ywas reminded on No No No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition:	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor.	Yes was reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: EM 4 Current Condition: ET 1	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending pector will monitor.	y was reminded on No No No No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition:	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending pector will monitor.	y was reminded on No No No No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: EM 4 Current Condition: ET 1	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending pector will monitor.	y was reminded on No No No No No No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition:	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monit	yes ywas reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be installed Erosion Control Terrace Pending - BMP will be installed Erosion Control Terrace Pending - BMP will be installed	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp	Pending tion. Ruff Grading Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor. Pending nspector will monitor.	yes yes reminded on No No No tor. No tor.
Current Condition: EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 2	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 is/ends in the area. E&A insp 4/20/2023 is/ends in the area. E&A in 4/20/2023 is/ends in the area. E&A in 4/20/2023	Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending	yes ywas reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ins/ends in the area. E&A in 4/20/2023 ins/ends in the area. E&A in 4/20/2023 ins/ends in the area. E&A in 4/20/2023 ins/ends in the area. E&A in 4/20/2023	Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor.	Yes yes was reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition:	7/14/23. Diversion Pending - Diversion should be installer Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor.	Yes Yes was reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i	Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor. Pending nspector will monitor.	Yes Yes was reminded on No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - B	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A i 4/20/2023 is/ends in the area. E&A i	Pending Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor.	yes was reminded on No No No No No tor. No tor. No tor. No tor. No tor. No tor. No
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	7/14/23. Diversion Pending - Diversion should be installed Ruff Grading was informed 7/14/23. Erosion Matting Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta Erosion Control Terrace Pending - BMP will be insta	K-14 to H-14 d per SWPPP. to complete by 6/8/23. See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when work begins/ See SWPPP lled when grading begin See SWPPP	4/20/2023 Not done as of last inspec 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A i 4/20/2023 is/ends in the area. E&A i	Pending Pending Pending Pending pector will monitor. Pending pector will monitor. Pending pector will monitor. Pending nspector will monitor.	yes was reminded on No No No No No tor. No tor. No tor. No tor. No tor. No

		Understand and some dies a lange of				
Current Condition: ET 7	Pending - BMP will be insta Erosion Control Terrace	See SWPPP	4/20/2023	Pending	tor. No	
Current Condition:	Pending - BMP will be insta					
ET 8	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begin	ns/ends in the area. E&A i			
FT 1	Fuel Tank	On site	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing brought a fuel tank	on site and installed a ber	m around it prior to	the 5/4/23 inspection	
PB 1	Portable toilet	On site	5/4/2023	Pending	No	
Current Condition:	Good Condition - Ruff Grad	ing installed and secure	ed a portable toilet on site	prior to the 5/4/23	inspection.	
SB A	Sediment Basin	AA-4	4/20/2023	Pending	Yes	
Current Condition:	Pending - Ruff Grading beg	an shaping the basin p	rior to the 6/8/23 inspectio	n.		
	Basin should be installed p Ruff Grading was informed 6/1/23, 7/14/23		Not done as of the last ir	nspection. Ruff Gra	iding was reminded o	
SB B	Sediment Basin	R-4	4/20/2023	Pending	Yes	
Current Condition:	Pending - Ruff Grading beg				100	
	Basin should be installed pe Ruff Grading was informed 6/1/23, 7/14/23		Not done as of the last in	nspection. Ruff Gra	ding was reminded o	
SB C			4/20/2023	Donding	Yes	
Current Condition:	Sediment Basin Pending - Ruff Grading beg	D-8		Pending	res	
	Basin should be installed per Ruff Grading was informed 6/1/23, 7/14/23	to complete by 5/25/23				
SB D	Sediment Basin	HH-32 to NN-29	4/20/2023	Pending	No	
Current Condition:	Pending -	Marta D	1/00/0000			
SF 1 Current Condition:	Silt Fence Fair Condition - Ruff Gradir	Western Perimeter	4/20/2023	Active	Yes	
SF 2 Current Condition:	Silt Fence Fair Condition - Ruff Gradir	Southeastern Perimeter	5/4/2023	Active	Yes	
	1.) Silt fence should be re 2.) Silt fence should be cl 1.) Ruff Grading was infor 2.) Ruff Grading was infor	eaned out. med to complete by 7	/20/23.			
		Southeastern	5/4/2023			
SF 3	Silt Fence	Perimeter		Active	Yes	
Current Condition:	Fair Condition - Ruff Gradir Silt fence should be clean Ruff Grading was informe Silt Fence	ed out.		Active	Yes	
Current Condition:					165	
	Fair Condition - Ruff Grading installed the silt fence prior to the 5/4/23 inspection. Silt fence should be cleaned out.					
	Ruff Grading was informe	Northeastern	23. 5/4/2023			
SF 5	Silt Fence	Perimeter		Active	No	
Current Condition:	Good Condition - Ruff Grad					
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No	
Current Condition: SF 7	Pending - BMP will be insta	Northeastern Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta		ns/ends in the area. E&A i			
ST A	Sediment Trap	H-13	4/20/2023	Pending	Yes	
Current Condition:	Pending -					
	Sediment trap should be ins	stalled per SWPPP.				

MS 1	Material Storage	On Site	4/20/2023	Pending	No			
Current Condition:	Pending -							
WO 1	Concrete Washout	On Site	4/20/2023	Pending	No			
Current Condition:	Pending -							
WS 1	Waste Storage	On Site	4/20/2023	Pending	No			
Current Condition:	Pending -							
STR	Streets	N 156th Street	4/20/2023	Active	No			
Current Condition:	Good Condition - The streets were free of track out as of the 4/20/23 inspection.							
SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Active	No			
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the 5/11/23 inspection.							
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."							
Inspector Signature:	Sm Magin			Reviewed By:	Cato Sul			