E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

The site was active during the most recent inspection.



Zachary A. Jilek, CPESC, CISI			Engineering Answers					
Environmental Services Dent	Manager	E&A - P2021.3		-				
Inspector: Shaun McGuire					Stage			
		Morgan Ridge						
		CSW-202207264						
Project Name:								
For Week Ending:		9/9/2023						
Basicat Lagretian	Southwest corner of K	Southwest corner of Kempten Creek Drive and 156th Street - Bennington, NE (Douglas County)						
Project Location:		Cou	inty)					
Grading:	75	10/6		T				
Sanitary Sewer:		%						
Storm Sewer:		1%						
Paving:		1%						
Seeding:	0	1%						
Utilities:	0	%						
Overall Development:	5	<mark>%</mark>						
DAIN FALL AMOUNTS		In	har it o its	T				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Wook			
Sunday:	0.00"				Week			
Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.00" 0.04"	9/7/2023	Darthy Claudy 90/FC	9:35 AM				
Thursday Friday	0.04	9///2023	Partly Cloudy 80/56	9:35 AW				
Saturday	0.00"							
•	<u> </u>		<u> </u>	•				
Complaints:								
•								
Construction Sequencing:								
Which portion(s) (i.e. drainage	e basins) of the site have had	a temporary or perm	anent cessation of grading	g, earthwork, or gr	ound disturbance in the			
last 14 days?								
Grading the site (4/20/23).	- basing a state of the state of the		d	ale and a late of the state of				
Which portion(s) (i.e. drainage	e basins) of the site do not ha	ve grading, earthwor	k, or ground disturbance s	scheduled in the n	ext 14 days?			
Grading the site (4/20/23). What temporary or permanent	t stabilization magazzas listad	Lin this section are h	oing implemented?					
Existing vegetation (4/20/23). N								
Existing Vegetation (4/20/23): 14	orthwestern area seeded (1721).	20). Godinem area se	Caca (0/11/25).					
Checklist Questions:								
Are receiving waters adjacent to the p	project free of any significant signs of	erosion or sediment that v	vould be associated with the cons	truction activity?				
Yes								
Create Corrective Action? N/A								
Have disturbed areas been seeded or	otherwise stabilized as required? List	inactive portions of the p	roject and if stabilization measure	are adequate or neede	d to prevent erosion.			
Yes Create Corrective Action?								
N/A								
Are waste materials (concrete, constr Yes	uction material, hazardous, etc.) being	managed properly?						
Create Corrective Action?								
N/A								
A		-h-0						
Are construction entrances and adjaction No.	ent streets being maintained adequate	ay:						
Create Corrective Action?								
No, See BMP section.								
Is dust associated with the construction activity adequately controlled on the site?								
Yes								
Create Corrective Action?								
N/A								
Comments								
Comments:								
Comments:								

Unique Name	Tymo	Location	Projected Install Date	Status	Maintenance	
Unique Name CE 1	Type Construction Entrance	00-23	Projected Install Date 4/20/2023	Active	No	
Current Condition:						
	Good Condition - 90% Effective - Ruff Grading installed the construction entrance prior to the 6/15/23 inspection. Ruff Grading added more rock to the construction entrance prior to the 8/17/23 inspection.					
				•		
D 1	Diversion	BB-4	6/29/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi	on prior to the 6/29/23 ins	pection.	•	
D 2	Diversion	R-5 to Z-4	7/27/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi	on prior to the 7/27/23 ins	pection.		
D 3	Diversion	R-5 to S-4	4/20/2023	Pending	Yes	
Current Condition:	Pending -					
	S	I OIMBBB				
	Diversion should be installe	d per SWPPP.				
	Ruff Grading was informed	to complete by E/2E/22	Not done so of the lest in	opposion Buff Cra	ding was reminded on	
	6/1/23, 7/14/23, 8/4/23, 8/10		. Not done as of the fast if	ispection. Rull Gra	ading was reminded on	
D 4	Diversion	I-9 to R-3	8/10/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				140	
D 5	Diversion	I-8 to E-8	7/13/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				140	
D 6	Diversion	C-8 to D-8	7/13/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				I INU	
D 7	Diversion	BB-11 to BB-12	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
D 8	Diversion	BB-18 to BB-20	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
D 9	Diversion	NN-23	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
D 10	Diversion	AA-33	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
D 11	Diversion	G-13 to H-13	8/3/2023	Active	No No	
Current Condition:	Good Condition - Ruff Grad				140	
D 12	Diversion	K-14 to H-14	8/3/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				140	
EM 1	Erosion Matting	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
EM 2	Erosion Matting	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
EM 3	Erosion Matting	See SWPPP	8/10/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				_	
EM 4	Erosion Matting	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
ET 1	Erosion Control Terrace	See SWPPP	4/20/2023	Pendina	No	
Current Condition:	Pending - BMP will be insta				_	
ET 2	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta				_	
ET 3	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
ET 4		See SWPPP	4/20/2023	r ·		
Current Condition:	Pending - BMP will be insta			Pending nspector will monit	l No tor	
ET 5	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
ET 6	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
ET 7	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
ET 8	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No No	
Current Condition:	Pending - BMP will be insta					
FT 1	Fuel Tank	On site		Removed		
Current Condition:	Removed - Ruff Grading rer		or to the 8/31/23 inspection		<u>I</u>	
PB 1	Portable toilet	On site	2. 12 1.10 5/5 1/20 mopoono	Removed		
Current Condition:	Removed - Ruff Grading re		coilet prior to the 9/7/23 i			
SB A	Sediment Basin	AA-4	4/20/2023	Pending	Yes	
Current Condition:		<u> </u>			163	
Guiterit Gorialion.	Pending - Ruff Grading began shaping the basin prior to the 6/8/23 inspection.					
	Basin should be installed per SWPPP.					
	Ruff Grading was informed	to complete by 5/25/23	. Not done as of the last in	spection. Ruff Gra	nding was reminded on	
	6/1/23, 7/14/23, 8/4/23, 8/10	the state of the s				
SB B	Sediment Basin	R-4	4/20/2023	Pending	Yes	

Current Condition:	Ponding Puff Grading bog	on chaning the bacin n	rior to the 6/9/22 increation	n		
Current Condition.	Pending - Ruff Grading began shaping the basin prior to the 6/8/23 inspection. Basin should be installed per SWPPP.					
	Ruff Grading was informed 6/1/23, 7/14/23, 8/4/23, 8/10		. Not done as of the last in	spection. Ruff Gra	ding was reminded on	
SB C	Sediment Basin	D-8	4/20/2023	Pending	Yes	
Current Condition:	Pending - Ruff Grading beg				163	
Current Condition.	r ending - Itali Clading beg	an snaping the basin p	nor to the 0/23/23 mapeon	OII.		
	Basin should be installed pe	er SWPPP.				
	Ruff Grading was informed 6/1/23, 7/14/23, 8/4/23, 8/10	the state of the s	. Not done as of the last in	spection. Ruff Gra	ding was reminded on	
SB D	Sediment Basin	HH-32 to NN-29	4/20/2023	Pending	No	
Current Condition:	Pending - The basin will be		astructure development.		117	
SF 1	Silt Fence	Western Perimeter	4/20/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad					
Current Condition.						
	4/20/23 inspection. Ruff Gra	•	· ·	r to the 5/4/23 insp	ection. Rull Grading	
	maintained the silt fence pri		ction.	1		
		Southeastern	5/4/2023			
SF 2	Silt Fence	Perimeter		Active	No	
Current Condition:	Good Condition - Ruff Grad the silt fence prior to the 8/3	1/23 inspection.	of the silt fence prior to the	e 5/4/23 inspection	. Ruff Grading maintained	
07.5	0.14 =	Southeastern	5/4/2023		.,	
SF 3	Silt Fence	Perimeter		Active	No No	
Current Condition:	Good Condition - Ruff Grad	•	ce prior to the 5/4/23 inspe	ection. Ruff Gradir	ng maintained the silt fence	
	prior to the 8/31/23 inspection			,		
SF 4	Silt Fence	Eastern Perimeter	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the silt fen	ce prior to the 5/4/23 inspe	ection. Ruff Gradin	ng maintained the silt fence	
	prior to the 8/31/23 inspection	on.				
		Northeastern	5/4/0000			
SF 5	Silt Fence	Perimeter	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad		ce prior to the 5/4/23 inspe	ection. Ruff Gradin	g maintained the silt fence	
	prior to the 8/31/23 inspection inspection.	•			•	
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begin	ns/ends in the area. E&A i	nspector will monit	or.	
	Ŭ	Northeastern				
SF 7	Silt Fence	Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta		os/ands in the area. E&A i			
ST A	Sediment Trap	H-13	8/3/2023	Active	No	
Current Condition:	Good Condition - 3% Filled			prior to the 7/27/23	inspection. Ruff Grading	
	installed the sediment trap p	orior to the 8/3/23 inspe	ection.			
MS 1	Material Storage	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Materials will be s	stored in designated are	eas.			
WO 1	Concrete Washout	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Concrete will be p					
WS 1	Waste Storage	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Waste will be sto			1 oriding	140	
			4/20/2023	A otivo	Voc	
STR	Streets Fair Condition The atreate	N 156th Street		Active	Yes	
Current Condition:	Fair Condition - The streets 8/17/23 inspection.	were free of track out a	as of the 4/20/23 Inspection	n. Streets were pa	rtially cleaned prior to the	
	Streets should be cleaned.					
	Ruff Grading was informed	to complete by 8/11/22	Not done as of last inche	ection		
SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Active	No	
					INO	
Current Condition:	Good Condition - E&A inspe					
Certification Statement:	"I certify, under penalty of la	'		,		
	direction or supervision in a	•	•			
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information,					
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I					
	am aware that there are sig	nificant penalties for su	bmitting false information	including the poss	ibility	
	of fines and imprisonment for	or knowing violations."				
			-			
	Show May ni				But Sul	
Inspector Signature:				Reviewed By:	000	