E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



		E & A CONSULTING GROUP, INC.						
Zachary A. Jilek, CPESC, CISE	Engineering Answers							
Environmental Services Dent	Manager	E&A - P2021.32	1.000					
Inspector: Shaun McGuire		LUA I ZUZII.UZ	1.000		Stage			
mapeotor: Ondan medane		Morgan Pidgo						
		Morgan Ridge						
Project Name:		CSW-202207264						
For Week Ending:		9/16/2023						
. ccg.	Southwest corner of Kemp			aton, NE (Douglas				
Project Location:		68007						
		Count	··					
Grading:	95%							
Sanitary Sewer:	0%							
Storm Sewer:	0%							
Paving:	0%							
Seeding:	0%							
Utilities:	0%							
Overall Development:	5%							
•			•					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week			
Sunday:	0.14"							
Monday	0.01"							
Tuesday	0.00"							
Wednesday	0.00"	0/4.4/2022	C.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	44.0F AM				
Thursday Friday	0.00" 0.01"	9/14/2023	Sunny 82/61	11:05 AM				
Saturday	0.01"							
- Caran any	10.02							
Complaints:								
Construction Sequencing:	haring a state of the base had a se							
	basins) of the site have had a te	imporary or permar	ient cessation of gradin	g, earthwork, or grou	ind disturbance in the			
last 14 days? Grading the site (4/20/23).								
	basins) of the site do not have g	rading parthwork	or ground disturbance	scheduled in the nev	t 14 days?			
Grading the site (4/20/23).	basins) of the site do not have t	grading, cartimork,	or ground disturbance	Scricultural III the nex	t 14 days:			
_ ,	stabilization massures listed in	this soction are hei	na implemented?					
	stabilization measures listed in orthwestern area seeded (7/27/23).							
Existing vegetation (4/20/23). No	orthwestern area seeded (7/27/23).	Southern area seed	eu (6/17/23).					
Checklist Questions:								
	oject free of any significant signs of eros	ion or sediment that wou	ld be associated with the con-	struction activity?				
Yes	ojout noo or any organicant organic or or or	ion or obtainion that not	na po accordatoa martino con	on action activity :				
Create Corrective Action?								
N/A								
Have disturbed areas been seeded or o	otherwise stabilized as required? List inac	ctive portions of the proje	act and if etabilization measure	a are adequate or needed t	o prevent erosion			
Yes	viterwise stabilized as required. Elst mac	save portions of the proje	ot and it Stabilization measure	are adequate or necueur	o prevent crosion.			
Create Corrective Action?								
N/A								
	ction material, hazardous, etc.) being ma	naged properly?						
Yes Create Corrective Action?								
N/A								
	nt streets being maintained adequately?							
No								
No. See BMP section.								
ito, occidin occidii.								
Is dust associated with the construction	n activity adequately controlled on the sit	te?						
Yes				-				
Create Corrective Action?								
N/A								

Comments:

The site was active during the most recent inspection.

		l					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	OO-23	4/20/2023	Active	No No		
Current Condition:	Good Condition - 90% Effective - Ruff Grading installed the construction entrance prior to the 6/15/23 inspection. Ruff Grading added more rock to the construction entrance prior to the 8/17/23 inspection.						
	Grading added more rock to	ine construction entra	ince prior to the 6/17/23 in	spection.			
D.1	Diversity of	DD 4	0/20/2022	A -45	NI-		
D 1	Diversion	BB-4	6/29/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad				<b>.</b>		
D 2	Diversion	R-5 to Z-4	7/27/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad						
D 3	Diversion	R-5 to S-4	4/20/2023	Pending	Yes		
Current Condition:	Pending -						
	Diversion should be installe	d nor CWDDD					
	Diversion should be installe	a per Swiff.					
	Ruff Grading was informed	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on					
	6/1/23, 7/14/23, 8/4/23, 8/10		. That do no do or and labe a	opodiom rtan Gro	iamig mas rominasa sin		
D 4	Diversion	I-9 to R-3	8/10/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad				110		
D 5	Diversion	I-8 to E-8	7/13/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad				140		
D 6	Diversion	C-8 to D-8	7/13/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad				INO		
D 7	Diversion	BB-11 to BB-12	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
D 8	Diversion	BB-18 to BB-20	4/20/2023	Pending	No No		
Current Condition:	Pending - BMP will be insta						
D 9	Diversion	NN-23	4/20/2023	Pending	No No		
Current Condition:	Pending - BMP will be insta	_					
D 10	Diversion	AA-33	9/14/2023	Active	No		
Current Condition:	Good Condition - Ruff Gra				INO		
D 11	Diversion	G-13 to H-13	8/3/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad				INU		
D 12		K-14 to H-14	8/3/2023		No		
Current Condition:	Diversion Good Condition - Ruff Grad			Active	No		
EM 1		See SWPPP	4/20/2023		No		
Current Condition:	Erosion Matting Pending - BMP will be insta			Pending	No		
EM 2		See SWPPP	4/20/2023				
Current Condition:	Erosion Matting Pending - BMP will be insta			Pending	No		
EM 3		See SWPPP	8/10/2023		No		
Current Condition:	Erosion Matting Good Condition - Ruff Grad			Active			
		See SWPPP					
EM 4	Erosion Matting Pending - BMP will be insta		4/20/2023	Pending	No		
Current Condition:							
ET 1	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
ET 2	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
ET 3	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
ET 4	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
ET 5	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta			nspector will monit	tor.		
ET 6	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta			nspector will monit	tor.		
ET 7	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta			nspector will moni	tor.		
ET 8	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta	lled when grading begi	ns/ends in the area. E&A i	nspector will monit	tor.		
FT 1	Fuel Tank	On site		Removed			
Current Condition:	Removed - Ruff Grading rer	moved the fuel tank pri	or to the 8/31/23 inspectio	n.			
PB 1	Portable toilet	On site		Removed			
Current Condition:	Removed - Ruff Grading rer		et prior to the 9/7/23 inspe				
SB A	Sediment Basin	AA-4	4/20/2023	Pending	Yes		
Current Condition:	Pending - Ruff Grading beg	<u> </u>	<u> </u>				
	<u> </u>	The state of the s					
	Basin should be installed per SWPPP.						
	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on						
	6/1/23, 7/14/23, 8/4/23, 8/10	0/23					
SB B	Sediment Basin	R-4	4/20/2023	Pending	Yes		

Current Condition:	Current Condition: Pending - Ruff Grading began shaping the basin prior to the 6/8/23 inspection.					
	Pasin should be installed by	or SWIDDD				
	Basin should be installed per SWPPP.					
	Ruff Grading was informed 6/1/23, 7/14/23, 8/4/23, 8/10		Not done as of the last in	nspection. Ruff Gra	iding was reminded on	
SB C	Sediment Basin	D-8	4/20/2023	Pending	Yes	
Current Condition:	Pending - Ruff Grading beg	an shaping the basin p	ior to the 6/29/23 inspect	ion.		
	Basin should be installed po	er SWPPP.				
	Ruff Grading was informed 6/1/23, 7/14/23, 8/4/23, 8/10		Not done as of the last in	nspection. Ruff Gra	ding was reminded on	
SB D	Sediment Basin	HH-32 to NN-29	4/20/2023	Pending	No	
Current Condition:	Pending - The basin will be	installed as part of infra				
SF 1	Silt Fence	Western Perimeter	4/20/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad					
	4/20/23 inspection. Ruff Gramaintained the silt fence pri	or to the 8/31/23 inspec		or to the 5/4/23 insp	pection. Ruff Grading	
CE 2	Cill Famor	Southeastern	5/4/2023	A ativo	No	
SF 2 Current Condition:	Silt Fence	Perimeter	of the cilt fence prior to th	Active	No No Puff Crading maintained	
Current Condition:	Good Condition - Ruff Grad the silt fence prior to the 8/3		or the silt rence prior to th	e 5/4/23 inspection	i. Kun Grauing maintained	
SF 3	Silt Fence	Perimeter	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad		ce prior to the 5/4/23 insp			
	prior to the 8/31/23 inspecti	•				
SF 4	Silt Fence	Eastern Perimeter	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad prior to the 8/31/23 inspecti	on.	ce prior to the 5/4/23 insp	ection. Ruff Gradir	ng maintained the silt fence	
SF 5	Silt Fence	Northeastern Perimeter	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the silt fen	ce prior to the 5/4/23 insp	ection. Ruff Gradin	g maintained the silt fence	
	prior to the 8/31/23 inspecti inspection.	_		empten Creek Driv	e prior to the 8/31/23	
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta		is/ends in the area. E&A	inspector will monit	tor.	
05.7	Cit Faran	Northeastern Perimeter	4/20/2023	Daniella a	NI-	
SF 7 Current Condition:	Silt Fence Pending - BMP will be insta		s/ends in the area E&A	Pending	No No	
ST A	Sediment Trap	H-13	8/3/2023	Active	No No	
Current Condition:	Good Condition - 3% Filled					
MS 1	installed the sediment trap		ction.			
Current Condition:	Material Storage Pending - Materials will be		4/20/2023	Pending	No	
WO 1	Concrete Washout	On Site	eas. 4/20/2023	Pending	No	
Current Condition:	Pending - Concrete will be		1/20/2020	1 onding	110	
WS 1	Waste Storage	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Waste will be sto	red in proper containme	ent.		•	
STR	Streets	N 156th Street	4/20/2023	Active	Yes	
Current Condition:	Fair Condition - The streets were free of track out as of the 4/20/23 inspection. Streets were partially cleaned prior to the 8/17/23 inspection.					
	Streets should be cleaned.					
	Ruff Grading was informed	to complete by 8/11/23	Not done as of last inspe	ection.		
SWPPP Sign	SWPPP Notification Sign		5/11/2023	Active	No	
Current Condition:	Good Condition - E&A inspe	ector installed the SWP	PP sign during the 5/11/2	3 inspection.		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inchestor Signatura	Shan Nagin	3 1121121101		Povious d Pro-	Put Sul	
nspector Signature:	· ·	J		Reviewed By:		