10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Ma	allagei	E&A- P2003.	191 000			
Inspector: Matt Vanicek		EGA-1 2000.	101.000		Stage	
		ı	Newport Hill			
Project Name:			NER110499		3	
•			10/8/2016			
For Week Ending:	4004	b 04 d NE 111-b			00007	
Project Location:	1800	n St and NE Highwa	ay 36- Bennington NE (Dou	igias County)	68007	
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	36%	(L			l .	
RAIN FALL AMOUNTS	Amount in inches	Data inspected	Weather Conditions			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		Week 1	Date to complete inspection.
Sunday:	0.00"				Week I	11/04/16
Monday	0.06"	09/12/16	83/62 Tstorm			
Tuesday	0.29"					
Wednesday	0.01"					
Thursday	0.51"					
Friday	0.94"	00/4=//0	70/54 01			
Saturday	0.00"	09/17/16	79/54 Clear		Wook 2	
Sunday:	0.00"				Week 2	
Monday	0.00"	 				
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.12"					
Over days	0.548				Week 3	
Sunday: Monday	0.54" 0.00"					
Tuesday	0.00"	9/27/2016	77/48 Clear			
Wednesday	0.00"		111110			
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.00"				Week 4	
Sunday: Monday	0.00"					
Tuesday	0.33"					
Wednesday	0.00"					
Thursday	0.27"					
Friday	0.09"					
Saturday	0.00"					
Sunday	IN/A	N/A			Week 5	
Sunday: Monday	N/A N/A	N/A N/A				
Tuesday	N/A	N/A				
Wednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
	INI					
O a manufacture of	None					
Complaints:						
Construction Sequencing:	ļ	1	1	1	ı	
Which portion(s) (i.e. drainage basins) of	the site have had a tempora	ary or permanent cessation	on of grading, earthwork, or grou	nd disturbance in the last 1	4 days?	
Entire Site, grading was completed						
Which portion(s) (i.e. drainage basins) of	the site do not have grading	g, earthwork, or ground d	isturbance scheduled in the next	14 days? :	_	
Entire Site, grading was completed						
What temporary or permanent stabilization						
Seeded (6/2007), Re-seeded (9/20	007), Paving (9/2007), S	Seeded (4/2008), Sm	all drainage ditch behind lot	41 was seeded and ma	atted (4/21/15)	

SUMMARY QUESTIONS: Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? HECKLIST QUESTIONS: material, hazardous, etc.) being managed properly Yes omments Comments: Multiple houses are being built as of the last inspection. Findings / Corrective Actions (Date) Findings / Corrective Actions (Date) 1) Maintenance required in the BMP section. 2.) Lot 67 needs to be stablized where it was disturbed by construction on lot 66. Dreamscape Homes was informed to complete by 10/4/16. **Projected Install Date Unique Name** Type Location Status Maintenance South of Northern Dr. DS 1 Swale between SB 1 and 2 6/13/2007 Active No **Current Condition:** Good Condition West of 182nd Cir. DS 9 Swale towards SB 4 6/13/2007 Active No **Current Condition:** Good Condition East of Northern Dr. and 182nd Cir towards DS 12 Swale SB 5 6/13/2007 Active No Good Condition **Current Condition:** East of Star grass Rd DS 13 towards SB 6 6/13/2007 Active Swale **Current Condition:** Good Condition North of Star grass Rd DS 14 towards SB 6 6/13/2007 Active Swale Nο **Current Condition:** Good Condition Lot 1 replat 1 Silt Fence 11/26/2015 Lot 1 replat 1 Active Current Condition: The Home Company repaired the silt fence on the side of the lot prior to inspection on 7/7/16. air Condition 1.) The neighboring lot was silted in and needs to be cleaned up and reseeded. 2.) The rest of the lot needs to be stabilized. 3.) The silt fence on the side of the lot needs to be repaired. 1.) The Home Company was informed to complete by 5/9/16. Not done as of last inspection. The Home Company was reminded on 5/13/16, 7/6/16, 7/14/16, 8/26/16, 9/28/16 2.) The Home Company was informed to complete by 5/31/16. Not done as of last inspection. The Home Company was reminded on 7/6/16, 7/14/16, 8/26/16, 9/28/16 3.) The Home Company was informed to complete by 7/20/16. Not done as of last inspection. The Home company was reminded on 8/26/16, 9/28/16 Lot 6 Removed **Current Condition:** Removed - Barr Homes sodded the lot prior to the inspection on 4/21/16. Lot 9 Individual Lot Lot 9 Removed **Current Condition:** Removed - Homestead Custom Builders sodded the lot prior to inspection on 5/24/16. Lot 10 Individual Lot Lot 10 3/1/2016 Removed Current Condition: Removed - Charles Thomas Homes sodded the lot prior to inspection on 4/21/16. Individual Lot Lot 11 Removed **Current Condition:** Removed - Proline Custom Homes sodded the lot prior to inspection on 7/4/16. Individual Lot Lot 12 Removed **Current Condition:** Removed - Charleston Homes sodded the lot prior to inspection on 7/13/16. Individual Lot Lot 17 Removed Current Condition Removed - Ramm Construction sodded the lot prior to inspection on 7/4/16 Silt Fence Lot 18 Removed Lot 18 Removed - Empire Homes sodded the lot prior to inspection on 5/2/16 **Current Condition**: Lot 32 Silt Fence Lot 32 Removed **Current Condition:** Removed - Prairie Homes sodded the lot prior to the 2/23/16 inspection. Silt Fence Lot 35 10/4/2016 Pending Pending - The Home Company began construction on the lot prior to inspection on 9/27/16. **Current Condition:** 1.) Silt fence needs to be installed on the south and east sides of the lot. 2.) The dirt pile needs to be removed from the ROW 1.) The Home Company was informed to complete by 10/4/16. Individual Lot Lot 43 Lot 43 Removed **Current Condition** Removed - Goodlife Homes sodded the lot prior to inspection on 7/4/16. Removed Individual Lot Lot 44 **Current Condition**: Removed - Legendary Homes sodded the lot prior to inspection on 7/4/16. Silt Fence Lot 45 Lot 45 10/24/2015 Active Yes

			e dirt pile from the ROW pri	or to inspection on 7/18/1	б.			
	1.) The silt fence	on the back of the lot ne	eds to be repaired and silt f	ence needs to be installe	d on the fron			
	the lot. 2.) Sediment needs to be cleaned up from the two adjacent lots. 1.) Andrew Jizba was informed to complete by 7/20/16. Not done as of last inspection. Andrew Jizba was							
	reminded on 8/26		e by 7/20/16. Not done as o	of last inspection. Andrew	Jizba was			
Lot 46	Silt Fence	Lot 46	- h O/4/4 C - N - 1 - 1 4	Removed				
Current Condition:			r to inspection on 5/2/16.					
Lot 54	Individual Lot	Lot 54	7/4/2016	Active	No DMDIa			
Current Condition:			d construction on the lot pri E&A will continue to monito		. NO BIVIPS			
Lot 59	Individual Lot	Lot 59	7/4/2016	Active	No			
Current Condition:			e curb line in front of the		n 9/27/16. No			
1 -1 04			being flat. E&A will continu		N-			
Lot 61 Current Condition:	Individual Lot	Lot 61	5/9/2016 an construction on the lot p	Active	No 6 The dirt n			
Current Condition.			vn builder prior to inspection					
		egetative buffer strip arou						
Lot 62	Individual Lot	Lot 62		Removed				
Current Condition:			t prior to inspection on 8/25					
Lot 63	Silt Fence	Lot 63	7/4/2016	Active	No			
Current Condition:			d Menard Construction. No	BMP's are currently need	ded due to th			
	lot being flat. E&A	will continue to monitor						
Lot 64	Silt Fence	Lot 64		Removed				
Current Condition:		1	ne lot prior to inspection on					
Lot 66	Individual Lot	Lot 66		Removed				
Current Condition:	Removed - Drear	nscape Homes sodded	the lot prior to inspectio	n on 9/27/16.				
Lot 80 Current Condition:	Individual Lot	Lot 80	e 12/16/15 inspection by Pr	Removed				
			12/10/13 ilispection by Fi					
Lot 81 Current Condition:	Individual Lot	Lot 81	prior to inspection on 5/3/16	Removed				
Lot 89	Silt Fence	Lot 89	9/12/2016	Active	No			
Current Condition:		<u> </u>	installed silt fence on the					
	inspection on 9/2	12/16.						
Lot 90	Silt Fence	Lot 90		Removed				
Current Condition:	Removed - Landn	nark Homes sodded the South of Northern Dr.	ot prior to the 11/13/15 ins	pection.				
		on southwest corner of						
SB 1	Sediment Basin	site	04/06/07	Active	No			
Current Condition:	Good Condition-	45% Filled. The voluntee	er trees were removed from	the basin prior to the 3/2	0/15 inspect			
		L South of Northern Dr						
		South of Northern Dr. between 185th St and						
SB 2	Sediment Basin		4/9/2007	Active	No			
SB 2 Current Condition:		between 185th St and 184th St.						
		between 185th St and 184th St. 20% Filled. The volunter	4/9/2007 er trees were removed from					
		between 185th St and 184th St.						
		between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr.						
Current Condition:	Good Condition -2	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St.	er trees were removed from 04/06/07	the basin prior to the 3/2 Active	0/15 inspect			
Current Condition:	Good Condition -2	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunte	er trees were removed from	the basin prior to the 3/2 Active	0/15 inspect No			
Current Condition:	Good Condition -2	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr.	er trees were removed from 04/06/07	the basin prior to the 3/2 Active	0/15 inspect No			
Current Condition:	Good Condition -2	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunte	er trees were removed from 04/06/07	the basin prior to the 3/2 Active	0/15 inspect No			
SB 3 Current Condition:	Good Condition -: Sediment Basin Good Condition - Sediment Basin	between 185th St and 184th St. 20% Filled. The volunted South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunted South of Northern Dr. between 182th St and 184th St.	or trees were removed from 04/06/07 er trees were removed from	Active Active Active	0/15 inspect No 20/15 inspec			
SB 3 Current Condition: SB 4 Current Condition:	Good Condition -: Sediment Basin Good Condition Sediment Basin Good Condition -:	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from	Active Active Active Active Active Active the basin prior to the 3/2	0/15 inspect No 20/15 inspec No 0/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 4 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter 182th St and 184th St. 22% Filled. The volunter	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07	Active	0/15 inspect No 20/15 inspect No 0/15 inspect No			
SB 3 Current Condition: SB 4 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter 182th St and 184th St. 22% Filled. The volunter	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from	Active	0/15 inspect No 20/15 inspect No 0/15 inspect No			
SB 3 Current Condition: SB 4 Current Condition: SB 4 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St.	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07	Active	0/15 inspect No 20/15 inspect No 0/15 inspect No			
SB 3 Current Condition: SB 4 Current Condition: SB 4 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter 182th St and 184th St. 22% Filled. The volunter	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07	Active	0/15 inspect No 20/15 inspect No 0/15 inspect No			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter East of 182nd Cir. 22% Filled. The volunter Northeast of Star grass Rd.	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from	Active Active Active Active Active the basin prior to the 3/2 Active Active Active Active Active Active Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 20/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Star Grass Rd. Northeast of Star Grass Rd. 45% Filled - The SID cu	o4/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 et down volunteer trees prior	Active	No 20/15 inspect No 20/15 inspect No 0/15 inspect No 20/15 inspect No 20/15 inspec			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunted South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunted South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunted East of 182nd Cir. 22% Filled. The volunted Northeast of Star grass Rd. 45% Filled - The SID cur. North of Star grass Rd. East of 182nd St.	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 4/9/2007	Active	No 20/15 inspect No 0/15 inspec No 0/15 inspect No 0/15 inspect No 0/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St. 22% Filled. The volunter Dr. between 182th St. 22% Filled. The Volunter Dr. between 182th St. 22% Filled. The SID Cu. North of Star grass Rd. 45% Filled - The SID Cu. North of Star grass Rd. East of 182nd St. 40% Filled - The SID Cu.	o4/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 et down volunteer trees prior	Active	No 20/15 inspect No 0/15 inspec No 0/15 inspect No 0/15 inspect No 0/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South St and 182th St. 22% Filled. The volunter South St and 182th St. 22% Filled. The Volunter South St and 182th St. 22% Filled. The Volunter South St and 182th St. 22% Filled. The Volunter South St and 182th St. 22% Filled - The SID Cu North of Star grass Rd.	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 4/9/2007	Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St. 22% Filled. The volunter Dr. between 182th St. 22% Filled. The Volunter Dr. between 182th St. 22% Filled. The SID Cu. North of Star grass Rd. 45% Filled - The SID Cu. North of Star grass Rd. East of 182nd St. 40% Filled - The SID Cu.	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 4/9/2007	Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 7 Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Star Grass Rd. Northeast of Star Grass Rd. Star Grass Rd. Star Grass Rd. 45% Filled - The SID curborth of Star Grass Rd. Star Rd. Sta	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 down volunteer trees prior 4/9/2007 t down volunteer trees prior 4/20/2007	Active To the 2/23/16 inspection Active To the 2/23/16 inspection Active Active Active	No 20/15 inspect No No No No			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 7 Current Condition: SB 8 Current Condition: SB 8 Current Condition: STR	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 184th St. 22% Filled. The volunter Dr. between 182th St and 182nd Cir. 22% Filled. The SID Cur. North of Star grass Rd. 45% Filled - The SID Cur. North of Star grass Rd. Between 184th St and 182nd St. 45% Filled - The SID Cur. North of Star grass Rd. Between 184th St and 182nd St. 45% Filled - The SID Cur. Dr. SID Cur. Dr	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 down volunteer trees prior 4/20/2007 down volunteer trees prior 4/20/2007	Active Active Active The basin prior to the 3/2 Active Active Active Active Active Active To the 2/23/16 inspection Active Active To the 2/23/16 inspection Active Active Active Active To the 2/23/16 inspection Active Active	No 20/15 inspect No No No No			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Sediment Basin Good Condition -	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Star Grass Rd. Northeast of Star Grass Rd. East of 182nd St. 45% Filled - The SID cu North of Star grass Rd. East of 182nd St. 40% Filled - The SID cu North of Star grass Rd. Between 184th St and 182nd St. 45% Filled - The SID cu Entire Site Conceptual Homes clea	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 at down volunteer trees prior 4/20/2007 at down volunteer trees prior 1/20/2007 at down volunteer trees prior 1/20/2007 and the streets prior to inspect	Active To the 2/23/16 inspection Active Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 20/15 inspect No			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: SB 8 Current Condition: STR Current Condition: STR Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Signs	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Star Grass Rd. Northeast of Star Grass Rd. East of 182nd St. 45% Filled - The SID cu North of Star grass Rd. East of 182nd St. 40% Filled - The SID cu North of Star Grass Rd. East of 182nd St. 45% Filled - The SID cu Entire Site Conceptual Homes clea	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 down volunteer trees prior 4/9/2007 down volunteer trees prior 4/20/2007 down volunteer trees prior 3/20/2007 ned the streets prior to insp. 8/19/2008	Active Active Active The basin prior to the 3/2 Active Active Active Active Active Active To the 2/23/16 inspection Active Active To the 2/23/16 inspection Active Active Active Active To the 2/23/16 inspection Active Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect No 1. No 1.			
SB 3 Current Condition: SB 4 Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR Current Condition:	Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition -: Sediment Basin Good Condition - Signs	between 185th St and 184th St. 20% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 27% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Northern Dr. between 182th St and 184th St. 22% Filled. The volunter South of Star Grass Rd. Northeast of Star Grass Rd. East of 182nd St. 45% Filled - The SID cu North of Star grass Rd. East of 182nd St. 40% Filled - The SID cu North of Star grass Rd. Between 184th St and 182nd St. 45% Filled - The SID cu Entire Site Conceptual Homes clea	er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 04/06/07 er trees were removed from 4/9/2007 down volunteer trees prior 4/9/2007 down volunteer trees prior 4/20/2007 down volunteer trees prior 3/20/2007 ned the streets prior to insp. 8/19/2008	Active To the 2/23/16 inspection Active Active	No 20/15 inspect No 0/15 inspect No 0/15 inspect No 0/15 inspect No			