E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services Dept.	. Manager			Engineering A	II3WEI3
		E&A- P2003.1	91.000		
Inspector: Alex Brown					Stage
•		N	ewport Hill		
<b>.</b>			ER110499		3
Project Name:					
For Week Ending:		6/11/2022			
Project Location:	180th	St and NE Highway	36- Bennington NE (Dougla	as County)	68007
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	92%				
•			•	•	•
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.17"				
Wednesday	0.05"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.66"				
Wednesday:	0.64"				
Thursday:	0.10"				
Friday:	0.00"				
Saturday:	0.00"				
outui uuyi	0.00				Week
Sunday:	0.00"				
Monday	0.01"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				1
Saturday	0.04"				1
	VIV-1				Week
Sunday:	0.01"				Week
Monday	0.00"				+
Tuesday	0.00"	6/7/2022	Partly Cloudy 82/60	11:25 AM	1
Wednesday	0.22"	V. I. ZVZZ	. a.a., c.oaa, oz.oo	11124 71111	+
Thursday	0.06"				1
Friday	0.00"				+
Saturday	0.46"				+
- Catal day	0.70				Week
Sunday:	N/A				vveek
Monday	N/A				+
Tuesday	N/A N/A				+
	N/A N/A				+
Wednesday	IN/A		+		

N/A

Thursday

Friday	N/A		
Friday Saturday	N/A		
	None		
Complaints:			

## Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

## Entire Site, grading was completed on 6/11/07.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

## Entire Site, grading was completed on 6/11/07.

What temporary or permanent stabilization measures listed in this section are being implemented?

Seeded (6/2007), Re-seeded (9/2007), Paving (9/2007), Seeded (4/2008), Small drainage ditch behind lot 41 was seeded and matted (4/21/15) The sidewalk by the entrance was seeded and matted (3/7/18). OL B next to lot 74 was seeded (11/4/19). River rock rip rap was installed at the flared end on OL B (12/2/19).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

#### Nο

Create Corrective Action?

No, See BMPs and Findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

## Comments:

### Comments:

The site was inactive during the last inspection.

# Findings / Corrective Actions (Date):

# Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) Outlot D has been disturbed by homeowner of Lot 36 prior to inspection on 6/27/18. E&A will monitor. Some BMPs are in place and needing maintenance.
  - a. straw wattles along outlot need cleaned out
  - b. erosion rills need backfilled and seeded

Maintenance responsibility is currently being determined by SID department. E&A will monitor. Maintenance responsibility is still being determined as of last inspection. E&A inspector is awaiting SID department's update as of April 2020. Area is currently being litigated as of 3/2021. E&A will inspector will update when more information is known.

				,			
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		South of Northern Dr.					
DS 1	Swale	between SB 1 and 2		Removed			
Current Condition:	Removed - The div	Removed - The diversion was removed prior to inspection on 5/2/17.					
		West of 182nd Cir.					
DS 9	Swale	towards SB 4		Removed			
Current Condition:	Removed - The diversion was removed prior to inspection on 5/2/17.						

		Foot of Newtharm					
		East of Northern Dr. and 182nd Cir towards					
DS 12	Swale	SB 5		Removed			
Current Condition:			or to inspection on 5/2/17.	1101110100			
		East of Star grass Rd					
DS 13	Swale	towards SB 6		Removed			
Current Condition:	Removed - No div	ersion swale was observ	ed during the inspection on	12/8/17.	•		
		North of Star grass Rd					
DS 14	Swale	towards SB 6		Removed			
Current Condition:	Removed - No div	ersion swale was observ	ed during the inspection on	12/8/17.			
Lot 24	Silt Fence						
Current Condition:	Removed - Nilius	Builders sodded the lot p	prior to the inspection on 7/31	1/21.			
Lot 42	Individual Lot	Lot 42		Removed			
Current Condition:	Removed - D and 11/22/21.	D Leasing sodded the lo	ot and grass has grown to sta	bilization as of the insp	ection on		
Lot 84	Individual Lot	Lot 84		Removed			
Current Condition:			or to the inspection on 7/7/21		-		
		<u> </u>			1		
Lot 88	Individual Lot	Lot 88		Removed			
Current Condition:		<del> </del>	rior to inspection on 4/22/21.				
Outlot B	Silt Fence	Outlot B		Removed			
Current Condition:			were removed by the SID in t		020		
SF 1	Silt Fence	South of Lot 21		Removed			
Current Condition:	Removed - Woodl		silt fence prior to inspection	on 8/16/18.			
		South of Northern Dr.					
05.4	0 " (D :	on southwest corner of					
SB 1	Sediment Basin	site	0/05/40	Removed			
Current Condition:	Removed - Basin	was closed prior to inspe	ection on 9/25/18.				
		South of Northern Dr.					
SB 2	Codiment Besin	between 185th St and	4/0/2007	Activo	No		
Current Condition:	Sediment Basin	184th St.	4/9/2007 er trees were removed from t	Active	No No.		
Current Condition:		painted by E&A inspector		tile basili prior to tile 3/2	to/15 inspection.		
			r on 3/30/2020				
			r on 3/30/2020.				
		South of Northern Dr.	r on 3/30/2020.				
CD 2		South of Northern Dr. between 182th St and		Activo	No		
SB 3	Sediment Basin	South of Northern Dr. between 182th St and 184th St.	04/06/07	Active	No 20/15 inspection		
SB 3 Current Condition:	Sediment Basin Good Condition - 3	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunted	04/06/07 er trees were removed from t	he basin prior to the 3/2	20/15 inspection.		
	Sediment Basin Good Condition - Basin was mowed	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/	04/06/07 er trees were removed from t 16/18. Minor riser damage w	he basin prior to the 3/2	20/15 inspection.		
	Sediment Basin Good Condition - Basin was mowed	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector	04/06/07 er trees were removed from t 16/18. Minor riser damage w	he basin prior to the 3/2	20/15 inspection.		
	Sediment Basin Good Condition - Basin was mowed	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr.	04/06/07 er trees were removed from t 16/18. Minor riser damage w	he basin prior to the 3/2	20/15 inspection.		
Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and	04/06/07 er trees were removed from t 16/18. Minor riser damage w r on 3/30/2020.	he basin prior to the 3/2 as observed during ins	20/15 inspection. pection on 8/13/1		
Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St.	04/06/07 er trees were removed from t 16/18. Minor riser damage w r on 3/30/2020. 04/06/07	he basin prior to the 3/2 as observed during ins Active	20/15 inspection. Dection on 8/13/1		
Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep Sediment Basin Good Condition -	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter	04/06/07 er trees were removed from t 16/18. Minor riser damage w r on 3/30/2020.  04/06/07 er trees were removed from t	he basin prior to the 3/2 as observed during ins Active	20/15 inspection. Dection on 8/13/1		
SB 4 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector	04/06/07 er trees were removed from t 16/18. Minor riser damage w r on 3/30/2020.  04/06/07 er trees were removed from t	he basin prior to the 3/2 as observed during insp  Active he basin prior to the 3/2	20/15 inspection. Dection on 8/13/1		
SB 4 Current Condition:  SB 5	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 10 3/30/2020.	he basin prior to the 3/2 as observed during ins Active	20/15 inspection. Dection on 8/13/1		
SB 4 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspect	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 10 3/30/2020.	he basin prior to the 3/2 as observed during insp  Active he basin prior to the 3/2	20/15 inspection. Dection on 8/13/1		
SB 4 Current Condition:  SB 5 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspection	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18. Minor riser damage were no 3/30/2020.	he basin prior to the 3/2 as observed during inspective  Active he basin prior to the 3/2  Removed	No 20/15 inspection.  No 20/15 inspection.		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep Sediment Basin Removed - Basin Sediment Basin	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspection Northeast of Star grass Rd.	04/06/07 er trees were removed from t 16/18. Minor riser damage w on 3/30/2020.  04/06/07 er trees were removed from t on 3/30/2020.  ection on 8/16/18.	he basin prior to the 3/2 as observed during inspective  Active he basin prior to the 3/2  Removed  Active	No No No		
SB 4 Current Condition:  SB 5 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspection Northeast of Star grass Rd.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18. Minor riser damage were no 3/30/2020.	he basin prior to the 3/2 as observed during inspective  Active he basin prior to the 3/2  Removed  Active	No No No		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspection of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020.	04/06/07 er trees were removed from t 16/18. Minor riser damage w on 3/30/2020.  04/06/07 er trees were removed from t on 3/30/2020.  ection on 8/16/18.	he basin prior to the 3/2 as observed during inspective  Active he basin prior to the 3/2  Removed  Active	No No No		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - 4 repainted by E&A	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspection of the start grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass	04/06/07 er trees were removed from to 16/18. Minor riser damage work on 3/30/2020.  04/06/07 er trees were removed from to 10 on 3/30/2020.  exction on 8/16/18.  4/9/2007 down volunteer trees prior to	Active he basin prior to the 3/2  Active he basin prior to the 3/2  Removed  Active  Active	No 20/15 inspection. No 20/15 inspection. No 20/15 inspection. No . Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter ainted by E&A inspector East of 182nd Cir. was closed prior to inspector Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St.	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18. 4/9/2007 down volunteer trees prior to 16/18.	he basin prior to the 3/2 as observed during inspection  Active he basin prior to the 3/2  Removed  Active o the 2/23/16 inspection  Active	No No Collaboration No Collaboration No Collaboration No Collaboration No Collaboration No No No No		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter be in the simulation of the simulati	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.	Active  O the 2/23/16 inspection	No No Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector East of 182nd Cir. was closed prior to inspector Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout in	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18. 4/9/2007 down volunteer trees prior to 16/18.	Active  O the 2/23/16 inspection	No No Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter ainted by E&A inspector East of 182nd Cir. was closed prior to inspector Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout m North of Star grass	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.	Active  O the 2/23/16 inspection	No No Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter aim to be East of 182nd Cir. was closed prior to inspector to inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. Botween 184th St.	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.	Active  Active Active Active Active Active Active Active Active Active Active Of the 2/23/16 inspection	No Cleanout mark  No There is erosic		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - repainted by E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter painted by E&A inspector. Was closed prior to inspect Northeast of Star grass Rd.  48% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. Between 184th St. and 182nd St.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.	Active Othe 2/23/16 inspection Active Othe 2/23/16 inspection Active	No Cleanout mark  No There is erosio		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - repainted by E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ bainted by E&A inspector.  South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter bainted by E&A inspector.  East of 182nd Cir.  was closed prior to inspector on 3/30/2020.  North of Star grass Rd.  48% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd.  North of Star grass Rd. between 184th St and 182nd St.  49% Filled - The SID cut	04/06/07 er trees were removed from to 16/18. Minor riser damage word on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.	Active Othe 2/23/16 inspection Active Othe 2/23/16 inspection Active	No Cleanout mark  No There is erosic		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - repainted by E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter painted by E&A inspector. Was closed prior to inspect Northeast of Star grass Rd.  48% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. Battled - The SID cut will monitor. Cleanout monitor. Star grass Rd. Battled - The SID cut will monitor. Star grass Rd. Battled - The SID cut inspector on 3/30/2020.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.  4/9/2007 down volunteer trees prior to 16/18.	Active  Active Active Active Active Active Active Active Active Active Othe 2/23/16 inspection Active Othe 2/23/16 inspection Active Othe 2/23/16 inspection Active Othe 2/23/16 inspection	No Cleanout mark  No Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - repainted by E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - A  Sediment Basin Good Condition - A  Sediment Basin Good Condition - A  Sediment Basin	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector.  South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter prior to inspector on 3/30/2020.  North of Star grass Rd.  Rd. East of 182nd Cir.  Was closed prior to inspector on 3/30/2020.  North of Star grass Rd.  Rd. East of 182nd St.  Will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd.  Rd. between 184th St and 182nd St.  Rd. between 184th St and 182nd St.  Rd. Filled - The SID cut inspector on 3/30/2020.  Entire Site	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 down volunteer trees prior to 16/18.	Active	No Cleanout mark  No Cleanout mark  No Cleanout mark  No Cleanout mark  No No No		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - Cleanout mark rep  Sediment Basin Removed - Basin Sediment Basin Good Condition - repainted by E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin Good Condition - at the outfall. E&A  Sediment Basin	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector.  South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter prior to inspector on 3/30/2020.  North of Star grass Rd.  Rd. East of 182nd Cir.  Was closed prior to inspector on 3/30/2020.  North of Star grass Rd.  Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd.  Rd. between 184th St and 182nd St.  49% Filled - The SID cut inspector on 3/30/2020.  Entire Site  Streets in front of Lot 77	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to ron 3/30/2020.  ection on 8/16/18.  4/9/2007 down volunteer trees prior to 16/18 to 16/18 to 16/18.  4/9/2007 down volunteer trees prior to 16/18 to	Active  Active  Active  Active  Active  Active  Active  Active  O the 2/23/16 inspection  Active  The 2/23/16 inspection  Active  The 2/23/16 inspection	No No Cleanout mark No Cleanout mark No Cleanout mark No Cleanout mark No		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep  Sediment Basin Removed - Basin  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A  Sediment Basin Good Condition - 4 at the outfall of the sediment Basin Good Condition - 4 frepainted by E&A  Streets Good Condition - 5 front of lots 42, 50	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector. Was closed prior to inspection and the standard	04/06/07 er trees were removed from to 16/18. Minor riser damage work on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 to down volunteer trees prior to 16/18.  4/20/2007 down volunteer trees prior to 16/18.  3/20/2007 were cleaned prior to inspection on 10/10/18. Streets were	Active  Active  Active  Active  Active  Active  Active  Active  O the 2/23/16 inspection  Active  Active	No No Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep Sediment Basin Removed - Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A  Sediment Basin Good Condition - 4 Tepainted by E&A  Sediment Basin Good Condition - 4 Tepainted by E&A  Streets Good Condition - 4 Streets Good Condition - 1 In the first of the	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter painted by E&A inspector. Was closed prior to inspection to inspector on 3/30/2020.  Northeast of Star grass Rd.  48% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. between 184th St. and 182nd St.  49% Filled - The SID cut inspector on 3/30/2020.  Entire Site  Streets in front of Lot 77 and 86 prior to inspection 1/18. Streets were cleaned.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  04/06/07 er trees were removed from to 16/19. excition on 8/16/18.  4/9/2007 down volunteer trees prior to 16/19. 4/9/2007 down volunteer trees prior to 16/19. 4/20/2007 down volunteer trees prior to 16/19. 3/20/2007 were cleaned prior to inspection on 10/10/18. Streets were 16/19.	Active  Active  Active  Active  Active  Active  Active  Active  O the 2/23/16 inspection  Active  O the 2/23/16 inspection  Active  Active  Active  Active  Active  Active  Active  Active  Cleaned in 182nd Circle  pection on 6/24/19. Hou	No No Cleanout mark  No Mo Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep Sediment Basin Removed - Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A  Sediment Basin Good Condition - 4 Tepainted by E&A  Sediment Basin Good Condition - 4 Tepainted by E&A  Sediment Basin Good Condition - 4 Tepainted by E&A  Streets Good Condition - 5 Tepainted by E&A	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter painted by E&A inspector. East of 182nd Cir. was closed prior to inspector to inspector on 3/30/2020.  Northeast of Star grass Rd. East of 182nd St.  42% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. between 184th St. and 182nd St.  49% Filled - The SID cut inspector on 3/30/2020.  Entire Site  Streets in front of Lot 77 and 86 prior to inspectic land 86 prior to inspectic land 85 streets were cleaned the streets in front of Lot.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  04/06/07 er trees were removed from to 16/19. extion on 8/16/18.  4/9/2007 down volunteer trees prior to 16/19/2007 down volunteer trees prior to 16/19/2007 down volunteer trees prior to 16/19/2007 were cleaned prior to inspection on 10/10/18. Streets were 16/19/2016 on 19/10/18.	Active  Active  Active  Active  Active  Active  Active  Active  O the 2/23/16 inspection  Active  O the 2/23/16 inspection  Active  Active  Active  Active  Active  Active  Active  Active  Cleaned in 182nd Circle  pection on 6/24/19. Hou	No No Cleanout mark  No Mo Cleanout mark		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:  STR Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep Sediment Basin Removed - Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A  Sediment Basin Good Condition - 4 at the outfall of the outfal	South of Northern Dr. between 182th St and 184th St. 39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St. 41% Filled. The volunter painted by E&A inspector. Was closed prior to inspection in the street of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. 48% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. between 184th St. 49% Filled - The SID cut inspector on 3/30/2020. Entire Site Streets in front of Lot 77 and 86 prior to inspection in Font of Lot mones prior to 9/20/20	04/06/07 er trees were removed from to 16/18. Minor riser damage work on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  04/06/07 er trees were removed from to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/9/2007 down volunteer trees prior to 16/18.  4/20/2007 down volunteer trees prior to 16/18.  3/20/2007 were cleaned prior to inspection on 10/10/18. Streets were 18/19 do 11/19.	Active he basin prior to the 3/2 Active he basin prior to the 3/2 Removed  Active o the 2/23/16 inspection ctor on 3/30/2020.  Active o the 2/23/16 inspection to the 2/23/16 inspection active o the 2/23/16 inspection to on 9/4/18. Streets were cleaned in 182nd Circle pection on 6/24/19. Hol 0/19. Streets were clear	No No Cleanout mark  No Cleanout mark  No Cleanout mark  No Cleanout mark  No Mo Decide of the prior to mestead Custom med by JD Martine		
SB 4 Current Condition:  SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:  SB 8 Current Condition:	Sediment Basin Good Condition - 3 Basin was mowed Cleanout mark rep  Sediment Basin Good Condition - 4 Cleanout mark rep Sediment Basin Removed - Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 at the outfall. E&A  Sediment Basin Good Condition - 4 repainted by E&A  Sediment Basin Good Condition - 4 repainted by E&A  Streets Good Condition - 4 repainted by E&A  Streets Good Condition - 4 streets Good Condition - 5 front of lots 42, 50 inspection on 12/4 Builders cleaned t and Knapp Custor  Signs	South of Northern Dr. between 182th St and 184th St.  39% Filled. The volunter prior to inspection on 8/ painted by E&A inspector. South of Northern Dr. between 182th St and 184th St.  41% Filled. The volunter painted by E&A inspector. East of 182nd Cir. was closed prior to inspector to inspector on 3/30/2020.  Northeast of Star grass Rd. East of 182nd St.  42% Filled - The SID cut inspector on 3/30/2020.  North of Star grass Rd. East of 182nd St.  42% Filled - The SID cut will monitor. Cleanout monitor. Cleanout monitor. Cleanout monitor. Star grass Rd. between 184th St. and 182nd St.  49% Filled - The SID cut inspector on 3/30/2020.  Entire Site  Streets in front of Lot 77 and 86 prior to inspectic land 86 prior to inspectic land 85 streets were cleaned the streets in front of Lot.	04/06/07 er trees were removed from to 16/18. Minor riser damage were on 3/30/2020.  04/06/07 er trees were removed from to 16/18.  04/06/07 er trees were removed from to 16/19/2007 down volunteer trees prior to 16/19/2007 down volunteer trees prior to 16/19/2007 down volunteer trees prior to 16/19/2007 were cleaned prior to inspection on 10/10/18. Streets were 16/19/2008 8/19/2008	Active  Active  Active  Active  Active  Active  Active  Active  O the 2/23/16 inspection  Active  O the 2/23/16 inspection  Active  Active  Active  Active  Active  Active  Active  Active  Cleaned in 182nd Circle  pection on 6/24/19. Hou	No  Cleanout mark  No  Mo  Mo  Cleanout mark  No  Mo  Mo  Cleanout mark  No  Mo  Mo  Mo  Mo  Mo  Mo  Mo  Mo  Mo		

Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	•		Reviewed By:	Go Se	