E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	•							
		E&A- P2003.1	91.000		Stage			
Inspector: Joe Manning								
	Newport Hill							
Project Name:		NER110499						
For Week Ending:		11/12/2022 180th St and NE Highway 36- Bennington NE (Douglas County)						
Project Location:	180th							
Grading:	100%							
Sanitary Sewer:	100%							
Storm Sewer:	100%							
Paving:	100%							
Seeding:	100%							
Utilities:	100%							
Overall Development:	92%							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week			
			1	1	1			

		Bate mepeeted	Trodation Contaitionio	11110	
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					Week 3
Sunday:	0.00"				
Monday	0.14"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"	11/1/2022	Sunny 78/40	1:15 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.42"				
Saturday	0.00"				
					Week 5
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.09"				
Wednesday	0.00"				
Thursday	0.02"				

Friday	0.00"						
Saturday	0.00"						
	Nono						
	None						
Complaints:							
		1		1			
Construction Sequencing:							
Which portion(s) (i.e. drainage basins) of the s	site have had a tempor	rary or permanent cessation	of grading, earthwork, or ground	disturbance in the last 14 day	s?		
Entire Site, grading was completed on 6	6/11/07.						
Which portion(s) (i.e. drainage basins) of the s	site do not have gradir	ng, earthwork, or ground dis	turbance scheduled in the next 14	4 days? :			
Entire Site, grading was completed on 6	6/11/07.						
What temporary or permanent stabilization me		ection are being implemente	ed?				
Seeded (6/2007), Re-seeded (9/2007), sidewalk by the entrance was seeded a OL B (12/2/19).							
Checklist Questions:							
Are receiving waters adjacent to the project fro	ee of any significant s	igns of erosion or sediment	that would be associated with the	e construction activity?			
Yes Create Corrective Action?							
N/A							
Have disturbed areas been seeded or otherwis erosion.	se stabilized as require	ed? List inactive portions of	the project and if stabilization me	easure are adequate or needeo	I to prevent		
No							
Create Corrective Action?							
No, See BMPs and Findings section							
Are waste materials (concrete, construction m	aterial, hazardous, etc	c.) being managed properly?					
Yes Create Corrective Action?							
N/A							
Are construction entrances and adjacent stree	ets being maintained a	dequately?					
Yes							
Create Corrective Action?							
N/A							
Is dust associated with the construction activi Yes	ity adequately controll	ed on the site?					
Create Corrective Action?							
N/A							
Comments:							
Comments:							
The site was inactive during the last inspection.							
Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date):							
 No maintenance is required in the BMP section. Outlot D has been disturbed by homeowner of Lot 36 prior to inspection on 6/27/18. E&A will monitor. Some BMPs are in place and needing maintenance. 							
a. straw wattles along outlot need cleaned out b. erosion rills need backfilled and seeded							
last inspection. E&A inspector is awaitir	Maintenance responsibility is currently being determined by SID department. E&A will monitor. Maintenance responsibility is still being determined as of last inspection. E&A inspector is awaiting SID department's update as of April 2020. Area is currently being litigated as of 3/2021. E&A will inspector will update when more information is known.						
				`			
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		South of Northern Dr.					

		South of Northern Dr.					
DS 1	Swale	between SB 1 and 2		Removed			
Current Condition:	Removed - The div	moved - The diversion was removed prior to inspection on 5/2/17.					
		West of 182nd Cir.					
DS 9	Swale	towards SB 4		Removed			
Current Condition:	Removed - The diversion was removed prior to inspection on 5/2/17.						

		East of North and Dr	r		1
		East of Northern Dr. and 182nd Cir towards			
DS 12	Swale	SB 5		Removed	
Current Condition:			or to inspection on 5/2/17.	rtomorou	
		East of Star grass Rd			
DS 13	Swale	towards SB 6		Removed	
Current Condition:	Removed - No div	version swale was observ	ed during the inspection on	12/8/17.	ł
		North of Star grass Rd			
DS 14	Swale	towards SB 6		Removed	
Current Condition:	Removed - No div	version swale was observ	ed during the inspection on	12/8/17.	•
Lot 24	Silt Fence	Lot 24		Removed	
Current Condition:	Removed - Nilius	Builders sodded the lot p	prior to the inspection on 7/3	1/21.	ł
Lot 42	Individual Lot	Lot 42	·	Removed	
Current Condition:	Removed - D and	D Leasing sodded the lo	t and grass has grown to sta	abilization as of the inspe	ection on
	11/22/21.	5	5 5		
Lot 73	Individual Lot	Lot 73		Removed	
Current Condition:			anish) sodded the lot prior		1/01/22.
Lot 84	Individual Lot	Lot 84		Removed	
Current Condition:	Removed - Russ I	Knapp sodded the lot pri-	or to the inspection on 7/7/21	1.	
Lot 88	Individual Lot	Lot 88		Removed	
Current Condition:	Removed - Ideal [Designs sodded the lot p	rior to inspection on 4/22/21.		
Outlot B	Silt Fence	Outlot B		Removed	
Current Condition:			were removed by the SID in		120
SF 1	Silt Fence	South of Lot 21		Removed	
Current Condition:			I silt fence prior to inspectior		
Current Condition.		South of Northern Dr.			1
		on southwest corner of			
SB 1	Sediment Basin	site		Removed	
Current Condition:		was closed prior to inspe	L action on 9/25/18	rtemoved	
ourient condition.		South of Northern Dr.			1
		between 185th St and			
SB 2	Sediment Basin	184th St.	4/9/2007	Active	No
Current Condition:		-	er trees were removed from t		
		painted by E&A inspector			
		South of Northern Dr.			1
		between 182th St and			
SB 3	Sediment Basin	184th St.	04/06/07	Active	No
Current Condition:			er trees were removed from t		
ourient obhanion.			16/18. Minor riser damage w		
		painted by E&A inspector			
		South of Northern Dr.		1	1
		between 182th St and			
SB 4	Sediment Basin	184th St.	04/06/07	Active	No
Current Condition:			er trees were removed from t		
		painted by E&A inspector			
SB 5			511 510012020.	Removed	
	Sediment Basin	East of 182nd Cir.	L	Removed	1
	Removed Design				
Current Condition:	Removed - Basin	· · ·		1	
		Northeast of Star		Activo	No
SB 6	Sediment Basin	Northeast of Star grass Rd.	4/9/2007	Active	No Cleanout ma
	Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut			
SB 6	Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020.	4/9/2007		
SB 6 Current Condition:	Sediment Basin Good Condition - repainted by E&A	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass	4/9/2007 down volunteer trees prior to	b the 2/23/16 inspection.	Cleanout ma
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - repainted by E&A Sediment Basin	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St.	4/9/2007 down volunteer trees prior to 4/9/2007	b the 2/23/16 inspection.	Cleanout ma
SB 6 Current Condition:	Sediment Basin Good Condition - repainted by E&A Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t	b the 2/23/16 inspection. Active to the 2/23/16 inspection	Cleanout man
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - repainted by E&A Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu	4/9/2007 down volunteer trees prior to 4/9/2007	b the 2/23/16 inspection. Active to the 2/23/16 inspection	Cleanout ma
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - repainted by E&A Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t	b the 2/23/16 inspection. Active to the 2/23/16 inspection	Cleanout ma
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - repainted by E&A Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu will monitor. Cleanout n	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t	b the 2/23/16 inspection. Active to the 2/23/16 inspection	Cleanout ma
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - repainted by E&A Sediment Basin Good Condition -	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu will monitor. Cleanout n North of Star grass	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t	b the 2/23/16 inspection. Active to the 2/23/16 inspection	Cleanout ma
SB 6 Current Condition: SB 7 Current Condition:	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t hark repainted by E&A inspec 4/20/2007	Active Active to the 2/23/16 inspection ctor on 3/30/2020. Active	Cleanout ma No . There is ero: No
SB 6 Current Condition: SB 7 Current Condition: SB 8	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cu will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t nark repainted by E&A inspec	Active Active to the 2/23/16 inspection ctor on 3/30/2020. Active	Cleanout ma No . There is ero No
SB 6 Current Condition: SB 7 Current Condition: SB 8	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St 49% Filled - The SID cut	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t hark repainted by E&A inspec 4/20/2007	Active Active to the 2/23/16 inspection ctor on 3/30/2020. Active	Cleanout ma No . There is ero: No
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition repainted by E&A Streets	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St 49% Filled - The SID cut inspector on 3/30/2020. Entire Site	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t hark repainted by E&A inspect 4/20/2007 down volunteer trees prior to	b the 2/23/16 inspection. Active to the 2/23/16 inspection to the 2/23/16 inspection to on 3/30/2020. Active the 2/23/16 inspection. Active Active	Cleanout ma No . There is ero No Cleanout ma
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition repainted by E&A Streets Good Condition	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St 49% Filled - The SID cut inspector on 3/30/2020. Entire Site Streets in front of Lot 77	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t hark repainted by E&A inspect 4/20/2007 down volunteer trees prior to 3/20/2007	b the 2/23/16 inspection. Active to the 2/23/16 inspection ctor on 3/30/2020. Active the 2/23/16 inspection. Active the 2/23/16 inspection.	Cleanout ma
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition repainted by E&A Streets Good Condition front of lots 42, 50	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St 49% Filled - The SID cut inspector on 3/30/2020. Entire Site Streets in front of Lot 77 and 86 prior to inspector	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior t hark repainted by E&A inspect 4/20/2007 down volunteer trees prior to 3/20/2007 were cleaned prior to inspec	b the 2/23/16 inspection. Active to the 2/23/16 inspection ctor on 3/30/2020. Active the 2/23/16 inspection. Active tion on 9/4/18. Streets w cleaned in 182nd Circle	Cleanout ma
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin Good Condition repainted by E&A Sediment Basin Good Condition at the outfall. E&A Sediment Basin Good Condition repainted by E&A Streets Good Condition front of lots 42, 50 inspection on 12/4	Northeast of Star grass Rd. 48% Filled - The SID cut inspector on 3/30/2020. North of Star grass Rd. East of 182nd St. 42% Filled - The SID cut will monitor. Cleanout n North of Star grass Rd. between 184th St and 182nd St 49% Filled - The SID cut inspector on 3/30/2020. Entire Site Streets in front of Lot 77 and 86 prior to inspection 4/18. Streets were cleaned	4/9/2007 down volunteer trees prior to 4/9/2007 t down volunteer trees prior to hark repainted by E&A inspect 4/20/2007 down volunteer trees prior to 3/20/2007 were cleaned prior to inspect on on 10/10/18. Streets were	b the 2/23/16 inspection. Active to the 2/23/16 inspection ctor on 3/30/2020. Active to the 2/23/16 inspection. Active tion on 9/4/18. Streets w cleaned in 182nd Circle spection on 6/24/19. Hon	Cleanout ma

SWPPP signs	Signs	1 sign	8/19/2008	Active	No			
Current Condition:	Good Condition - SW corner of 180th St and Northern Hills Dr.							
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.							
Inspector Signature:								