E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager



## Engineering Answers

		E&A- P2003.191	.000			
Inspector: Josh Ellington					Stage	
		Nev	vport Hill			
Project Name:		NE	R110499		3	
For Week Ending:		6/10/2023				
Project Location:	180th	6/10/2023 180th St and NE Highway 36- Bennington NE (Douglas County)				
	10011					
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	92%					
			-		•	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
					Week '	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"	5/40/0000	0	0.50.444		
Friday	0.00"	5/19/2023	Sunny 57	8:50 AM		
Saturday	0.00				Week 2	
Sunday:	0.00"				Week 2	
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.07"					
Friday	0.00"					
Saturday	0.02"				Mach	
Sunday:	0.26" (13:35 - 19:55)				Week 4	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.28" (11:15 - 19:55)					
Saturday	0.44" (18:15 - 19:55)					
					Week 5	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					

Saturday	N/A						
Complaints:	None						
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the s	site have had a temporary o	or permanent cessation of g	rading, earthwork, or ground dist	urbance in the last 14 days?			
Entire Site, grading was completed on 6	5/11/2007.						
Which portion(s) (i.e. drainage basins) of the		arthwork, or ground disturba	ince scheduled in the next 14 day	/s? :			
Entire Site, grading was completed on 6							
What temporary or permanent stabilization m							
Seeded (6/2007), Re-seeded (9/2007), sidewalk by the entrance was seeded a OL B (12/2/2019).							
Checklist Questioner							
Checklist Questions: Are receiving waters adjacent to the	project free of any sig	nificant signs of erosio	n or sediment that would b	e associated with the co	nstruction		
Yes	siejeet nee er uny eig				nou douon		
Create Corrective Action?							
N/A							
Have disturbed areas been seeded or		as required? List inacti	ve portions of the project a	and if stabilization measu	ure are		
adequate or needed to prevent erosion	on.						
Create Corrective Action?							
No - See BMPs and Findings Section.							
Are waste materials (concrete, const	ruction material, hazar	dous, etc.) being mana	aged properly?				
Yes	, , , , , , , , , , , , , , , , , , ,		.304 h. cho J .				
Create Corrective Action?							
Are construction entrances and adjace	cent streets being mai	ntained adequately?					
Yes Create Corrective Action?							
N/A							
			-				
Is dust associated with the construct Yes	ion activity adequately	y controlled on the site	<b>?</b>				
Create Corrective Action?							
N/A							
Comments:							
Comments:							
The site was inactive during the last ins	pection.						
Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date):	MD exetion						
<ol> <li>No maintenance is required in the Bl</li> <li>Outlot D has been disturbed by hom</li> </ol>		o inspection on 6/27/18.	E&A will monitor. Some BMF	s are in place and needin	g maintenance.		
a. straw wattles along outlot need cleaned out b. erosion rills need backfilled and seeded							
Maintananaa kaananaihiiitu ja aurrantuuk	aing datarminad by CIF	) depertment F8A will m	anitar Maintananaa raanan	vibility is still being determi	ned as of last		
Maintenance responsibility is currently being determined by SID department. E&A will monitor. Maintenance responsibility is still being determined as of last inspection. E&A inspector is awaiting SID department's update as of April 2020. Area is currently being litigated as of 3/2021. E&A will inspector will update							
when more information is known.							
3.) Construction activity was observed along the back of Lot 72 during the inspection on 2/15/23. E&A inspector will monitor and make recommendations as							
necessary.							
		`					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
DS 1	Swale	South of Northern Dr. between SB 1 and 2		Removed			
Current Condition:		ion was removed prior to	inspection on 5/2/17.	Romovou			
		West of 182nd Cir.					
DS 9	Swale	towards SB 4		Removed			
Current Condition:	Removed - The diversi	ion was removed prior to	inspection on 5/2/17.				

				1	1	
		East of Northern Dr. and 182nd Cir towards				
DS 12	Swale	SB 5		Removed		
Current Condition:		ion was removed prior to	inspection on 5/2/17	Renioved		
ourient condition.		East of Star grass Rd				
DS 13	Swale	towards SB 6		Removed		
0010			L during the inspection on 12/8			
		North of Star grass Rd				
DS 14	Swale	towards SB 6		Removed		
Current Condition:			uduring the inspection on 12/8			
Lot 24	Silt Fence	Lot 24		Removed		
Current Condition:			to the inspection on 7/31/21.			
Lot 42	Individual Lot	Lot 42		Removed	1	
Current Condition:			l d grass has grown to stabiliz		on 11/22/21	
Current Condition.		easing source the lot an	d grass has grown to stabiliz	auon as or the inspection	011 11/22/21	
Lot 73	Individual Lot	Lot 73		Removed	1	
Current Condition:		-	l ) sodded the lot prior to the ir			
		, , , , , , , , , , , , , , , , , , , ,			1	
Lot 84	Individual Lot	Lot 84		Removed		
Current Condition:		· · ·	the inspection on 7/7/21.		1	
Lot 88	Individual Lot	Lot 88		Removed		
Current Condition:		gns sodded the lot prior t	o inspection on 4/22/21.	1	1	
Outlot B	Silt Fence	Outlot B		Removed		
Current Condition:	Removed-Silt fence ch	necks and silt fence were	e removed by the SID in the o	putlot prior to 10/6/2020		
SF 1	Silt Fence	South of Lot 21		Removed		
Current Condition:	Removed - Woodland	Homes removed the silt	fence prior to inspection on	8/16/18.	-	
		South of Northern Dr.				
		on southwest corner of				
SB 1	Sediment Basin	site		Removed		
Current Condition:	Removed - Basin was	closed prior to inspectio	n on 9/25/18.			
		South of Northern Dr.				
		between 185th St and				
SB 2	Sediment Basin	184th St.	4/9/2007	Active	No	
Current Condition:		Good Condition - 29% Filled. The volunteer trees were removed from the basin prior to the 3/20/15 inspection.				
	Cleanout mark repaint	ed by E&A inspector on	3/30/2020.			
		South of Northern Dr.				
		between 182th St and				
SB 3	Sediment Basin	184th St.	4/6/2007	Active	No	
Current Condition:	Good Condition - 43%	Filled. The volunteer tre	es were removed from the b	asin prior to the 3/20/15 i	inspection. B	
	was mowed prior to in	spection on 8/16/18. Min	or riser damage was observe	ed during inspection on 8	/13/19. Clear	
	mark repainted by E&/	A inspector on 3/30/2020	l.			
		South of Northern Dr.		1	1	
		between 182th St and				
SB 4	Sediment Basin	184th St.	4/6/2007	Active	No	
Current Condition:			ees were removed from the b			
Current Condition.		ted by E&A inspector on			inspection.	
SB 5		East of 182nd Cir.		Domovod	1	
<u> 36 0</u>	Sediment Basin	closed prior to inspectio		Removed		
Occurrent Occurrentiations			n on 8/16/18.			
Current Condition:		· · · ·				
		Northeast of Star	4/0/0007	Artiur	Ne	
SB 6	Sediment Basin	Northeast of Star grass Rd.	4/9/2007	Active	No	
	Sediment Basin Good Condition - 48%	Northeast of Star grass Rd. Filled - The SID cut dow	4/9/2007 n volunteer trees prior to the			
SB 6	Sediment Basin	Northeast of Star grass Rd. Filled - The SID cut dow				
SB 6	Sediment Basin Good Condition - 48%	Northeast of Star grass Rd. Filled - The SID cut dow	n volunteer trees prior to the			
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St.	n volunteer trees prior to the 4/9/2007	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition:	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow	n volunteer trees prior to the 4/9/2007	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow ponitor. Cleanout mark rep	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow ponitor. Cleanout mark rep North of Star grass Rd.	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition: SB 7	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow ponitor. Cleanout mark rep	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea	nout mark	
SB 6 Current Condition: SB 7 Current Condition:	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42% the outfall. E&A will mo Sediment Basin	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow onitor. Cleanout mark rep North of Star grass Rd. between 184th St and 182nd St	4/9/2007 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on 4/20/2007	Active 2/23/16 inspection. Clea Active 2/23/16 inspection. The 3/30/2020. Active	nout mark No re is erosion No	
SB 6 Current Condition: SB 7 Current Condition: SB 8	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42% the outfall. E&A will mo Sediment Basin Good Condition - 49%	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow onitor. Cleanout mark rep North of Star grass Rd. between 184th St and 182nd St Filled - The SID cut dow	4/9/2007 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on	Active 2/23/16 inspection. Clea Active 2/23/16 inspection. The 3/30/2020. Active	nout mark No re is erosion No	
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42% the outfall. E&A will me Sediment Basin Good Condition - 49% repainted by E&A insp	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow onitor. Cleanout mark rep North of Star grass Rd. between 184th St and 182nd St Filled - The SID cut dow ector on 3/30/2020.	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on 4/20/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea	nout mark No re is erosion No nout mark	
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42% the outfall. E&A will me Sediment Basin Good Condition - 49% repainted by E&A insp Streets	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow onitor. Cleanout mark rep North of Star grass Rd. between 184th St and 182nd St Filled - The SID cut dow ector on 3/30/2020. Entire Site	A/9/2007 vn volunteer trees prior to the 2/9/2007 vn volunteer trees prior to the 2007 vn volunteer trees prior to the 3/20/2007	2/23/16 inspection. Clea	nout mark No re is erosion No nout mark No	
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Sediment Basin Good Condition - 48% repainted by E&A insp Sediment Basin Good Condition - 42% the outfall. E&A will me Sediment Basin Good Condition - 49% repainted by E&A insp Streets Good Condition - Streets	Northeast of Star grass Rd. Filled - The SID cut dow ector on 3/30/2020. North of Star grass Rd. East of 182nd St. Filled - The SID cut dow onitor. Cleanout mark rep North of Star grass Rd. between 184th St and 182nd St Filled - The SID cut dow ector on 3/30/2020. Entire Site ets in front of Lot 77 were	n volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on 4/20/2007 vn volunteer trees prior to the	2/23/16 inspection. Clea Active 2/23/16 inspection. The 3/30/2020. Active 2/23/16 inspection. Clea Active on 9/4/18. Streets were c	nout mark No re is erosion No nout mark No leaned in frc	
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin           Good Condition - 48%           repainted by E&A insp           Sediment Basin           Good Condition - 42%           the outfall. E&A will me           Sediment Basin           Good Condition - 42%           the outfall. E&A will me           Sediment Basin           Good Condition - 49%           repainted by E&A insp           Streets           Good Condition - Street           lots 42, 50 and 86 prior	Northeast of Star grass Rd.           Filled - The SID cut down tector on 3/30/2020.           North of Star grass Rd.           East of 182nd St.           Filled - The SID cut down tector on 3/30/2020.           North of Star grass Rd.           between 184th St and 182nd St           Filled - The SID cut down tector on 3/30/2020.           Entire Site           ets in front of Lot 77 were to inspection on 10/10/	A volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on 4/20/2007 vn volunteer trees prior to the 3/20/2007 e cleaned prior to inspection	2/23/16 inspection. Clea Active 2/23/16 inspection. The 3/30/2020. Active 2/23/16 inspection. Clea Active on 9/4/18. Streets were c 182nd Circle prior to inspe	No re is erosion No nout mark No leaned in frc ection on 12/	
SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Sediment Basin           Good Condition - 48%           repainted by E&A insp           Sediment Basin           Good Condition - 42%           the outfall. E&A will me           Sediment Basin           Good Condition - 42%           the outfall. E&A will me           Sediment Basin           Good Condition - 49%           repainted by E&A insp           Streets           Good Condition - Street           Iots 42, 50 and 86 prio           Streets were cleaned if	Northeast of Star grass Rd.           Filled - The SID cut downector on 3/30/2020.           North of Star grass Rd.           East of 182nd St.           Filled - The SID cut downector           Control of Star grass Rd.           East of 182nd St.           Filled - The SID cut downector           North of Star grass Rd.           between 184th St and 182nd St           Filled - The SID cut downector on 3/30/2020.           Entire Site           ets in front of Lot 77 were           or to inspection on 10/10/           in 182nd Circle prior to ir	A/9/2007 vn volunteer trees prior to the 4/9/2007 vn volunteer trees prior to the painted by E&A inspector on 4/20/2007 vn volunteer trees prior to the 3/20/2007 e cleaned prior to inspection 18. Streets were cleaned in 2	Active 2/23/16 inspection. Clea Active 2/23/16 inspection. The 3/30/2020. Active 2/23/16 inspection. Clea Active 0 9/4/18. Streets were c 182nd Circle prior to inspected tead Custom Builders clea	No re is erosion No nout mark No leaned in fro ection on 12/ paned the str	

SWPPP signs	Signs	1 sign	8/19/2008	Active	No	
Current Condition:	Good Condition - SW corner of 180th St and Northern Hills Dr.					
	•					
Certification Statement:	direction or supervision properly gathered and persons who manage t the information submitt am aware that there an	n in accordance with a sy evaluated the information he system or those pers ed is, to the best of my k	It and all attachments were pr vstem designed to assure that n submitted. Based on my inq ons directly responsible for ga nowledge and belief, true, ac r submitting false information s.	qualified personnel uiry of the person or athering the information, curate, and complete. I		
	J.E			Gree	- Sur	
spector Signature:	v .			Reviewed By:		