E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager



**Engineering Answers** 

		E&A- P2003.1	91.000		
Inspector: Josh Ellington					Stage
	Newport Hill				
Project Name:			202206288		3
For Week Ending:			9/2023		
Project Location:	180th S		i- Bennington NE (Douglas	Countyl	68007
Froject Location.	1000110	t and NE mgnway 30	- Deminigion NL (Douglas	County	00001
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	92%				
			· · · · · · · · · · · · · · · · · · ·		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
O. m. do. m.	0.000				Week
Sunday:	<b>0.26"</b> 0.00"	8/14/2023	Cloudy 64	9:40 AM	05:00 - 22:00
Monday Tuesday	0.00"	0/ 14/2023	Cloudy 64	9:40 AW	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
outur day	0.00				Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.03"				
Friday:	0.00"				
Saturday:	0.00"				
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	0.00				
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.04"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				

		I .	I .	l .
Complaints:	None			
Saturday	N/A			
	N/A			
Thursday	N/A			

### Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed on 6/11/2007.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site, grading was completed on 6/11/2007.

What temporary or permanent stabilization measures listed in this section are being implemented?

Seeded (6/2007), Re-seeded (9/2007), Paving (9/2007), Seeded (4/2008), Small drainage ditch behind lot 41 was seeded and matted (4/21/2015) The sidewalk by the entrance was seeded and matted (3/7/2018). OL B next to lot 74 was seeded (11/4/2019). River rock rip rap was installed at the flared end on OL B (12/2/2019).

# **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

#### **Create Corrective Action?**

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Nο

**Create Corrective Action?** 

No - See BMPs and Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

VI/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

**Create Corrective Action?** 

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

**Create Corrective Action?** 

N/A

#### Comments:

#### Comments:

The site was inactive during the last inspection.

# Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) Outlot D has been disturbed by homeowner of Lot 36 prior to inspection on 6/27/18. E&A will monitor. Some BMPs are in place and needing maintenance.
  - a. straw wattles along outlot need cleaned out
  - b. erosion rills need backfilled and seeded

Maintenance responsibility is currently being determined by SID department. E&A will monitor. Maintenance responsibility is still being determined as of last inspection. E&A inspector is awaiting SID department's update as of April 2020. Area is currently being litigated as of 3/2021. E&A will inspector will update when more information is known.

3.) Construction activity was observed along the back of Lot 72 during the inspection on 2/15/23. E&A inspector will monitor and make recommendations as necessary.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
		South of Northern Dr.			
DS 1	Swale	between SB 1 and 2		Removed	
Current Condition:	Removed - The diversion was removed prior to inspection on 5/2/17.				

		West of 182nd Cir.			
DS 9	Swale	towards SB 4		Removed	
Current Condition:	Removed - The divers	ion was removed prior to	inspection on 5/2/17.		
		East of Northern Dr.			
		and 182nd Cir towards			
DS 12	Swale	SB 5		Removed	
Current Condition:	Removed - The divers	ion was removed prior to	inspection on 5/2/17.		
		East of Star grass Rd			
DS 13	Swale	towards SB 6		Removed	
	Removed - No diversi		luring the inspection on 12/8/	17.	
D0 44	01	North of Star grass Rd		D	
DS 14 Current Condition:	Swale	towards SB 6	luring the inspection on 12/8/	Removed	
Lot 24			uring the inspection on 12/6/	Removed	
Current Condition:	Silt Fence	Lot 24	to the inspection on 7/31/21.	Removed	
Lot 42	Individual Lot	Lot 42	to the inspection on 7/3 1/21.	Domeyod	
Current Condition:		1	d grass has grown to stabiliza	Removed	n 11/22/21
Current Condition:	Removed - D and D L	easing souded the lot and	a grass has grown to stabiliza	ation as of the inspection of	ON 11/22/21.
Lot 73	Individual Lot	Lot 73		Removed	
Current Condition:		·	sodded the lot prior to the in		
Lot 84	Individual Lot	Lot 84	sedded the let phor to the in	Removed	
Current Condition:		op sodded the lot prior to	the inspection on 7/7/21	Removed	
Lot 88	Individual Lot	Lot 88	and moposition on I/I/Z1.	Removed	
Current Condition:		gns sodded the lot prior to	n inspection on 4/22/21	1 torriovou	
Outlot B	Silt Fence	Outlot B	, mepeeden en 1,22,21.	Removed	
Current Condition:			removed by the SID in the o		
SF 1	Silt Fence	South of Lot 21		Removed	
Current Condition:			fence prior to inspection on 8		
		South of Northern Dr.			
		on southwest corner of			
SB 1	Sediment Basin	site		Removed	
Current Condition:	Removed - Basin was	closed prior to inspection	n on 9/25/18.		
		South of Northern Dr.			
		between 185th St and			
SB 2	Sediment Basin	184th St.	4/9/2007	Active	No
Current Condition:			es were removed from the b	asin prior to the 3/20/15 in	spection. Cleanout
	mark repainted by E&/	A inspector on 3/30/2020	-		
		South of Northern Dr.			
		between 182th St and			
SB 3	Sediment Basin	184th St.	4/6/2007	Active	No
Current Condition:			es were removed from the b		
	repainted by E&A inspec		er damage was observed du	ring inspection on 8/13/19	. Cleanout mark
	repainted by E&A insp	ector on 5/30/2020.			
		South of Northern Dr.			
		between 182th St and			
SB 4	Sediment Basin	184th St.	4/6/2007	Active	No
0	0 10 100 000	THE THE PERSON OF THE PERSON O			spection Cleanout
Current Condition:		Filled. The volunteer tre		asin prior to the 3/20/15 in	opodion. Oldanoat
	mark repainted by E&/	A inspector on 3/30/2020			- Clourious
SB 5	mark repainted by E&  Sediment Basin	A inspector on 3/30/2020 East of 182nd Cir.		Removed	
	mark repainted by E&  Sediment Basin	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection			opeciioni. Giodinedi
SB 5 Current Condition:	mark repainted by E&/ Sediment Basin Removed - Basin was	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass	n on 8/16/18.	Removed	
SB 5 Current Condition: SB 6	mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.	on 8/16/18.	Removed	No
SB 5 Current Condition:	mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48%	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow	n on 8/16/18.	Removed	No
SB 5 Current Condition: SB 6	mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  1/2020.	on 8/16/18.	Removed	No
SB 5  Current Condition:  SB 6  Current Condition:	mark repainted by E&A Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  //2020.  North of Star grass Rd.	n on 8/16/18.  4/9/2007  n volunteer trees prior to the	Removed  Active 2/23/16 inspection. Clean	No out mark repainted
SB 5 Current Condition:  SB 6 Current Condition:  SB 7	mark repainted by E&A Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  //2020.  North of Star grass Rd.  East of 182nd St.	4/9/2007 n volunteer trees prior to the	Removed  Active 2/23/16 inspection. Clean	No out mark repainted No
SB 5  Current Condition:  SB 6  Current Condition:	mark repainted by E&d Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  //2020.  North of Star grass Rd.  East of 182nd St.  Filled - The SID cut dow	n on 8/16/18.  4/9/2007  n volunteer trees prior to the  4/9/2007  vn volunteer trees prior to the	Active  Active  Active  2/23/16 inspection. Clean	No out mark repainted No
SB 5 Current Condition:  SB 6 Current Condition:  SB 7	mark repainted by E&d Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  2020.  North of Star grass Rd.  East of 182nd St.  Filled - The SID cut dow  created a star of 182nd St.  Filled - The SID cut dow  created a star grass Rd.  East of 182nd St.	4/9/2007 n volunteer trees prior to the	Active  Active  Active  2/23/16 inspection. Clean	No out mark repainted No
SB 5 Current Condition:  SB 6 Current Condition:  SB 7	mark repainted by E&d Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  2020.  North of Star grass Rd.  East of 182nd St.  Filled - The SID cut dow  cr. Cleanout mark repaint  North of Star grass Rd.	n on 8/16/18.  4/9/2007  n volunteer trees prior to the  4/9/2007  vn volunteer trees prior to the	Active  Active  Active  2/23/16 inspection. Clean	No out mark repainted No
SB 5 Current Condition:  SB 6 Current Condition:  SB 7 Current Condition:	mark repainted by E&J Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42% outfall. E&A will monite	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  2020.  North of Star grass Rd.  East of 182nd St.  Filled - The SID cut dow  cr. Cleanout mark repaint  North of Star grass Rd.  between 184th St and	n on 8/16/18.  4/9/2007  In volunteer trees prior to the  4/9/2007  In volunteer trees prior to the led by E&A inspector on 3/30	Active 2/23/16 inspection. Clean  Active 2/23/16 inspection. There 2/23/16 inspection. There	No out mark repainted  No e is erosion at the
SB 5 Current Condition:  SB 6 Current Condition:  SB 7	mark repainted by E&J Sediment Basin Removed - Basin was  Sediment Basin Good Condition - 48% E&A inspector on 3/30  Sediment Basin Good Condition - 42% outfall. E&A will monite  Sediment Basin	A inspector on 3/30/2020  East of 182nd Cir.  closed prior to inspection  Northeast of Star grass  Rd.  Filled - The SID cut dow  2020.  North of Star grass Rd.  East of 182nd St.  Filled - The SID cut dow  cr. Cleanout mark repaint  North of Star grass Rd.  between 184th St and  182nd St	n on 8/16/18.  4/9/2007  n volunteer trees prior to the  4/9/2007  vn volunteer trees prior to the	Active 2/23/16 inspection. Clean  Active 2/23/16 inspection. There 2/2020.	No out mark repainted I  No e is erosion at the

STR	Streets	Entire Site	3/20/2007	Active	No		
Current Condition:	Good Condition - Streets in front of Lot 77 were cleaned prior to inspection on 9/4/18. Streets were cleaned in front of lots 42, 50 and 86 prior to inspection on 10/10/18. Streets were cleaned in 182nd Circle prior to inspection on 12/4/18. Streets were cleaned in 182nd Circle prior to inspection on 6/24/19. Homestead Custom Builders cleaned the streets in front of Lot 74 prior to inspection on 9/10/19. Streets were cleaned by JD Martinez and Knapp Custom Homes prior to 9/20/2019						
SWPPP signs	Signs	1 sign	8/19/2008	Active	No		
Current Condition:	Good Condition - SW of	corner of 180th St and N	lorthern Hills Dr.				
Certification Statement:  I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.							
Inspector Signature:	HE			Reviewed By:	+ See		