E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E&A- P2003.191.000			
Inspector: Josh Ellington			Stage	
Project Name:	Newport Hill CSW-2022062		3	
For Week Ending:	8/10/2024			
Project Location:	180th St and NE Highway 36- Bennington NE (Douglas County)			
			·	
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	92%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.37" [16:55 - 23:55]				
Saturday	1.18" [00:15 - 00:55]				
					Week 2
Sunday:	0.00"				
Monday:	0.00"	7/22/2024	Mostly Sunny 83/64	2:50 PM	
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
					Week 3
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.01"				
Wednesday:	0.72" [17:55 - 18:35]				
Thursday:	0.00"	8/1/2024	Mostly Sunny 91/68	8:10 AM	
Friday:	0.00"				
Saturday:	0.00"				
					Week 4
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.02"				
Friday:	0.00"				
Saturday:	0.00"				
					Week 5
Sunday:	N/A				
Monday:	N/A				
Tuesday:	N/A				
Wednesday:	N/A				

Thursday:	N/A				
Friday:	N/A				
Saturday:	N/A				
Complaints: None					
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the s	ito havo had a tomporany o	r pormanont consistion of ar	ding oarthwork or ground distur	hanco in the last 14 days?	
		permanent cessation of gra	aning, earthwork, or ground distar	ballee in the last 14 days!	
Entire Site, grading was completed on 6					
Which portion(s) (i.e. drainage basins) of the s		rthwork, or ground disturbar	nce scheduled in the next 14 days	?:	
Entire Site, grading was completed on 6					
What temporary or permanent stabilization me	asures listed in this section	n are being implemented?			
Seeded (6/2007), Re-seeded (9/2007), the entrance was seeded and matted (3 Erosion behind Lot 36 was backfilled an	/7/2018). OL B next to				
Checklist Questions:	nation from of any sta	nificant class of anothe			onotruction activity 0
Are receiving waters adjacent to the Yes	project free of any sig	nincant signs of erosic	on or seament that would b	be associated with the c	onstruction activity?
Create Corrective Action?					
N/A					
Have disturbed areas been seeded of needed to prevent erosion. Yes	r otherwise stabilized	as required? List inact	ive portions of the project	and if stabilization meas	sure are adequate or
Create Corrective Action?					
N/A					
Are waste materials (concrete, const	ruction material, haza	rdous, etc.) being man	aged properly?		
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and adja	cont stroots hoing ma	intained adequately?			
Yes	cent streets being ma	intained adequatery:			
Create Corrective Action?					
N/A					
Is dust associated with the construct	tion activity adequatel	y controlled on the site	?		
Yes					
Create Corrective Action?					
Comments:					
Comments:					
The site was inactive during the last inspection.					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date):					
1.) No maintenance is required in the BMP section.					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	7 11	South of Northern Dr.			
DS 1	Swale	between SB 1 and 2		Removed	
Current Condition:		ion was removed prior to	inspection on 5/2/17.		
DS 9	Swale	West of 182nd Cir. towards SB 4	· ·	Removed	
Current Condition:			inspection on 5/2/17	Kennoveu	l
		East of Northern Dr. and 182nd Cir towards			
DS 12	Swale	SB 5		Removed	
Current Condition:	Removed - The divers	ion was removed prior to	inspection on 5/2/17.		
		East of Star grass Rd			
DS 13	Swale	towards SB 6		Removed	
	•	•			

	Removed - No diversi	rr	uring the inspection on 12/8/	1 <i>1</i> .	
	Swala	North of Star grass Rd		Demoved	
DS 14	Swale	towards SB 6	ring the inexection on 10/0/	Removed	
Current Condition: Lot 24		Lot 24	uring the inspection on 12/8/		
Current Condition:	Silt Fence		the inspection on 7/31/21.	Removed	
		· · ·		Demonstra	
Lot 42	Individual Lot	Lot 42	grass has grown to stabiliza	Removed	m 11/00/01
Current Condition:	Removed - D and D L	easing sodded the lot and	grass has grown to stabiliza	tion as of the inspection c	on 11/22/21.
Lot 73	Individual Lot	Lot 73		Removed	
Current Condition:		-	sodded the lot prior to the ins		
Lot 84	Individual Lot	Lot 84		Removed	
Current Condition:		pp sodded the lot prior to t	he inspection on 7/7/21	Removed	
Lot 88	Individual Lot	Lot 88		Removed	
Current Condition:		gns sodded the lot prior to	inspection on 4/22/21	rteinoved	
Outlot B	Silt Fence	Outlot B		Removed	
Current Condition:			ا removed by the SID in the ou		
SF 1	Silt Fence	South of Lot 21		Removed	
Current Condition:			ence prior to inspection on 8		
ourrent condition.		South of Northern Dr.			
		on southwest corner of			
SB 1	Sediment Basin	site		Removed	
Current Condition:		closed prior to inspection	on 9/25/18.		
		South of Northern Dr.			
		between 185th St and			
SB 2	Sediment Basin	184th St.	4/9/2007	Active	No
Current Condition:	Good Condition - 29%	Filled. The volunteer tree	es were removed from the ba	asin prior to the 3/20/15 in	spection. Clean
		A inspector on 3/30/2020.		•	•
		South of Northern Dr.			
		between 182th St and			
SB 3	Sediment Basin	184th St.	4/6/2007	Active	No
	repainted by E&A insp		er damage was observed dur	ing inspection on 8/13/19	. Cleanout mark
		South of Northern Dr.			
SB 4	Sediment Basin	between 182th St and 184th St.	4/6/2007	Active	No
SB 4 Current Condition:	Sediment Basin Good Condition - 31%	184th St.	4/6/2007 es were removed from the ba	Active asin prior to the 3/20/15 in	No spection. Clean
	Good Condition - 31%	184th St.	4/6/2007 es were removed from the ba		
	Good Condition - 31%	184th St. Filled. The volunteer tree			
Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin	184th St. Filled. The volunteer tree A inspector on 3/30/2020.	es were removed from the ba	asin prior to the 3/20/15 in	
Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir.	es were removed from the ba	asin prior to the 3/20/15 in	
Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd.	es were removed from the ba on 8/16/18. 4/9/2007	asin prior to the 3/20/15 in Removed	spection. Clean
Current Condition: SB 5 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020.	es were removed from the ba on 8/16/18.	asin prior to the 3/20/15 in Removed	spection. Clean
Current Condition: SB 5 Current Condition: SB 6 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd.	on 8/16/18. 4/9/2007 volunteer trees prior to the 2	Asin prior to the 3/20/15 in Removed Active 2/23/16 inspection. Clean	No No No
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin	184th St. Filled. The volunteer treed inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St.	on 8/16/18. 4/9/2007 volunteer trees prior to the 3 4/9/2007	Asin prior to the 3/20/15 in Removed Active 2/23/16 inspection. Clean Active	spection. Clean No out mark repaint
Current Condition: SB 5 Current Condition: SB 6 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. 5 closed prior to inspection Northeast of Star grass Rd. 5 Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down	on 8/16/18. 4/9/2007 volunteer trees prior to the 2 4/9/2007 n volunteer trees prior to the	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There	spection. Clean No out mark repainte
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. 5 closed prior to inspection Northeast of Star grass Rd. 5 Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down	on 8/16/18. 4/9/2007 volunteer trees prior to the 3 4/9/2007	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There	spection. Clean No out mark repainte
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. 5 closed prior to inspection Northeast of Star grass Rd. 5 Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down	on 8/16/18. 4/9/2007 volunteer trees prior to the 2 4/9/2007 n volunteer trees prior to the	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There	spection. Clean No out mark repainte
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down or. Cleanout mark repainter	on 8/16/18. 4/9/2007 volunteer trees prior to the 2 4/9/2007 n volunteer trees prior to the	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There	spection. Clean No out mark repaint
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42%	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down 0/2020. North of Star grass Rd. Filled - The SID cut down or. Cleanout mark repaintee North of Star grass Rd.	on 8/16/18. 4/9/2007 volunteer trees prior to the 2 4/9/2007 n volunteer trees prior to the	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There	spection. Clean No out mark repaint
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42% outfall. E&A will monit	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. o Filled - The SID cut down 0/2020. North of Star grass Rd. b Filled - The SID cut down or. Cleanout mark repaintee North of Star grass Rd. between 184th St and 182nd St	on 8/16/18. 4/9/2007 a volunteer trees prior to the 3 4/9/2007 n volunteer trees prior to the ed by E&A inspector on 3/30/	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There 2/2020.	spection. Clean No out mark repainte No e is erosion at the No
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42% outfall. E&A will monit	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down 0/2020. North of Star grass Rd. Filled - The SID cut down or. Cleanout mark repaintee North of Star grass Rd. between 184th St and 182nd St o Filled - The SID cut down	es were removed from the ba on 8/16/18. 4/9/2007 a volunteer trees prior to the 3 4/9/2007 n volunteer trees prior to the ed by E&A inspector on 3/30/ 4/20/2007	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There 2/2020.	spection. Clean No out mark repainte No e is erosion at the No
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 42% outfall. E&A will monit Sediment Basin Good Condition - 42% outfall. E&A will monit Sediment Basin Good Condition - 49% E&A inspector on 3/30 Streets	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down 0/2020. North of Star grass Rd. belined - The SID cut down or. Cleanout mark repainter North of Star grass Rd. between 184th St and 182nd St 0 Filled - The SID cut down 0/2020. Entire Site	es were removed from the bases were removed from the bases on 8/16/18. 4/9/2007 volunteer trees prior to the set by E&A inspector on 3/30/ 4/20/2007 volunteer trees prior to the set by E&A inspector on 3/30/ 3/20/2007	Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There 2020. Active 2/23/16 inspection. There 2/23/16 inspection. Clean Active	No No No e is erosion at the No out mark repaint
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition:	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 48% outfall. E&A will monit Sediment Basin Good Condition - 42% outfall. E&A will monit Sediment Basin Good Condition - 49% E&A inspector on 3/30 Streets Good Condition - Stre 42, 50 and 86 prior to were cleaned in 182m	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. P Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down or. Cleanout mark repainter North of Star grass Rd. between 184th St and 182nd St 0 Filled - The SID cut down 0/2020. Entire Site ets in front of Lot 77 were inspection on 10/10/18. Sid d Circle prior to inspection	es were removed from the bases were removed from the bases on 8/16/18. 4/9/2007 volunteer trees prior to the set by E&A inspector on 3/30/ 4/20/2007 volunteer trees prior to the set by E&A inspector on 3/30/	Active Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There 2/23/16 inspection. There 2/23/16 inspection. Clean Active Active 1/2/23/16 inspection. Clean	No No out mark repaint No e is erosion at the No out mark repaint No saned in front of I on 12/4/18. Stre streets in front of o
Current Condition: SB 5 Current Condition: SB 6 Current Condition: SB 7 Current Condition: SB 8 Current Condition: STR	Good Condition - 31% mark repainted by E& Sediment Basin Removed - Basin was Sediment Basin Good Condition - 48% E&A inspector on 3/30 Sediment Basin Good Condition - 48% outfall. E&A will monit Sediment Basin Good Condition - 42% outfall. E&A will monit Sediment Basin Good Condition - 49% E&A inspector on 3/30 Streets Good Condition - Stre 42, 50 and 86 prior to were cleaned in 182m	184th St. Filled. The volunteer tree A inspector on 3/30/2020. East of 182nd Cir. closed prior to inspection Northeast of Star grass Rd. P Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down 0/2020. North of Star grass Rd. East of 182nd St. 0 Filled - The SID cut down or. Cleanout mark repainter North of Star grass Rd. between 184th St and 182nd St 0 Filled - The SID cut down 0/2020. Entire Site ets in front of Lot 77 were inspection on 10/10/18. Sid d Circle prior to inspection	on 8/16/18. 4/9/2007 volunteer trees prior to the 2 4/9/2007 volunteer trees prior to the 2 4/9/2007 n volunteer trees prior to the 2 4/20/2007 volunteer trees prior to the 2 3/20/2007 cleaned prior to inspection o treets were cleaned in 182nc on 6/24/19. Homestead Cus	Active Active Active 2/23/16 inspection. Clean Active 2/23/16 inspection. There 2/23/16 inspection. There 2/23/16 inspection. Clean Active Active 1/2/23/16 inspection. Clean	No No out mark repainte No e is erosion at the No out mark repainte No saned in front of I on 12/4/18. Stre streets in front of o

	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.			
Inspector Signature:	U.C.		Reviewed By:	