E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

No

Create Corrective Action?

Engineering Answers

Environmental Services Dept.		E	004				
		E&A - P2020.259	.001		T 0:		
Inspector: Josh Ellington			Stage				
		North H	ighlands		1		
Project Name:		CSW-202105801 7/6/2024					
For Week Ending:							
Project Location: 23rd Street & N Locust Street - Wahoo, NE (Saunders County) 68066							
Out all a su	050	v I			T		
Grading:	959						
Sanitary Sewer:	959	_					
Storm Sewer:	959						
Paving:	859						
Seeding:	25%						
Utilities:	95%						
Overall Development:	55%	%			1		
5.411.5.411.4.4.611N1 7 .							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Model		
Sunday	0.00"				Week 1		
Sunday:					<u> </u>		
Monday: Tuesday:	1.91" [07:15 - 09:55] 1.31" [22:35 - 13:55]	7/2/2024	Light rain 79	1:05 PM			
Wednesday:	0.00"	11212024	Light rain 79	1.05 PW	+		
Thursday:	0.00"	+			+		
Friday:	0.09	+			+		
Saturday:	0.00"	+			+		
Saturday.	0.09	_					
Compleinte							
Complaints:	 						
		1			T		
Construction Conversions							
Construction Sequencing:	e basins) of the site have had a te		ant acception of avading		d disturbance in the		
last 14 days?	basins) of the site have had a te	emporary or perman	ent cessation of grading,	earthwork, or ground	a disturbance in the		
Most of the site has been graded	d and paved prior to the first E&A ir	nspection on 6/6/24.					
Which portion(s) (i.e. drainage	e basins) of the site do not have	grading, earthwork,	or ground disturbance sc	heduled in the next 1	4 days?		
	d and paved prior to the first E&A ir						
	stabilization measures listed in	this section are bei	ig implemented?				
lwost of the site is vegetated whe	ere building is not active (6/6/24).						
Checklist Questions:							
1.) Are receiving waters adjacent to the	e project free of any significant signs of e	erosion or sediment that	would be associated with the cor	struction activity?			
Yes							
Create Corrective Action?							
N/A							
2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.							
Yes							
Create Corrective Action? NI/A							
N/A							
3) Are waste materials (concrete cons	struction material hazardous etc) being	managed properly?					

No - See BMP section 4.) Are construction entrances and adjacent streets being maintained adequately? Yes Create Corrective Action? i.) Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: Site was active for home construction during the last inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. **Unique Name** Location Projected Install Date Maintenance Type **Status** IF 1-6 Inlet filters On site 6/6/2024 Active No Good Condition - Inlet filter 5 was installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** Inlet filters On site No **Current Condition:** Good Condition - The inlet filter was installed prior to E&A inspections beginning on 6/6/24. IF 8-11 Inlet filters On site 6/6/2024 Active No Good Condition - Inlet filters 8 and 9 were installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 12-17 Inlet filters 6/6/2024 On site Active No Good Condition - Inlet filters 12, 13, 14, 15, and 16 were installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 18-19 On site 6/6/2024 Yes **Current Condition:** Fair Condition - Inlet filter 19 was installed prior to E&A inspections beginning on 6/6/24. Inlet filter should be cleaned out. Water Tower Place was informed to complete by 6/25/24. Not done as of last inspection. Inlet filters IF 20 On site 6/6/2024 Active Nο Good Condition - The inlet filter was installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 21-24 Inlet filters On site 6/6/2024 No Good Condition - Inlet filters 22 and 23 were installed prior to E&A inspections beginning on 6/6/24. Current Condition: IF 25-26 On site 6/6/2024 No **Current Condition:** Good Condition - The inlet filters were installed prior to E&A inspections beginning on 6/6/24. Lot 1 Individual Lot 6/11/2024 Good Condition - Lot is inactive and vegetated. A silt fence was installed prior to the 6/11/24 inspection. The silt fence **Current Condition:** was damaged during the 6/11/24 inspection; E&A inspector will monitor for maintenance. Lot 6 Individual Lot Lot 6 6/6/2024 Active No Good Condition - Scott and Tara Dailey began construction on the lot prior to E&A inspections beginning on 6/6/24. **Current Condition:** During the 6/6/24 inspection, damage was observed to the silt fence along the back of the lot; E&A inspector will monitor for maintenance. Lot 7 Individual Lot Lot 7 Removed Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. **Current Condition:** Lot 9 Individual Lot Lot 9 Removed **Current Condition:** Removed - Don Johnson Homes sodded the lot prior to the 6/25/24 inspection. Lot 10 Individual Lot Lot 10 Removed **Current Condition:** Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. Lot 11 Removed Individual Lot Lot 11 Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. **Current Condition:** Lot 16 Individual Lot Lot 16 Removed **Current Condition:** Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. Lot 17 Individual Lot Lot 17 6/6/2024 Active

Current Condition:	Fair Condition - Don Johnson Homes began construction and secured a portable toilet prior to E&A inspections beginning on 6/6/24. Don Johnson Homes partially sodded the lot prior to the 6/25/24 inspection. Don Johnson fully sodded the lot prior to the 7/2/24 inspection.						
	Portable toilet should be secured or removed. Don Johnson Homes was informed to complete by 7/2/24. Not done as of last inspection.						
Lot 18	Individual Lot	Lot 18	6/6/2024	Active	No		
Current Condition:	Good Condition - Janelle G 6/6/24.	ivens began construction	and secured a portable to	pilet prior to E&A inspe	ections beginning		
Lot 20	Individual Lot	Lot 20	6/6/2024	Active	No		
Current Condition:	Good Condition - Justin and beginning on 6/6/24.	_	truction and secured a po	rtable toilet prior to E&	A inspections		
Lot 23	Individual Lot	Lot 23		Removed			
Current Condition:	Removed - The lot was sod	Ided prior to E&A inspection	ons beginning on 6/6/24.				
Lot 37	Individual Lot	Lot 47	6/6/2024	Active	No		
Current Condition:	Good Condition - OnCenter the 6/11/24 inspection.	Construction began exca	avating the lot and installed	d silt fence in the sout	heast corner prior		
Lot 38	Individual Lot	Lot 38		Removed			
Current Condition:	Removed - The lot was sod	Ided prior to E&A inspection	ons beginning on 6/6/24.				
Lot 40	Individual Lot	Lot 47	6/6/2024	Active	No		
Current Condition:	Good Condition - OnCenter to the 6/11/24 inspection.	Construction began exca	avating the lot and installed	d silt fence in the sout	hwest corner prio		
Lot 47	Individual Lot	Lot 47	6/6/2024	Active	No		
Current Condition:	Good Condition - Water Tower LLC began grading the lot during the 6/6/24 inspection. Water Tower LLC installed and secured a portable toilet prior to the 6/11/24 inspection.						
Lot 50	Individual Lot	Lot 50		Removed			
Current Condition:	Removed - The lot was soo	Ided prior to E&A inspection	ons beginning on 6/6/24.	'			
Lot 56	Individual Lot	Lot 56	6/6/2024	Active	No		
Current Condition:	Good Condition - Justin and beginning on 6/6/24.	d Alicia Haun began const	truction and secured a po	rtable toilet prior to E8	A inspections		
SF 1	Silt Fence	Northeastern corner	6/6/2024	Active	Yes		
Current Condition:	Fair Condition - The silt fen Silt fence should be cleane		.ax inspections beginning	J 011 0/0/24.			
05.0	Water Tower Place was info			1	No		
SF 2	Silt Fence	Eastern perimeter	6/6/2024	Active	No		
Current Condition:	Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern	6/6/2024 E&A inspections beginnin	Active ng on 6/6/24.			
Current Condition: SF 2A	Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern perimeter	6/6/2024 E&A inspections beginnin 6/6/2024	Active ng on 6/6/24.	No No		
SF 2A Current Condition:	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to	6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginnin	Active ng on 6/6/24. Active ng on 6/6/24.	No		
SF 2A Current Condition: SF 3	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner	6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginnin 6/6/2024	Active ng on 6/6/24. Active ng on 6/6/24. Active Active			
SF 2A Current Condition:	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner ce was installed prior to Edd out.	6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active of on 6/6/24.	No		
SF 2A Current Condition: SF 3	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe Silt Fence Fair Condition - The silt fence Silt fence should be cleane	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner ce was installed prior to Edd out.	6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginnin 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active of on 6/6/24.	No		
SF 2A Current Condition: SF 3 Current Condition:	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe Silt Fence Fair Condition - The silt fen Silt fence should be cleane Water Tower Place was infe	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner ace was installed prior to Ed out. Ormed to complete by 6/20 Northwestern corner	6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active on 6/6/24. Active on 6/6/24. Active on 6/6/24. Active on 6/6/24.	No Yes		
SF 2A Current Condition: SF 3 Current Condition: SF 3 SF 4	Silt Fence Good Condition - The silt fer Silt Fence Good Condition - The silt fer Silt Fence Fair Condition - The silt fen Silt fence should be cleane Water Tower Place was info	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner ce was installed prior to Ed out. Tormed to complete by 6/20 Northwestern corner ence was installed prior to	6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active on 6/6/24. Active on 6/6/24. Active on 6/6/24. Active on 6/6/24.	No Yes		
SF 2A Current Condition: SF 3 Current Condition: SF 3 Current Condition:	Silt Fence Good Condition - The silt fe Silt Fence Good Condition - The silt fe Silt Fence Fair Condition - The silt fence Silt fence should be cleane Water Tower Place was info Silt Fence Good Condition - The silt fe	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner are was installed prior to Ed out. Northwestern corner ence was installed prior to Eastern perimeter	6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 5/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active g on 6/6/24. Active Jon 6/6/24. Active ng on 6/6/24. Active Active Active Active Active Active Active Active	No Yes No		
SF 2A Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 4 Current Condition: SB A Current Condition:	Silt Fence Good Condition - The silt fer Silt Fence Good Condition - The silt fer Silt Fence Fair Condition - The silt fer Silt fence should be cleane Water Tower Place was info Silt Fence Good Condition - The silt fer Sediment Basin	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner ce was installed prior to Ed out. Ormed to complete by 6/2s Northwestern corner ence was installed prior to Eastern perimeter d - The sediment basin was	6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 5/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning	Active ng on 6/6/24. Active ng on 6/6/24. Active g on 6/6/24. Active Jon 6/6/24. Active ng on 6/6/24. Active Active Active Active Active Active Active Active	No Yes No		
SF 2A Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 4 Current Condition: SB A	Silt Fence Good Condition - The silt fer Silt Fence Good Condition - The silt fer Silt Fence Fair Condition - The silt fer Silt fence should be cleane Water Tower Place was information - The silt fer Silt Fence Good Condition - The silt fer Sediment Basin Good Condition - 40% Fille	Eastern perimeter ence was installed prior to Southeastern perimeter ence was installed prior to Southwestern corner are was installed prior to E d out. Ormed to complete by 6/29 Northwestern corner ence was installed prior to Eastern perimeter d - The sediment basin was On site	6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 6/6/2024 E&A inspections beginning 5/24. Not done as of last if 6/6/2024 E&A inspections beginning 6/6/2024 as installed prior to E&A in	Active ng on 6/6/24. Active ng on 6/6/24. Active g on 6/6/24. Active g on 6/6/24. Active ng on 6/6/24. Active ng on 6/6/24. Active ng on 6/6/24. Active nspections beginning active	No Yes No No on 6/6/24.		

Current Condition:	·	be installed and concrete waste removed. ormed to complete by 6/13/24. Not done as of last	inspection. Don Johnson Homes was		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	H		Reviewed By:		