E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Engineering Answers

| Environmental Services Dept. Ma | | - | .04 | | | | | | |
|---|---|---|---------------------------------|----------------------------|-----------------------|--|--|--|--|
| Increase Inch Ellipoten | | &A - P2020.259.0 | 101 | | Ctarra | | | | |
| Inspector: Josh Ellington | | | Stage | | | | | | |
| | | North Highlands | | | | | | | |
| Project Name: | | CSW-202 | 105801 | | 1 | | | | |
| | | | | | | | | | |
| For Week Ending: | | 20000 | | | | | | | |
| Project Location: | 23rd Street & N Locust Street - Wahoo, NE (Saunders County) 68066 | | | | | | | | |
| | | T | | - | I | | | | |
| Grading: | 95% | | | | | | | | |
| Sanitary Sewer: | 95% | | | | | | | | |
| Storm Sewer: | 95% | | | | | | | | |
| Paving: | 85% | | | | | | | | |
| Seeding: | 25% | | | | | | | | |
| Utilities: Overall Development: | 95% | | | | | | | | |
| Overall Development: | 55% | 1 | | | | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Data isana atau | \\\ 4b C di4i | T: | | | | | |
| RAIN FALL AMOUNTS | Amount in tentis | Date inspected | Weather Conditions | Time | Week 1 | | | | |
| Sunday: | 0.00" | | | | week | | | | |
| Monday: | 0.00" | | | | | | | | |
| Tuesday: | 0.00" | 9/3/2024 | Sunny 81 | 5:40 PM | | | | | |
| Wednesday: | 0.00" | 0/0/2024 | - Cumy or | 0.401 III | | | | | |
| Thursday: | 0.00" | | | | | | | | |
| Friday: | 0.00" | | | | | | | | |
| Saturday: | 0.00" | | | | | | | | |
| | | • | | | | | | | |
| | | | | | | | | | |
| Complaints: | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Construction Sequencing: | | ' | | | | | | | |
| Which portion(s) (i.e. drainage ba | asins) of the site have had a ter | mporary or permanei | nt cessation of grading, | earthwork, or ground | disturbance in the | | | | |
| last 14 days? | | | | | | | | | |
| Most of the site has been graded ar | nd paved prior to the first F&A ins | spection on 6/6/24 | | | | | | | |
| • | · | • | | | | | | | |
| Which portion(s) (i.e. drainage ba | <u> </u> | | r ground disturbance so | heduled in the next 1 | 4 days? | | | | |
| Most of the site has been graded ar | nd paved prior to the first E&A ins | spection on 6/6/24. | | | | | | | |
| What temporary or permanent sta | abilization measures listed in the | his section are being | j implemented? | | | | | | |
| Most of the site is vegetated where | building is not active (6/6/24). | | | | | | | | |
| | | | | | | | | | |
| Checklist Questions: | | | | | | | | | |
| 1.) Are receiving waters adjacent to the pr | roject free of any significant signs of er | osion or sediment that wo | ould be associated with the co | nstruction activity? | | | | | |
| Yes | , , | | | , | | | | | |
| Create Corrective Action? | | | | | | | | | |
| N/A | | | | | | | | | |
| | | | | | | | | | |
| 2.) Have disturbed areas been seeded or o | otherwise stabilized as required? List ir | nactive portions of the pro | ject and if stabilization measu | res are adequate or needed | d to prevent erosion. | | | | |
| Yes | 11 14 11 2001 | , | | | • | | | | |
| Create Corrective Action? | | | | | | | | | |
| N/A | | | | | | | | | |

No - See BMP section 4.) Are construction entrances and adjacent streets being maintained adequately? No - See BMP section 5.) Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: Site was active for home construction during the last inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. **Unique Name** Location Projected Install Date Type **Status** Maintenance IF 1-6 Inlet filters On site 6/6/2024 Active No Good Condition - Inlet filter 5 was installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 7 Inlet filters On site No **Current Condition:** Good Condition - The inlet filter was installed prior to E&A inspections beginning on 6/6/24. IF 8-11 Inlet filters On site 6/6/2024 Active Nο Good Condition - Inlet filters 8 and 9 were installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 12-17 Inlet filters 6/6/2024 On site Active No Good Condition - Inlet filters 12, 13, 14, 15, and 16 were installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 18-19 On site 6/6/2024 Yes **Current Condition:** Fair Condition - Inlet filter 19 was installed prior to E&A inspections beginning on 6/6/24. Inlet filter 19 should be cleaned out. Water Tower Place was informed to complete by 6/25/24. Not done as of last inspection. Water Tower Place was reminded on 7/19/24. Inlet filters On site 6/6/2024 IF 20 Active No Good Condition - The inlet filter was installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 21-24 Inlet filters On site 6/6/2024 No Good Condition - Inlet filters 22 and 23 were installed prior to E&A inspections beginning on 6/6/24. **Current Condition:** IF 25-26 Inlet filters 6/6/2024 On site Active No **Current Condition:** Good Condition - The inlet filters were installed prior to E&A inspections beginning on 6/6/24. Lot 1 Lot 1 6/11/2024 Active No Good Condition - Lot is inactive and vegetated. A silt fence was installed prior to the 6/11/24 inspection. The silt fence Current Condition: was damaged during the 6/11/24 inspection; E&A inspector will monitor for maintenance. Lot 6 Individual Lot Lot 6 6/6/2024 Good Condition - Scott and Tara Dailey began construction on the lot prior to E&A inspections beginning on 6/6/24. **Current Condition:** During the 6/6/24 inspection, damage was observed to the silt fence along the back of the lot; E&A inspector will monitor for maintenance. Individual Lot Lot 7 Lot 7 Removed **Current Condition:** Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. Lot 9 Individual Lot Lot 9 Removed Removed - Don Johnson Homes sodded the lot prior to the 6/25/24 inspection. **Current Condition:** Lot 10 Individual Lot Lot 10 Removed Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. **Current Condition:** Lot 11 Individual Lot Lot 11 Removed Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. **Current Condition:** Lot 16 Individual Lot Lot 16 Removed **Current Condition:** Removed - The lot was sodded prior to E&A inspections beginning on 6/6/24. Lot 17 Individual Lot Lot 17 Removed

| | toilet prior to the 7/16/24 ins | spection. | | | - | |
|---------------------------|--|--|---|----------------------------|---------------|--|
| Lot 18 | Individual Lot | Lot 18 | | Removed | | |
| Current Condition: | Removed - Janelle Givens I 6/6/24. Janelle Gives sodde | | d secured a portable toilet pri 13/24 inspection. | ior to E&A inspections | beginning o | |
| Lot 19 | Individual Lot | Lot 19 | 7/30/2024 | Active | Yes | |
| Current Condition: | on 7/30/24. 1.) Portable toilet should I 2.) Silt fence or straw wate 1.) Alexander and Alexand | be secured. tles should be installe dria Janssen were info | excavating the lot and installed around the lot. ormed to complete by 9/10 ormed to complete by 9/10 | 1/24. | for to the in | |
| Lot 20 | Individual Lot | Lot 20 | 6/6/2024 | Active | Yes | |
| Current Condition: | Fair Condition - Justin and Alicia Haun began construction and secured a portable toilet prior to E&A inspections beginning on 6/6/24. Justin and Alicia Haun resecured the portable toilet prior to the 8/13/24 inspection. Perimeter controls should be installed at the back of the lot. Justin and Alicia Haun were informed to complete by 7/23/24. Not done as of last inspection. Justin and Alicia Haun were reminded on 8/8/24. | | | | | |
| Lot 21 | Individual Lot | Lot 21 | 8/13/2024 | Active | No | |
| Current Condition: | Good Condition - Don John | | avating the lot and secured a attles along the back of the l | a portable toilet prior to | | |
| Lot 23 | Individual Lot | Lot 23 | | Removed | | |
| Current Condition: | Removed - The lot was sod | ded prior to E&A inspe | ctions beginning on 6/6/24. | - | | |
| Lot 31 | Individual Lot | Lot 31 | | Removed | | |
| Current Condition: | Removed - The lot was sod | ded prior to E&A inspe | ctions beginning on 6/6/24. | | | |
| Lot 35 | Individual Lot | Lot 35 | | Removed | | |
| Current Condition: | Removed - OnCenter Cons | truction sodded the lot | prior to the 8/27/24 inspection | on. | | |
| Lot 37 | Individual Lot | Lot 37 | 6/6/2024 | Active | Yes | |
| Current Condition: | the 6/11/24 inspection. Perimeter controls should be | pe installed along the w | eavating the lot and installed estern side of the lot. by 7/23/24. Not done as of la | | | |
| Lot 38 | Individual Lot | Lot 38 | | Removed | | |
| Current Condition: | Removed - The lot was sod | ded prior to E&A inspe | ections beginning on 6/6/24. | - | | |
| Lot 40 | Individual Lot | Lot 47 | 6/6/2024 | Active | No | |
| Current Condition: | | | xcavating the lot and installed installed a portable toilet acro | | | |
| Lot 44 | Individual Lot | Lot 44 | | Removed | | |
| Current Condition: | Removed - The lot was sod | | | | | |
| Lot 46 | Individual Lot | Lot 46 | 7/30/2024 | Active | No | |
| Current Condition: | Active - OnCenter Construct BMP installation. | tion began excavating | the lot prior to the 7/30/24 in | spection. E&A inspec | tor will mon | |
| Lot 47 | Individual Lot | Lot 47 | 6/6/2024 | Active | No | |
| Current Condition: | Good Condition - Water Tove secured a portable toilet pri | | g the lot during the 6/6/24 ins ction. | pection. Water Tower | LLC install | |
| Lot 50 | Individual Lot | Lot 50 | | Removed | | |
| | Removed - The lot was sod | ded prior to E&A inspe | ections beginning on 6/6/24. | | | |
| Current Condition: | | Lot 51 | | | | |

| Lot 59-60 | Individual Lot | Lot 59-60 | | Removed | | |
|--------------------------|---|------------------------|--------------------------|-----------------|--------|--|
| Current Condition: | Removed - The lot was sod | | ons beginning on 6/6/24. | | | |
| Lot 57-58 | Individual Lot | Lot 57-58 | 6/6/2024 | Active | Yes | |
| Current Condition: | Fair Condition - OnCenter C | | | | | |
| | beginning on 6/6/24. OnCenter Construction installed a single-walled fuel tank prior to the 8/13/24 inspection. OnCent Construction removed the fuel tank prior to the 9/3/24 inspection. Street should be cleaned around the lots. | | | | | |
| | OnCenter Construction was | | | ast inspection. | | |
| SF 1 | Silt Fence | Northeastern corner | 6/6/2024 | Active | Yes | |
| Current Condition: | Fair Condition - The silt fence was installed prior to E&A inspections beginning on 6/6/24. Silt fence should be cleaned out. Water Tower Place was informed to complete by 6/25/24. Not done as of last inspection. Water Tower Place was reminded on 7/19/24. | | | | | |
| SF 2 | Silt Fence | Eastern perimeter | 6/6/2024 | Active | No | |
| Current Condition: | Good Condition - The silt fence was installed prior to E&A inspections beginning on 6/6/24. Damage was observed to the silt fence during the 7/9/24 inspection; the area is well-vegetated and the E&A inspector will monitor for maintenance. | | | | | |
| SF 2A | Silt Fence | Southeastern perimeter | 6/6/2024 | Active | No | |
| Current Condition: | Good Condition - The silt fe | <u> </u> | | | | |
| SF 3 | Silt Fence | Southwestern corner | 6/6/2024 | Active | Yes | |
| SF 4 | Water Tower Place was informed on 7/19/24. Silt Fence | Northwestern corner | 6/6/2024 | Active | No | |
| Current Condition: | Good Condition - The silt fe | | | | 140 | |
| SB A | Sediment Basin | Eastern perimeter | 6/6/2024 | Active | No | |
| Current Condition: | Good Condition - 40% Filled | | | | | |
| SWPPP Sign | SWPPP Notification Sign | On site | 7/2/2024 | Active | No | |
| Current Condition: | Good Condition - E&A inspe | | | | 140 | |
| WO 1 | Concrete washout pit | On site | 6/13/2024 | Pending | Yes | |
| Current Condition: | Pending - 1.) Concrete washout pit should be installed and concrete waste removed. 2.) Concrete waste by Lot 30 should be removed. 1.) Don Johnson Homes was informed to complete by 6/13/24. Not done as of last inspection. Don Johnson Homes w reminded on 6/27/24, 7/19/24 2.) Water Tower Place was informed to complete by 7/23/24. Not done as of last inspection. | | | | | |
| Certification Statement: | "I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations." | | | | | |
| pector Signature: | Jet | | | Reviewed By: | Set Se | |