E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dent Manager

Engineering Answers

Plattsmouth Historic High School Housing and New Apartments				A- P2022.261.001	E8		
Project Name: S/13/2023 S/13/2023	Stage	Anderson					
For Week Ending: 5/13/2023	1	ırtments	Project Name:				
RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Time	68003		5/13/2023				
Sanitary Sewer: 50%			Cass County)	in St Plattsmouth, NE (C	814 Ma		
Sanitary Sewer: 50%							
Storm Sewer: 50%							
Paving: 50%							
Seeding:							
Utilities: 50%							
Date inspected Date inspected Weather Conditions Time							
RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Time Sunday: 0.30"							
Sunday: 0.30" Monday: 0.24" Tuesday: 0.00" Wednesday: 0.04" 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00"				·	50%	Overall Development:	
Sunday: 0.30" Monday: 0.24" Tuesday: 0.00" Wednesday: 0.04" 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00"							
Monday: 0.24" Tuesday: 0.00" Wednesday: 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00"	Storm Event Times	Time	Weather Conditions	Date inspected	Amount in tenths	RAIN FALL AMOUNTS	
Monday: 0.24" Tuesday: 0.00" Wednesday: 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00"	Week						
Tuesday: 0.00" Wednesday: 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00"	8:15PM - 11:55PM				0.30"	Sunday:	
Wednesday: 0.04" 5/10/2023 Sunny 83/59 1:00 PM Thursday: 0.00" Friday: 0.00" Saturday: 0.00" Indicate the part of the	12:15AM - 1:55AM				0.24"	Monday:	
Thursday: 0.00" Friday: 0.00" Saturday: 0.00"					0.00"	Tuesday:	
Friday: 0.00" Saturday: 0.00" None		1:00 PM	Sunny 83/59	5/10/2023	0.04"	Wednesday:	
Saturday: 0.00" None					0.00"	Thursday:	
None					0.00"	Friday:	
Complaints: None					0.00"	Saturday:	
Complaints: None				•			
					None	Complaints:	
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?							

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

hat temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Site was active during the current inspection.

Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):
 1.) Some maintenance required in the BMP Section
 2.) Disturbed area to the south east should be stabilized. Lund Ross was informed to complete by 11/16/22. Not done as of last inspection. Lund Ross reminded on 12/5/23, 2/3/23.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
ČE 01	Construction Entrance	D2		Removed	
Current Condition:	Removed- Lund Ross paved the construction	ction entrance prior to the ins	spection on 11/16/22.	•	
CE 02	Construction Entrance	M11	1	Removed	
Current Condition:	Removed- Lund Ross paved the rest con	struction entrance prior to th	e inspection on 11/16/22.		
IF 01	Inlet Filter	A7	11/16/2022	Pending	Yes
Current Condition:	Pending - Lund Ross cleaned off inlet			, onang	100
Current Condition.	rending - Lund Ross cleaned on linet	prior to inspection on 3/10/	123.		
	Index Silver about the investigation				
	Inlet filter should be installed.				
	Land December 1 of the Land Land	44/40/00 Not love on the	North Association of Bridge	404	JE 100 010100 AJE 100
	Lund Ross was informed to complete by	1 1/16/22. Not done as of las	i inspection. Lund Ross w	vas reminded on 12/	5122, 213123, 415123
IF 02	Inlet Filter	A9	11/16/2022	Pending	Yes
Current Condition:	Pending - Lund Ross cleaned off inlet	prior to inspection on 5/10	/23.		
	Inlet filter should be installed.				
	Lund Ross was informed to complete by	11/16/22 Not done as of las	st inspection Lund Ross v	vas reminded on 12/	5/22 2/3/23 4/5/23
	Zama riese mae imerimea te semprete zy	,	t moposiism Zana i toos t	140 10111111404 011 121	0/22, 2/0/20, 1/0/20
IF 03	Inlet Filter	B10	11/16/2022	Active	No
Current Condition:	Good Contition - Lund Ross installed a si				I INU
				3/23.	
MS 01	Material Storage	On Site	9/30/2022	Active	No
Current Condition:	Good Condition- Lund Ross stored mater	rial is organized designated	areas prior to the inspecti-	on on 11/9/22.Lund	Ross is using parking
	lot near SB A used as material storage, in	ncluding lumber prior to the i	inspection on 2/8/23.		
DD 04		T 0.00		T	
PB 01	Portable Toilet	On Site	9/30/2022	Active	No
Current Condition:	Good Condition - Lund Ross installed and			2 inspection. The poi	table toilets on site
	were adequately secured with pallets aga	ainst the side of an existing b	ouilding.		
PB 02	Portable Toilet	On Site	5/10/2023	Active	Yes
Current Condition:	Fair Condition - Lund Ross installed a	set of portable toilets price	r to the 5/10/23 inspecti	on.	
	PT needs to be secured.				
	r i fleeus to be secureu.				
	Land Barrell Street and Assessment and	h 5140/00			
SB A	Lund Ross was informed to complete Sediment Basin	B3	9/30/2022	Pending	Yes
Current Condition:	Pending - Inlet and outfall for the basin a		*****		
Current Condition:			nor to the inspection on 4	120/23. Lunu Ross II	ned in the undermined
	inlet and outfall prior to the inspection on	5/3/23.			
	The sediment basin should be installed p	er SWPPP, including outfall	cleanout and repair.		
	Lund Ross was informed to complete by	11/02/22. Not done as of las	st inspection. Lund Ross v	vas reminded on 11/	10/22, 12/5/22, 2/3/23
	4/5/23		· ·		
OD D				·	
SB B	Sediment Basin	G14	9/30/2022	Pending	Yes
Current Condition:	Pending -				
	The sediment basin should be installed p	er SWPPP.			
	Lund Ross was informed to complete by	11/02/22. Not done as of las	st inspection. Lund Ross w	vas reminded on 11/	10/22, 12/5/22, 2/3/23
	4/5/23				
SF 01	Silt Fence	A2-D2	9/28/2022	Active	Yes
Current Condition:	Fair Condition- Lund Ross installed silt fe	ence prior to the 9/28/22 insp	ection. Lund Ross exter	ded the silt fence	up the CE and
	installed the remaining section on the				- p
	installed the remaining section on the	South side of the OL prior	to the inspection on or	10/20.	
	4) Additional ailt fance aback is a state	to the north			
	1.) Additional silt fence check is needed to				
	2.) Area above SF 01 should be stabilize	d.			
	1.) Lund Ross was informed to complete	by 11/16/22. Not done as of	last inspection. Lund Ros	ss was reminded on	12/5/22, 2/3/23, 4/5/2
	2.) Lund Ross was informed to complete	by 4/12/23. Not done as of I	ast inspection		
SF 02	Silt Fence	A3-H12	9/30/2022	Pending	Yes
Current Condition:	Pending - For consistency, silt fence nort		ignated as SF 02 for future		
	maintenance plans on 2/3/23.	, 100.			
	, p 2 or 2 or 2 or 2 or 2 or 2 or 2 o				
	Silt fence should be installed.				
	5 Torroo orionia de instanca.				
	Lund Poss was informed to sometate but	11/16/22 Not done as of last	at inapportion Lund Deserv	vac reminded on 404	5100 010100 AIE100
	Lund Ross was informed to complete by	TITOTZZ. NOT done as of las	i inspection. Luna Ross W	vas reminded on 12/	JIZZ, ZIJIZJ, 4/5/23
SF 03	Silt Fence	G12-N15	9/30/2022	Pending	Yes
Current Condition:	Pending - The silt fence will be installed of				
	across future reports, SWPPP maps, and	d maintenance plans, this rur	n of silt fence will be design	gnated as SF 03, as	of 2/3/23.
	Silt fence should be installed.				
	Lund Ross was informed to complete by	11/16/22 Not done as of los	st inspection Lund Rose w	vas reminded on 12/	5/22 2/3/23 4/5/22
	Euria Ross was informed to complete by	11/10/22: 110t dollo do 01 lac	t mopostion Lana 11000 1	rao rominada dir 12,	0/22. 2/0/20, 4/0/20
	Lund 1033 was informed to complete by	11/10/22. 1101 45115 45 51 145	opoduom Euna 11000 i	140 10111111404 011 121	G/22. 2/6/26, 4/6/26
SE 04			1		1
SF 04	Silt Fence	E1-E4		Removed	1

Current Condition:	Removed- Silt fence is uphill of disturbed	area. There is no recommen	ndation for this BMP as o	f the 11/30/22 inspe	ection.		
STR	Streets	ADJ and Internal Streets	9/30/2022	Active	Yes		
Current Condition:	Fair Condition- A trail of escaped sediment was observed along the street curb on N 10th st traveling all the way down to Washington Ave. The interior and exterior streets should be cleaned. Lund Ross was informed to complete by 4/26/23. Not done as of last inspection						
SW 1	Straw Wattles	Main St	5/10/2023	Active	No		
Current Condition:	Good Condition - Lund Ross installed 5/10/23.	straw wattles along the so	outh side of property alc	ong Main St. prior to	o the inspection on		
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the SWPPP sign with the correct permit information website during the 12/21/22 inspection.						
WO 01	Concrete Washout	On site	9/30/2022	Active	Yes		
	concrete washout bin onsite prior to the inspection on 11/30/22. More concrete waste was observed during the 2/8/23 inspection. It effort to utilize the concrete washout bin onsite is needed. More concrete waste was observed escaping designated areas during the 2/22/23 inspection. Concrete mixing bucket was removed prior to the 3/8/23 inspection. 1.) Concrete waste near the material storage (H13) should be cleaned up. 2.) A concrete washout should be installed on site. 1.) Lund Ross was informed to complete by 2/8/23. Not done as of the last inspection. Lund Ross was reminded on 4/5/23. 2.) Lund Ross was informed to complete by 3/1/23. Not done as of the last inspection. Lund Ross was reminded on 4/5/23.						
WS 01	Waste storage	On site	3/22/2023	Active	No		
Current Condition:	Active - Additional waste storage on site was observed during the inspection on 3/22/23.						
Certification Statement	"I certify, under penalty of law, that this do with a system designed to assure that qui inquiry of the person or persons who man information submitted is, to the best of my penalties for submitting false information	alified personnel properly ga nage the system or those per y knowledge and belief, true	thered and evaluated the sons directly responsible , accurate, and complete.	information submitte for gathering the inf I am aware that the knowing violations."	ed. Based on my ormation, the re are significant		
spector Signature:	En Chale			Reviewed By:			