E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E	&A- P2022.261.001							
Inspector: Ethan Anderson		Stage							
Project Name:	Plattsmouth Historic	1							
For Week Ending:		68003							
Project Location:	814 Ma	814 Main St Plattsmouth, NE (Cass County)							
Grading:	80%								
Sanitary Sewer:	100%								
Storm Sewer:	100%)							
Paving:	70%								
Seeding:	50%	1							
Utilities:	50%	,							
Overall Development:	70%	,							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times				
					Week '				
Sunday:	0.00"								
Monday:	0.00"								
Tuesday:	0.00"								
Wednesday:	0.00"	12/6/2023	Sunny 57/28	1:15 PM					
Thursday:	0.00"								
Friday:	0.00"								
Saturday:	0.00"								

Construction Sequencing:

Complaints:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days'

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

None

Existing Vegetation (9/21/22). Sod installation around north building (11/8/23). Seed and matting installed in SB A (11/8/23). Seed and matting installed along the west entrance and adjacent slope (11/15/23). Seed and matting installed along the north perimeter and west entrance parking lot edges (11/22/23).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

No. See BMP Section

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed No

Create Corrective Action?

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

lo, See BMP Section.

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:
1.) Site was active during the current inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance required in the BMP Section.

	_			-	
Unique Name CE 01	Type Construction Entrance	Location D2	Projected Install Date	Status Removed	Maintenance
Current Condition:	Removed- Lund Ross paved the construction		spection on 11/16/22.	Removed	
CE 02	Construction Entrance	M11	14/40/00	Removed	
Current Condition: CW 1	Removed- Lund Ross paved the rest con Concrete washout	West entrance prior to tr	11/22/2023	Active	No
Current Condition:	Good Condition - Lund Ross installed 2 p				
CIM 2	washouts to one location near the west e		ne inspection on 11/29/23.	D	I
CW 2 Current Condition:	Concrete washout Removed - Lund Ross removed the cond	N 10th St	pection on 11/29/23	Removed	
EM 01	Erosion Control Matting	West entrance	11/15/2023	Active	Yes
Current Condition:	Fair Condition - Lund Ross installed matt		n 11/15/23.		
	Lund Ross was informed to complete by		st inspection.		
IF 01	Inlet Filter	A7		Removed	
Current Condition: IF 02	Removed - Lund Ross installed sod arou Inlet Filter	nd the inlet prior to the inspect A9	ection on 11/8/23.	Removed	I
Current Condition:	Removed - Lund Ross installed sod arou		ection on 11/8/23.	Removed	
IF 03	Inlet Filter	B10		Removed	
Current Condition:	Removed - Lund Ross installed sod arou		ection on 11/8/23.	Demonstrat	I
IF 04 Current Condition:	Inlet Filter Removed - Lund Ross paved around t	H11	tion on 12/6/23	Removed	
IF 05	Inlet Filter	H12	LICITED I	Removed	
Current Condition:	Removed - Lund Ross paved around t				
IF 06 Current Condition:	Inlet Filter Active- Lund Ross installed the inlet and	K13	et prior to the inspection of	Active n 11/29/23	No
IF 07	Inlet Filter	K13	12/6/2023	Active	No
Current Condition:	Active- Lund Ross installed the inlet a	nd began paving around t	he inlet prior to the insp	ection on 12/6/23.	
IF 08	Inlet Filter	K13	12/6/2023	Active	No
Current Condition: MS 01	Active- Lund Ross installed the inlet a Material Storage	On Site	9/30/2022	Active	No
Current Condition:	Good Condition- Lund Ross stored mater				
	near SB A used as material storage, incli		<u> </u>		
PB 01 Current Condition:	Portable Toilet Good Condition - Lund Ross installed and	On Site	9/30/2022	Active	No
Current Condition:	adequately secured with pallets against t				
	against the wall prior to the inspection	n on 12/6/23.	<u> </u>		
PB 02	Portable Toilet	On Site		Removed	
Current Condition: SB A	Removed - Lund Ross removed the po Sediment Basin/swale/drainage ditch		nspection on 12/6/23.	Removed	
Current Condition:	Removed - Lund Ross installed matting a	and seeded in the swale/dra		pection on 11/8/23.	
SB B	Sediment Basin/swale/drainage ditch	G14	9/30/2022	Pending	Yes
Current Condition:	Pending - Lund Ross was actively working the basin/swale/drainage ditch prior to the				
	to the inspection 8/2/23. Lund Ross finish	ned shaping the sides and bo	ottom of the basin/swale/d	rainage ditch prior to	the inspection on
	10/4/23. Lund Ross began installing the p	oost construction clean out p	oorts in the basin/swale/dra	ainage ditch prior to	the inspection on
	1.) The sediment basin should be installed	ed per SWPPP.			
	2.) Inlet protection should be installed are	ound inlet.			
	1.) Lund Ross was informed to complete	by 11/02/22 Not done so of	Flast inspection Lund Dec	o was reminded on	11/10/00 10/5/00
	2/3/23, 4/5/23, 5/10/23, 5/31/23, 6/7/23, 7	•		s was reminded on	11/10/22, 12/5/22,
	2.) Lund Ross was informed to complete			was reminded on 8	/9/23, 9/7/23, 10/19/23,
CE 0.4	11/16/23	40 D0		Demant 4	I
SF 01 Current Condition:	Silt Fence Removed - Lund Ross removed the silt fe	A2-D2 ence prior to the inspection of	n 11/29/23.	Removed	l
SF 02	Silt Fence	A3-H12	9/30/2022	Pending	Yes
Current Condition:	Pending - For consistency, silt fence nort maintenance plans on 2/3/23.	h of SB A was correctly des	ignated as SF 02 for future	e reports, SWPPP m	nap updates and
	Silt fence should be installed.				
	Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9/		st inspection. Lund Ross w	as reminded on 12/	5/22, 2/3/23, 4/5/23,
SF 03	Silt Fence	G12-N15	9/30/2022	Pending	Yes
Current Condition:	Pending - The silt fence will be installed of future reports, SWPPP maps, and maintenance.				
	Silt fence should be installed.				
05.04	Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9/	7/23, 10/19/23, 11/16/23	st inspection. Lund Ross w		5/22. 2/3/23, 4/5/23,
SF 04 Current Condition:	Silt Fence Removed- Silt fence is uphill of disturbed	E1-E4 Larea There is no recomme	I endation for this RMP as of	Removed the 11/30/22 inspe	ction
Guildin Golianion.					

STR	Streets	ADJ and Internal Streets	9/30/2022	Active	Yes		
Current Condition:	Fair Condition- A trail of escaped sediment was observed along the street curb on N 10th st traveling all the way down to Washington Ave. Lund Ross cleaned the interior streets prior to the inspection on 7/5/23. Lund Ross cleaned the internal streets prior to the inspection on 8/23/23. Lund Ross was in the process of cleaning the eastern streets during the inspection on 10/18/23. The internal streets and sidewalk should be cleaned and at the southeast corner of the site. Lund Ross was informed to complete by 7/6/23. Not done as of last inspection. Lund Ross was reminded on 8/9/23, 9/7/23, 10/19/23,						
SW 1	11/16/23 Straw Wattles	Main St		Removed			
Current Condition:	Removed - Lund Ross removed the wa		idowalk prior to the incr				
SW 2	Straw Wattles	N 10th St	11/22/2023	Active	No		
Current Condition:	Good Condition - Lund Ross installed str		,				
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	Yes		
	SWPPP sign with the correct permit infor SWPPP sign should be recovered and re Lund Ross was informed to complete by						
WO 01	Concrete Washout	On site		Removed			
Current Condition:	Removed - Lund Ross installed a concrete washout on site prior to the inspection on 12/6/23. All recommendations will be unde						
WS 01	Waste storage	On site	3/22/2023	Active	No		
Current Condition:	Active - Additional waste storage on site	was observed during the ins	pection on 3/22/23.		•		
Certification Statement	"I certify, under penalty of law, that this di a system designed to assure that qualified the person or persons who manage the s submitted is, to the best of my knowledge submitting false information including the	d personnel properly gathere ystem or those persons direct and belief, true, accurate, a	ed and evaluated the infor otly responsible for gather and complete. I am aware	mation submitted. E ring the information, that there are signif ations."	lased on my inquiry of the information icant penalties for		
spector Signature:	En Center			Reviewed By:	to Sil		