E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Engineering Answers** 

Environmental Services Dept.		E&A- P2022.261.00	1		
nspector: Ethan Anderson		LGA- F 2022.201.00			Stage
Project Name:	Plattsmouth Histori	1 68003			
For Week Ending:					
Project Location:	814 1				
Grading:	I QF	5%		T	
Sanitary Sewer:	100				
Storm Sewer:	100	1%			
Paving:	99	9%			
Seeding:	50	0%			
Utilities:	99	9%			
Overall Development:	85	5%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times
					Week
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	2/14/2024	Sunny 63/34	2:45 PM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				

## **Construction Sequencing:**

n(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

nich portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22). Sod installation around north building (11/8/23). Seed and matting installed in SB A (11/8/23). Seed and matting installed along the west entrance and adjacent slope (11/15/23). Seed and matting installed along the north perimeter and west entrance parking lot edges (11/22/23).

## **Checklist Questions:**

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed

Create Corrective Action?

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

4.) Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

5.) Is dust associated with the construction activity adequately controlled on the site?

**Create Corrective Action?** 

N/A

Comments:
Comments:
1.) Site was active during the current inspection.

- Findings / Corrective Actions (Date):

  Findings / Corrective Actions (Date):

  1.) Some maintenance required in the BMP Section.

  2.) Disturbed areas should be stabilized per SWPPP. Lund Ross was informed to complete by 12/27/23. Not done as of last inspection.

	zeu per SWPPP. Lunu Ross was miormeu						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	D2	.,	Removed			
Current Condition:	Removed- Lund Ross paved the construc	tion entrance prior to the in	spection on 11/16/22.				
CE 02	Construction Entrance M11 Removed  Removed- Lund Ross paved the rest construction entrance prior to the inspection on 11/16/22.						
Current Condition:				A .45	l N.		
CW 1 Current Condition:	Concrete washout Good Condition - Lund Ross installed 2 p	West entrance	11/22/2023	Active	No No		
Current Condition:							
	washouts to one location near the west entrance to the site prior to the inspection on 11/29/23. Lund Ross installed an additional concret washout on N 10th St prior to the inspection on 12/13/23. Lund Ross moved the concrete washout to near the south entrance to the site						
	prior to the inspection on 12/20/23.						
CW 2	Concrete washout	N 10th St		Removed			
Current Condition:	Removed - Lund Ross removed the conc						
EM 01	Erosion Control Matting	West entrance	11/15/2023	Active	Yes		
Current Condition:	Fair Condition - Lund Ross installed matting prior to the inspection on 11/15/23.  Matting should be properly secured around the outfall.						
	Matting should be properly secured aroun	iu trie outiali.					
	Lund Ross was informed to complete by	11/22/23 Not done as of las	st inspection Lund Ross v	vas reminded on 12/	21/23		
IF 01	Inlet Filter	A7	Lana Hoos I	Removed			
Current Condition:	Removed - Lund Ross installed sod arou	nd the inlet prior to the inspe	ection on 11/8/23.				
IF 02	Inlet Filter	A9		Removed			
Current Condition:	Removed - Lund Ross installed sod around the inlet prior to the inspection on 11/8/23.						
IF 03	Inlet Filter	B10		Removed			
Current Condition: IF 04	Removed - Lund Ross installed sod arou		ection on 11/8/23.	Damasuad	1		
Current Condition:	Removed - Lund Ross paved around the	H11	n 12/6/23	Removed			
IF 05	Inlet Filter	H12	12/0/23.	Removed			
Current Condition:	Removed - Lund Ross paved around the		on 12/6/23.	1.0			
IF 06	Inlet Filter	K13	11/29/2023	Active	No		
Current Condition:	Active- Lund Ross installed the inlet and	began paving around the inl	et prior to the inspection of	n 11/29/23.			
IF 07	Inlet Filter	K13	12/6/2023	Active	No		
Current Condition:	Active- Lund Ross installed the inlet and						
IF 08 Current Condition:	Inlet Filter Active- Lund Ross installed the inlet and	K13	12/6/2023	Active	No		
MS 01	Material Storage	On Site	9/30/2022	Active	No		
Current Condition:	Good Condition- Lund Ross stored mater						
	near SB A used as material storage, inclu						
PB 01	Portable Toilet	On Site	9/30/2022	Active	No		
Current Condition:	Good Condition - Lund Ross installed and						
	adequately secured with pallets against t						
	wall prior to the inspection on 12/6/23. Lu 12/20/23.	ina Ross moved and reposit	lioned the portable tollets	against the building	prior to the inspection on		
PB 02	Portable Toilet	On Site	I	Removed	1		
Current Condition:	Removed - Lund Ross removed the porta		ction on 12/6/23	Removed			
SB A	Sediment Basin/swale/drainage ditch	B3	12,0,20.	Removed			
Current Condition:	Removed - Lund Ross installed matting a	and seeded in the swale/dra	inage ditch prior to the ins	pection on 11/8/23.	•		
SB B	Sediment Basin/swale/drainage ditch	G14	9/30/2022	Pending	Yes		
Current Condition:	Pending - Lund Ross was actively working						
	the basin/swale/drainage ditch prior to the inspection on 6/14/23. Lund Ross was shaping and grading the basin/swale/drainage ditch prior						
	to the inspection 8/2/23. Lund Ross finished shaping the sides and bottom of the basin/swale/drainage ditch prior to the inspection on 10/4/23. Lund Ross began installing the post construction clean out ports in the basin/swale/drainage ditch prior to the inspection on						
	10/4/23. Lund Ross began installing the post construction clean out ports in the basin/swale/drainage ditch prior to the inspection on 11/1/23.						
	1.) The sediment basin should be installed per SWPPP.						
	2.) Inlet protection should be installed arc	ound inlet.					
	1.) Lund Ross was informed to complete			ss was reminded on	11/10/22, 12/5/22,		
	2/3/23, 4/5/23, 5/10/23, 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9/7/23, 10/19/23, 11/16/23, 12/21/23 2.) Lund Ross was informed to complete by 7/12/23. Not done as of last inspection. Lund Ross was reminded on 8/9/23, 9/7/23, 10/19/23,						
	11/16/23, 12/21/23	by 7/12/23. Not dolle as of t	ast inspection. Lund Ross	was reminded on o	19123, 911123, 10/19/23,		
SF 01	Silt Fence	A2-D2		Removed			
Current Condition:	Removed - Lund Ross removed the silt fe		on 11/29/23.		1		
SF 02	Silt Fence	A3-H12	9/30/2022	Pending	Yes		
Current Condition:	Pending - For consistency, silt fence nort						
	maintenance plans on 2/3/23.						
	Silt fence should be installed.						
		444000 N 4			5/00 0/0/00 1/5/00		
	Lund Ross was informed to complete by			vas reminded on 12/	5/22, 2/3/23, 4/5/23,		
05.00	5/3/23, 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9/						
SF 03	Silt Fence	G12-N15	9/30/2022	Pending	Yes		

Current Condition:	Pending - The silt fence will be installed					
	future reports, SWPPP maps, and maintenance plans, this run of silt fence will be designated as SF 03, as of 2/3/23.  Silt fence should be installed.					
	Silt ferice should be installed.					
	Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9			vas reminded on 12/5	/22. 2/3/23, 4/5/23,	
SF 04	Silt Fence	E1-E4		Removed		
Current Condition:	Removed- Silt fence is uphill of disturbe	d area. There is no recommer	ndation for this BMP as o	f the 11/30/22 inspec	tion.	
STR	Streets	ADJ and Internal Streets	9/30/2022	Active	Yes	
Current Condition:	Fair Condition- A trail of escaped sedim	ent was observed along the s	treet curb on N 10th st tra	aveling all the way do	wn to Washington Ave	
	Lund Ross cleaned the interior streets prior to the inspection on 7/5/23. Lund Ross cleaned the internal streets prior to the inspection on					
	8/23/23. Lund Ross was in the process of	<mark>of cleaning the eastern streets</mark>	during the inspection on	10/18/23. Lund Ross	scraped the streets	
	and sidewalk prior to the inspection on 1	1/17/24.				
	Street and sidewalk should be cleaned at Main St and 8th St.					
	Lund Ross was informed to complete by 2/1/24. Not done as of last inspection.					
SW 1	Straw Wattles	Main St	ispection.	Removed		
Current Condition:	Removed - Lund Ross removed the wat		alk prior to the increation			
SW 2	Straw Wattles	N 10th St	11/22/2023	Active	No	
Current Condition:	Good Condition - Lund Ross installed straw wattles along the western slope of property along S 10th St prior to the inspection on 11/22/					
current condition.	Cood Condition - Edita 1033 installed 3t	naw watties along the western	i slope of property along	o tour or prior to the	mopeodon on 11/22/20	
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	Yes	
Current Condition:	Fair Condition - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the					
	SWPPP sign with the correct permit information website during the 12/21/22 inspection.					
	SWPPP sign should be recovered and reinstalled.					
	Lund Ross was informed to complete by	<mark>/ 11/22/23. Not done as of las</mark>	t inspection. Lund Ross v	vas reminded on 12/2	1/23.	
WO 01	Concrete Washout	On site		Removed		
Current Condition:	Removed - Lund Ross installed a concre	ete washout on site prior to the	e inspection on 12/6/23.	All recommendations	will be under CW 1.	
WS 01	Waste storage	On site	3/22/2023	Active	No	
Current Condition:	Active - Additional waste storage on site was observed during the inspection on 3/22/23.					
Certification Statement	"I certify, under penalty of law, that this of			direction or supervis	ion in accordance with	
	a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of					
	the person or persons who manage the system or those persons directly responsible for gathering the information, the information					
	submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for					
	submitting false information including the possibility of fines and imprisonment for knowing violations."					
	"	, ,				
	/ / /			G.	411	
	En Castar			6.	to Sol	