E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services De	pu manage.	E&A - P2	021.167.005			
Inspector: Jason Brackett		Stage				
	Ponde	Ponderosa Place (Seventy-Two Place South) PAP-20230221-6811-GP1				
Project Name:		68133				
For Week Ending:						
Project Location:	SE of Ponderos					
Grading:	55%					
Sanitary Sewer:	0%					
Storm Sewer:	0%					
Paving:	0%	,				
Seeding:	0%	,				
Utilities:	0%	,				
Overall Development:	6%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
<u> </u>					Week	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"					
Friday:	0.00"	9/13/2024	Mostly Sunny 87/59	1:35 PM		
Saturday:	0.00"					
Complaints:	None.		·			

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading in the northeast corner began (12/6/23). Grading ceased (12/21/23). Grading started east side of site (7/17/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading in the northeast corner began (12/6/23). Grading ceased (12/21/23). Grading started east side of site (7/17/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (12/6/23).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

. ...

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMPs section.

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No, see BMPs section.

s dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments: Site was active for grading.

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 01	Construction Entrance	NW Corner	8/16/2024	Active	Yes

Current Condition:	Fair Condition - 40% Effective - Ruff began installing an entrance prior to the 8/7/24 inspection, the inspector will continue to						
	monitor. Ruff finished installing the construction entrance prior to the 8/16/24 inspection.						
	Additional rock needs to be added.						
	Ruff Grading was informe	d to complete by 9/6/24	Not done as of the last inspe	ection.			
D 01	Diversion	SW of SB A	3/3/2024	Pending	Yes		
Current Condition:	Pending -						
	The diversion should be installed with sediment basin installation.						
	Ruff Grading was informe	d to complete by 9/6/24	Not done as of the last inspe	ection.			
D 02	Diversion	SE of SB A	3/3/2024	Pending	Yes		
Current Condition:	Pending - The diversion w	vill be installed with SB A	A. D 02 is not specifically insta	alled; however, the sw	vale is graded as of the		
	8/16/24 inspection, D 02 will be added when basin is constructed.						
	The diversion should be in	nstalled with sediment b	asin installation.				
	Ruff Grading was informe	d to complete by 9/6/24.	Not done as of the last inspe	ection.			
D 03	Diversion	N of SB B1	3/3/2024	Pending	Yes		
Current Condition:	Pending -	14 01 00 01	3/3/2024	rending	163		
Carroni Condition.	1 Orlaing						
	The diversion should be in	nstalled with sediment b	asin installation.				
	Ruff Grading was informe	d to complete by 9/6/24	Not done as of the last inspe	ection.			
D 04	Diversion	SB B1 to SB B2	3/3/2024	Pending	Yes		
Current Condition:	Pending -						
	The diversion should be in	nstalled with sediment b	asın ınstallatıon.				
	Buff Crading was informa	d to complete by 0/6/24	Not done as of the last inspe	notion			
D.O.F	, and the second		Thot dolle as of the last inspe		I		
D 05	Diversion	SE of SB B2	2/04	Removed			
Current Condition: D 06	Removed - Revision remo	E of SB A	8/23/2024	Active	No		
Current Condition:			of the diversion prior to the ins		INO		
D 07	Diversion	NE Corner of Site	6/1/2024	Pending	Yes		
Current Condition:	Pending -						
	The diversion should be in	nstalled with sediment b	asin installation.				
	D ((O - 1	d to a constate to 0/0/04	Not done or of the local base.				
			Not done as of the last inspe				
D 08	Diversion	SE of SB B1	6/1/2024	Pending	Yes		
Current Condition:	Pending -						
	The diversion should be in	netalled with sediment h	asin installation				
	The diversion should be in	istalied with sediment b	asiii iiistaiiatioii.				
	Ruff Grading was informe	d to complete by 9/6/24	Not done as of the last inspe	ection.			
D 09	Diversion	SE of SB B2	8/30/2024	Active	No		
Current Condition:			ary diversion prior to the 8/30/				
EM 01	Erosion Control Matting	W of SB A	3/3/2024	Pending	No		
Current Condition:			lled after the area reaches fir				
EM 02	Erosion Control Matting	N and E of SB A	3/3/2024	Pending	No		
Current Condition:			alled after the area reaches fir		L 61-		
FT 01 Current Condition:	Vehicle Fueling	Staging Area	7/17/2024 k and berm on site prior to the	Active	No		
MS 01	Material Storage	On Site	3/3/2024	Pending	No		
Current Condition:	Pending - Materials will be			. 5			
PB XX	Portable Bathroom	On Site	8/30/2024	Active	Yes		
Current Condition:		ling installed a portable	toilet in the staging area prior	to the 8/30/24 inspect			
	The portable toilet needs to be staked down.						
	Ruff Grading was informed to complete by 9/6/24. Not done as of the last inspection.						
65.4			· · · · · · · · · · · · · · · · · · ·		V		
SB A	Sediment Basin	NW	3/3/2024	Pending	Yes		
Current Condition:	Pending - Ruff Grading be	egan digging out the bas	in prior to the 9/6/24 inspection	л.			
	The basin should be installed.						
	THE PASIT SHOULD BE INSTALLED.						
	Ruff Grading was informe	d to complete by 8/23/2	4. Not done as of last inspecti	on. Ruff Grading was	reminded on 8/30/24.		
SB B1	Sediment Basin	W Central	3/3/2024	Pending	Yes		
·			3,0,2021				

Current Condition:	Pending -					
	The basin should be installed.					
	Duff Crading was informe	g was informed to complete by 8/30/24. Not done as of the last inspection.				
07.70						
SB B2	Sediment Basin	SW Corner	3/3/2024	Pending	Yes	
Current Condition:	Pending - Ruff Grading began digging out the basin prior to the 9/13/24 inspection.					
	The basin should be insta	alled.				
	Ruff Grading was informed to complete by 8/30/24. Not done as of the last inspection.					
SF 01	Silt Fence	Western Perimeter N of Mass Road	4/3/2024	Active	No	
Current Condition:	Good Condition - An unid	entified contractor install	ed the silt fence prior to the	1/3/24 inspection.		
SF 02	Silt Fence	Western Perimeter S	4/3/2024	Active	No	
		of Mass Road			140	
Current Condition:			ed the silt fence prior to the			
SF 03	Silt Fence	Northeast Corner		Removed		
Current Condition:	Removed - The remaining		e were removed prior to the 8	3/16/24 inspection.	1	
SF 04	Silt Fence	Southern Perimeter W of S 69th Street	6/1/2024	Pending	No	
Current Condition:	Pending - The silt fence v		ding reaches the area.	1		
SF 05	Silt Fence	Southern Perimeter E of S 69th Street	6/1/2024	Pending	No	
Current Condition:	Pending - The silt fence will be installed when grading reaches the area.					
SF 06	Silt Fence	Drainage at SB A outfall	8/16/2024	Active	Yes	
Current Condition:	Fair Condition - The silt fe	ence has been transferre	d from the Seventy-Two Place	e SWPPP due to acti	ve ground disturbance on	
	Ponderosa Place.					
	The silt fence needs to be	e repaired and additional	checks need to be installed.			
	Ruff Grading was informed to complete by 8/23/24. Not done as of last inspection. Ruff Grading was reminded on 8/30/24.					
SWPPP Sign	SWPPP Sign	At CE 01	12/20/2023	Active	No	
Current Condition:	Good Condition - The E&	A inspector installed the	SWPPP sign at the central s	tub road prior to the 1	2/20/23 inspection. The	
	E&A inspector moved the	SWPPP sign to the nor	thwest corner of the property	near the Ponderosa F	Place connection on 4/3/24.	
WO 01	Concrete Washout	On Site	3/3/2024	Pending	No	
Current Condition:	Pending - A concrete was	shout will be installed wh	en concrete work begins on s	site.		
WS 01	Waste Storage	On Site	3/3/2024	Pending	No	
Current Condition:	Pending - Waste will be p	roperly stored on site.				
	"I certify under penalty of	law that this document	and all attachments were pre	nared under my direc	tion or supervision in	
			•	•	•	
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for					
Certification Statement:	gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I					
			ubmitting false information in			
	for knowing violations."		•	5 , ,	·	
	Jan Co Mart				0.1.	
	Chuce sound			B	Get Sul	
Inspector Signature:		J		Reviewed By:		