E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager				Engineering Answers				
		E&A- P2017	7.463.001		C+			
Project Name: Prairie Hollow (aka Hidden Hollow per NDEQ Normalist CSW-201802726				DEQ NOI)	Stage 1			
Project Name:					00007			
For Week Ending:			3/2018		68007			
Project Location:		150th Street	and Highway 36					
Grading:	30%							
Sanitary Sewer:	0%							
Storm Sewer:	0%							
Paving: Seeding:	0%							
Utilities:	0%							
Overall Development:	4%							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions					
					Week 1			
Sunday:	0.01"			-				
Monday Tuesday	0.00"			+				
Wednesday	0.00"			+				
Thursday	0.03"							
Friday	0.06"							
Saturday	1.40"							
·					Week '			
Sunday:	0.01"							
Monday	0.00"	12/03/18	26/23 Snow					
Tuesday Wednesday	0.00"							
wednesday Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week			
Sunday:	NA							
Monday Tuesday	NA NA							
Wednesday	NA							
Thursday	NA							
Friday	NA							
Saturday	NA							
Complaints:								
Construction Sequencing:								
Which portion(s) (i.e. drainage basi	ns) of the site have had a temp	orary or permanent cessa	ation of grading, earthwork, or	ground disturbance in th	e last 14 days?			
Entire Site: Grading commend	ced (11/8/18)							
Which portion(s) (i.e. drainage basins		earthwork, or ground distur	rbance scheduled in the next 14	days?:				
Entire Site: Grading commend	ced (11/8/18)							
What temporary or permanent stabilize	cation measures listed in this sect	ion are being implemented	?					
Existing vegetation (11/8/18)								
OLIMAN OLIMANIA								
SUMMARY QUESTIONS:								
Are approved entrances and adjacent streets being maintained adequately? Yes								
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?								
No, See BMP Section								
CHECKLIST QUESTIONS:								
Are waste materials (concrete, con-	struction material, hazardous, e	etc.) being managed prop	erly?					

Vac

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Grading is active on site. The site was covered in 4" of snow during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) The t-posts along the entire run of per miter silt fence needs to be spaced properly. They are currently too wide. Negis Construction was informed to complete by 11/29/18. Not done as of the last inspection.
- 3. Sediment basin B was being shaped during the inspection on 12/3/18. The inspector will add it to the BMP section when installment is complete.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Stabilized Construction Entrance	N Molley Street (EE11)	11/20/2018	Active	No			
Current Condition:	Good Condition- Negis Construction installed the entrance prior to the inspection on 11/20/18.							
CW 1	Concrete Washout	Site	11/15/2018	Pending	No			
Current Condition:		shout will be recommende	d when paving is close to	commencing.				
D1	Temporary Diversion Ditch	(Z17-II17)	11/15/2018	Pending	No			
Current Condition:	Pending - The diversion will be recommended upon completion of grading.							
D2	Temporary Diversion Ditch	(F25-P21)	11/15/2018	Pending	No			
Current Condition:	Pending - The diversion v	vill be recommended upor	completion of grading.	•				
D3	Temporary Diversion Ditch	(P21-R20)	11/15/2018	Pending	No			
Current Condition:		Pending - The diversion will be recommended upon completion of grading.						
D4	Temporary Diversion Ditch	(B26-D26)	11/15/2018	Pending	No			
Current Condition:		vill be recommended upor	n completion of grading.					
EM 1	Erosion Control Matting	(C22-DD11)	11/15/2018	Pendina	No			
Current Condition:		ill be recommended upon		relialing	INU			
SB A	-	D26		Danding	Na			
Current Condition:	Sediment Basin	D20	11/15/2018	Pending	No			
SB B	Pending - Sediment Basin	R20	11/15/2018	Pending	No			
Current Condition:		pe recommended upon co		rending	NO			
SF 1	Silt fence	,	11/8/2018	Active	Vaa			
Current Condition:		(A25-II18) Instruction installed the sile			Yes			
	Negis Construction was in	nded to cover an existing	1/29/18. Not done as of th	e last inspection.				
SF 2	Silt fence	II18	11/8/2018	Active	No			
Current Condition: Good Condition - Negis Construction installed the silt fence prior to the inspection on 11/8/18.								
SF 3	Silt fence	II17	11/29/2018	Pending	Yes			
Current Condition:	Pending-							
	The silt fence needs to be installed to cover the adjacent waterway. Negis Construction was informed to complete by 11/29/18. Not done as of the last inspection.							
SF 4	Silt fence	(DD1-DD14)	11/8/2018	Active	No			
Current Condition:	Good Condition - Negis Construction installed the silt fence prior to the inspection on 11/8/18.							
STR	Streets	Site	11/8/2018	Active	No			
	rent Condition: Good Condition- No major signs of track off.							
Current Condition:		O .						

Current Condition:	Pending-				
	The SWPPP Sign needs installed.				
	18. Not done as of the	last inspection.			
Inspector Signature:	Clase aulack		Reviewed By:	But Sur	