E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Week

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E&A - P2017.463.001

Inspector: Bryce Wright					Stage		
Project Name:	Prairie He	Prairie Hollow (aka Hidden Hollow per NDEQ NOI) CSW-201802726					
For Week Ending:		11/27	/2021		68007		
Project Location:	156th Str	eet and Highway 36 (B	ennington Ne, Douglas	County)			
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	85%						
Utilities:	100%						
Overall Development:	59%						
			•	•			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week 1		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
					Week 2		
Sunday:	0.00"						
Monday:	0.00"	11/22/2021	Sunny 37	11:05 AM			

Complaints:

Tuesday:

Thursday:

Saturday:

Sunday: Monday

Tuesday

Wednesday

Thursday

Saturday

Friday

Friday:

Wednesday:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (11/13/20). Regrading of the slope in the southeast corner of the area inlets at the north end of the site (11/13/20). Regrading of the slope in the southeast corner of the area inlets at the north end of the site (11/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (11/3/20). Regrading of the slope in the southeast corner of the site, grading around the area inlets at the north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

0.00'

0.00

0.00

0.00

0.00'

N/A

N/A

N/A

N/A

N/A

N/A

N/A None Existing vegetation (11/8/18). Negus & Son's Construction seeded the flat area and seeded/matted the slope north of N. Allen Street (12/02/19). West side of southern entrance mulched, planted with trees (4/01/20). Area around IF 1 and 2 seeded and matted (8/11/20). Excavated silt spread out over area between SB-A and SB-B and seeded, SB-A and SB-B slopes seeded and matted (10/05/20). South entrance seeded/matted (10/26/20).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

- Yes Create Corrective Action?
- N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes

Create Corrective Action?

N/A

re waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action? No - See BMP Section

Are construction entrances and adjacent streets being maintained adequately? No

Create Corrective Action?

No - See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Yes Create Corrective Action?

N/A

Comments

## Comments:

Site was active for homebuilding during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

2.) An erosion rill was observed across from lot 10 on 8/31/21. Ryan Schwarz was informed to backfill, compact, and restabilize the erosion by 9/7/21. Not done as of the last inspection. Erosion rill is on state road property. State was contacted and no response was received as of 11/24/21.

Unique Name	Туре	Location	<b>Projected Install Date</b>	Status	Maintenance
	Stabilized Construction				
CE 1	Entrance	N Molley Street (EE11)		Removed	
Current Condition:	Removed - The former cor	nstruction entrance was p	aved prior to the inspection	on on 11/04/19.	
	Stabilized Construction				
CE 2	Entrance	N 2nd Street (B24)		Removed	
Current Condition:	Removed - The former cor	nstruction entrance was p	aved prior to the inspection	on on 11/04/19.	
CW 1	Concrete Washout	X10	9/8/2020	Pending	Yes
Current Condition:	Pending- Concrete washout the northwest corner of the on 3/15/21. The washout should be re- Ryan Schwarz was inform	e site prior to the inspectio	on on 9/08/20. Concrete w	ashout was removed the development shou	prior to the inspeculation of the inspeculation of the second sec
D1	01/15/21, 3/2/21, 3/17/21, 3/ Temporary Diversion Ditch	<u>4/13/21, 5/12/21, 7/6/21, 8</u> (Z17-II17)	8/11/21, 9/2/21, 10/15/21	Removed	
Current Condition:	Removed - The diversion i	is no longer necessary as	of the inspection on 4/01	20 due to lot-level co	nstruction starting
	area.				J
	Temporary Diversion				
	,	(F25-P21)	7/14/2020	Active	NIS
D2	Difch				INO
D2 Current Condition:	Ditch Good Condition - Negus &	(	led the diversion prior to t	he inspection on 7/14	No No
D2 Current Condition:	Good Condition - Negus &	(	lled the diversion prior to t	he inspection on 7/14	
Current Condition:	Good Condition - Negus & Temporary Diversion	Son's Construction instal		•	/20.
Current Condition:	Good Condition - Negus & Temporary Diversion Ditch	Son's Construction instal (P21-R20)	7/14/2020	Active	/20. No
Current Condition:	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus &	Son's Construction instal (P21-R20)	7/14/2020	Active	/20. No
Current Condition:	Good Condition - Negus & Temporary Diversion Ditch	Son's Construction instal (P21-R20)	7/14/2020	Active	/20. No
Current Condition: D3 Current Condition:	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus & Temporary Diversion	Son's Construction instal (P21-R20) Son's Construction instal (B26-D26)	7/14/2020 led the diversion prior to t	Active he inspection on 7/14 Removed	/20. No //20.
Current Condition: D3 Current Condition: D4	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus & Temporary Diversion Ditch Removed - As of the inspe	Son's Construction instal (P21-R20) Son's Construction instal (B26-D26)	7/14/2020 led the diversion prior to t	Active he inspection on 7/14 Removed	/20. No //20.
Current Condition: D3 Current Condition: D4 Current Condition:	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus & Temporary Diversion Ditch Removed - As of the inspe adjacent slope.	Son's Construction instal (P21-R20) Son's Construction instal (B26-D26) ection on 7/28/20, the dive (C22-DD11)	7/14/2020 Iled the diversion prior to t ersion is no longer necess	Active he inspection on 7/14 Removed ary due to establishm Active	/20. No //20. ent of vegetation o
Current Condition: D3 Current Condition: D4 Current Condition: EM 1	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus & Temporary Diversion Ditch Removed - As of the inspe adjacent slope. Erosion Control Matting	Son's Construction instal (P21-R20) Son's Construction instal (B26-D26) ection on 7/28/20, the dive (C22-DD11)	7/14/2020 Iled the diversion prior to t ersion is no longer necess	Active he inspection on 7/14 Removed ary due to establishm Active	/20. No //20. ent of vegetation o
Current Condition: D3 Current Condition: D4 Current Condition: EM 1 Current Condition:	Good Condition - Negus & Temporary Diversion Ditch Good Condition - Negus & Temporary Diversion Ditch Removed - As of the inspe adjacent slope. Erosion Control Matting Good Condition - Negus &	Son's Construction instal (P21-R20) Son's Construction instal (B26-D26) action on 7/28/20, the dive (C22-DD11) Son's Construction instal W11	7/14/2020 led the diversion prior to t rrsion is no longer necess 12/2/2019 led the erosion control ma	Active he inspection on 7/14 Removed ary due to establishm Active atting prior to the inspe	/20. No //20. ent of vegetation o No

IP2         Intel Film         I11         Removed           Current Condition:         Removed Films Iffence warp and seeded and matter actuation the intel prior to the inspection of \$1122.           Current Condition:         11125         11115         12722200         Active Yate           Current Condition:         12720. Negas & Son's Construction regulated the damaged intel filter and cleaned the intel filter on too the inspection on 7/1420.         Pyan Schwarz regulated positioned the intel filter prior to the inspection on 7/1420.           Pyan Schwarz regulated positioned the intel filter prior to the inspection on 9/1521.         Negas & Son's Construction installed wob get of intel filters in the sub intel prior to the inspection on 7/1420.           Pyan Schwarz regulated positioned the intel filter prior to the inspection on 9/1521.         Negas & Son's Construction installed wob get of intel filter inspection on 0/1720.           EXA inspector repositioned the intel filter spots to the inspection on 0/1720.         Extince         Negas & Son's Construction installed wob get of intel filter inspection on 0/1720.           EXA inspector repositioned the intel filter spots to the inspection on 0/1720.         Extince inspection on 0/1720.         Negas & Son's Construction installed wob get of intel filter spots to the inspection on 0/1720.           EXA inspector repositioned the intel filter spots to the inspection on 0/1720.         Extince inspection on 0/1720.         Negas & Son's Construction installed wob get of intel filter spots to the inspection on 0/1720.           EXA ins	Current Condition:	Removed - Ryan Schwarz removed the silt fence wrap and seeded and matted around the inlet prior to the inspec 8/11/20.	tion or
Bit 120.         Inde Filter         H115         1/27/2020         Active         Yes           Current Condition:         Fair Condition - Negue & Sorts Construction instatiled two big red rink filters in the cub inite filters on the inspection on 7/1420. Ryin 50/warz regular/dependent dhe inite filters in the cub inite filters on the inspection on 7/1420. Ryin 50/warz regular/dependent dhe inite filters in the solution of the inspection on 7/1420.           Bit 2         Inite filter shuld be cleared out.         Ryin 50/warz regular/dependent dhe inite filters in the inspection on 7/1420.           Bit 4         Ryin 50/warz regular/dependent dhe inite filters in the inspection on 7/1420.         Ryin 50/warz regular/dependent dhe inite filters in the inspection on 10/270.           Bit 4         Ryin 50/warz regular/dependent dhe inite filters in the inspection on 7/1420.         Ryin 50/warz regular/dependent dhe inite filter in the inspection on 10/270.           Current Condition:         Advent - Negue & Sorts Construction installed two big red infilters in the inspection on 10/270.         Red in the inspection on 10/270.           EA inspector regularized the inspection on 31/120. The inite filter appeared prior to the inspection on 10/270.         Red in the inspector will on the inspection on 31/120. The inite filter appeared by the inspector will on the inspection on 10/270.           Current Condition:         Red in the inspection on 31/120. The inite filter appeared by the inspection will not be ensetted on the inspection on 10/2700.           EA inspector will contructin inspection on 31/120. The inite filter appeared by the			
Current Condition:         Fair Condition: Negue & Soris Construction installed two big red intel filters in the cuto intel price to the inspection on 4/07/20. Negue & Soris Construction reinstalled two big red intel filters in the inlet price to the inspection on 7/4/20. Ryn Schwarz regarined-positioned the intel filter price to the inspection on 7/4/20. Ryn Schwarz researcher positioned the intel filter price to the inspection on 7/4/20. Ryn Schwarz researcher positioned the intel filter price to the inspection on 7/4/20. Ryn Schwarz researcher positioned the intel filter price to the inspection on 7/12/20. Ryn Schwarz researcher positioned the intel filter in the cuto intel inspection on 7/12/20. EAA inspector mosilianed two big red intel filters in the cuto intel price to the inspection on 1/2/20. EAA inspector mosilianed the intel filter in the large position of the street. The intel filter as price to intel during the inspection on 1/2/20. EAA inspector mosilianed to the inspection on 7/2/20 alleviate ponding on the street. The intel filter as price to intel filter a	Current Condition:		tion or
1/27/20. Negus & Soris Construction repaired the damaged intel filter and cleaned the intel filters out prior to the inspection on 7/14/20. Ryan Schwarz repaired/repositioned the intel filter prior to the inspection on 7/14/20. Ryan Schwarz was informed to complete by 4/14/21. Not done as of last inspection. Ryan Schwarz was reminded on end/321, 10/122, 10/221, 10/1221, 10/1221, 10/1221         IF 4       Intel Filter       Attive       No.         Current Condition:       Active       No.       No.         Current Condition:       Active reposition of 12/20. Intel Science 10/2020       Active No.       No.         Current Condition:       Active reposition of No.       No.       Construction installed two big reduined the inspection on 10/2200 and integrate prior to the inspection on 10/2200 and integrate prior			
IF 4       Intel Filter       H113       8/11/2020       Active       No         Current Condition:       Active - Negus & Sor's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. E&A inspector repositioned the intel filter sport to the inspection on 7/27/20. To intel filter intel filter sport to the inspection on 7/27/20. Negus & Sor's Construction removed the intel filter sport to the inspection on 8/112/2. The intel filter intel filter sport to the inspection on 8/15/21. E&A inspector Will continue to monitor. Ryan Schwarz removed the intel filter prior to the inspection on 9/15/21. E&A inspector Will continue to monitor.         IF 5       Intel Filter       A17       1/27/20/20       Active       No         Current Condition:       Active - Negus & Sor's Construction installed two big red linet filters in the curb intel prior to the inspection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter spection on 1/27/20. Negus & Sor's Construction removed the intel filter sprint to the inspectin on 1/27/20. Negus & Sor's	Current Condition:	1/27/20. Negus & Son's Construction repaired the damaged inlet filter and cleaned the inlet filters out prior to the ir on 4/01/20. Negus & Son's Construction reinstalled two big red inlet filters in the inlet prior to the inspection on 7/1- Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21.	nspec
Current Condition:         Active - Negue & Son's Construction installed two big red linet filters in the curb interport to the inspection on 1/27/20.           EARlive - Negue & Son's Construction removed the intel filters to fully protect the intel during the inspection on 40/02/20. Negue & Son's Construction removed the intel filters protro the inspection on 31/52/12. A fully the inspection on 41/20/20. Negue & Son's Construction removed the intel filter spectra to have been repaired prior to the 1/32/1. Duo to the street. Negue Son's Construction will not be inspection on 31/52/12. A inspector will continue to monitor. Negue Son's Construction prior to the inspection on 31/52/12. A inspector will continue to monitor.           IF 5         Intel Filter         AA17         1/27/20/20         Active         No           Current Condition:         Active Negue & Son's Construction installed two big red intel filters in the curb interport to the inspector on 1/2/22. No gue & Son's Construction restalled the intel filters prior to the inspection on 1/2/22. No gue & Son's Construction restalled the intel filters prior to the inspection on 1/2/22. No gue & Son's Construction restalled the intel filters prior to the inspection on 1/2/22. No gue & Son's Construction restalled the intel filters prior to the inspection on 1/2/22. No gue & Son's Construction removed the intel filters in the curb intel prior to the inspection on 1/2/22. No gue & Son's Construction removed the intel filters in the curb intel prior to the inspection on 1/2/22. No gue & Son's Construction removed the intel filters in the curb intel prior to the inspection on 1/2/22. No gue & Son's Construction removed the intel filters in the curb intel prior to the inspection on 1/2/22. No gue & Son's Construction removed the intel filters in the curb intel prior to the inspectint on 1/2/22. N			on
E&A inspector repositioned the intel filters to fully protect the inlet during the inspection on 401720. Negus & Son's         Construction removed the initel filter appars to have been repaired prior to the 11/10/20 inspection. Ryan Schwarz removed the initel filter appars to have been repaired prior to the 11/10/20 inspection. Ryan Schwarz removed the initel filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor. Ryan Schwarz removed the initel protection prior to the inspection on 3/15/21. Due to the street flooding during rain and all init being connected to basins, inlet protection ull not be recommended to be reinstalled at this time. E&A inspector will continue to monitor.         IF 6       Inite Filter       AA17       1/27/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two hild prior to the inspection on 1/22/20. Negus & Son's Construction removed the initel filters prior to the inspection on 1/22/20. Negus & Son's Construction removed the initel filters prior to the inspection on 1/22/20. Negus & Son's Construction removed the initel filters will be recommended in lique 10. Lower controls to preve sediment runoff as well as frequent street cleaning will be recommended in lique 10/20 to alleviate ponding on the street. The 1/1/27/2020         Current Condition:       1/27.0. Negus & Son's Construction installed two big red initel filters in the curb interprior to the inspection on 3/15/21. E&A inspector will continue to monitor for the need to reinstall the intel filters prior to the inspection on 3/15/21. Sel4 inspector will continue to monitor in the intel filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor in the intel filter prior to the inspectin and all in the filter street on the inspec	IF 4	Inlet Filter HH13 8/11/2020 Active No	
Current Condition:         Active - Negus & Son's Construction installed two big red intel filters in the curb inter prior to the inspection on 1/27/20. Negus & Son's Construction reinstalled the intel filters prior to the inspection on 7/0/220. Negus & Son's Construction removed the intel filters.           IF 6         Intel Filter         Y17         Y127/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 40/12/02 and leviate ponding on 40/12/02 to alleviate ponding on 51/57/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. Negus & Son's Construction removed the intel filters in the curb intel prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. The need to reinstall the intel filters. Nan Schwarz repaired/repositioned the intel filter prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. The need to reinstall the intel filters. Nan Schwarz repaired/repositioned the intel filter prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction remo	Current Condition:	E&A inspector repositioned the inlet filters to fully protect the inlet during the inspection on 4/01/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on the street. The inlet were partially reinstalled prior to the inspection on 8/11/20. The inlet filter was repositioned to block the inlet prior to inspection on 10/05/20. The inlet filter appears to have been repaired prior to the 11/10/20 inspection. Ryan Schw repaired/repositioned the inlet prior to the inspection on 3/15/21. E&A inspector will continue to monitor. Ryan Schwarz removed the inlet protection prior to the inspection on 9/13/21. Due to the street flooding during rain and being connected to basins, inlet protection will not be recommended to be reinstalled at this time. E&A inspector w	filters o the varz all inl
Current Condition:         Active - Negus & Son's Construction installed two big red intel filters in the curb inter prior to the inspection on 1/27/20. Negus & Son's Construction reinstalled the intel filters prior to the inspection on 7/0/220. Negus & Son's Construction removed the intel filters.           IF 6         Intel Filter         Y17         Y127/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 40/12/02 and leviate ponding on 40/12/02 to alleviate ponding on 51/57/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. Negus & Son's Construction removed the intel filters in the curb intel prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. The need to reinstall the intel filters. Nan Schwarz repaired/repositioned the intel filter prior to the inspection on 40/12/02 to alleviate ponding on 51/57/20. The need to reinstall the intel filters. Nan Schwarz repaired/repositioned the intel filter prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction remo	IE 5		
IF 6         Inlet Filter         Y17         1/27/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/07/20. Negus & Son's Construction removed the intel filters prior to the inspection on 4/01/20 to alleviate ponding on street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu of the intel filters. The intel filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue to monitor.           IF 7         Intel Filter         E25         1/27/20.00         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 2/10/20. Active         Yes           Current Condition:         Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction installed two big red inlet filters i	Current Condition:	Negus & Son's Construction reinstalled the inlet filters prior to the inspection on 7/02/20. Negus & Son's Construct removed the inlet filters prior to the inspection on 10/12/20 to alleviate ponding on the street. Lot-level controls to p sediment runoff as well as frequent street cleaning will be recommended in lieu of the inlet filters. The inlet filters w stored on-site and can be reinstalled if necessary. The E&A inspector will continue to monitor for the need to reins	tion preve /ill be
Current Condition:         Good Condition - Negus & Son's Construction installed two big red intel filters in the curb intel prior to the inspection on 1/27/20. Negus & Son's Construction removed the intel filters are lead as there inspection on 4/01/20 to alleviate ponding on 1/27/20. Negus & Son's Construction removed the intel filters in the curb intel prior to the inspector will continue to monitor for the need to reinstall the intel filters. Ryan Schwarz repaired/repositioned the intel filter prior to the inspection on 1/27/2020           IF 7         Intel Filter         E25         1/27/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 1/27/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 3/15/21.           IF 8         Inlet Filter         GG15         2/10/2020         Active         Yes           Current Condition:         Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction intermoved the inlet filter prior to the inspection on 3/15/21.         If Ea           Inlet Filter         GG15         2/10/2020         Active         Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspector on 2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspector on 2/10/20. Negus & Son's C			
Current Condition:         Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter           IF 8         Inlet Filter         GG15         2/10/2020         Active         Yes           Current Condition:         Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 7/02/20 to alleviate ponding on 1/21/02/00. Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue monitor.           IF 9         Inlet Filter         GG13         2/10/2020         Active         No           Current Condition:         Kyan Schwarz repaired/repositioned the volg red inlet filters in the curb inlet prior to the inspector will continue monitor.         Inlet Filter         GG13         2/10/2020         Active         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.         No           Current Condition:         Acti		Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection         No	
1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter to the inspection on 3/15/21.         IF 8       Inlet Filter       GG15       2/10/2020       Active       Yes         Current Condition:       Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 7/02/20 to alleviate ponding on street. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue monitor.         Inlet filter should be cleaned out.       Ryan Schwarz was informed to complete by 4/14/21. Not done as of last inspection. Ryan Schwarz was reminded on 4/1/3/21, 5/12/21, 7/6/21, 8/11/21, 9/2/21, 10/15/21         IF 9       Inlet Filter       GG13       2/10/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspector on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on the street Ryan Schwarz repaired/repositioned the inlet filters prior to the inspection on 9/13/21. E&A inspector will continue to monitor. Ryan Schwarz removed the inlet prior to the inspection on 9/13/21. E&A inspector will continue to monitor. Ryan Schwarz removed the inlet filters prior to the inspection on 9/13/21. Due to the street flooding during rain and all inlets being connected to basins, inlet protection will not be re	Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspect 3/15/21. E&A inspector will continue to monitor.	g on t u of th ue to
Current Condition:         Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on a street. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue monitor.           Inlet filter should be cleaned out.         Ryan Schwarz was informed to complete by 4/14/21. Not done as of last inspection. Ryan Schwarz was reminded on 4/13/21, 5/12/21, 7/6/21, 8/11/21, 9/2/21, 10/15/21           IF 9         Inlet Filter         GG13         2/10/2020         Active         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.         Netwer         No           IF 9         Inlet Filter         GG13         2/10/2020         Active         No           Ryan Schwarz repaired/repositioned the inlet filters prior to the inspection on 3/15/21. E&A inspector will continue to monitor.         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.         Netwer repaired/repositioned the inlet filter prior to the inspection on 9/13/21. E&A inspector will continue to monitor.           IF 10         Inlet Filter         DD17         7/28/2020         Active         No           Current Condition:         Active - Negus & Son's Co	Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspect 3/15/21. E&A inspector will continue to monitor.           Inlet Filter         E25         1/27/2020         Active         No	g on t u of th ue to ection
2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on street. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue monitor.         Inlet filter should be cleaned out.         Ryan Schwarz was informed to complete by 4/14/21. Not done as of last inspection. Ryan Schwarz was reminded on 4/13/21, 5/12/21, 7/6/21, 8/11/21, 9/2/21, 10/15/21         IF 9       Inlet Filter       GG13       2/10/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspector on 2/10/20.       Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor.         Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor.         IF 10       Inlet Filter       DD17       7/28/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspector on 2/10/20.       No         IF 10       Inlet Filter       DD17       7/28/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.	Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liet inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspect 3/15/21. E&A inspector will continue to monitor.         No           Inlet Filter         E25         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 4/01/20 to alleviate ponding street. The inlet Filter         E25         1/27/2020         Active         No	g on t u of th ue to ection
Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on the stree Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor. Ryan Schwarz removed the inlet protection prior to the inspection on 9/13/21. Due to the street flooding during rain and all inlets being connected to basins, inlet protection will not be recommended to be reinstalled at this time. E&A inspector will continue to monitor.         IF 10       Inlet Filter       DD17       7/28/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.       No         IF 10       Inlet Filter       DD17       7/28/2020       Active       No         Current Condition:       Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.       Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on the stree Ryan Schwarz partially reinstalled the filters prior to the inspection on 7/28/20. Ryan Schwarz removed the inlet filters prior to the inspection on 7/28/20. Ryan Schwarz removed the inlet filters.	IF 7 Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liet inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection 3/15/21. E&A inspector will continue to monitor.         No           Inlet Filter         E25         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection of 4/01/20 to alleviate ponding street. The inlet filter         E25         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter to the inspection on 3/15/21.           Inlet Filter         GG15         2/10/2020         Active         Yes	g on g u of tl ection on on g on g
Negus & Son's Construction removed the inlet filters prior to the inspection on 7/02/20 to alleviate ponding on the street Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection on 3/15/21. E&A inspector will continue to monitor. Ryan Schwarz removed the inlet protection prior to the inspection on 9/13/21. Due to the street flooding during rain and all inlets being connected to basins, inlet protection will not be recommended to be reinstalled at this time. E&A inspector will continue to monitor.           IF 10         Inlet Filter         DD17         7/28/2020         Active         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on the street Ryan Schwarz partially reinstalled the filters prior to the inspection on 7/28/20. Ryan Schwarz removed the inlet filters prior to the inspection on 8/25/20. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu of the inlet filters.	IF 7 Current Condition: IF 8 Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liet inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection of 4/01/20 to alleviate ponding 3/15/21. E&A inspector will continue to monitor.           Inlet Filter         E25         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter to the inspection on 3/15/21.         Inlet Filter         GG15         2/10/2020         Active         Yes           Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 3/15/21. E&A inspe	g on t u of th ue to cection on on g on t tilter p on g on t
IF 10         Inlet Filter         DD17         7/28/2020         Active         No           Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on the street Ryan Schwarz partially reinstalled the filters prior to the inspection on 7/28/20. Ryan Schwarz removed the inlet filters prior to the inspection on 8/25/20. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu of the inlet filters.	IF 7 Current Condition: IF 8 Current Condition: IF 8	Inlet FilterY171/27/2020ActiveNoGood Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate pondingstreet. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieuinlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continuemonitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspect3/15/21. E&A inspector will continue to monitor.Inlet FilterE251/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate pondingstreet. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filterto the inspection on 3/15/21.Inlet FilterGG152/10/2020ActiveYesFair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection2/10/20. Negus & Son's Construction removed the inlet filt	g on t u of th ue to ection on on on g on t tilter p on on g on t tinue
Current Condition:         Active - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20.           Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding on the street Ryan Schwarz partially reinstalled the filters prior to the inspection on 7/28/20. Ryan Schwarz removed the inlet filters prior to the inspection on 8/25/20. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in lieu of the inlet filters.	IF 7 Current Condition: IF 8 Current Condition: IF 8	Inlet Filter         Y17         1/27/202         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspectiti         1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liter inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection double condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21.           Inlet Filter         GG15         2/10/2020         Active         Yes           Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21. E&A ins	g on t a of the control of the control of the g on t tiller p on on g on t tiller p on on on on on on on on on on
	IF 7 Current Condition: IF 8 Current Condition: IF 9 Current Condition:	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liter inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continu monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection of 4/01/20 to alleviate ponding 3/15/21. E&A inspector will continue to monitor.         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 4/01/20 to alleviate ponding street. The inlet filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repositioned the inlet filter is the curb inlet prior to the inspection 0.3/15/21.           Inlet Filter         GG15         2/10/2020         Active         Yes           Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21.         Inlet Filter         GG15         2/10/2020         Active         Yes           Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 2/10/20. Negus & Son's Construction removed the inlet filter prior to the inspection on 3/15/21. E&A inspector will conti	g on t t u of th ue to cction on on on g on t tinue on on y on t tinue on y on t tinue on on y on t tinue on on on on t to on on on on to on on on to on on on to on on on to on on to on on to on on to on on to to on to to on to to to to to to to to to to to to to
	IF 7 Current Condition: IF 8 Current Condition: IF 9 Current Condition: IF 9	Inlet Filter         Y17         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection         Active         No           1/27/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/0/20 to alleviate ponding         street. Lot-level controls to prevent sediment runoff as well as frequent street cleaning will be recommended in liet inlet filters. The inlet filters will be stored on-site and can be reinstalled if necessary. The E&A inspector will continu monitor for the need to reinstall the inlet filters. Ryan Schwarz repaired/repositioned the inlet filter prior to the inspection 3/15/21. E&A inspector will continue to monitor.           Inlet Filter         E25         1/27/2020         Active         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 1/07/20 to alleviate ponding.         streat.         No           Good Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 03/15/21.         Inlet Filter         GG15         2/10/2020         Active         Yes.           Fair Condition - Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection 03/15/21.         Inlet Filter         GG15         2/10/2020         Active         Yes.           Fair Condition - Negus & Son's Construction removed the inlet filters prior to the inspection on 3/15/21. E&A inspector will contm	g on ti u of the ection on on on g on ti liter p on g on ti tinue on y/20. street ouring v/20.

IF 12       Intel Filer       R19       2/10/2020       Active       Yes         Current Condition:       Fair Condition - Negus & Sons Construction metallative big red intel filters in the curb negletion on 4/10/20 to allevise pording of street. The intel filter was installed prior to the inspection on 4/10/20 to allevise pording of street. The intel filter sin backback pording of street. Active       No.         IF 13       Intel Filter       K22       2/10/2020       Active       No.         Current Condition:       Good Condition - Negus & Sons Construction installed two big red intel filters in the curb intel prior to the inspection on 4/01/20 to allevise ponding of street. Active controls on street and streegater street change with the inspection on 4/01/20 to allevise ponding of street. Active controls on street and streegater street change with streegater street change with the inspection on 4/01/20 to allevise ponding of street. Active controls on street and street streegater street change with streegater street streegater street change with streegater street streegater streegater streegater streegater streegater stre		2/10/20. Negus & Son's C street. Ryan Schwarz rep	onstruction removed the i		pection on 4/01/20 to a			
IF 12       Intel Filer       R19       2/10/2020       Active       Yes         Current Condition:       Fair Condition - Negus & Sons Construction metallative big red intel filters in the curb negletion on 4/10/20 to allevise pording of street. The intel filter was installed prior to the inspection on 4/10/20 to allevise pording of street. The intel filter sin backback pording of street. Active       No.         IF 13       Intel Filter       K22       2/10/2020       Active       No.         Current Condition:       Good Condition - Negus & Sons Construction installed two big red intel filters in the curb intel prior to the inspection on 4/01/20 to allevise ponding of street. Active controls on street and streegater street change with the inspection on 4/01/20 to allevise ponding of street. Active controls on street and streegater street change with streegater street change with the inspection on 4/01/20 to allevise ponding of street. Active controls on street and street streegater street change with streegater street streegater street change with streegater street streegater streegater streegater streegater streegater stre		Inlet filter should be added.						
IF12         Intel Filer         R19         2/10/200         Active         Yes           Current Condition:         Figure Condition: Negues & Som's Construction memory and the intel filters prior to the inspection on 4/12/20 to alleviate ponding of a stretce. The intel filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repairsonand the intel filter to the inspection on 4/12/20 to alleviate ponding of a stretce. The intel filter was installed prior to the 11/10/20 inspection. Ryan Schwarz repaired/repairsonand the intel filter to the inspection on 4/12/20 to alleviate ponding of a stretce. As interval in a stretce and interval in		Ryan Schwarz was informed to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was reminded o						
Current Condition:         Feir Condition - Negus & Son's Construction installed two big red linet filters in the curb hiles ponding of street. The intel filter was installed prior to the inspection on 4/1220 a allowing ponding of street. The intel filter was installed prior to the inspection on 4/1220 to allowing ponding of street. The intel filter should be cleaned out.           Ryan Schwarz was informed to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was termined to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was termined in Euro Intel Filter Schwarz was informed to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was termined in Euro Intel Filter Schwarz was informed to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was termined in Euro Intel Filter Schwarz was informed to complete by 5/17/21. Not done as of the last inspection. Ryan Schwarz was termined in Euro Intel Filter Schwarz	IF 12			2/10/2020	Active	Yes		
IF 13         Intel Filter         K22         2/10/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red intel filters in the ucb intel prior to the inspection on intel filters. The intel filters will be stored on-site and can be reinstalled in freessary. The EAA inspector will continue monitor for the need to reinstall the intel filters. Ryan Schwarz repaired/repositioned the intel filter prior to the inspection of the need to reinstall the intel filters. Ryan Schwarz repaired/repositioned the intel filter prior to the inspection 2/10/20. Negus & Son's Construction installed mucb big red intel filters in the curb integrint of the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction removed the intel filters prior to the inspection 2/10/20. Negus & Son's Construction installed two big red intel filters in the active head in the interprior to the inspection 2/10/20. Negus & Son's Construction installed two big red intel filters in the intel filter prior to the inspection 2/10/20. Negus & Son's Construction installed two big red intel filters in the intel filter prior to the inspection 2/10/20. Negus & Son's Construction installed two big red intel filters in the intel filter in the intel filter in the intel filter prior to the inspection on 40/12/10 calleviate ponding on 2/10/20. Negus & Son's Construction installed two big red intel filters in the intel filter intel filter in the intel filter in the inspection on 4	Current Condition:	2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/ Inlet filter should be clean	onstruction removed the i installed prior to the 11/10 21. ed out.	inlet filters prior to the insp )/20 inspection. Ryan Sch	pection on 4/01/20 to a warz repaired/repositi	alleviate ponding or oned the inlet filter		
Current Condition:         Good Condition - Negus & Son's Construction installed two big red linet filters in the inspection on 40/12/to alleviate ponding of attract. Lot-level controls to prevent sadiment runoff as well as frequent street clanking will be recommended in lieu on inter filters. The index filters will be stored on-site and can be reinstalled in frequents, The E&A inspector will continue to monitor.           IF 14         Inlet Filter         G23         2/10/2020         Active         No           Current Condition:         Good Condition - Negus & Son's Construction installed two big red inlet filters in the inspection on 2/10/20. Negus & Son's Construction installed two big red inlet filters in the inter ponding on a prevent sediment runoff as well as frequent street clanking will be recommended in lieu on inite filters. The inlet filters in the contor interaction on 4/01/20 to alleviate ponding on street. Lot-level controls to prevent sediment runoff as well as frequent street clanking will be recommended in lieu on a prevent sediment runoff as well as frequent street clanking will be recommended in lieu on a prevent sediment runoff as well as frequent street clanking will be recommended in lieu on a prevent sediment runoff as well as frequent street. Lot-level controls to prevent sediment runoff as well as frequent street clanking to the inspection on 4/01/20 to alleviate ponding on the street. If the intert inter instruction removed the intert filters in the curb inter prior to the inspection on 2/10/20. Negus & Son's Construction installed two big red intert filters in the curb inter provide on the inspection on a street sediment sediment will be recommended at this time. The EAA inspector will continue to monitor.           IF 15         Intel Filter         E2A         2/10/20. Negus & Son's Constru	IE 13	7/6/21.8/11/21.9/2/21.10	)/15/21					
Current Condition:         Goad Condition - Negus & Son's Construction installed two big red linet filters in the curb linet prior to the inspection on 40/120 to lequivate ponding of 210/20. Negus & Son's Construction removed the linet filters prior to the inspection on 40/120 to lequivate ponding of 210/20. Negus & Son's Construction removed the linet filters. The inet filters will be stored on-site and can be reinstalled if necessary. The E&A inspect or will continue to minor for the need to reinstallation will not be recommended at this time. The E&A inspect or will continue to the inspection of 310/21 to alleviate ponding on the street. I the intest leading to a basin reinstallation will not be recommended at this time. The E&A inspect or will continue to minor to the inspection on 310/21 to alleviate ponding or street. The intel filter will be a basin reinstallation will not be inspection an 401/20 to alleviate ponding or street. The intel filter will be a basin reinstallation will not be recommended at this time. The E&A inspector will continue to move the inspection on 310/21 to alleviate ponding or street. The intel filter will be store the intel filter prior to the inspection an 401/20 to alleviate ponding or street. The intel filter will be store the recommended in the intel filter will be inspection on 316/21. EAA inspector will continue to movintor.           Lot 1         Individual Lot         Lot 1         Removed           Current Condition:         Removed - New Chapter sodded the lot prior to the inspection on 3/3121. Ead will be installed sill fence along the northeast corner of the lot prior to the inspection on 7/20.           Lot 3         Individual Lot         Lot 4         Removed           Current Condition:         Ear Condition example will be installed aling frenor to the inspec		Good Condition - Negus & 2/10/20. Negus & Son's C street. Lot-level controls to inlet filters. The inlet filters monitor for the need to rei	Son's Construction insta onstruction removed the prevent sediment runoff will be stored on-site and nstall the inlet filters. Rya	lled two big red inlet filters inlet filters prior to the insp as well as frequent street d can be reinstalled if nece	s in the curb inlet prior bection on 4/01/20 to a t cleaning will be recor essary. The E&A inspe	to the inspection of alleviate ponding or mmended in lieu of ector will continue t		
2/10/20. Negus & Son's Construction removed the inlet filters prior to the inspection on 4/01/20 to alleviate ponding or inlet filters. The inlet filters will be stored on-site and can be reinstalled freexesary. The E&A inspector will continue monitor for the need to reinstall the inlet filters. Ryan Schwarz removed the inlet filters prior to the inspection on 9/13/21 to alleviate ponding on the street. L filter inlets leading to a basin reinstallation will not be recommended at this time. The E&A inspector will continue to more the inspection on 9/13/21 to alleviate ponding on the street. L filter inlets leading to a basin reinstallation will not be recommended at this time. The E&A inspector will continue to more construction installed will be great the inlet filter prior to the inspection on 2/10/200 Active No         Current Condition:       Good Condition Negus & Son's Construction installed will be recommended at this time. The E&A inspector will continue to monitor.         Lot 1       Individual Lot       Lot 1       Removed         Current Condition:       Removed - New Chapter Homes sodded the lot prior to the 11/11/21 inspection.       Removed         Lot 2       Individual Lot       Lot 2       Removed         Current Condition:       Fair Condition inspection bags arcs/axis on the lot prior to the inspection on 3/13/21.       Lot 2       Removed         Lot 3       Individual Lot       Lot 4       Removed       Yes         Current Condition:       Fair Condition installed along the northesit proved to the inspection on 3/15/21.       Lot 4       No         Gurrent Condition:       Fair C	IF 14	Inlet Filter	G23	2/10/2020	Active	No		
Current Condition:         Good Condition Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters in the curb inlet prior to the inspection on 4/01/20 to alleviate ponding or street. The inlet filter was installed prior to the 11/10/20 inspection. Ray Schwarz repaired/repositioned the inlet filters in the curb inlet filter was installed prior to the 11/10/20 inspection. Ray Schwarz repaired/repositioned the inlet filter the inspection on 3/15/21. E&A inspector will continue to monitor.           Lot 1         Individual Lot         Lot 1         Removed           Current Condition:         Removed - New Chapter Homes sodded the lot prior to the inspection on 8/31/21.         Removed           Lot 3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.           Lot 4         Individual Lot         Lot 4         3/15/2021         Active         No           Current Condition:         Good Condition + output construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot.         Silt fence         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt f		street. Lot-level controls to inlet filters. The inlet filters monitor for the need to rei 3/15/21. Ryan Schwarz re	o prevent sediment runoff will be stored on-site and nstall the inlet filters. Rya moved the inlet filters prio	as well as frequent street d can be reinstalled if nec n Schwarz repaired/repos or to the inspection on 9/1	t cleaning will be recor essary. The E&A inspe sitioned the inlet filter p 3/21 to alleviate pondi	mmended in lieu of ector will continue t prior to the inspection ing on the street. D		
Current Condition:         Good Condition Negus & Son's Construction installed two big red inlet filters in the curb inlet prior to the inspection on 2/10/20. Negus & Son's Construction removed the inlet filters in the curb inlet prior to the inspection on 4/01/20 to alleviate ponding or street. The inlet filter was installed prior to the 11/10/20 inspection. Ray Schwarz repaired/repositioned the inlet filters in the curb inlet filter was installed prior to the 11/10/20 inspection. Ray Schwarz repaired/repositioned the inlet filter the inspection on 3/15/21. E&A inspector will continue to monitor.           Lot 1         Individual Lot         Lot 1         Removed           Current Condition:         Removed - New Chapter Homes sodded the lot prior to the inspection on 8/31/21.         Removed           Lot 3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.           Lot 4         Individual Lot         Lot 4         3/15/2021         Active         No           Current Condition:         Good Condition + output construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot.         Silt fence         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt f		Inlet Filter	F24	0/40/0000	A	L NL		
Current Condition:         Removed - New Chapter Homes sodded the lot prior to the 11/11/21 inspection.           Lot 2         Individual Lot         Lot 2         Removed           Current Condition:         Removed - New Chapter sodded the lot prior to the inspection on 8/31/21.         Removed           Lot 3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21         Active         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the onth side of the lot prior to the 3/24/21 inspection, E&A inspector will continue to monitor. L Construction removed the dirt pile prior to the inspection on 9/27/21.         No           Lot 5         Silt Fence         Lot 6         Removed         Removed           Lot 5         Silt Fence         Lot 6         Removed         Removed           Lot 5         Silt Fence         Lot 6         Removed         Removed           Lot 5         Silt Fence         Lot 6         Removed         Rem								
Lot 2         Individual Lot         Lot 2         Removed           Current Condition:         Removed - New Chapter sodded the lot prior to the inspection on 8/31/21.         Removed         Active         Yes           Lot 3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 7/3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition began excavation on the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21         No           Lot 4         Individual Lot         Lot 4         3/15/2021         Active         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the inspection on 3/15/21. LIM Construction removed the dir prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 9/27/21.           Lot 5         Silt Fence         Lot 5         Removed           Current Condition:         Removed - LIM Construct		Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was	Son's Construction instal onstruction removed the installed prior to the 11/10	led two big red inlet filters inlet filters prior to the insp 0/20 inspection. Ryan Sch	in the curb inlet prior pection on 4/01/20 to a	to the inspection or alleviate ponding or		
Current Condition:         Removed - New Chapter sodded the lot prior to the inspection on 8/31/21.           Lot 3         Individual Lot         Lot 3         7/31/2021         Active         Yes           Current Condition:         Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 7/3         LM Construction began excavation on the lot prior to the inspection on 9/27/21.           Silt fence should be installed along the north side of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21           Lot 4         Individual Lot         Lot 4         3/15/2021         Active         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction was rem on 10/27/21, 11/12/21         No           Lot 4         Individual Lot         Lot 4         3/15/2021         Active         No           Current Condition:         Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction removed the dirt pie prior to the inspection on 4/26/21. LIM Construction installed silt fence on the north side of the lot prior to the inspection on 9/27/21.         No           Current Condition:         Removed         Lot 5         Removed           Current Condition:         Removed Structures sodded the lot prior to the inspection	Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.	in the curb inlet prior pection on 4/01/20 to a warz repaired/repositi Removed	to the inspection or alleviate ponding or		
Lot 3       Individual Lot       Lot 3       7/31/2021       Active       Yes         Current Condition:       Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 7/2         Lit M Construction began excavation on the lot prior to the inspection on 9/27/21.       Silt fence should be installed along the north side of the lot.         Lit M Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21       Lot 4       3/15/2021       Active       No         Current Condition:       Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the inspector will continue to monitor. L Construction removed the dirt pile prior to the inspection on 4/26/21. LIM Construction installed silt fence on the north side of the lot prior to the inspector will continue to monitor. L Construction removed the dirt pile prior to the inspection on 9/27/21.         Lot 5       Silt Fence       Lot 5       Removed         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Active       Yes         Lot 6       Individual Lot       Lot 6       Removed       Removed       Prior         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Active       Yes         Current Condition: <td>Current Condition:</td> <td>Good Condition Negus &amp; 2/10/20. Negus &amp; Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot</td> <td>Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&amp;A inspector will con Lot 1</td> <td>led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.</td> <td>in the curb inlet prior pection on 4/01/20 to a warz repaired/repositi Removed</td> <td>to the inspection or alleviate ponding or</td>	Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.	in the curb inlet prior pection on 4/01/20 to a warz repaired/repositi Removed	to the inspection or alleviate ponding or		
Current Condition:       Fair Condition - LIM Construction installed silt fence along the northeast corner of the lot prior to the inspection on 7/3 LIM Construction began excavation on the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.       LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21         Lot 4       Individual Lot       Lot 4       3/15/2021       Active       No         Current Condition:       Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the inspector on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the 3/24/21 inspection, EAA inspector will continue to monitor. L Construction removed the dit pile prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 9/27/21.         Lot 5       Silt Fence       Lot 5       Removed         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Lot 6       Removed         Current Condition:       Removed - Lot 6       Removed       Removed         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Lot 6       Removed         Current Condition:       Removed - Lot 6       Removed       Removed       Removed       <	Current Condition: Lot 1 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter	Son's Construction instal onstruction removed the installed prior to the 11/1( 21. E&A inspector will con Lot 1 Homes sodded the lot prior	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.	in the curb inlet prior in the curb inlet prior in the curb inlet prior in the curb in 4/01/20 to a warz repaired/repositi Removed ion.	to the inspection or alleviate ponding or		
LIM Construction began excavation on the lot prior to the inspection on 9/27/21.         Silt fence should be installed along the north side of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21         Lot 4       Individual Lot       Lot 4       3/15/2021       Active       No         Current Condition:       Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the 3/24/21 inspection, E&A inspector will continue to monitor. L Construction removed the dirt pile prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 9/27/21.         Lot 5       Silt Fence       Lot 5       Removed         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Removed       Removed         Lot 7       Silt fence       Lot 7       3/24/2021       Active       Yes         Current Condition:       Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.       Lot 6       Removed       Ves         Lot 7       Silt fence       Lot 7       3/24/2021       Active       Yes         Current Condition:       Fair Condition - Smart Development LLC In	Current Condition: Lot 1 Current Condition: Lot 2	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.	in the curb inlet prior in the curb inlet prior in the curb inlet prior in the curb in 4/01/20 to a warz repaired/repositi Removed ion.	to the inspection or alleviate ponding or		
Current Condition:       Good Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. LIM Construction installed silt fence on the north side of the lot prior to the 3/24/21 inspection, E&A inspector will continue to monitor. L Construction removed the dirt pile prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the inspection on 7/31/21.         Lot 5       Silt Fence       Lot 5       Removed         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.       Removed         Lot 6       Individual Lot       Lot 6       Removed         Current Condition:       Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.       Active       Yes         Lot 7       Silt fence       Lot 7       3/24/2021       Active       Yes         Current Condition:       Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.       Street should be cleaned in front of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed on 10/27/21, 11/12/21       Street should be cleaned in front of the lot.	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. por to the 11/11/21 inspect to the 11/11/21 inspect inspection on 8/31/21. 7/31/2021	in the curb inlet prior in the curb inlet prior in the curb inlet prior in the curb in 4/01/20 to a swarz repaired/repositi Removed ion.	to the inspection of alleviate ponding of oned the inlet filter		
installed silt fence on the north side of the lot prior to the 3/24/21 inspection, E&A inspector will continue to monitor. L         Construction removed the dirt pile prior to the inspection on 4/26/21. LIM Construction installed new silt fence on the side of the lot prior to the inspection on 7/31/21.         Lot 5       Silt Fence       Lot 5         Current Condition:       Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.         Lot 6       Individual Lot       Lot 6         Current Condition:       Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.         Lot 7       Silt fence       Lot 7         Lot 7       Silt fence       Lot 7         Silt fence       Lot 7       3/24/2021         Active       Yes         Current Condition:       Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.         Street should be cleaned in front of the lot.       LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed in 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor.	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.    Removed  Active  er of the lot prior to the 21.	to the inspection or alleviate ponding or oned the inlet filter		
Current Condition:         Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.           Lot 6         Individual Lot         Lot 6         Removed           Current Condition:         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.           Lot 7         Silt fence         Lot 7         3/24/2021         Active         Yes           Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.         Street should be cleaned in front of the lot.           LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed on 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o primed to complete by 10/4 Lot 4	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect por to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.	to the inspection or alleviate ponding or oned the inlet filter Yes e inspection on 7/3 hstruction was reministruction was rem		
Current Condition:         Removed - Evolved Structures sodded the lot prior to the inspection on 9/27/21.           Lot 6         Individual Lot         Lot 6         Removed           Current Condition:         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.           Lot 7         Silt fence         Lot 7         3/24/2021         Active         Yes           Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.         Street should be cleaned in front of the lot.           LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was removed on 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15// Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the Construction removed the	Son's Construction instal onstruction removed the installed prior to the 11/1( 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o true to complete by 10/4 Lot 4 istruction began excavatio north side of the lot prior to dift pile prior to the inspe	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. por to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, 1	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.	to the inspection or alleviate ponding or oned the inlet filter <u>Yes</u> e inspection on 7/3 nstruction was reminent No LIM Construction tinue to monitor. LI		
Lot 6         Individual Lot         Lot 6         Removed           Current Condition:         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.         Active         Yes           Lot 7         Silt fence         Lot 7         3/24/2021         Active         Yes           Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.         Street should be cleaned in front of the lot.         LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the Construction removed the side of the lot prior to the Silt Fence	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side of the lot prior to the struction began excavation orth side of the lot prior to dift pile prior to the inspe inspection on 7/31/21. Lot 5	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, I ction on 4/26/21. LIM Cor	in the curb inlet prior in bection on 4/01/20 to a swarz repaired/repositi Removed ion.	to the inspection or alleviate ponding or oned the inlet filter <u>Yes</u> e inspection on 7/3 nstruction was reminent No LIM Construction tinue to monitor. LI		
Current Condition:         Removed - LIM Construction sodded the lot prior to the inspection on 9/27/21.           Lot 7         Silt fence         Lot 7         3/24/2021         Active         Yes           Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.         Street should be cleaned in front of the lot.           LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to complete by 10/4/21. Not done as of the last inspection. LIM Construction was remoned to comple	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the Construction removed the side of the lot prior to the Silt Fence	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side of the lot prior to the struction began excavation orth side of the lot prior to dift pile prior to the inspe inspection on 7/31/21. Lot 5	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, I ction on 4/26/21. LIM Cor	in the curb inlet prior in bection on 4/01/20 to a swarz repaired/repositi Removed ion.	to the inspection or alleviate ponding or oned the inlet filter <u>Yes</u> e inspection on 7/3 nstruction was reminent No LIM Construction tinue to monitor. LI		
Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.           Street should be cleaned in front of the lot.           LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition: Lot 5 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15// Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the Silt fence should be instal Silt fence the lot prior to the Silt Fence Removed - Evolved Strue	Son's Construction instal onstruction removed the installed prior to the 11/1( 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o true to complete by 10/4 Lot 4 struction began excavatio north side of the lot prior to dift pile prior to the inspe nspection on 7/31/21. Lot 5 ctures sodded the lot prior	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, I ction on 4/26/21. LIM Cor	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.    Removed  Active  r of the lot prior to the 21.  Active  spection on 3/15/21. L E&A inspector will con  struction installed new  Removed /21.	to the inspection or alleviate ponding or oned the inlet filter <u>Yes</u> e inspection on 7/3 nstruction was reminent No LIM Construction tinue to monitor. LI		
Current Condition:         Fair Condition - Smart Development LLC Installed silt fence in the back of the lot prior to the 3/24/21 inspection. LIM Construction started excavation on the lot prior to the inspection on 9/27/21.           Street should be cleaned in front of the lot.           LIM Construction was informed to complete by 10/4/21. Not done as of the last inspection. LIM Construction was rem on 10/27/21, 11/12/21	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition: Lot 5 Current Condition: Lot 5 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the Construction removed the side of the lot prior to the Silt Fence Removed - Evolved Struct Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o rmed to complete by 10/4 Lot 4 struction began excavation north side of the lot prior to dift pile prior to the inspe inspection on 7/31/21. Lot 5 ctures sodded the lot prior Lot 6	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. /21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, l ction on 4/26/21. LIM Cor	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.    Removed  Active  Active  Active  Active  Active  Active  Removed  Removed  Removed  Removed  Removed  Removed  Z1.  Removed  Removed  Z1.  Removed  Z2.  Removed  Z2.  Removed  Z3.  Removed  Z4.  Removed	to the inspection or alleviate ponding or oned the inlet filter <u>Yes</u> e inspection on 7/3 nstruction was reminent No LIM Construction tinue to monitor. LI		
	Current Condition:  Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition: Lot 5 Current Condition: Lot 6 Current Condition:	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Cor installed silt fence on the I Construction removed the side of the lot prior to the Silt Fence Removed - Evolved Struct Individual Lot	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o prmed to complete by 10/4 Lot 4 istruction began excavation orth side of the lot prior t difficult file prior to the inspec inspection on 7/31/21. Lot 5 ctures sodded the lot prior to Lot 6 ion sodded the lot prior to	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, i ction on 4/26/21. LIM Cor to the inspection on 9/27/21 the inspection on 9/27/21	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.   Removed  Active  Active  Active  Active  Active  Spection on 3/15/21. L  Active  Removed  Removed  /21.  Removed /21.  Removed /21.  Removed /21.  Removed /21.  Removed /21.  Removed /21.	to the inspection or alleviate ponding or oned the inlet filter Yes e inspection on 7/3 hstruction was remi No IM Construction tinue to monitor. LI w silt fence on the r		
Lot 8 Individual Lot Lot 8 3/15/2021 Active Yes	Current Condition: Lot 1 Current Condition: Lot 2 Current Condition: Lot 3 Current Condition: Lot 4 Current Condition: Lot 5 Current Condition: Lot 6 Current Condition: Lot 7	Good Condition Negus & 2/10/20. Negus & Son's C street. The inlet filter was to the inspection on 3/15/2 Individual Lot Removed - New Chapter Individual Lot Removed - New Chapter Individual Lot Fair Condition - LIM Cons LIM Construction began e Silt fence should be instal LIM Construction was info on 10/27/21, 11/12/21 Individual Lot Good Condition - LIM Corr installed silt fence on the Silt Fence Removed - Evolved Struct Silt Fence Removed - LIM Construct Silt Fence Removed - LIM Construct Silt fence Silt fence Silt fence Removed - LIM Construct Silt fence Silt fence Silt fence	Son's Construction instal onstruction removed the i installed prior to the 11/10 21. E&A inspector will con Lot 1 Homes sodded the lot prior Lot 2 sodded the lot prior to the Lot 3 truction installed silt fence xcavation on the lot prior led along the north side o rmed to complete by 10/4 Lot 4 struction began excavati north side of the lot prior ditt pile prior to the inspe nspection on 7/31/21. Lot 5 ctures sodded the lot prior to Lot 6 ion sodded the lot prior to Lot 7 evelopment LLC Installed vation on the lot prior to the in front of the lot.	led two big red inlet filters inlet filters prior to the insp //20 inspection. Ryan Sch tinue to monitor. or to the 11/11/21 inspect a inspection on 8/31/21. 7/31/2021 a along the northeast corn to the inspection on 9/27/ f the lot. //21. Not done as of the la 3/15/2021 on on the lot prior to the ir o the 3/24/21 inspection, I ction on 4/26/21. LIM Cor to the inspection on 9/27/21 silt fence in the back of the ne inspection on 9/27/21.	in the curb inlet prior in bection on 4/01/20 to a warz repaired/repositi Removed ion.  Removed Active Active Active Active Active Active Active Active Removed Removed Removed Active Removed Active Removed Active Removed Active Activ	to the inspection or alleviate ponding or oned the inlet filter yes e inspection on 7/3 No IM Construction tinue to monitor. LI w silt fence on the r Yes 21 inspection. LIM		

	Fair Condition - LIM Construction began excavation on the lot prior to the inspection on 3/15/21. Silt fence was installed the back of the lot prior to the 3/24/21 inspection. The driveway in front of the lot was paved prior to the 4/7/21 inspection								
	<ol> <li>The street should be cleaned in the front of the lot.</li> <li>Silt fence at the rear of the lot should be repaired.</li> </ol>								
		<ol> <li>LIM Construction was informed to complete by 3/22/21. Not done as of last inspection. LIM Construction was remind on 3/26/21, 4/10/21, 4/28/21, 6/22/21, 7/6/21, 7/14/21, 7/27/21, 8/11/21, 8/26/21, 9/30/21, 10/27/21, 11/12/21</li> </ol>							
	2.) LIM Construction was i reminded on 11/12/21	informed to complete by	11/1/21. Not done as of th	he last inspection. LIM	Construction was				
Lot 9	Individual Lot	Lot 9	5/24/2021	Active	Yes				
Current Condition:	Fair Condition - LIM Cons silt fence at the rear of the concrete waste from the re of the back of the lot prior	truction began excavatio of on 5/24/21. LIM Con ear of the lot prior to the	n on the lot prior to the ins struction removed the dirt inspection on 6/21/21. LIN	spection on 5/24/21. L pile from the ROW ar	IM Construction ins				
	Silt fence should be repair		4/21. Not done as of the la	ast inspection. LIM Co	onstruction was rem				
	on 10/27/21. 11/12/21			· · ·					
Lot 10 Current Condition:	Individual Lot Removed - Viking Homes	Lot 10 sodded the lot prior to th	ne inspection on 10/13/21	Removed					
Lot 11	Individual Lot	GG15		Removed	1				
Current Condition:	Removed - LIM Construct inspection on 7/11/20.		nstalled a run of silt fence		ect the sod prior to				
Lot 12	Individual Lot	FF15		Removed					
Current Condition:	Removed - Viking Homes		e 11/10/20 inspection.		1				
Lot 13 Current Condition:	Individual Lot Removed - LIM Construct	DD15 ion sodded the lot, and in	stalled a run of silt fence	Removed	ect the sod prior to				
Current Condition.	inspection on 4/26/21.			benind the lot to prote	set the sou phot to				
Lot 14	Individual Lot	Lot 14	1/14/2021	Pending	Yes				
Current Condition:	Pending - Edward Custom the ROW during the 01/14								
	1.) Curb line should be cle 2.) Silt fence or straw watt	tles should be installed a	long the front of the lot.		51.010.00				
	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home	tles should be installed a s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not d	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp	80/21, 10/27/21				
Lot 15	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on	tles should be installed a s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not d	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp	80/21, 10/27/21				
Lot 15 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 es LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not d , 9/2/21, 9/30/21, 10/27/2	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp 1 Removed	80/21, 10/27/21 Dection. Edward Cu				
	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on Individual Lot Removed - LIM Construct	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 es LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not d , 9/2/21, 9/30/21, 10/27/2	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp 1 Removed	80/21, 10/27/21 Dection. Edward Cu				
Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on Individual Lot Removed - LIM Construct inspection on 4/26/21.	tles should be installed at s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 is LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16	long the front of the lot. omplete by 3/8/21. Not do l, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not d . 9/2/21. 9/30/21, 10/27/2 Installed a run of silt fence	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp 1 Removed behind the lot to prote Removed	80/21, 10/27/21 Dection. Edward Cu				
Current Condition: Lot 16 Current Condition: Lot 17	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot	tles should be installed al status and the stalled al as LLC was informed to c 3/17/21, 3/26/21, 4/10/21 es LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and in Lot 16 ction sodded the lot print Lot 17	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do 	1, 8/11/21, 9/2/21, 9/3 tone as of the last insp 1 Removed behind the lot to prote Removed 1/22/21. Active	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 es LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 ction sodded the lot pri Lot 17 truction installed silt fenc	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do , 9/2/21, 9/30/21, 10/27/2 natalled a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout	1, 8/11/21, 9/2/21, 9/3 tone as of the last insp 1 Removed behind the lot to prote Removed 1/22/21. Active	0/21, 10/27/21 Dection. Edward Cu ect the sod prior to the Yes				
Current Condition: Lot 16 Current Condition: Lot 17	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 1 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 Ction sodded the lot pri Lot 17 truction installed silt fenc began prior to the 11/11/ e lot needs to be repaired	long the front of the lot. omplete by $3/8/21$ . Not dd 1, 6/22/21, 7/14/21, 7/27/2 omplete by $7/17/21$ . Not di .9/2/21. 9/30/21. 10/27/2 Installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d.	1, 8/11/21, 9/2/21, 9/3 lone as of the last insp 1 Removed behind the lot to prote <b>Removed</b> 1/22/21. Active th side of the lot prior t	0/21, 10/27/21 Dection. Edward Cu set the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tion sodded the lot print Lot 17 truction installed silt fenc began prior to the 11/11/21 e lot needs to be repaired to complete by 11/18/21	long the front of the lot. omplete by $3/8/21$ . Not dd 1, 6/22/21, 7/14/21, 7/27/2 omplete by $7/17/21$ . Not di .9/2/21. 9/30/21. 10/27/2 Installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d.	1, 8/11/21, 9/2/21, 9/3 tone as of the last insp 1 Removed behind the lot to prote <b>Removed</b> 1/22/21. Active th side of the lot prior to the side of the side of the lot prior to the side of the side o	0/21, 10/27/21 Dection. Edward Cu set the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 18	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed Individual Lot	tles should be installed al as LLC was informed to c 3/17/21, 3/26/21, 4/10/21 as LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 Lot 16 Lot 17 truction installed silt fenc began prior to the 11/11/ e lot needs to be repaired to complete by 11/18/20 AA15	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do 1, 9/2/21. 9/30/21. 10/27/2 hstalled a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las	1, 8/11/21, 9/2/21, 9/3 tone as of the last insp 1 Removed behind the lot to prote Removed 1/22/21. Active th side of the lot prior the th side of t	0/21, 10/27/21 Dection. Edward Cu set the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 18 Current Condition: Lot 18 Current Condition: Lot 19	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed	tles should be installed al as LLC was informed to c 3/17/21, 3/26/21, 4/10/21 as LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 Lot 16 Lot 17 truction installed silt fenc began prior to the 11/11/ e lot needs to be repaired to complete by 11/18/20 AA15	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do 1, 9/2/21. 9/30/21. 10/27/2 hstalled a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las	1, 8/11/21, 9/2/21, 9/3 tone as of the last insp 1 Removed behind the lot to prote Removed 1/22/21. Active th side of the lot prior the th side of t	0/21, 10/27/21 Dection. Edward Cu set the sod prior to Yes				
Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 1 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of the LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 ction sodded the lot price Lot 17 truction installed silt fence began prior to the 11/11/ re lot needs to be repaired d to complete by 11/18/27 AA15 e Homes sodded the lot price Z15 e Homes sodded the lot price 2 15	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do , 9/2/21. 9/30/21. 10/27/2 nstalled a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d. 1. Not done as of the las prior to the inspection on 1	1, 8/11/21, 9/2/21, 9/3         tope as of the last insp         1       Removed         behind the lot to prote         Removed         11/22/21.         Active         th side of the lot prior to         .t inspection.         Removed         10/05/20.         Removed         10/05/20.	0/21, 10/27/21 Dection. Edward Cu set the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Lot 18 Current Condition: Lot 18 Current Condition: Lot 19	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 1 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tion sodded the lot print Lot 17 truction installed silt fenc began prior to the 11/11/21 e lot needs to be repaired to complete by 11/18/21 AA15 e Homes sodded the lot print 215 e Homes sodded the lot print 215	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not di . 9/2/21. 9/30/21. 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las prior to the inspection on 1 orior to the inspection on 1	1, 8/11/21, 9/2/21, 9/3         tope as of the last inspanded in the lot to protect the lot the lot the lot the lot to protect the lot the	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 20	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot	tles should be installed al as LLC was informed to c 3/17/21, 3/26/21, 4/10/21 as LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tuct on installed silt fence began prior to the 11/11/12 e lot needs to be repaired to complete by 11/18/20 AA15 e Homes sodded the lot prior 215 e Homes sodded the lot prior 215	Iong the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do , 9/2/21. 9/30/21. 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 1 0 1	1, 8/11/21, 9/2/21, 9/3         Ione as of the last inspanded in the lot to protect the lot to protect the lot to protect the lot to protect the lot to prior to the lot the lot to prior to the lot pris the lot pris the lot prior to the lot prior to the lo	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 1 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot	tles should be installed al as LLC was informed to c 3/17/21, 3/26/21, 4/10/21 as LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tuct on installed silt fence began prior to the 11/11/12 e lot needs to be repaired to complete by 11/18/20 AA15 e Homes sodded the lot prior 215 e Homes sodded the lot prior 215	Iong the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do , 9/2/21. 9/30/21. 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 1 0 1	1, 8/11/21, 9/2/21, 9/3         Ione as of the last inspanded in the lot to protect the lot to protect the lot to protect the lot to protect the lot to prior to the lot the lot to prior to the lot pris the lot pris the lot prior to the lot prior to the lo	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 21 Current Condition: Lot 22 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Fair Condition - LIM Construct Individual Lot Fair Condition - LIM Construct Silt fence at the front of the LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot	tles should be installed al is LLC was informed to c 3/17/21, 3/26/21, 4/10/21 be LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 ction sodded the lot privi- truction installed silt fenc began prior to the 11/11/ ruction installed silt fenc began prior to the 11/11/ e lot needs to be repaired d to complete by 11/18/27 AA15 e Homes sodded the lot privi- z15 e Homes sodded the lot privi- Lot 22 e LLC sodded the lot privi-	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do J. 9/2/21, 9/30/21, 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 1	1, 8/11/21, 9/2/21, 9/3         tone as of the last insp         1       Removed         behind the lot to prote         Removed         It inspection.         1       Active         th side of the lot prior to         It inspection.         10/05/20.       Removed         Removed	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 21 Current Condition: Lot 22 Current Condition: Lot 22 Current Condition: Lot 22	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Construct Silt fence at the front of the LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence	tles should be installed al is LLC was informed to c 3/17/21, 3/26/21, 4/10/21 is LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 ction sodded the lot privi- truction installed silt fenc began prior to the 11/11/ ruction installed silt fenc began prior to the 11/11/ e lot needs to be repaired d to complete by 11/18/27 AA15 e Homes sodded the lot privi- 215 e Homes sodded the lot privi- Lot 22 e LLC sodded the lot privi- Lot 23	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do J. 9/2/21, 9/30/21, 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 10/1	1, 8/11/21, 9/2/21, 9/3         tope as of the last insp         1       Removed         behind the lot to prote         Removed         It inspection.         1       Active         th side of the lot prior to         topo the lot prior to<	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 21 Current Condition: Lot 22 Current Condition: Lot 22 Current Condition: Lot 23 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot <b>Removed - LIM Construct</b> Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of the LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence Removed - Seeing Double	tles should be installed al is LLC was informed to c 3/17/21, 3/26/21, 4/10/21 bs LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 ction sodded the lot privi- truction installed silt fenc began prior to the 11/11/ ruction installed silt fenc began prior to the 11/11/ e lot needs to be repaired d to complete by 11/18/27 AA15 e Homes sodded the lot privi- e Lot 22 e LLC sodded the lot privi- Lot 23 e LLC sodded the lot privi- e LLC so	long the front of the lot. omplete by 3/8/21. Not do , 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not do J. 9/2/21, 9/30/21, 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout (21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 10/1	1, 8/11/21, 9/2/21, 9/3         tone as of the last insp         1       Removed         behind the lot to prote         Removed         It inspection.         1       Active         th side of the lot prior to         t inspection.         10/05/20.       Removed         11/21.       Removed	0/21, 10/27/21 Dection. Edward Cu control the sod prior to Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 21 Current Condition: Lot 22 Current Condition: Lot 23 Current Condition: Lot 23 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2.) Edward Custom Home Homes was reminded on Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot Removed - LIM Construct Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of th LIM Construction informed Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tion sodded the lot privi- began prior to the 11/11/2 e lot needs to be repaired to complete by 11/18/27 A A15 e Homes sodded the lot p Z15 e Homes sodded the lot p Z15 e Homes sodded the lot p Lot 22 e LLC sodded the lot privi- tot 23 e LLC sodded the lot privi- Lot 23 e LLC sodded the lot privi- Lot 24	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not di , 9/2/21. 9/30/21. 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 10/2 prior to the inspectio	1, 8/11/21, 9/2/21, 9/3         tone as of the last insp         1       Removed         behind the lot to prote         Removed         Intervention         Interventinterventinterventinterventintervention	0/21, 10/27/21 Dection. Edward Cu ect the sod prior to the Yes				
Current Condition: Lot 16 Current Condition: Lot 17 Current Condition: Current Condition: Lot 18 Current Condition: Lot 19 Current Condition: Lot 20 Current Condition: Lot 21 Current Condition: Lot 22 Current Condition: Lot 22 Current Condition: Lot 23 Current Condition:	2.) Silt fence or straw watt 1.) Edward Custom Home Homes was reminded on 2 2.) Edward Custom Home Homes was reminded on 2 Individual Lot Removed - LIM Construct inspection on 4/26/21. Individual Lot <b>Removed - LIM Construct</b> Individual Lot Fair Condition - LIM Const 7/31/21. Excavation work Silt fence at the front of the LIM Construction informer Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Individual Lot Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence Removed - Seeing Double Silt Fence Removed - Seeing Double	tles should be installed al s LLC was informed to c 3/17/21, 3/26/21, 4/10/21 s LLC was informed to c 7/14/21, 7/27/21, 8/11/21 Lot 15 ion sodded the lot, and ir Lot 16 tion sodded the lot privi- began prior to the 11/11/2 e lot needs to be repaired to complete by 11/18/27 A A15 e Homes sodded the lot p Z15 e Homes sodded the lot p Z15 e Homes sodded the lot p Lot 22 e LLC sodded the lot privi- tot 23 e LLC sodded the lot privi- Lot 23 e LLC sodded the lot privi- Lot 24	long the front of the lot. omplete by 3/8/21. Not do 1, 6/22/21, 7/14/21, 7/27/2 omplete by 7/17/21. Not di , 9/2/21. 9/30/21. 10/27/2 installed a run of silt fence or to the inspection on 1 7/31/2021 e along the front and sout 21 inspection. d. 1. Not done as of the las prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 1 prior to the inspection on 10/2 prior to the inspectio	1, 8/11/21, 9/2/21, 9/3         tone as of the last insp         1       Removed         behind the lot to prote         Removed         Intervention         Interventinterventinterventinterventintervention	0/21, 10/27/21 Dection. Edward Cu ect the sod prior to to Yes				

al Lot eeing Double LLC eing Double LLC be should be cleaned. tles should be insta	Lot 27 Sodded the lot print Lot 28 Sodded the lot print Lot 28 Sodded the lot print Lot 33	ior to the inspection on ior to the inspection on ior to the inspection on ior to the inspection on 11/11/2021 or to the inspection on 11,	Removed           11/22/21.           Removed           11/22/21.           Removed           11/22/21.           Pending	
eeing Double LLC al Lot eeing Double LLC al Lot eeing Double LLC al Lot eing Double LLC be should be cleaned. tles should be insta buble LLC was infor	C sodded the lot pri Lot 28 C sodded the lot pri Lot 28 C sodded the lot pri Lot 33 Egan excavation prio	ior to the inspection on ior to the inspection on 11/11/2021	11/22/21. Removed 11/22/21. Removed 11/22/21. Pending	
al Lot eeing Double LLC eeing Double LLC eeing Double LLC eing Double LLC be should be cleaned. tles should be insta ouble LLC was infor	Lot 28 Sodded the lot pri Lot 28 Sodded the lot pri Lot 33 egan excavation prio	ior to the inspection on ior to the inspection on 11/11/2021	Removed 11/22/21. Removed 11/22/21. Pending	
eeing Double LLC aal Lot aal Lot aal Lot eing Double LLC be should be cleaned. tles should be insta buble LLC was infor	C sodded the lot pri Lot 28 C sodded the lot pri Lot 33 egan excavation prio	ior to the inspection on	11/22/21. Removed 11/22/21. Pending	
Ial Lot eeing Double LLC ial Lot eing Double LLC be should be cleaned. tles should be insta ouble LLC was infor	Lot 28 C sodded the lot pri Lot 33 egan excavation prio	ior to the inspection on	Removed 11/22/21. Pending	
eeing Double LLC al Lot eing Double LLC be should be cleaned. tles should be insta puble LLC was infor	C sodded the lot pri Lot 33 egan excavation prio	11/11/2021	11/22/21. Pending	
ial Lot eing Double LLC be should be cleaned. tles should be insta puble LLC was infor	Lot 33 egan excavation pric	11/11/2021	Pending	
eing Double LLC be should be cleaned. tles should be insta puble LLC was infor	egan excavation prio			
eing Double LLC be should be cleaned. tles should be insta puble LLC was infor	egan excavation prio			Yes
tles should be insta buble LLC was infor				
		t.		
		/ 11/18/21. Not done as o / 11/18/21. Not done as o		
			-	
al Lot	Lot 33	11/11/2021 or to the inspection on 11/	Pending /11/21	Yes
Ŭ	igan oncertaion pin			
	lled along the stree	t.		
while LLC was infer	med to complete h	(11/19/21 Net dans as	of the last increation	
		11/11/2021	Des l'as	
				Yes
	-			
		t.		
	ũ			
				Yes inspection.
-		Ŭ		
		t.		
uble LLC was infor	mod to complete by	(11/18/21 Not dono as (	of the last inspection	
ual Lot	Lot 34	10/11/2021	Active	Yes
should be cleaned.				
les should be insta	lled along the street	t.		
uble LLC was infor	med to complete by	/ 11/18/21. Not done as (	of the last inspection	
uble LLC was infor	med to complete by	/ 11/18/21. Not done as o	of the last inspection	
ual Lot	Lot 35	10/11/2021	Active	Yes
I - Seeing Double L	LC installed silt fen	ce along the side of the lo	ot prior to the 10/11/21	inspection.
should be cleaned.				
les should be insta	alled along the street	t.		
	med to complete by	44/40/04 N 4		
			of the last inspection.	
		/ 11/18/21. <b>Not done as (</b> / 11/18/21. <b>Not done as (</b>	of the last inspection.	
ouble LLC was infor	rmed to complete by Lot 56		of the last inspection. Removed	
	uble LLC was infor uble LLC was infor al Lot should be cleaned. les should be insta uble LLC was infor uble LLC was infor	tes should be installed along the street suble LLC was informed to complete by tal Lot Lot 33 along Double LLC began excavation prior should be cleaned. tes should be installed along the street suble LLC was informed to complete by tal Lot Lot 33 1 - Seeing Double LLC installed silt fend should be cleaned. tes should be installed along the street should be installed along the street should be installed along the street should be should be installed along the street should be sh	Ites should be installed along the street.         uble LLC was informed to complete by 11/18/21. Not done as one of the location of	Ites should be installed along the street.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         ial Lot       Lot 33       11/11/2021       Pending         sing Double LLC began excavation prior to the inspection on 11/11/21.       Should be cleaned.       Ites should be installed along the street.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection on uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed to complete by 11/18/21. Not done as of the last inspection.         uble LLC was informed t

Lot 62 Current Condition:	<ol> <li>Silt fence should be clean the second struction was in reminded on 9/30/21, 10/.</li> <li>LIM Construction was in reminded on 9/30/21, 10/.</li> <li>Individual Lot</li> <li>Fair Condition - LIM Construction</li> </ol>	eaned out and repaired at t nformed to complete by 8/ 27/21, 11/12/21							
Lot 62 Current Condition:	reminded on 9/30/21, 10/ 2. LIM Construction was i reminded on 9/30/21_10/ Individual Lot Fair Condition - LIM Cons	27/21, 11/12/21	<ol> <li>Curb line should be cleaned in the front of the lot.</li> <li>Silt fence should be cleaned out and repaired at the rear of the lot.</li> </ol>						
Lot 62 Current Condition:	2. LIM Construction was i reminded on 9/30/21_10/ Individual Lot Fair Condition - LIM Cons		30/21. Not done as of the	last inspection. LIM C	Construction was				
Lot 62 Current Condition:	Individual Lot Fair Condition - LIM Cons		30/21. Not done as of the	last inspection. LIM C	Construction was				
Current Condition:	Fair Condition - LIM Cons	Lot 63	11/11/2021	Active	Yes				
		truction excavated the lot	prior to the 11/11/21 insp	ection. Silt fence alrea	adv installed at the				
	of the lot no other BMPs r 1. Curb line should be cle	ecommended as of 11/11/ aned in the front of the lot. the lot should be reinstalle	21.						
		nformed to complete by 11 nformed to complete by 11							
Lot 63	Individual Lot	Lot 63	7/26/2021	Active	Yes				
Current Condition:	Fair Condition - LIM Cons	struction excavated the lot commended as of 7/26/21.							
		noved from the ROW. aned in the front of the lot. the lot should be reinstalle							
	reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 8/11/21, 8/2 3. LIM Construction was i	nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21	/12/21 2/21. Not done as of the l /12/21	ast inspection. LIM Co	onstruction was				
	reminded on 9/30/21_10/								
Lot 64 Current Condition:	Individual Lot Removed - LIM Constru	Lot 64 ction sodded the lot prio	r to the inspection on 1	Removed 1/22/21.					
Lot 68	Individual Lot	Lot 68	7/26/2021	Active	Yes				
		aned in the front of the lot. the lot should be reinstalle			the 11/11/21 insp				
	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2		ed. 2/21. Not done as of the I /12/21	ast inspection. LIM Co	onstruction was				
	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/	ed. 2/21. Not done as of the I /12/21	ast inspection. LIM Co					
	<ol> <li>Silt fence at the rear of</li> <li>LIM Construction was i reminded on 8/11/21, 8/2</li> <li>LIM Construction was i</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/	ed. 2/21. Not done as of the I /12/21	ast inspection. LIM Co	onstruction was				
	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21	ed. 2/21. Not done as of the k /12/21 30/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed	onstruction was				
Lot 69 Current Condition: Lot 70	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the 20/21. Not done as of the line as of the lin	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed	onstruction was				
Lot 69 Current Condition:	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the 20/21. Not done as of the line as of the lin	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed	onstruction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71	2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot Individual Lot	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot Lot 71	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active	onstruction was Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	2. Silt fence at the rear of     1. LIM Construction was i     reminded on 8/11/21, 8/2     2. LIM Construction was i     reminded on 9/30/21, 10/2     Individual Lot     Individual Lot     Removed- New Chapter I     Individual Lot     Removed - Smart Develo     Individual Lot     Fair Condition - LIM Cons     the lot no other BMPs rec     inspection on 8/31/21.     1. Curb line should be cle	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot Lot 71 truction excavated the lot ommended as of 8/9/21. L aned in the front of the lot.	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the analytic formation of the prior to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already	onstruction was Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	<ol> <li>Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2: 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot Removed - Smart Develo Individual Lot Fair Condition - LIM Cons the lot no other BMPs rea inspection on 8/31/21.</li> <li>Curb line should be cle 2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/26/21, 9/3</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot commended as of 8/9/21. L the lot should be reinstalle nformed to complete by 8/ 0/21, 10/27/21, 11/12/21	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ad. 16/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM C	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	<ol> <li>Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot Removed - Smart Develo Individual Lot Fair Condition - LIM Cons the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle 2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/26/21, 9/3 2. LIM Construction was i</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot commended as of 8/9/21. L truction excavated the lot commended as of 8/9/21. L caned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ad. 16/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM C	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	2. Silt fence at the rear of     1. LIM Construction was i     reminded on 8/11/21, 8/2     2. LIM Construction was i     reminded on 9/30/21, 10/     Individual Lot     Removed- New Chapter I     Individual Lot     Removed - Smart Develo     Individual Lot     Fair Condition - LIM Cons     the lot no other BMPs rec     inspection on 8/31/21.     1. Curb line should be cle     2. Silt fence at the rear of     1. LIM Construction was i     reminded on 8/26/21, 9/3     2. LIM Construction was     i     reminded on 9/30/21, 10/	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot commended as of 8/9/21. L commended be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 and to complete by 8/ 27/24. 11/12/21	ed. 2/21. Not done as of the l /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ad. 16/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	<ol> <li>Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed- New Chapter I Individual Lot Removed - Smart Develo Individual Lot Fair Condition - LIM Cons the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle 2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/26/21, 9/3 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot commended as of 8/9/21. L truction excavated the lot commended as of 8/9/21. L caned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	<ol> <li>Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10// Individual Lot Removed- New Chapter I Individual Lot Removed - Smart Develor Individual Lot Fair Condition - LIM Const the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle 2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/26/21, 9/3 2. LIM Construction was i reminded on 9/30/21. 10// Individual Lot Removed - LIM Construct</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot truction excavated the lot commended as of 8/9/21. L aned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 27/21, 11/12/21 Lot 72 tion sodded the lot prior to	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition:	<ol> <li>Silt fence at the rear of         <ol> <li>LIM Construction was i             reminded on 8/11/21, 8/2             <li>LIM Construction was i             reminded on 9/30/21, 10/.</li> <li>Individual Lot</li></li></ol></li></ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot to 71 truction excavated the lot sommended as of 8/9/21. L aned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 Lot 72	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the prior to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the the inspection on 6/11/21	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition: Current Condition:	<ol> <li>Silt fence at the rear of 1. LIM Construction was i reminded on 8/11/21, 8/2 2. LIM Construction was i reminded on 9/30/21, 10/ Individual Lot Removed - New Chapter I Individual Lot Removed - Smart Develo Individual Lot Fair Condition - LIM Const the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle 2. Silt fence at the rear of 1. LIM Construction was i reminded on 8/26/21, 9/3 2. LIM Construction was i reminded on 9/30/21.10/ Individual Lot Removed - LIM Construct Individual Lot Removed - LIM Construct Individual Lot</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot to 71 truction excavated the lot commended as of 8/9/21. L the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 0/21, 11/12/21 to rzz tion sodded the lot prior to AA18 tion sodded the lot prior to BB18	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the 10/21. Not done as of the the inspection on 6/11/21 the inspection on 6/11/21	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition: Lot 72 Current Condition: Lot 73 Current Condition: Lot 73 Current Condition: Lot 74	<ol> <li>Silt fence at the rear of reminded on 8/11/21, 8/2</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>Individual Lot</li> <li>Removed - New Chapter I Individual Lot</li> <li>Removed - Smart Develo</li> <li>Individual Lot</li> <li>Fair Condition - LIM Const the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle</li> <li>Silt fence at the rear of reminded on 9/30/21, 10/ Individual Lot</li> <li>LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> <li>Removed - LIM Construct Individual Lot</li> <li>Removed - LIM Construct Individual Lot</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot ommended as of 8/9/21. L truction excavated the lot ommended as of 8/9/21. L aned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 27/21. 11/12/21 Lot 72 tion sodded the lot prior to BB18 tion sodded the lot prior to	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the r to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the 10/21. Not done as of the the inspection on 6/11/21 the inspection on 6/11/21	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition: Current Condition: Lot 72 Current Condition: Lot 73 Current Condition: Lot 73 Current Condition: Lot 74	<ol> <li>Silt fence at the rear of reminded on 8/11/21, 8/2</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>Individual Lot Removed- New Chapter I Individual Lot</li> <li>Removed - Smart Develo</li> <li>Individual Lot</li> <li>Fair Condition - LIM Const the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle</li> <li>Silt fence at the rear of</li> <li>LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> <li>Emoved - LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> <li>Removed - LIM Construction Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot truction excavated the lot ommended as of 8/9/21. L truction excavated the lot ommended as of 8/9/21. L the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 27/21. 11/12/21 Lot 72 tion sodded the lot prior to BB18 tion sodded the lot prior to BB18	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the prior to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the the inspection on 6/11/21 the 10/26/20 inspection.	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed Removed Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				
Lot 69 Current Condition: Lot 70 Current Condition: Lot 71 Current Condition: Lot 72 Current Condition: Lot 73 Current Condition: Lot 73 Current Condition:	<ol> <li>Silt fence at the rear of reminded on 8/11/21, 8/2</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>LIM Construction was i reminded on 9/30/21, 10/</li> <li>Individual Lot Removed- New Chapter I Individual Lot</li> <li>Removed - Smart Develo</li> <li>Individual Lot</li> <li>Fair Condition - LIM Const the lot no other BMPs rec inspection on 8/31/21.</li> <li>Curb line should be cle</li> <li>Silt fence at the rear of</li> <li>LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> <li>Emoved - LIM Construction was i reminded on 9/30/21, 10/ Individual Lot</li> <li>Removed - LIM Construction Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> <li>Removed - LIM Construction</li> <li>Individual Lot</li> </ol>	the lot should be reinstalle nformed to complete by 8/ 6/21, 9/30/21, 10/27/21, 11 nformed to complete by 8/ 27/21, 11/12/21 Lot 69 Homes sodded the lot prio Lot 70 pment LLC sodded the lot ommended as of 8/9/21. L truction excavated the lot ommended as of 8/9/21. L aned in the front of the lot. the lot should be reinstalled nformed to complete by 8/ 0/21, 10/27/21, 11/12/21 nformed to complete by 8/ 27/21. 11/12/21 Lot 72 tion sodded the lot prior to BB18 tion sodded the lot prior to	ed. 2/21. Not done as of the I /12/21 30/21. Not done as of the prior to the inspection on 8/9/ prior to the inspection on 8/9/2021 prior to the 8/9/21 inspect IM Construction removed ed. 16/21. Not done as of the 30/21. Not done as of the the inspection on 6/11/21 the 10/26/20 inspection.	ast inspection. LIM Co last inspection. LIM Co Removed 21. Removed 8/31/21. Active ion. Silt fence already the dirt pile from the last inspection. LIM Co last inspection. LIM Co Removed Removed Removed	onstruction was Construction was Construction was y installed at the re ROW prior to the Construction was				

	Demonstrate Militian Llamaa	بمغيبة فالمحام والألم والمام			
Current Condition: Lot 78	Removed - Viking Homes Individual Lot	Lot 78	the inspection on 8/11/20.	Removed	
Current Condition:			to the inspection on 7/6/21		
Lot 79	Individual Lot	EE18		Removed	
Current Condition:			ot prior to the inspection or		
					1
Lot 80	Individual Lot	Lot 80		Removed	
Current Condition:			or to the inspection on 6/21	1	
Lot 81 Current Condition:	Individual Lot	Lot 81	the inspection on 7/26/21.	Removed	
Lot 82	Individual Lot	Lot 82		Removed	
Current Condition:			or to the inspection on 6/21		
Lot 83	Individual Lot	HH18		Removed	
Current Condition:			prior to the inspection on 9		
PB 1	Portable Bathroom	HH14	5/5/2020	Active	Yes
Current Condition:			able toilet on lot 10, which is		
	The portable toilet should LIM Construction LLC was reminded on 5/29/20, 6/11	be secured. s informed to complete 1/20, 7/14/20, 8/13/20, 8	ilet to lot 14 prior to the insp by 5/05/20. Not done as of 3/25/20, 10/05/20, 11/11/20 1, 8/26/21, 9/30/21, 10/27/2	the last inspection. Lll , 01/15/21, 3/2/21, 3/1	
SB A	Sediment Basin	D26	11/15/2018	Active	No
Current Condition:	9/19/19. The E&A inspect is completed. Negus & So within the wall of the basin the sediment basin prior to outlet pipe prior to the insp along the northern outlet p below both riser outfalls p	or will monitor and dete on's Construction backfil on prior to the inspection on the inspection on 12/1 pection on 1/27/20. Neg oppe prior to the inspection	truction partially installed the rmine if all elements of the led and compacted dirt arc on 12/16/19. Negus & Son 6/19. Negus & Son's Cons jus & Son's Construction bas on on 7/14/20. Negus & Soc 7/28/20. Roth Enterprises	basin have been corre- ound the riser and the 's Construction partiall truction backfilled and ackfilled and compacted on's Construction insta- cleaned out the basin	ectly installed when wo portion of the outlet pip y dug out and reshape compacted along the ed the subsided area lled the Scour Holes prior to the inspection
	9/22/20. Roth Enterprises				
SB B	Sediment Basin	R20	11/15/2018	Active	No
SB B Current Condition:	Sediment Basin Good Condition - 15% fille The E&A inspector will mo completed. Negus & Son's	R20 ed - Negus and Son's C ponitor and determine if a s Construction installed	11/15/2018 onstruction installed one of all elements of the basin ha the second riser in the bas	Active the riser pipes prior to ve been correctly insta in prior to the inspecti	o inspection on 9/19/19 alled when work is on on 10/02/19. Rip ra
Current Condition:	Sediment Basin Good Condition - 15% fille The E&A inspector will mo completed. Negus & Son's still needs to be installed t compacted along the leng the inspection on 7/28/20.	R20 ad - Negus and Son's C onitor and determine if a s Construction installed selow both outfalls, and th of the pipe. Negus & Roth Enterprises clear	11/15/2018 onstruction installed one of all elements of the basin ha	Active the riser pipes prior to ve been correctly insta- in prior to the inspecti- inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2	o inspection on 9/19/19 alled when work is on on 10/02/19. Rip raj o be backfilled and w the riser outfall prior
	Sediment Basin Good Condition - 15% fille The E&A inspector will mo completed. Negus & Son's still needs to be installed t compacted along the leng the inspection on 7/28/20. seeded and matted the ske Silt fence Fair Condition - Negus & S	R20 ed - Negus and Son's C ponitor and determine if a s Construction installed pelow both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta	11/15/2018 onstruction installed one of all elements of the basin ha the second riser in the bas open area around the orig Son's Construction installe the out the basin prior to th	Active the riser pipes prior to ve been correctly insta in prior to the inspecti inal riser pipe needs to do the Scour Hole belo e inspection on 9/22/2 0. Active he inspection on 11/8/	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ra b be backfilled and w the riser outfall prior 0. Roth Enterprises Yes 18. There is a remaining
Current Condition: SF 1	Sediment Basin           Good Condition - 15% fille           The E&A inspector will modely completed. Negus & Son's           still needs to be installed the compacted along the leng the inspection on 7/28/20.           seeded and matted the leng the inspection on 7/28/20.           seeded and matted the slope stretch that needs to be readded t-posts to the new run of sill reinstalled the silt fence we north of SB B prior to the inspection to the inspection 5/24/21.           1.) The silt fence should b           2.) Silted fence needs to b           1.) Ryan Schwarz was infor on 8/12/20, 10/05/20, 1/15	R20 ad - Negus and Son's C onitor and determine if a s Construction installed the of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta epaired. Negus & Son's run of silt fence between nd SB B, cleaned out an t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw the retied to several t-pos- be cleaned out and reties ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/	11/15/2018         onstruction installed one of all elements of the basin has open area around the orig Son's Construction installe and out the basin prior to the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho SB A, and the underminer of SB B, repaired the newer run of epaired the newer run of epaired the newer run of the patch over the t-posts bectended the silt fence in a state of SB B, and the silt fence in a state of the patch over the toposts of the patch over the toposts of the patch over the toposts of the patch over the silt fence in a state of in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/14	Active the riser pipes prior to ve been correctly insta in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 0. Active he inspection on 11/8/ he new run of silt fence d area, cleaned out an of silt fence between S ad the old run of silt fen- between the undermin nd the top of the outfa few locations prior to of the site.	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t nice east of SB B, ence where removed ce where undermined ed portion and SB A at III at the north end of the the inspection on
Current Condition: SF 1 Current Condition:	Sediment Basin           Good Condition - 15% fille           The E&A inspector will modeled           completed. Negus & Son's           still needs to be installed to           compacted along the leng           the inspection on 7/28/20.           seeded and matted the slop           Silt fence           Fair Condition - Negus & S           stretch that needs to be readed t-posts to the new run of silt           reinstalled the silt fence will near the southeast corner           between the undermined p           run prior to the inspection           5/24/21.           1.) The silt fence should b           2.) Silted fence needs to to           1.) Ryan Schwarz was inform           on 8/12/20, 10/05/20, 1/15           2.) Ryan Schwarz was inform	R20 ed - Negus and Son's C pnitor and determine if a s Construction installed below both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction inst apaired. Negus & Son's run of silt fence between there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw the retied to several t-pos be cleaned out and retier ormed to complete by 8 5/21, 3/17/21, 4/ ormed to complete by 4 5/21, 10/15/21	11/15/2018         onstruction installed one of all elements of the basin hat the second riser in the basi open area around the orig Son's Construction installe and out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to th Construction trenched-in the nSB A and the undermineer and repaired the newer run construction the tenser state of SB B, repaire e northeast side of SB B, and the patch over the t-posts lawtended the silt fence around the silt fence in a state in the southwest corner and in multiple locations.         /04/20. Not done as of the	Active the riser pipes prior to ve been correctly inst in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 0. Active he inspection on 11/8/ he new run of silt fence backfilled the silt fen- backfilled the silt fen- between the undermin nd the top of the outfa few locations prior to of the site.	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t nice east of SB B, ence where removed ce where undermined ed portion and SB A at III at the north end of the the inspection on
Current Condition: SF 1 Current Condition:	Sediment Basin           Good Condition - 15% fille           The E&A inspector will modeling           completed. Negus & Son's           still needs to be installed be           compacted along the leng           the inspection on 7/28/20.           seeded and matted the slope           Silt fence           Fair Condition - Negus & S           stretch that needs to be readded t-posts to the new run of silt           reinstalled the silt fence will near the southeast corner           between the undermined p           run prior to the inspection           5/24/21.           1.) The silt fence should b           2.) Silted fence needs to b           1.) Ryan Schwarz was inforon 8/12/20, 10/05/20, 1/15           2.) Ryan Schwarz was inforon 8/12/20, 10/05/20, 1/15           Silt fence	R20 ed - Negus and Son's C pnitor and determine if a s Construction installed below both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta paried. Negus & Son's run of silt fence betweer in SB B, cleaned out and t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw er retied to several t-pos be cleaned out and retier formed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 3/2/21, 10/15/21 II18	11/15/2018         onstruction installed one of all elements of the basin ha the second riser in the basis open area around the orig Son's Construction installe ed out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the or the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the of repaired the newer run of east corner of SB B, repaire e northeast side of SB B, an legus & Son's Construction the patch over the t-posts is extended the silt fence arou varz repaired silt fence in a         sts in the southwest corner ed in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/11	Active the riser pipes prior to ve been correctly insta in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 to. Active he inspection on 11/8/ ne new run of silt fence d area, cleaned out an f silt fence between S ad the old run of silt fence between the undermin nd the top of the outfa few locations prior to of the site.	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip raj o be backfilled and w the riser outfall prior 0. Roth Enterprises <u>Yes</u> 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t ence east of SB B, ence where removed ce where undermined ed portion and SB A au III at the north end of the the inspection on Schwarz was reminded on
Current Condition: SF 1 Current Condition:	Sediment Basin         Good Condition - 15% fille         The E&A inspector will model         completed. Negus & Son's         still needs to be installed be         compacted along the leng         the inspection on 7/28/20.         seeded and matted the slope         Silt fence         Fair Condition - Negus & S         stretch that needs to be readded t-posts to the new run         silt fence between SB a ar         posts to the new run of silt         reinstalled the silt fence will near the southeast corner         between the undermined p         run prior to the inspection         5/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         1.) Ryan Schwarz was inforon 8/12/20, 10/05/20, 1/15         2.) Ryan Schwarz was inforon 8/12/21, 7/6/21, 8/11/21, S         Silt fence         Silt fence         Removed - Silt fence installed	R20 ed - Negus and Son's C pnitor and determine if a s Construction installed below both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta paried. Negus & Son's run of silt fence betweer in SB B, cleaned out and t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw er retied to several t-pos be cleaned out and retier formed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 3/2/21, 10/15/21 II18	11/15/2018         onstruction installed one of all elements of the basin has open area around the orig Son's Construction installe and out the basin prior to the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho SB A, and the underminer of SB B, repaired the newer run of epaired the newer run of epaired the newer run of the patch over the t-posts bectended the silt fence in a state of SB B, and the silt fence in a state of the patch over the toposts of the patch over the toposts of the patch over the toposts of the patch over the silt fence in a state of in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/14	Active the riser pipes prior to ve been correctly insta in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 to. Active he inspection on 11/8/ ne new run of silt fence d area, cleaned out an f silt fence between S ad the old run of silt fence between the undermin nd the top of the outfa few locations prior to of the site.	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip raj o be backfilled and w the riser outfall prior 0. Roth Enterprises <u>Yes</u> 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t ence east of SB B, ence where removed ce where undermined ed portion and SB A au III at the north end of the the inspection on Schwarz was reminded on
Current Condition: SF 1 Current Condition: SF 2 Current Condition:	Sediment Basin         Good Condition - 15% fille         The E&A inspector will modely completed. Negus & Son's         still needs to be installed the compacted along the leng the inspection on 7/28/20.         seeded and matted the site         Sill fence         Fair Condition - Negus & S         stretch that needs to be readded t-posts to the new run of sill reinstalled the sill fence will not the undermined prun prior to the inspection 5/24/21.         1.) The sill fence needs to be for the sill fence needs to be for the sill fence will not the inspection s/24/21.         1.) The sill fence should b         2.) Silted fence needs to be for the inspection s/24/21.         1.) Ryan Schwarz was inform 8/12/20, 10/05/20, 1/15         2.) Ryan Schwarz was inform 8/12/21, 7/6/21, 8/11/21, 9         Sill fence         Removed - Silt fence installed fence         area (Lot 83).	R20 ad - Negus and Son's C onitor and determine if a s Construction installed both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta epaired. Negus & Son's run of silt fence between nd SB B, cleaned out an t fence along the souther here removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw be cleaned out and retie ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 0/2/21, 10/15/21 I118 allation will now be reco	11/15/2018         onstruction installed one of all elements of the basin ha the second riser in the basis open area around the orig Son's Construction installe ed out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the or the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the of repaired the newer run of east corner of SB B, repaire e northeast side of SB B, an legus & Son's Construction the patch over the t-posts is extended the silt fence arou varz repaired silt fence in a         sts in the southwest corner ed in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/11	Active the riser pipes prior to ve been correctly insta- in prior to the inspection in riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 0. Active he inspection on 11/8/ he new run of silt fence d area, cleaned out an of silt fence between S ad the old run of silt fen- n backfilled the silt fen- n backfilled the silt fen- backfilled the silt fen- fen- state silt fen- ten silt fen- fen- state silt fen- fen- state silt fen- fen- state silt fen-	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ra o be backfilled and w the riser outfall prior 0. Roth Enterprises <u>Yes</u> 18. There is a remaining e east of SB A, retied a d repaired the old runs B A and SB B, added race ast of SB B, ence where removed ce where undermined ed portion and SB A a III at the north end of the the inspection on Schwarz was reminded on
Current Condition: SF 1 Current Condition:	Sediment Basin           Good Condition - 15% fille           The E&A inspector will modely completed. Negus & Son's           still needs to be installed be compacted along the leng the inspection on 7/28/20.           seeded and matted the leng the inspection on 7/28/20.           seeded and matted the set Silt fence           Fair Condition - Negus & Son's           stretch that needs to be readded t-posts to the new run of silt reinstalled the silt fence with of SB B prior to the inspection north of SB B prior to the inspection 5/24/21.           1.) The silt fence should be           2.) Silted fence needs to be free added to the inspection S/24/21.           1.) The silt fence way north of SB B prior to the inspection S/24/21.           1.) The silt fence should be           2.) Silted fence needs to be free area (Lot 83).           Silt fence           Removed - Silt fence instararea (Lot 83).	R20 ad - Negus and Son's C onitor and determine if a s Construction installed the of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta epaired. Negus & Son's run of silf tence between nd SB B, cleaned out an t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw be cleaned out and retie ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 3/2/21, 10/15/21 II18 allation will now be reco	11/15/2018         onstruction installed one of all elements of the basin ha the second riser in the basis open area around the orig Son's Construction installe ed out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the or the inspection on 10/05/2         11/8/2018         alled the silt fence prior to the of repaired the newer run of east corner of SB B, repaire e northeast side of SB B, an legus & Son's Construction the patch over the t-posts is extended the silt fence arou varz repaired silt fence in a         sts in the southwest corner ed in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/11	Active the riser pipes prior to ve been correctly insta- in prior to the inspection in riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 0. Active he inspection on 11/8/ he new run of silt fence d area, cleaned out an of silt fence between S ad the old run of silt fen- between the undermin- he nestalled the silt fen- between the undermin- between the undermin- of the site. Iast inspection. Ryan S 1/21, 9/2/21, 10/15/21 inspection. Ryan Schu- Removed the report for the lot the Removed	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises 18. There is a remaining e east of SB A, retied a d repaired the old runs B A and SB B, added the noce east of SB B, ence where removed ce where undermined ed portion and SB A a III at the north end of the the inspection on Schwarz was reminded on hat is now active in the
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition:	Sediment Basin         Good Condition - 15% fille         The E&A inspector will modely completed. Negus & Son's         still needs to be installed be compacted along the leng the inspection on 7/28/20.         seeded and matted the leng the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         setterch that needs to be readded t-posts to the new run of sill reinstalled the silt fence with of SB B prior to the inspection north of SB B prior to the inspection 5/24/21.         1.) The silt fence should be         2.) Silted fence needs to be         2.) Silted fence needs to be         3.) Ryan Schwarz was infron 8/12/20, 10/05/20, 1/15         2.) Ryan Schwarz was infron 8/12/20, 10/05/20, 1/15         2.) Ryan Schwarz was infron 8/12/21, 1/1	R20 ad - Negus and Son's C onitor and determine if a s Construction installed the of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta epaired. Negus & Son's run of silf tence between nd SB B, cleaned out an t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw the retied to several t-pos be cleaned out and retien ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 3/2/21, 10/15/21 II18 allation will now be reco	11/15/2018         onstruction installed one of all elements of the basin has open area around the orig Son's Construction installe and out the basin prior to the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho n SB A, and the underminer on repaired the newer run of epaired the newer run of epaired the newer run of seast corner of SB B, repaired and repaired the silt fence around a repaired the silt fence around a repaired the silt fence around a repaired silt fence in a set on the patch over the t-posts lawtended the silt fence around a repaired silt fence in a set on multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/14/16/21. Not done as of last         /mmended in the section of	Active the riser pipes prior to ve been correctly insta in prior to the inspecti in prior to the belo e inspection on 9/22/2 to. Active he inspection on 11/8/ he inspection on 11/8/ he new run of silt fence d area, cleaned out an of silt fence between S ad the old run of silt fence he installed the silt fence between the undermin nd the top of the outfa few locations prior to of the site. Removed the report for the lot th Removed the report for the lot th	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises <u>Yes</u> 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t noce east of SB B, ence where removed ce where undermined ed portion and SB A a III at the north end of the the inspection on Schwarz was reminded on hat is now active in the
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4	Sediment Basin         Good Condition - 15% fille         The E&A inspector will modely completed. Negus & Son's still needs to be installed to be installed the leng the inspection on 7/28/20.         seeded and matted the leng the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         seeded and matted the set of the inspection on 7/28/20.         stretch that needs to be readded t-posts to the new run of sill reinstalled the set of the inspection on 7/28/20.         silt fence between SB a ar posts to the new run of sill reinstalled the set of the inspection on 7/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         2.) Silted fence needs to b         1.) Ryan Schwarz was inforon 8/12/20, 10/05/20, 1/15         2.) Ryan Schwarz was inforon 8/12/20, 10/05/20, 1/15         3.) Sit fence         Removed - Silt fence insta area (Lot 83).         Silt fence         Removed - Silt fence insta area (Lot 83).         Silt fence	R20 ad - Negus and Son's C pnitor and determine if a s Construction installed th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta spaired. Negus & Son's run of silt fence between nd SB B, cleaned out an t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw the retied to several t-pos- pe cleaned out and retie ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 4 3/2/21, 10/15/21 II18 allation will now be reco (DD1-DD14)	11/15/2018         onstruction installed one of all elements of the basin ha the second riser in the basis open area around the orig Son's Construction installe led out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to th         Construction trenched-in th         n SB A and the undermined of repaired the newer run of east corner of SB B, repaire e northeast side of SB B, and kegus & Son's Construction the patch over the t-posts I extended the silt fence arou varz repaired silt fence in a         sts in the southwest corner id in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/11         /16/21. Not done as of last         mmended in the section of	Active the riser pipes prior to been correctly insta in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 to Active he inspection on 11/8/ he new run of silt fence between S ad the old run of silt fence between the undermin nd the top of the outfa few locations prior to of the site. Removed the report for the lot th Removed the report for the lot th Removed	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises 19. There is a remainin e east of SB A, retied a d repaired the old runs B A and SB B, added t noce east of SB B, ence where removed ce where undermined ed portion and SB A and all at the north end of the the inspection on Schwarz was reminded on at is now active in the
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4 Current Condition:	Sediment Basin         Good Condition - 15% fille         The E&A inspector will modely completed. Negus & Son's         still needs to be installed the compacted along the leng the inspection on 7/28/20.         seeded and matted the slope still fence         Fair Condition - Negus & Stretch that needs to be readded t-posts to the new run of sill reinstalled the silt fence will fence between SB a ar posts to the new run of sill reinstalled the silt fence will not the inspection of 5/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         5/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         5/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         2.) Silted fence needs to b         3.) The silt fence should b         2.) Silte fence         Removed - Silt fence insta area (Lot 83).         Silt fence         Removed - Silt fence insta area (Lot 83).         Silt fence         Removed - Negus & Son's	R20 ad - Negus and Son's C pnitor and determine if a s Construction installed below both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction insta spaired. Negus & Son's run of silt fence between nd SB B, cleaned out an t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw e retied to several t-pos- pe cleaned out and retie ormed to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 8 5/21, 3/2/21, 10/15/21 II18 allation will now be reco (DD1-DD14) s Construction removed	11/15/2018         onstruction installed one of all elements of the basin has open area around the orig Son's Construction installe and out the basin prior to the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to tho n SB A, and the underminer on repaired the newer run of epaired the newer run of epaired the newer run of seast corner of SB B, repaired and repaired the silt fence around a repaired the silt fence around a repaired the silt fence around a repaired silt fence in a set on the patch over the t-posts lawtended the silt fence around a repaired silt fence in a set on multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/14/16/21. Not done as of last         /mmended in the section of	Active the riser pipes prior to been correctly insta in prior to the inspecti inal riser pipe needs to d the Scour Hole belo e inspection on 9/22/2 to Active he inspection on 9/22/2 to Active he inspection on 11/8/ he new run of silt fence between S ad the old run of silt fence between the undermin nd the top of the outfa few locations prior to the site. Removed the report for the lot th Removed the report for	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises 18. There is a remaining e east of SB A, retied a d repaired the old runs B A and SB B, added the noce east of SB B, ence where removed ce where undermined ed portion and SB A a III at the north end of the the inspection on Schwarz was reminded on hat is now active in the
Current Condition: SF 1 Current Condition: SF 2 Current Condition: SF 3 Current Condition: SF 4	Sediment Basin         Good Condition - 15% fille         The E&A inspector will modely completed. Negus & Son's         still needs to be installed to compacted along the leng the inspection on 7/28/20.         seeded and matted the slope seeded and matted the slope silt fence         Fair Condition - Negus & Sattertch that needs to be readded t-posts to the new run of silt reinstalled the silt fence with fence between SB a an posts to the new run of silt reinstalled the silt fence with of SB B prior to the inspection 5/24/21.         1.) The silt fence should b         2.) Silted fence needs to b         2.) Silted fence needs to b         1.) Ryan Schwarz was inform 8/12/20, 10/05/20, 1/15         2.) Silt fence         Removed - Silt fence instatarea (Lot 83).         Silt fence         Removed - Silt fence instatarea (Lot 83).         Silt fence         Removed - Negus & Son's         Silt fence         Removed - Negus & Son's	R20 ad - Negus and Son's C pnitor and determine if a s Construction installed below both outfalls, and th of the pipe. Negus & Roth Enterprises clear opes of the basin prior t (A25-II18) Son's Construction inst apaired. Negus & Son's construction inst apaired. Negus & Son's run of silt fence between and SB B, cleaned out and t fence along the souther there removed along the inspection on 6/11/20. N of the site, trenched in portion and SB B, and e on 7/14/20. Ryan Schw be retied to several t-pos- be cleaned out and retie or med to complete by 8 5/21, 3/2/21, 3/17/21, 4/ ormed to complete by 8 5/21, 10/15/21 II18 allation will now be reco (DD1-DD14) s Construction removed F23 - V16	11/15/2018         onstruction installed one of all elements of the basin ha the second riser in the basis open area around the orig Son's Construction installe led out the basin prior to th o the inspection on 10/05/2         11/8/2018         alled the silt fence prior to th         Construction trenched-in th         n SB A and the undermined of repaired the newer run of east corner of SB B, repaire e northeast side of SB B, and kegus & Son's Construction the patch over the t-posts I extended the silt fence arou varz repaired silt fence in a         sts in the southwest corner id in multiple locations.         /04/20. Not done as of the 13/21, 5/12/21, 7/6/21, 8/11         /16/21. Not done as of last         mmended in the section of	Active the riser pipes prior to the inser pipes prior to the inspection on the inspection the scour Hole belo e inspection on 9/22/2 to. Active the inspection on 11/8/ the inspection on 11/8/ the old run of silt fence the old	D inspection on 9/19/19 alled when work is on on 10/02/19. Rip ray o be backfilled and w the riser outfall prior 0. Roth Enterprises <u>Yes</u> 18. There is a remainir e east of SB A, retied a d repaired the old runs B A and SB B, added t hace east of SB B, ence where removed ce where undermined led portion and SB A an all at the north end of th the inspection on Schwarz was reminded on at is now active in the

SF 7	Silt fence	GG16 - HH16	7/14/2020	Active	Yes
Current Condition:	Fair Condition - LIM Cons on that lot prior to the insp the inspection on 7/28/20. Both silt fence checks aro LIM Construction was info on 8/25/20, 10/05/20, 11/1	und Lot 11 should be repa	nstruction installed an ad ired or removed. 20. Not done as of the la	ditional run of silt fenc	e east of Lot 11 prior to
SF 8	Silt fence	AA6	9/8/2020	Active	No
Current Condition:		chwarz installed two runs o an Schwarz reinstalled the		0	· ·
STR	Streets	Site	11/8/2018	Active	Yes
Current Condition:	The condition - Negus & 3 The condition of the street adjacent streets were free off North Molley Street pri- to the inspection on 7/28/2 Ryan Schwarz cleaned the cleaned the street in front Lots 18-21 prior to the insi 9/22/02. LIM cleaned the Some street cleaning is no All builders were informed 01/15/21, 3/2/21, 3/17/21, 11/12/21	e of track out during the ins or to the inspection on 2/10 20. Viking Homes cleaned e street where silt ran off b of Lot 76 prior to the inspe pection on 9/22/02. Viking street prior to the 11/9/20 seeded. UPDATE: All street I to complete by 11/11/20.	ined during the inspection pection on 1/13/20. Negu 0/20. LIM Construction clut the street in front of lots are / sparse areas prior to ction on 9/08/20. Seeing Homes cleaned the street inspection. s need to be cleaned with Not done as of the last in	on on 12/16/19 due to sus & Son's Construction eaned the street in from 75 and 77 prior to the is to the inspection on 8/ Double Homes cleaned et in front of Lot 12 prior hin development.	anow and ice cover. The n cleaned the track out nt of lots 73 and 74 prior nspection on 7/28/20. 11/20. LIM Construction ad the street in front of or to the inspection on were reminded on
SWPPP Sign Current Condition:	prior to the inspection on	N. Allen St. & N. 2nd St. ector installed the sign dur 12/30/19. The E&A inspect SWPPP sign to southern of pection on 4/01/20. The E	or reinstalled the SWPPI entrance of the developm	P sign during the inspen- ment near the N. Allen	ction on 12/30/19. The St. and N. 2nd St.
Inspector Signature:	M Zhayth			Reviewed By:	Parts Sull