E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Bryce Wright					Stage
Project Name:	Prairie H	3			
For Week Ending:)1802726 /2023		68007
Project Location:	1EC+h C+		Bennington Ne, Douglas	County	00007
Project Location.	13601 30	reet and mighway 36 (i	bennington Ne, Douglas	County)	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	85%				
Utilities:	100%				
Overall Development:	70%				
Overall Development.	1070				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
RAINT ALL AMOUNTS	Amount in tentils	Date inspected	Weather Conditions	Time	
Sunday	0.00"				Week
Sunday Monday	0.00"	1	+		+
	0.51"	-	+		8 AM - 5 PM
Tuesday	0.00"	0/45/0000	0,,,,,,,,,,	0.50 414	o Aivi - 5 Pivi
Wednesday		2/15/2023	Overcast 25	8:50 AM	+
Thursday	0.15"	-			
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
,					Week
Sunday	0.72"				11 PM - 1 AM
Monday	0.11"	2/27/2023	Overcast 40	8:25 AM	
Tuesday	0.00"		0.00.000.10	0.207	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
outu. uuy	0.00				Week
Sunday	0.00"				Week
Monday	0.00"	1	+	+	
Tuesday	0.20"	1			
Wednesday	0.00"	 			
Thursday	0.00"	1			
Friday	0.02	1	+	+	
Saturday	0.20"	+	+		+
- Julius day	0.20				101
Cunday	NIA				Week
Sunday	N/A	1			+
Monday	N/A	1	+		+
Tuesday	N/A	 	+		+
Wednesday	N/A	1			+
Thursday	N/A	1	+		+
Friday	N/A	 	+		+
Saturday	N/A				
	ls:				
	None				
Complaints:					

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/13/20). Regrading of the slope in the southeast corner of the site, grading around the area inlets at the north end of the site complete (1/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/13/20). Regrading of the slope in the southeast corner of the site, grading around the area inlets at the north end of the site complete (1/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18). Negus & Son's Construction seeded the flat area and seeded/matted the slope north of N. Allen Street (12/02/19). West side of southern entrance mulched, planted with trees (4/01/20). Area around IF 1 and 2 seeded and matted (8/11/20). Excavated silt spread out over area between SB-A and SB-B and seeded, SB-A and SB-B slopes seeded and matted (10/05/20). South entrance seeded/matted (10/26/20). Seed and mat on bare area south of lot 56 (1/3/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

No

Create Corrective Action?

No - See BMP Section

Are construction entrances and adjacent streets being maintained adequately

No

Create Corrective Action

No - See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

Site was active for homebuilding during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) An erosion rill was observed across from lot 10 on 8/31/21. Ryan Schwarz was informed to backfill, compact, and restabilize the erosion by 9/7/21. Not done as of the last inspection. Erosion rill is on state road property. State was contacted and no response was received as of 11/24/21.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
omquo rtamo	Stabilized Construction	Location	1 Tojootoa motam Bato	Otatao	mantonanoo		
CE 1	Entrance	N Molley Street (EE11)		Removed			
Current Condition:	Removed - The former cor	nstruction entrance was pa	ved prior to the inspection	on 11/04/19.	•		
	Stabilized Construction						
CE 2	Entrance	N 2nd Street (B24)		Removed			
Current Condition:	Removed - The former construction entrance was paved prior to the inspection on 11/04/19.						
CW 1	Concrete Washout	X10	9/8/2020	Pending	Yes		
Current Condition:	Pending- Concrete washout waste was observed on-site on 2/10/20. Ryan Schwarz installed a concrete washout pit near the northwest corner of the site prior to the inspection on 9/08/20. Concrete washout was removed prior to the inspection on 3/15/21.						
	The washout should be re-installed. UPDATE: All concrete waste throughout the development should be removed.						
	Ryan Schwarz was informed to complete by 10/12/20. Not done as of the last inspection. Ryan Schwarz was reminded on 01/15/21, 3/2/21, 3/17/21, 4/13/21, 5/12/21, 7/6/21, 8/11/21, 9/2/21, 10/15/21, 12/9/21, 12/9/21, 4/27/22						

	Temporary Diversion				
D1	Ditch	(Z17-II17)		Removed	
Current Condition:		s no longer necessary as o	of the inspection on 4/01/2	20 due to lot-level cons	truction starting in the
	area. Temporary Diversion			Г	
D2	Ditch	(F25-P21)	7/14/2020	Active	No
Current Condition:		Son's Construction installe			
	Temporary Diversion				
D3	Ditch	(P21-R20)	7/14/2020	Active	No
Current Condition:	Good Condition - Negus & Temporary Diversion	Son's Construction installe	ed the diversion prior to th	ie inspection on 7/14/2	0. I
D4	Ditch	(B26-D26)		Removed	
Current Condition:		ction on 7/28/20, the diver	i sion is no longer necessa		t of vegetation on the
	adjacent slope.		ŭ	•	Ū
EM 1	Erosion Control Matting	(C22-DD11)	12/2/2019	Active	No
Current Condition:		Son's Construction installe	ed the erosion control ma		tion on 12/02/19.
FT 1	Fuel Tank	W11	2/40/00: "	Removed	
Current Condition: IF 1	Removed - The fuel tank v	vas removed prior to the 10)/12/20 inspection.	Removed	
Current Condition:		removed the silt fence wra	L op and seeded and matted		L to the inspection on
ourient obligation.	8/11/20.	Tomovou and one fortion with	ip and booded and matter	a around the milet prior	to the moposition on
IF 2	Inlet Filter	II11		Removed	
Current Condition:	•	removed the silt fence wra	p and seeded and matte	around the inlet prior	to the inspection on
ات د	8/11/20.	HH15	T	Damayad	T
IF 3 Current Condition:	Inlet Filter	removed the inlet filter price	r to the inspection on 11/	Removed	
IF 4	Inlet Filter	HH13	א ניים וויסףפטנוטוו טוו דו/ [
Current Condition:		removed the inlet filter price	r to the inspection on 11/	Removed	
IF 5	Inlet Filter	AA17	л ю ше шэресион он П/	Removed	
Current Condition:		removed the inlet filter price	or to the inspection on 11/		
	,	<u>'</u>	I to the hispection on 11/		T
IF 6 Current Condition:	Inlet Filter	Y17 removed the inlet filter prid	or to the inspection on 11/	Removed	
Current Condition.	Removed - Ryan Schwarz	·	or to the mapeculon on 11/	0/22.	
IF 7	Inlet Filter	E25		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 8	Inlet Filter	GG15		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	•
IF 9	Inlet Filter	GG13		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 10	Inlet Filter	DD17		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 11	Inlet Filter	X17		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 12	Inlet Filter	R19	2/10/2020	Active	Yes
Current Condition:	street. The inlet filter was in the inspection on 3/15/21. Inlet filter should be cleaned.	onstruction removed the innstalled prior to the 11/10/2 ed out.	let filters prior to the inspe 20 inspection. Ryan Schw	ection on 4/01/20 to alle arz repaired/reposition	eviate ponding on the ed the inlet filter prior to
IF 13	Inlet Filter	K22	2/10/2020	Active	No
Current Condition:		onstruction removed the in prevent sediment runoff a be stored on-site and can b et filters. Ryan Schwarz re	let filters prior to the inspe s well as frequent street on the reinstalled if necessary	ection on 4/01/20 to alle leaning will be recomn . The E&A inspector wi	eviate ponding on the nended in lieu of the inlet Il continue to monitor for
IF 14	Inlet Filter	G23		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on $11/$	8/22.	
IF 15	Inlet Filter	F24		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
Lot 3	Individual Lot	Lot 3		Removed	
Current Condition:		ion sodded the lot prior to t	the inspection on 6/21/22.		
Lot 4	Individual Lot	Lot 4		Removed	
Current Condition:		on sodded the lot prior to the	ne inspection on 1/3/22.		
Lot 7	Silt fence	Lot 7		Removed	
Current Condition:		ion sodded the lot prior to t	the inspection on 6/21/22.		•
Latin	Individual Lat	l at 0		Domested	
Lot 8	Individual Lot	Lot 8		Removed	

Current Condition:	Removed - LIM Construction	on sodded the lot prior to the	he inspection on 1/3/22.			
Lot 9	Individual Lot	Lot 9		Removed		
Current Condition:	Removed - LIM Construction sodded the lot prior to the inspection on 1/3/22.					
Lot 14	Individual Lot	Lot 14		Removed		
Current Condition:	Removed - Edward Custor	n Homes LLC sodded the	lot prior to the inspection	on 9/13/22.		
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed - LIM Construction	on sodded the lot prior to the	he inspection on 7/19/22.			
Lot 30	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double		o the inspection on 8/16/2			
Lot 31	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double		I o the inspection on 8/16/2			
		·	· 			
Lot 32 Current Condition:	Individual Lot Removed - Seeing Double	Lot 33	o the inspection on 8/16/2	Removed 2		
Current Condition.	Removed - Seeing Double	LEG souded the lot phor to		2 .		
Lot 33	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double	LLC sodded the lot prior to	o the inspection on 8/16/2	2.		
Lot 34	Individual Lot	Lot 34		Removed		
Current Condition:	Removed - Seeing Double	LLC sodded the lot prior to	o the inspection on 8/16/2	2.		
Lat 25	Individual Lat	L at 25		Domested		
Lot 35 Current Condition:	Individual Lot Removed - Seeing Double	Lot 35 LLC sodded the lot prior to	l o the inspection on 8/16/2	Removed 2.		
			I			
Lot 36	Individual Lot	Lot 36	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double L	LC began excavation prior	r to the inspection on 5/25	5/22.		
	1.) Curb line should be cleaned.					
	2.) Straw wattles should be installed along the street.					
	1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was reminded on 8/18/22, 10/13/22, 3/1/23 2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/1		6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was	
Lot 37	Individual Lot	Lot 37	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double L				165	
	 Curb line should be cleaned. Straw wattles should be installed along the street. Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was reminded on 8/18/22, 10/13/22, 3/1/23 					
	2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/1	<u>3/22, 3/1/23 </u>	I			
Lot 38	Individual Lot	Lot 38	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double LLC began excavation prior to the inspection on 5/25/22.					
	1.) Curb line should be cleaned.					
	2.) Straw wattles should be installed along the street.					
	1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/13/22, 3/1/23 2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/13		6/1/22. Not done as of the	e last ilispection. Seem	g Double LLC was	
Lot 39	Individual Lot	Lot 39	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double L				163	
	Curb line should be cleaned. Straw wattles should be installed along the street.					
	,	· ·				
	1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was reminded on 8/18/22, 10/13/22, 3/1/23					
	2.) Seeing Double LLC wa	s informed to complete by	6/1/22. Not done as of the	last inspection. Seein	g Double LLC was	
	reminded on 8/18/22, 10/13	2/22 2/4/22				
	Terrimaca ori o/ 10/22, 10/1	3/22, 3/1/23				
Lot 40	Individual Lot	Lot 40	5/26/2022	Pending	Yes	

Current Condition:	Pending - Seeing Double L	LC began excavation prio	to the inspection on 5/25	5/22.			
	1.) Curb line should be cleaned. 2.) Straw wattles should be installed along the street.						
	1.) Seeing Double LLC wa reminded on 8/18/22, 10/1		6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	2.) Seeing Double LLC wa	s informed to complete by	6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	reminded on 8/18/22, 10/1	<mark>3/22. 3/1/23</mark>		I			
Lot 41	Individual Lot	Lot 41	5/26/2022	Pending	Yes		
Current Condition:	Pending - Seeing Double L	LC began excavation prio	to the inspection on 5/25	5/22.			
	1.) Curb line should be cleaned.						
	2.) Straw wattles should be	e installed along the street.					
	1.) Seeing Double LLC wa	s informed to complete by	6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	reminded on 8/18/22, 10/1		0/4/00 N. /		5 11 110		
	2.) Seeing Double LLC wa reminded on 8/18/22, 10/1		b/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
Lot 57	Individual Lot	Lot 57		Removed			
Current Condition:	Removed - LIM Construction		ne inspection on 4/25/22.				
Lot 60	Individual Lot	Lot 60	2/15/2023	Active	Yes		
Current Condition:	Fair Condition - LIM Con						
	installed at the rear of the						
	1) Dirt nile and concrete	wasto should be remove	d from the BOW				
	Dirt pile and concrete waste should be removed from the ROW. Silt fence at the rear of the lot should be repaired.						
	1.) LIM Construction was 2.) LIM Construction was						
1.104		·	010/23.	ъ .			
Lot 61 Current Condition:	Individual Lot Removed - LIM Construction	Lot 61 on sodded the lot prior to tl	ne inspection on 9/13/22.	Removed			
		<u> </u>					
Lot 63 Current Condition:	Individual Lot Removed - LIM Construction	Lot 63	ne inspection on 4/25/22	Removed			
	Tromovou Envi Conociuosi	<u> </u>	10 moposition 1/20/22.	<u> </u>			
Lot 65 Current Condition:	Individual Lot Removed - LIM Construction	Lot 65	ne inspection on 10/11/22	Removed			
		<u> </u>	10 110 000 001 011 10/11/22				
Lot 66 Current Condition:	Individual Lot	Lot 66 on sodded the lot prior to tl	ne inspection on 8/16/22	Removed			
		<u> </u>					
Lot 67 Current Condition:	Individual Lot Removed - LIM Construction	Lot 67 on sodded the lot prior to tl	ne inspection on 8/16/22.	Removed			
		<u>'</u>					
Lot 68 Current Condition:	Individual Lot	Lot 68 on sodded the lot prior to tl	ne inspection on 4/25/22	Removed			
			10 1113pcottor1 011 4/20/22.	D			
Lot 71 Current Condition:	Individual Lot Removed - LIM Construction	Lot 71 on sodded the lot prior to tl	ne inspection on 4/25/22.	Removed			
PB 1	Portable Bathroom	HH14		Removed			
Current Condition:		on removed the portable to					
SB A Current Condition:	Sediment Basin Good Condition - 8% filled	- Negus & Son's Construc	11/15/2018	Active	No to inspection on 9/19/19		
Current Condition.	Good Condition - 8% filled - Negus & Son's Construction partially installed the riser in the basin prior to inspection on 9/19/19. The E&A inspector will monitor and determine if all elements of the basin have been correctly installed when work is						
	completed. Negus & Son's Construction backfilled and compacted dirt around the riser and the portion of the outlet pipe						
	within the wall of the basin prior to the inspection on 12/16/19. Negus & Son's Construction partially dug out and reshaped the sediment basin prior to the inspection on 12/16/19. Negus & Son's Construction backfilled and compacted along the outlet						
	pipe prior to the inspection on 1/27/20. Negus & Son's Construction backfilled and compacted the subsided area along the						
	northern outlet pipe prior to the inspection on 7/14/20. Negus & Son's Construction installed the Scour Holes below both riser outfalls prior to the inspection on 7/28/20. Roth Enterprises cleaned out the basin prior to the inspection on 9/22/20. Roth						
	Enterprises seeded and m				on on 5/22/20. Roun		
SB B	Sediment Basin	R20	11/15/2018	Active	No		
Current Condition:	Good Condition - 15% filled The E&A inspector will mo						
	completed. Negus & Son's	Construction installed the	second riser in the basin	prior to the inspection	on 10/02/19. Rip rap still		
	needs to be installed below along the length of the pipe	· ·	•		·		
	on 7/28/20. Roth Enterpris	•					
	the slopes of the basin price	or to the inspection on 10/0	5/20.				
SF 1	Silt fence	(A25-II18)	11/8/2018	Active	No		

	Brega M Want					
Certification Statement:	"I certify, under penalty of I direction or supervision in properly gathered and eva persons who manage the the information submitted am aware that there are si of fines and imprisonment	luated the information sub- system or those persons d is, to the best of my knowle gnificant penalties for subr	designed to assure that q mitted. Based on my inqui rectly responsible for gath edge and belief, true, accu	ualified personnel iry of the person or nering the information, urate, and complete. I		
	Good Condition- The inspector installed the sign during the inspection on 12/17/18. The SWPPP sign had been removed prior to the inspection on 12/30/19. The E&A inspector reinstalled the SWPPP sign during the inspection on 12/30/19. The E&A inspector moved the SWPPP sign to southern entrance of the development near the N. Allen St. and N. 2nd St. intersection during the inspection on 4/01/20. The E&A inspector reinstalled the SWPPP sign during the 11/10/20 inspection					
SWPPP Sign Current Condition:	Misc./Other Good Condition- The inspe	N. Allen St. & N. 2nd St. ector installed the sign duri	12/17/2018 na the inspection on 12/1	Active 7/18. The SWPPP sign	No had been removed	
	01/15/21, 3/2/21, 3/17/21,	eeded. UPDATE: All streets to complete by 11/11/20.	Not done as of the last ins 7/6/21, 7/14/21, 7/27/21, 8	spection. All builders w		
	The condition of the streets could not be fully determined during the inspection on 12/16/19 due to snow and ice cover. The adjacent streets were free of track out during the inspection on 1/13/20. Negus & Son's Construction cleaned the track out o North Molley Street prior to the inspection on 2/10/20. LIM Construction cleaned the street in front of lots 73 and 74 prior to the inspection on 7/28/20. Viking Homes cleaned the street in front of lots 75 and 77 prior to the inspection on 7/28/20. Ryan Schwarz cleaned the street where silt ran off bare / sparse areas prior to the inspection on 8/11/20. LIM Construction cleaned the street in front of Lot 76 prior to the inspection on 9/08/20. Seeing Double Homes cleaned the street in front of Lots 18-21 prior to the inspection on 9/22/02. Viking Homes cleaned the street in front of Lot 12 prior to the inspection on 9/22/02. LIM					
Current Condition:	Fair Condition - Negus & S	Son's Construction cleaned	up the track out on the a	djacent streets prior to	inspection on 8/05/19	
STR	inspection on 9/08/20. Rya	an Schwarz reinstalled the Site	top row of silt fence prior t	to the inspection on 7/3 Active	1/21. Yes	
Current Condition:		hwarz installed two runs of				
Current Condition: SF 8	Removed - LIM Constructi Silt fence	on removed the silt fence p AA6	orior to the inspection on 1 9/8/2020	1/3/22. Active	No	
SF 7	Silt fence	GG16 - HH16		Removed		
Current Condition:		tion growth, silt fence is no	longer recommended as		ion.	
SF 6	inspection on 7/28/20.	DD11 - HH11	Γ	Removed		
Current Condition:		s become sufficiently estab	I lished in the ROW north o		vent erosion as of the	
Current Condition: SF 5	Removed - Negus & Son's Silt fence	Construction removed the F23 - V16	esut tence prior to the insp I	pection on 7/28/20.		
SF 4	Silt fence	(DD1-DD14)	20.6	Removed		
Current Condition:	Removed - Silt fence insta (Lot 83).	illation will now be recomm	ended in the section of th	e report for the lot that	is now active in the a	
SF 3	Silt fence	II17		Removed		
Current Condition:	Removed - Silt fence insta (Lot 83).	illation will now be recomm	ended in the section of th	e report for the lot that	is now active in the a	
SF 2	Silt fence	II18		Removed		
	added t-posts to the new rusilt fence between SB a ar posts to the new run of silt reinstalled the silt fence whof SB B prior to the inspec southeast corner of the sitt the undermined portion an the inspection on 7/14/20. Schwarz seeded and matte behind all sodded lot and the silt fence silt fermion of the silt fermion of th	nd SB B, cleaned out and r fence along the southeast here removed along the nc tion on 6/11/20. Negus & S e, trenched in the patch ov d SB B, and extended the Ryan Schwarz repaired sil ed bare area south of lot 5	epaired the newer run of scorner of SB B, repaired ritheast side of SB B, and son's Construction backfill er the t-posts between the silt fence around the top of the fence in a few locations of prior to the inspection of	silt fence between SB A the old run of silt fence reinstalled the silt fence led the silt fence where e undermined portion at of the outfall at the north prior to the inspection of n 1/3/22. Ryan Schwarz	A and SB B, added t- east of SB B, e where removed not undermined near the nd SB A and between n end of the run prior on 5/24/21. Ryan	
	stretch that needs to be re	paired. Negus & Son's Coi	istruction trenched-in the	new run or sill lence ea	isi oi od A, relieu ario	