E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

laanaatan Barra Weinkt		E&A - P2017.	+03.001		Stage	
Inspector: Bryce Wright						
Project Name:	Prairie H	3				
-			201802726		69007	
For Week Ending:			3/2023		68007	
Project Location:	156th S	treet and Highway 36	(Bennington Ne, Douglas	s County)		
Grading:	1004	%I				
Sanitary Sewer:	100					
Storm Sewer:	100					
Paving:	1009	%				
Seeding:	85					
Utilities:	100					
Overall Development:	709	%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
TAIL AMOUNTO	7 thouse in tentilo	Date inspected	Weather Conditions	Time	Wee	
Sunday	0.00"				1100	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.15"					
Friday	0.00"					
Saturday	0.00"					
-					Wee	
Sunday	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday Saturday	0.00"					
Saturday	0.00				Wee	
Sunday	0.01"				1100	
Monday	0.00"					
Tuesday	0.00"	3/28/2023	Sunny 31	11:10 AM		
Wednesday	0.00"					
Thursday	0.02"					
Friday	0.00"					
Saturday	0.00"					
	0.001				Wee	
Sunday	0.00"					
Monday Tuesday	0.00"					
Nednesday	0.00"				+	
Thursday	0.00"				+	
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	None					
Complainte	INOHE					
Complaints:						

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/13/20). Regrading of the slope in the southeast corner of the site, grading around the area inlets at the north end of the site complete (1/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

## Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/13/20). Regrading of the slope in the southeast corner of the site, grading around the area inlets at the north end of the site complete (1/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20). Excavated silt from SB-A and SB-B spread over southern half of the area between the basins. Grading around lots 5 and 6 (1/28/21). Excavation by lots 1 and 2 (3/1/21).

## What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18). Negus & Son's Construction seeded the flat area and seeded/matted the slope north of N. Allen Street (12/02/19). West side of southern entrance mulched, planted with trees (4/01/20). Area around IF 1 and 2 seeded and matted (8/11/20). Excavated silt spread out over area between SB-A and SB-B and seeded, SB-A and SB-B slopes seeded and matted (10/05/20). South entrance seeded/matted (10/26/20). Seed and mat on bare area south of lot 56 (1/3/22).

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

No

Create Corrective Action?

No - See BMP Section

Are construction entrances and adjacent streets being maintained adequately

No

Create Corrective Action

No - See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

Site was active for homebuilding during the most recent inspection.

Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) An erosion rill was observed across from lot 10 on 8/31/21. Ryan Schwarz was informed to backfill, compact, and restabilize the erosion by 9/7/21. Not done as of the last inspection. Erosion rill is on state road property. State was contacted and no response was received as of 11/24/21.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
omquo rtamo	Stabilized Construction	Location	1 Tojootoa motam Bato	Otatao	mantonanoo		
CE 1	Entrance	N Molley Street (EE11)		Removed			
Current Condition:	Removed - The former cor	nstruction entrance was pa	ved prior to the inspection	on 11/04/19.	•		
	Stabilized Construction						
CE 2	Entrance	N 2nd Street (B24)		Removed			
Current Condition:	Removed - The former construction entrance was paved prior to the inspection on 11/04/19.						
CW 1	Concrete Washout	X10	9/8/2020	Pending	Yes		
Current Condition:	Pending- Concrete washout waste was observed on-site on 2/10/20. Ryan Schwarz installed a concrete washout pit near the northwest corner of the site prior to the inspection on 9/08/20. Concrete washout was removed prior to the inspection on 3/15/21.						
	The washout should be re-installed. UPDATE: All concrete waste throughout the development should be removed.						
	Ryan Schwarz was informed to complete by 10/12/20. Not done as of the last inspection. Ryan Schwarz was reminded on 01/15/21, 3/2/21, 3/17/21, 4/13/21, 5/12/21, 7/6/21, 8/11/21, 9/2/21, 10/15/21, 12/9/21, 4/27/22						

	Temporary Diversion				
D1	Ditch	(Z17-II17)		Removed	
Current Condition:		s no longer necessary as o	of the inspection on 4/01/2	20 due to lot-level cons	truction starting in the
	area.  Temporary Diversion			Г	
D2	Ditch	(F25-P21)	7/14/2020	Active	No
Current Condition:		Son's Construction installe			
	Temporary Diversion				
D3	Ditch	(P21-R20)	7/14/2020	Active	No
Current Condition:	Good Condition - Negus & Temporary Diversion	Son's Construction installe	ed the diversion prior to th	ie inspection on 7/14/2	0. I
D4	Ditch	(B26-D26)		Removed	
Current Condition:		ction on 7/28/20, the diver	i sion is no longer necessa		t of vegetation on the
	adjacent slope.		ŭ	•	Ū
EM 1	Erosion Control Matting	(C22-DD11)	12/2/2019	Active	No
Current Condition:		Son's Construction installe	ed the erosion control ma		tion on 12/02/19.
FT 1	Fuel Tank	W11	2/40/00: "	Removed	
Current Condition: IF 1	Removed - The fuel tank v	vas removed prior to the 10	)/12/20 inspection.	Removed	
Current Condition:		removed the silt fence wra	L op and seeded and matted		L to the inspection on
ourient obligation.	8/11/20.	Tomovou and one fortion with	ip and booded and matter	a around the milet prior	to the moposition on
IF 2	Inlet Filter	II11		Removed	
Current Condition:	•	removed the silt fence wra	p and seeded and matte	around the inlet prior	to the inspection on
ات د	8/11/20.	HH15	T	Damayad	T
IF 3 Current Condition:	Inlet Filter	removed the inlet filter price	r to the inspection on 11/	Removed	
IF 4	Inlet Filter	HH13	א ניים וויסףפטנוטוו טוו דו/ [		
Current Condition:		removed the inlet filter price	r to the inspection on 11/	Removed	
IF 5	Inlet Filter	AA17	л ю ше шэресион он П/	Removed	
Current Condition:		removed the inlet filter price	or to the inspection on 11/		
	,	<u>'</u>	I to the hispection on 11/		T
IF 6 Current Condition:	Inlet Filter	Y17 removed the inlet filter prid	or to the inspection on 11/	Removed	
Current Condition.	Removed - Ryan Schwarz	·	or to the mapeculon on 11/	0/22.	
IF 7	Inlet Filter	E25		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 8	Inlet Filter	GG15		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter prid	or to the inspection on 11/	8/22.	•
IF 9	Inlet Filter	GG13		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 10	Inlet Filter	DD17		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 11	Inlet Filter	X17		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
IF 12	Inlet Filter	R19	2/10/2020	Active	Yes
Current Condition:	street. The inlet filter was in the inspection on 3/15/21.  Inlet filter should be cleaned.	onstruction removed the innstalled prior to the 11/10/2 ed out.	let filters prior to the inspe 20 inspection. Ryan Schw	ection on 4/01/20 to alle arz repaired/reposition	eviate ponding on the ed the inlet filter prior to
IF 13	Inlet Filter	K22	2/10/2020	Active	No
Current Condition:		onstruction removed the in prevent sediment runoff a be stored on-site and can b et filters. Ryan Schwarz re	let filters prior to the inspe s well as frequent street on the reinstalled if necessary	ection on 4/01/20 to alle leaning will be recomn . The E&A inspector wi	eviate ponding on the nended in lieu of the inlet Il continue to monitor for
IF 14	Inlet Filter	G23		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on $11/$	8/22.	
IF 15	Inlet Filter	F24		Removed	
Current Condition:	Removed - Ryan Schwarz	removed the inlet filter price	or to the inspection on 11/	8/22.	
Lot 3	Individual Lot	Lot 3		Removed	
Current Condition:		ion sodded the lot prior to t	the inspection on 6/21/22.		
Lot 4	Individual Lot	Lot 4		Removed	
Current Condition:		on sodded the lot prior to the	ne inspection on 1/3/22.		
Lot 7	Silt fence	Lot 7		Removed	
Current Condition:		ion sodded the lot prior to t	the inspection on 6/21/22.		•
Latin	Individual Lat	l at 0		Domested	
Lot 8	Individual Lot	Lot 8		Removed	

Current Condition:	Removed - LIM Construction	on sodded the lot prior to the	ne inspection on 1/3/22.			
Lot 9	Individual Lot	Lot 9		Removed		
Current Condition:	Removed - LIM Construction sodded the lot prior to the inspection on 1/3/22.					
Lot 14	Individual Lot	Lot 14		Removed		
Current Condition:	Removed - Edward Custor		lot prior to the inspection			
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed - LIM Construction		Ll ne inspection on 7/19/22.	Removed		
			,			
Lot 30  Current Condition:	Individual Lot Removed - Seeing Double	Lot 33	o the inspection on 8/16/2	Removed		
Current Condition.	Temoved - Geeing Boubie	LEO Sodded the lot phor t		<b>-</b> .		
Lot 31	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double	LLC sodded the lot prior to	o the inspection on 8/16/2	2.		
Lot 32	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double	LLC sodded the lot prior to	the inspection on 8/16/2	2.		
Lot 33	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Seeing Double		the inspection on 8/16/2			
			· 			
Lot 34	Individual Lot	Lot 34		Removed		
Current Condition:	Removed - Seeing Double	LLC sodded the lot prior to	o the inspection on 8/16/2	Z. 		
Lot 35	Individual Lot	Lot 35		Removed		
Current Condition:	Removed - Seeing Double		o the inspection on 8/16/2			
Lot 36	Individual Lot	Lot 36	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double L	LC began excavation prior	r to the inspection on 5/25	/22.		
	1.) Curb line should be cleaned.					
	2.) Straw wattles should be installed along the street.					
	1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was reminded on 8/18/22, 10/13/22, 3/1/23 2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was reminded on 8/18/22, 10/13/22, 3/1/23					
Lot 37 Current Condition:	Individual Lot Pending - Seeing Double L	Lot 37	5/26/2022	Pending	Yes	
Current Condition.	Feliding - Seeing Double L	LC began excavation prior	to the inspection on 5/25	122.		
	<ol> <li>1.) Curb line should be cleaned.</li> <li>2.) Straw wattles should be installed along the street.</li> <li>1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was</li> </ol>					
	reminded on 8/18/22, 10/13/22, 3/1/23 2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/13		6/1/22. Not done as of the	last inspection. Seein	g Double LLC was	
L at 20		Lot 38	E/26/2022	Donding	Yes	
Lot 38 Current Condition:	Individual Lot Pending - Seeing Double L		5/26/2022 r to the inspection on 5/25	Pending /22.	169	
	Curb line should be cleaned.     Straw wattles should be installed along the street.					
	2.) Outur mattles should be installed along the sheet.					
	1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/13/22, 3/1/23 2.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was					
	reminded on 8/18/22, 10/13		0/ 1/22. 110t dono do or ano	idot inopodioni. Coom	g Double LLO Muo	
Lot 39	Individual Lot	Lot 39	5/26/2022	Pending	Yes	
Current Condition:	Pending - Seeing Double L				103	
	1.) Curb line should be cleaned.					
	2.) Straw wattles should be installed along the street.					
	1.) Seeing Double LLC was		6/1/22. Not done as of the	last inspection. Seein	g Double LLC was	
	reminded on 8/18/22, 10/13	3/22, 3/1/23		·		
	, ,	3/22, 3/1/23 s informed to complete by		·		
Lot 40	reminded on 8/18/22, 10/13 2.) Seeing Double LLC was	3/22, 3/1/23 s informed to complete by		·		

Current Condition:	Pending - Seeing Double I	LC began excavation prio	to the inspection on 5/25	5/22.			
	<ol> <li>1.) Curb line should be cleaned.</li> <li>2.) Straw wattles should be installed along the street.</li> <li>1.) Seeing Double LLC was informed to complete by 6/1/22. Not done as of the last inspection. Seeing Double LLC was</li> </ol>						
	reminded on 8/18/22, 10/1 2.) Seeing Double LLC wa		6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	reminded on 8/18/22, 10/1						
Lot 41	Individual Lot	Lot 41	5/26/2022	Pending	Yes		
Current Condition:	Pending - Seeing Double I	LC began excavation prio	to the inspection on 5/25	5/22.			
	1.) Curb line should be cle						
	2.) Straw wattles should be	e installed along the street.					
		s informed to complete by	6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	reminded on 8/18/22, 10/1 2.) Seeing Double LLC wa		6/1/22. Not done as of the	e last inspection. Seein	g Double LLC was		
	reminded on 8/18/22, 10/1				9		
Lot 57	Individual Lot	Lot 57		Removed			
Current Condition:	Removed - LIM Constructi	on sodded the lot prior to t	ne inspection on 4/25/22.				
Lot 60	Individual Lot	Lot 60	2/15/2023	Active	Yes		
Current Condition:	Fair Condition - LIM Const the rear of the lot as of 2/1						
	3/28/23.	o/20. Ziiii Gonoti dotion re	moved the dire phoe he	in the reest prior to a	io inopositori sii		
	Silt fence at the rear of the	lot should be repaired					
	Silt fence at the rear of the lot should be repaired.						
	LIM Construction was infor	med to complete by 3/6/23	. Not done as of the last	t inspection.			
Lot 61 Current Condition:	Individual Lot Removed - LIM Constructi	Lot 61	as inspection on 0/12/22	Removed			
Current Condition:	Removed - Liivi Constructi	on sodded the lot prior to ti I	ne inspection on 9/13/22.				
Lot 63	Individual Lot	Lot 63	:	Removed			
Current Condition:	Removed - LIM Constructi	on sodded the lot prior to ti I	ne inspection on 4/25/22.	I			
Lot 65	Individual Lot	Lot 65		Removed			
Current Condition:	Removed - LIM Constructi	on sodded the lot prior to t I	ne inspection on 10/11/22	I			
Lot 66	Individual Lot Removed - LIM Constructi	Lot 66		Removed			
Current Condition:			le inspection on 6/16/22.	<u> </u>			
Lot 67 Current Condition:	Individual Lot Removed - LIM Constructi	Lot 67	ne inspection on 8/16/22	Removed			
		<u> </u>	le mapection on o/ 10/22.				
Lot 68  Current Condition:	Individual Lot Removed - LIM Constructi	Lot 68	ne inspection on 4/25/22	Removed			
		·	ie inspection on 4/25/22.	Daman d			
Lot 71  Current Condition:	Individual Lot Removed - LIM Constructi	Lot 71 on sodded the lot prior to t	ne inspection on 4/25/22.	Removed			
PB 1	Portable Bathroom	HH14		Removed			
Current Condition:	Removed - LIM Constructi				N		
SB A Current Condition:	Sediment Basin	- Negus & Son's Construc	11/15/2018	Active	No o inspection on 9/19/19		
Current Condition.	Good Condition - 8% filled - Negus & Son's Construction partially installed the riser in the basin prior to inspection on 9/19/19. The E&A inspector will monitor and determine if all elements of the basin have been correctly installed when work is						
	completed. Negus & Son's Construction backfilled and compacted dirt around the riser and the portion of the outlet pipe						
	within the wall of the basin prior to the inspection on 12/16/19. Negus & Son's Construction partially dug out and reshaped the						
	sediment basin prior to the inspection on 12/16/19. Negus & Son's Construction backfilled and compacted along the outlet pipe prior to the inspection on 1/27/20. Negus & Son's Construction backfilled and compacted the subsided area along the						
	northern outlet pipe prior to the inspection on 7/14/20. Negus & Son's Construction backfilled and compacted the subsided area along the northern outlet pipe prior to the inspection on 7/14/20. Negus & Son's Construction installed the Scour Holes below both riser						
	outfalls prior to the inspection on 7/28/20. Roth Enterprises cleaned out the basin prior to the inspection on 9/22/20. Roth						
	Enterprises seeded and m	atted the slopes of the bas	in prior to the inspection of	on 10/05/20.			
SB B	Sediment Basin	R20	11/15/2018	Active	No		
Current Condition:	Good Condition - 15% fille						
	The E&A inspector will mo	nitor and determine if all e	ements of the basin have	been correctly installed	d when work is		
	completed. Negus & Son's			•			
	needs to be installed below both outfalls, and open area around the original riser pipe needs to be backfilled and compacted along the length of the pipe. Negus & Son's Construction installed the Scour Hole below the riser outfall prior to the inspection						
	on 7/28/20. Roth Enterpris	es cleaned out the basin p	rior to the inspection on 9				
SF 1	the slopes of the basin price	or to the inspection on 10/0 (A25-II18)	5/20. 11/8/2018	Active	No		
	I SILLIGING	1 (7.25-1110)	11/5/2010	7.0.170	110		

	Brega M Waght	I		<u> </u>		
Certification Statement:	direction or supervision in properly gathered and eva persons who manage the the information submitted am aware that there are si	luated the information sub- system or those persons d is, to the best of my knowle	designed to assure that q mitted. Based on my inqui rectly responsible for gath edge and belief, true, accu	ualified personnel iry of the person or nering the information, urate, and complete. I		
	prior to the inspection on 1 E&A inspector moved the intersection during the insp	12/30/19. The E&A inspect SWPPP sign to southern e pection on 4/01/20. The E	or reinstalled the SWPPP entrance of the developme &A inspector reinstalled the	sign during the inspectent near the N. Allen Store SWPPP sign during	tion on 12/30/19. The . and N. 2nd St.	
SWPPP Sign  Current Condition:	Misc./Other Good Condition- The inspe	N. Allen St. & N. 2nd St. ector installed the sign duri	12/17/2018 na the inspection on 12/1	Active 7/18. The SWPPP sign	No had been removed	
	01/15/21, 3/2/21, 3/17/21,	eeded. UPDATE: All streets to complete by 11/11/20.	Not done as of the last ins 7/6/21, 7/14/21, 7/27/21, 8	spection. All builders w		
	The condition of the streets could not be fully determined during the inspection on 12/16/19 due to snow and ice cover. The adjacent streets were free of track out during the inspection on 1/13/20. Negus & Son's Construction cleaned the track out o North Molley Street prior to the inspection on 2/10/20. LIM Construction cleaned the street in front of lots 73 and 74 prior to the inspection on 7/28/20. Viking Homes cleaned the street in front of lots 75 and 77 prior to the inspection on 7/28/20. Ryar Schwarz cleaned the street where silt ran off bare / sparse areas prior to the inspection on 8/11/20. LIM Construction cleaned the street in front of Lot 76 prior to the inspection on 9/08/20. Seeing Double Homes cleaned the street in front of Lots 18-21 prior to the inspection on 9/22/02. Viking Homes cleaned the street in front of Lot 12 prior to the inspection on 9/22/02. LIM					
Current Condition:	Fair Condition - Negus & S	Son's Construction cleaned	up the track out on the a	djacent streets prior to	inspection on 8/05/19	
STR	inspection on 9/08/20. Rya	an Schwarz reinstalled the Site	top row of silt fence prior t	to the inspection on 7/3 Active	1/21. Yes	
Current Condition:		hwarz installed two runs of				
Current Condition: SF 8	Removed - LIM Constructi Silt fence	on removed the silt fence p  AA6	orior to the inspection on 1	1/3/22. Active	No	
SF 7	Silt fence	GG16 - HH16		Removed		
Current Condition:		tion growth, silt fence is no	longer recommended as		ion.	
SF 6	inspection on 7/28/20.	DD11 - HH11	<u> </u>	Removed		
Current Condition:		s become sufficiently estab	I lished in the ROW north o		vent erosion as of th	
Current Condition: SF 5	Removed - Negus & Son's Silt fence	Construction removed the F23 - V16	ទ siit tence prior to the insp l	Removed		
SF 4	Silt fence	(DD1-DD14)	20.6	Removed		
Current Condition:	Removed - Silt fence insta (Lot 83).	illation will now be recomm	ended in the section of th	e report for the lot that	is now active in the a	
SF 3	Silt fence	II17		Removed		
Current Condition:	Removed - Silt fence insta (Lot 83).	Illation will now be recomm	ended in the section of th	e report for the lot that	is now active in the a	
SF 2	Silt fence	II18		Removed		
	added t-posts to the new risilt fence between SB a ar posts to the new run of silt reinstalled the silt fence who of SB B prior to the inspecs southeast corner of the sitt the undermined portion an the inspection on 7/14/20. Schwarz seeded and mattibehind all sodded lot and be silt fence when the silt fence with the silt fence when the silt fence when the silt fence with the silt fence when the silt fen	nd SB B, cleaned out and r fence along the southeast here removed along the nc tion on 6/11/20. Negus & S e, trenched in the patch ov d SB B, and extended the Ryan Schwarz repaired sil ed bare area south of lot 5	epaired the newer run of scorner of SB B, repaired rtheast side of SB B, and son's Construction backfill er the t-posts between the silt fence around the top of the fence in a few locations of prior to the inspection of	silt fence between SB A the old run of silt fence reinstalled the silt fence led the silt fence where e undermined portion at of the outfall at the north prior to the inspection of n 1/3/22. Ryan Schwarz	a and SB B, added t- east of SB B, e where removed noi undermined near the nd SB A and between n end of the run prior on 5/24/21. Ryan	
		paired. Negus & Son's Co				