E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	Eδ	&A- P2011.160.006			
Inspector: Nathan Hack					Stage
Project Name:		Ridgeview Apartı CSW-2021060			1
For Week Ending:		68048			
Project Location:	211 S 2				
Grading:	65%	<u>′</u> о́			
Sanitary Sewer:	0%				
Storm Sewer:	0%	ó			
Paving:	0%	ó			
Seeding:	0%				
Utilities:	0%				
Overall Development:	10%	ō			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
	0.000				Week
Sunday:	0.00"	+			
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	2/22/2023	Cloudy 48/10	11:09 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None				
Construction Sequencing:					

Construction Sequencing:

nage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23), Some grading and concrete work related to apartment construction active (2/01/23)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23), Some grading and concrete work related to apartment construction active (2/01/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Yes

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

Comments:

1.) Site was active during the current inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance in BMP Section.

Unique Name	Type	Location	Projected Install Date	Status	Maintena			
ČE 01	Construction Entrance	North East Corner	12/1/2022	Active	No			
Current Condition:	Good Condition - 80% effective - Calabretto Building Group installed a construction entrance prior to the 1/18/23 inspection. Calabi							
	Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection.							
MS 01	Material Storage	Near CE 01	11/23/2022	Active	No			
Current Condition:	Active - Calabretto Building Group is storing building materials on site. A waste storage container was installed near the construct							
	entrance (2/8/23).							
PB 01	Material Storage	Near CE 01	11/30/2022	Active	No			
Current Condition:	Good Condition - Calabretto Building Gro	<u> </u>						
SF 01	Silt Fence	East perimeter	9/9/2022	Active	Yes			
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. The silt fence needs to be repaired and extended along the eastern perimeter. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was informed to complete by 11/30/22.							
05.00	reminded on 2/23/23.		10/4/0000	5 "				
SF 02 Current Condition:	Silt Fence Pending -	Eastern Slope	12/1/2022	Pending	Yes			
	Silt fence should be installed once grading in the area is complete. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23.							
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	No			
Current Condition:	Good Condition- No major signs of track	off.						
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No			
Current Condition:	Good Condition- E&A inspector installed				on 12/7/22. E			
	inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection.							
WO 01 Current Condition:	Concrete Washout Pending -	On site	12/1/2022	Pending	Yes			
	 1.) Concrete waste related to construction on the north central portion of the site should be cleaned up and removed. 2.) A concrete washout should be installed to contain any washouts. 1.) Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection Calabretto Building Group was reminded on 2/23/23. 2.) Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection 							
	Calabretto Building Group was remine	ded on 2/23/23.						
WS 01	Waste Storage Area	On site	12/7/2022	Active	No			
Current Condition:	Active - Calabretto Building Group is sto entrance (2/8/23).	ring building materials on sit	e. A waste storage contain	er was installed ne	ar the construc			
WT 01	Wattle	North East Corner	11/30/2022	Pending	Yes			
*****	Pending -							
Current Condition:	Wattles should be installed in front of dra	·	ot done as of last inspectio	n. Calabretto Build	ling Group wa			
	Wattles should be installed in front of dra	to complete by 11/30/22. No locument and all attachments ualified personnel properly ganage the system or those per ly knowledge and belief, true	s were prepared under my athered and evaluated the rsons directly responsible a, accurate, and complete.	direction or superv information submitt for gathering the in I am aware that the	sion in accorded. Based on roormation, the re are signification.			