E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E	&A- P2011.160.006					
Inspector: Ethan Anderson					Stage		
Project Name:	Ridgeview Apartments CSW-202106011						
For Week Ending:		4/22/2023			68048		
Project Location:	211 S	211 S 23RD ST - Plattsmouth, NE (Cass County)					
Grading:	65	5%					
Sanitary Sewer:		0%					
Storm Sewer:		0%					
Paving:		0%					
Seeding:		0%					
Utilities:	(0%					
Overall Development:	10	0%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.30"	4/19/2023	Cloudy 78/53	1:00 PM	9:30PM - 10PM		
Thursday:	0.81"				3:15AM - 6AM		
Friday:	0.00"						
Saturday:	0.00"						
Complaints:	None						

=0.1 =00.11.100.000

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23), Some grading and concrete work related to apartment construction active (2/01/23), electric installation begins (4/5/23)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23), Some grading and concrete work related to apartment construction active (2/01/23), electric installation begins (4/5/23)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

reate Corrective Action?

N/A

Comments:

- 1.) Site was active during the current inspection.
- 2.) Concrete forms related to apartment foundation in progress (3/1/23).

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance in BMP Section.

- 2.) Areas of site should be stablilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23.

CE 01	Туре	Location	Projected Install Date	Status	Maintena		
	Construction Entrance	North East Corner	12/1/2022	Active	Yes		
Current Condition:	Fair Condition - 50% effective - Calabretto Building Group installed a construction entrance prior to the 1/18/23 inspection. Calabre Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection. Trackout was observed during inspection on 4/21/23.						
	Construction entrance should be installed.						
MS 01	Calabretto Building Group was info Material Storage	rmed to complete by 4/26/23. Near CE 01	11/23/2022	Active	No		
Current Condition:	Active - Calabretto Building Group is s						
	entrance (2/8/23). Lumber and other of storage on site (3/29/23).						
PB 01	Material Storage	Near CE 01	11/30/2022	Active	No		
Current Condition:	Good Condition - Calabretto Building (Group staked down the portabl	e toilet prior to the 12/21/2	22 inspection.			
SF 01	Silt Fence	East perimeter	9/9/2022	Active	Yes		
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. The silt fence needs to be repaired and extended along the eastern perimeter. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was						
	reminded on 2/23/23, 4/21/23						
SF 02 Current Condition:	Silt Fence Pending -	Eastern Slope	12/1/2022	Pending	Yes		
	Silt fence should be installed once grading in the area is complete. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23						
STR Current Condition:	Streets Fair Condition- No major signs of tract	ADJ and Internal Streets	10/31/2022	Active	Yes		
	Calabretto Building Group was info	rance should be cleaned.					
SWPPP Sign	Calabretto Building Group was info	rmed to complete by 4/26/23. Adjacent to CE 1	9/30/2022	Active	No.		
Current Condition:	SWPPP Signs Good Condition- E&A inspector install- inspector reinstalled the SWPPP sign	rmed to complete by 4/26/23. Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site do	9/30/2022 th east corner of the site our 1/4/23 inspection	during the inspection			
Current Condition: WO 01	SWPPP Signs Good Condition- E&A inspector install- inspector reinstalled the SWPPP sign Concrete Washout	rmed to complete by 4/26/23. Adjacent to CE 1 ed the SWPPP sign on the nor	9/30/2022 th east corner of the site of	during the inspection			
Current Condition:	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed. 1.) Calabretto Building Group was remind 2.) Calabretto Building Group was information of the control of	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 or ed on 2/23/23, 4/21/23 rmed to complete by 1/25/23 or	9/30/2022 th east corner of the site of uring the 1/4/23 inspection 12/1/2022 n of the site should be clear or as weather conditions a	during the inspection Pending aned up and remove	Yes Id. Id. Id. Id. Id. Id. Id. Id		
WO 01 Current Condition:	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be inste 1.) Calabretto Building Group was info Calabretto Building Group was info Calabretto Building Group was remind 2.) Calabretto Building Group was remind	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23	9/30/2022 th east corner of the site curing the 1/4/23 inspection 12/1/2022 n of the site should be clear as weather conditions a	uring the inspection Pending aned up and remove llow. Not done as of	Yes d. last inspection		
Current Condition: WO 01	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed. 1.) Calabretto Building Group was info Calabretto Building Group was remind 2.) Calabretto Building Group was remind Waste Storage Area Active - Calabretto Building Group is s	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 On site	9/30/2022 th east corner of the site of uring the 1/4/23 inspection 12/11/2022 n of the site should be clear as weather conditions a ras weather conditions a 12/7/2022	Turing the inspection Pending aned up and remove llow. Not done as of Active	Yes I ast inspection last inspection No		
WO 01 Current Condition: WS 01 Current Condition:	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed. 1.) Calabretto Building Group was inform Calabretto Building Group was remind 2.) Calabretto Building Group was remind Waste Storage Area Active - Calabretto Building Group is sentrance (2/8/23).	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 On site toring building materials on site	9/30/2022 th east corner of the site of uring the 1/4/23 inspection 12/1/2022 n of the site should be clear as weather conditions a ras weather conditions a 12/7/2022 e. A waste storage contain	Juring the inspection Pending aned up and remove llow. Not done as of llow. Not done as of Active ner was installed nea	Yes I ast inspection last inspection No ar the construct		
WO 01 Current Condition: WO 01 Current Condition:	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed. 1.) Calabretto Building Group was info Calabretto Building Group was remind 2.) Calabretto Building Group was remind Waste Storage Area Active - Calabretto Building Group is s	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 On site	9/30/2022 th east corner of the site of uring the 1/4/23 inspection 12/11/2022 n of the site should be clear as weather conditions a ras weather conditions a 12/7/2022	Turing the inspection Pending aned up and remove llow. Not done as of Active	Yes I ast inspection last inspection No		
WO 01 Current Condition: WS 01 Current Condition: WS 01 Current Condition:	SWPPP Signs Good Condition- E&A inspector installed inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed the SWPPP sign Concrete Washout 1.) Calabretto Building Group was remind 2.) Calabretto Building Group was remind Waste Storage Area Active - Calabretto Building Group is sentrance (2/8/23). Wattle Pending - Wattles should be installed in front of Calabretto Building Group was informed was should be installed in front of Calabretto Building Group was informed was should be installed in front of Calabretto Building Group was informed was should be installed in front of Calabretto Building Group was informed was i	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 rmed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 ced on 2/23/23, 4/21/23 I On site toring building materials on site North East Corner	9/30/2022 th east corner of the site of uring the 1/4/23 inspection 12/1/2022 n of the site should be clear as weather conditions a 12/7/2022 e. A waste storage contain 11/30/2022	Juring the inspection Pending aned up and remove llow. Not done as of llow. Not done as of Active ner was installed ner	Yes I ast inspection. I ast inspection. No ar the construct Yes		
WO 01 Current Condition: WS 01 Current Condition: WS 01 Current Condition:	SWPPP Signs Good Condition- E&A inspector installe inspector reinstalled the SWPPP sign Concrete Washout Pending - 1.) Concrete waste related to construct 2.) A concrete washout should be installed. 1.) Calabretto Building Group was info Calabretto Building Group was remind 2.) Calabretto Building Group was remind Waste Storage Area Active - Calabretto Building Group is sentrance (2/8/23). Wattle Pending - Wattles should be installed in front of the	Adjacent to CE 1 ed the SWPPP sign on the nor near the entrance of the site di On site tion on the north central portion alled to contain any washouts. Timed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 Timed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 Timed to complete by 1/25/23 of ed on 2/23/23, 4/21/23 On site North East Corner drainage area. ed to complete by 11/30/22. No site document and all attachment qualified personnel properly grananage the system or those per my knowledge and belief, true	9/30/2022 th east corner of the site ouring the 1/4/23 inspection 12/1/2022 th of the site should be clear or as weather conditions a tras weather conditions a tran weather c	Pending Active ner was installed ner Pending Active ner was installed ner pending Active ner was installed ner in the pending Active ner was installed ner pending Active ner was installed ner pending	Yes I ast inspection. I ast inspection. I ast inspection. Yes Yes Yes Yes Yes Yes Yes Ye		