10909 Mill Valley Road, Suite 100	E&	A- P2011.160.006			7 =			
Inspector: Ethan Anderson					је			
Project Name:	Ridgeview Apartments							
For Week Ending:		5/6/2023	F & Δ	CONSULTING GR	ROUP, INC. Hes			
Project Location:	211 S 23	RD ST - Plattsmouth, NE	(Odda Ocumy)					
One discussion	750/	I		Engineering Ans	wers			
Grading: Sanitary Sewer:	75%							
Storm Sewer:	0%							
Paving:	0%							
Seeding:	0%							
Utilities:	0%	,						
Overall Development:	20%	,						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week 1			
Sunday:	0.00"							
Monday:	0.00"							
Tuesday: Wednesday:	0.00"	E/2/2022	Cummy 72/27	4.20 DM				
Thursday:	0.00"	5/3/2023	Sunny 73/37	1:30 PM				
Friday:	0.00"			1				
Saturday:	0.01"							
	None							
Complaints:								
Construction Sequencing:	the site have had a town over a warman and a constant	tion of avading continuous or a	unional allationhauman in the last d	4 days 2				
	the site have had a temporary or permanent cessal				installation active			
E&A filled as SWFFF Illispector (11	/21/22). Entire site active for grading as of	(11/23/2022). Removal of	concrete at entrance (11/3	0/22). Retailing wall	installation active.			
Which portion(s) (i.e. drainage basins) of t	the site do not have grading, earthwork, or ground	disturbance scheduled in the r	next 14 days?					
	/21/22). Entire site active for grading as of			0/22). Retaining wall	installation active.			
, ,	, ,	,	`	,				
What temporary or permanent stabilization	n measures listed in this section are being implem	nented?						
Existing vegetation (11/23/2022).								
Checklist Questions:								
	the project free of any significant signs	of erosion or sediment th	at would be associated	with the construction	on activity?			
Yes								
Create Corrective Action?								
N/A								
prevent erosion.					_			
No								
Create Corrective Action?								
No, See Findings Section								
Are waste materials (concrete, co	nstruction material, hazardous, etc.) be	ing managed properly?						
No								
Create Corrective Action?								
No, See BMP Section								
Are construction entrances and a	djacent streets being maintained adequ	untolu?						
No	lajacent streets being maintained adequ	lately r						
Create Corrective Action?								
No, See BMP Section								
Is dust associated with the const	ruction activity adequately controlled or	n the site?						
Yes								
Create Corrective Action?								
N/A								
Comments:								
Comments:	4-1-							
Findings / Corrective Actions (Da	·							
Findings / Corrective Actions (Da	iej.							

Construction Entrance condition - 40% effective - Calabret Fuel Tank g - Calabretto Building Group inst Material Storage - Calabretto Building Group is storage - Condition - Calabretto Building Group Silt Fence condition - Calabretto Building Group Silt Fence g - Streets condition- No major signs of track or Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed	Near RN 6 alled a portable fuel tank pri Near CE 01 ring building materials on site Near CE 01 bup staked down the portable East perimeter prinstalled silt fence prior to Eastern Slope ADJ and Internal Streets ff. Trackout was observed of RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and	4/26/2023 or to the inspection on 4/26 11/23/2022 e. A waste storage contain 11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr	Pending 6/23. Active ser was installed near Active 2 inspection. Active 2. Pending Active section on 4/19/23. Pending rade. Pending	Yes
Fuel Tank g - Calabretto Building Group inst Material Storage - Calabretto Building Group is storage - Calabretto Building Group is storage Condition - Calabretto Building Group Silt Fence Indition - Calabretto Building Group Silt Fence g - Streets Indition- No major signs of track or Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	Near RN 6 alled a portable fuel tank pri Near CE 01 ring building materials on site Near CE 01 bup staked down the portable East perimeter prinstalled silt fence prior to Eastern Slope ADJ and Internal Streets ff. Trackout was observed of RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and	4/26/2023 or to the inspection on 4/26 11/23/2022 e. A waste storage contain 11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr	Pending 6/23. Active ler was installed nea Active 2 inspection. Active 2. Pending Active lection on 4/19/23. Pending leade. Pending leade. Pending	Yes No ar the construction No Yes Yes No No No
g - Calabretto Building Group inst Material Storage - Calabretto Building Group is storage - Calabretto Building Group is storage Condition - Calabretto Building Group Silt Fence Indition - Calabretto Building Group Silt Fence g - Streets Condition - No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	Alled a portable fuel tank pri Near CE 01 ring building materials on site Near CE 01 pup staked down the portable East perimeter pup installed silt fence prior to Eastern Slope ADJ and Internal Streets F. Trackout was observed of RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	or to the inspection on 4/26 11/23/2022 e. A waste storage contain 11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active ser was installed near Active 2 inspection. Active 2. Pending Active section on 4/19/23. Pending rade. Pending	No ar the construction No Yes Yes No No
Material Storage - Calabretto Building Group is storage Condition - Calabretto Building Group Silt Fence condition - Calabretto Building Group Silt Fence g - Streets condition- No major signs of track or Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	Near CE 01 ring building materials on site Near CE 01 pup staked down the portable East perimeter prinstalled silt fence prior to Eastern Slope ADJ and Internal Streets Ff. Trackout was observed of RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and	11/23/2022 e. A waste storage contain 11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active ner was installed nea Active 2 inspection. Active 2. Pending Active section on 4/19/23. Pending rade. Pending ade.	retained the construction No No Yes Yes No No No
- Calabretto Building Group is stored Material Storage Condition - Calabretto Building Group Silt Fence Condition - No major signs of track of Inlet Protection Condition - No major signs of track of Inlet Protection Condition - The inlet filter will be installed Inlet Protection Condition - The inlet filter will be installed Inlet Protection	ring building materials on situ Near CE 01 pup staked down the portable East perimeter up installed silt fence prior to Eastern Slope ADJ and Internal Streets FI. Trackout was observed or RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	e. A waste storage contain 11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the inspection of 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	er was installed near Active 2 inspection. Active 2. Pending Active section on 4/19/23. Pending rade. Pending ade.	retained the construction No No Yes Yes No No No
Material Storage Condition - Calabretto Building Groundition - No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	Near CE 01 pup staked down the portable East perimeter pup installed silt fence prior to Eastern Slope ADJ and Internal Streets Ff. Trackout was observed on RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	11/30/2022 e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active 2 inspection. Active 2. Pending Active ection on 4/19/23. Pending rade. Pending	Yes Yes No No
Condition - Calabretto Building Grossilt Fence ondition - Calabretto Building Grossilt Fence g - Streets ondition- No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	ADJ and Internal Streets FI. Trackout was observed on RN 1 - RN 6 once the inlet is installed and Near RN 6 Near RN 6	e toilet prior to the 12/21/2: 9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 the street during the inspection of the street during the inspection of the inlet is at or below grade the inlet in the inlet inlet inlet in the inlet inlet inlet in the inlet in	2 inspection. Active 2. Pending Active ection on 4/19/23. Pending rade. Pending rade.	Yes Yes Yes No
Silt Fence pondition - Calabretto Building Grou Silt Fence g - Streets pondition- No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection Inlet Protection	East perimeter prinstalled silt fence prior to Eastern Slope ADJ and Internal Streets ff. Trackout was observed or RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	9/9/2022 the inspection on 11/23/22 12/1/2022 10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active Pending Active section on 4/19/23. Pending rade. Pending rade.	Yes Yes No
silt Fence g - Streets Indition - No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	ADJ and Internal Streets FI. Trackout was observed on RN 1 - RN 6 once the inlet is installed and Near RN 6 Near RN 6 Near RN 6	10/31/2022 10/31/2022 10/31/2022 10 the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active ection on 4/19/23. Pending rade. Pending rade.	Yes Yes No
Silt Fence g - Streets ondition- No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection Inlet Protection	ADJ and Internal Streets ff. Trackout was observed or RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	10/31/2022 n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active section on 4/19/23. Pending rade. Pending rade.	Yes No No
g - Streets ondition- No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection Inlet Protection	ADJ and Internal Streets ff. Trackout was observed of RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	10/31/2022 In the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Active section on 4/19/23. Pending rade. Pending rade.	Yes No No
Streets condition- No major signs of track of Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	ff. Trackout was observed or RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6 Near RN 6	n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Pending rade. Pending rade.	No No
ondition- No major signs of track on Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	ff. Trackout was observed or RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6 Near RN 6	n the street during the insp 4/26/2023 d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Pending rade. Pending rade.	No No
Inlet Protection g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	RN 1 - RN 6 once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	Pending rade. Pending rade.	No
g - The inlet filter will be installed Inlet Protection g - The inlet filter will be installed Inlet Protection	once the inlet is installed and Near RN 6 once the inlet is installed and Near RN 6	d the inlet is at or below gr 4/26/2023 d the inlet is at or below gr	rade. Pending rade.	No
Inlet Protection g - The inlet filter will be installed Inlet Protection	Near RN 6 once the inlet is installed and Near RN 6	4/26/2023 d the inlet is at or below gr	Pending rade.	
g - The inlet filter will be installed Inlet Protection	once the inlet is installed and	d the inlet is at or below gr	ade.	
Inlet Protection	Near RN 6	·		N-
		4/26/2022	Donding	N-
a - The inlet filter will be installed		4/20/2023	renung	I NO
	once the inlet is installed and	d the inlet is at or below gr	ade.	•
Erosion Control Mat	RM 1	4/26/2023	Pending	No
g -		'		
Erosion Control Mat	RM 2	4/26/2023	Pending	No
g -		<u> </u>		
Erosion Control Mat	RM 3	4/26/2023	Pending	No
g -		'		
SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No
Condition- E&A inspector installed	the SWPPP sign on the nor	th east corner of the site du	uring the inspection	on 12/7/22. E&A
Concrete Washout	On site	12/1/2022	Pending	Yes
g -				
Waste Storage Area	On site	12/7/2022	Active	No
- Calabretto Building Group is stor	ring building materials on site	e. A waste storage contain	er was installed nea	ar the construction
Wattle	North East Corner	11/30/2022	Pending	Yes
g -	·	·		
y, under penalty of law, that this d	ocument and all attachments	s were prepared under my	direction or supervi	sion in accordance
	Erosion Control Mat g - SWPPP Signs Condition- E&A inspector installed Concrete Washout g - Waste Storage Area - Calabretto Building Group is stor	Erosion Control Mat RM 3 g - SWPPP Signs Adjacent to CE 1 Condition- E&A inspector installed the SWPPP sign on the nor Concrete Washout On site g - Waste Storage Area On site - Calabretto Building Group is storing building materials on sit Wattle North East Corner g -	Erosion Control Mat RM 3 4/26/2023 g - SWPPP Signs Adjacent to CE 1 9/30/2022 Condition- E&A inspector installed the SWPPP sign on the north east corner of the site d Concrete Washout On site 12/1/2022 g - Waste Storage Area On site 12/7/2022 Calabretto Building Group is storing building materials on site. A waste storage contain Wattle North East Corner 11/30/2022 g - y, under penalty of law, that this document and all attachments were prepared under my	Erosion Control Mat RM 3 4/26/2023 Pending g - SWPPP Signs Adjacent to CE 1 9/30/2022 Active Condition- E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection Concrete Washout On site 12/1/2022 Pending g - Waste Storage Area On site 12/17/2022 Active - Calabretto Building Group is storing building materials on site. A waste storage container was installed nea Wattle North East Corner 11/30/2022 Pending