E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| | | E& | A- P2011.160.006 | | | | | |
|---------------------------|------------------|---|------------------|--------------------|----------|--------|--|--|
| Inspector: Ethan Anderson | | | | | | Stage | | |
| Project Name: | | Ridgeview Apartments CSW-202106011 | | | | | | |
| For Week Ending: | | 5/20/2023 | | | | | | |
| Project Location: | 21 | 211 S 23RD ST - Plattsmouth, NE (Cass County) | | | | | | |
| | | | | | | | | |
| Grading: | | 75% | | | | | | |
| Sanitary Sewer: | | 0% | | | | | | |
| Storm Sewer: | | 0% | | | | | | |
| Paving: | | 0% | | | | | | |
| Seeding: | | 0% | | | | | | |
| Utilities: | | 0% | | | | | | |
| Overall Development: | | 20% | | | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | | Date inspected | Weather Conditions | Time | | | |
| | | | | | | Week 1 | | |
| Sunday: | 0.00" | | | | | | | |
| Monday: | 0.11' | | | | | | | |
| Tuesday: | 0.00" | | | | | | | |
| Wednesday: | 0.00" | | 5/17/2023 | Sunny 81/52 | 12:45 PM | | | |
| Thursday: | 0.06" | | | | | | | |
| Friday: | 0.00" | | | | | | | |
| Saturday: | 0.00" | | | | | | | |
| | | | | | | | | |
| Complaints: | None | | | | | | | |

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23). Electrical installation begins (4/5/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23). Electrical installation begins (4/5/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?
No, See Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Site was active for concrete work during the inspection (3/1/23, 5/3/23, 5/11/23).

- Findings / Corrective Actions (Date):

 Findings / Corrective Actions (Date):

 1.) Some maintenance in BMP Section.

 2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection.

| CE 01 Current Condition: | Construction Entrance | North East Corner | 12/1/2022 | Active | Yes | | |
|--------------------------|--|--|--|------------------------------|-----------------|--|--|
| | Fair Condition - 45% effective - Calabrett | | | | | | |
| | Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection. Trackout was observed during the | | | | | | |
| | inspection on 4/21/23. | | | | | | |
| | 1100000101111120 | | | | | | |
| | Construction entrance should be extended adjacent to entrance being used currently. | | | | | | |
| | Construction of the first section of the first sect | | | | | | |
| | Calabretto Building Group was informed | to complete by 4/26/23. Not | done as of last inspection | | | | |
| FT X | Fuel Tank | Near RN 6 | 4/26/2023 | Pending | Yes | | |
| Current Condition: | Pending - Calabretto Building Group inst | | | | 163 | | |
| ourient condition. | rending - Galabretto Ballaring Group inst | tailed a portable ruel talik pri | or to the mapeedon on 4/2 | 0/20. | | | |
| | Secondary containment should be install | led around fuel tank | | | | | |
| | Secondary Containment should be installed around their tank. | | | | | | |
| | Calabretto Building Group was informed to complete by 5/3/23. Not done as of last inspection. | | | | | | |
| MC 04 | • • | <u> </u> | <u> </u> | A - 11 | N. | | |
| MS 01 | Material Storage | Near CE 01 | 11/23/2022 | Active | No | | |
| Current Condition: | Active - Calabretto Building Group is stor | | | | | | |
| | entrance (2/8/23). Lumber and other cor | nstruction materials moved o | n site in designated storag | ge areas (3/22/23). <i>I</i> | Additional lumb | | |
| | storage on site (3/29/23). | | | | | | |
| PB 01 | Material Storage | Near CE 01 | 11/30/2022 | Active | No | | |
| Current Condition: | Good Condition - Calabretto Building Gro | | | | | | |
| RN 1 - RN 6 | Inlet Protection | RN 1 - RN 6 | 4/26/2023 | Pending | No | | |
| Current Condition: | Pending - The inlet filter will be installed | once the inlet is installed an | d the inlet is at or below gı | rade. | | | |
| RN 7 - RN 12 | Inlet Protection | Near RN 6 | 4/26/2023 | Pending | No | | |
| Current Condition: | Pending - The inlet filter will be installed | | d the inlet is at or below qu | | | | |
| DN 40 DN 40 | | | | | т | | |
| RN 13 - RN 18 | Inlet Protection | Near RN 6 | 4/26/2023 | Pending | No | | |
| Current Condition: | Pending - The inlet filter will be installed | once the inlet is installed an | d the inlet is at or below gi | rade. | | | |
| RM 1 | Erosion Control Mat | RM 1 | 4/26/2023 | Pending | Yes | | |
| Current Condition: | Pending - | | | | | | |
| | | | | | | | |
| | Erosion Matting should be installed. | | | | | | |
| | | | | | | | |
| | Calabretto Building Group was informed | to complete by 5/3/23. Not o | lone as of last inspection. | | | | |
| RM 2 | Erosion Control Mat | RM 2 | 4/26/2023 | Pending | Yes | | |
| Current Condition: | Pending - | TAIVI Z | 4/20/2020 | rending | 103 | | |
| | ·g | | | | | | |
| | Erosion Matting should be installed. | | | | | | |
| | 27 Solon matang should 20 metanga. | | | | | | |
| | Calabretto Building Group was informed | to complete by 5/3/23. Not o | lone as of last inspection. | | | | |
| DMO | | | | D i' | | | |
| RM 3 | Erosion Control Mat | RM 3 | 4/26/2023 | Pending | Yes | | |
| Current Condition: | Pending - | | | | | | |
| | | | | | | | |
| | Erosion Matting should be installed. | | | | | | |
| | Out to the Dutting Output in Comment | 1 | to an arrange of the Atlantan and the arrange of | | | | |
| | Calabretto Building Group was informed | to complete by 5/3/23. Not o | ione as of last inspection. | | | | |
| SF 01 | Silt Fence | East perimeter | 9/9/2022 | Active | Yes | | |
| Current Condition: | Fair Condition - Calabretto Building Grou | up installed silt fence prior to | the inspection on 11/23/2 | 2. | | | |
| | | | | | | | |
| | The silt fence needs to be repaired and extended along the eastern perimeter. | | | | | | |
| | | | | | | | |
| | Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was | | | | | | |
| | reminded on 2/23/23, 4/21/23 | | | | | | |
| SF 02 | Silt Fence | Eastern Slope | 12/1/2022 | Pending | Yes | | |
| Current Condition: | Pending - | • | | 5 | | | |
| | | | | | | | |
| | Silt fence should be installed once grading in the area is complete. | | | | | | |
| | | | | | | | |
| | Calabretto Building Group was informed | to complete by 11/30/22. No | ot done as of last inspection | n. Calabretto Buildi | ng Group was | | |
| | reminded on 2/23/23, 4/21/23 | , | | | , | | |
| STR | Streets | ADJ and Internal Streets | 10/31/2022 | Active | Yes | | |
| Current Condition: | Fair Condition- No major signs of track of | | | | 162 | | |
| Current Condition: | Tan Condition No major signs of track o | . Hackout was observed of | raio succi during the msp | | | | |
| | The street in front of the project entrance | es should be cleaned | | | | | |
| | | o onould be ofcaricu. | | | | | |
| | The street in front of the project charance | | | | | | |
| | . , | to complete by 4/26/23. Not | done as of last inspection | | | | |
| SWPPP Sign | Calabretto Building Group was informed SWPPP Signs | to complete by 4/26/23. Not Adjacent to CE 1 | done as of last inspection 9/30/2022 | Active | No | | |

| WO 01 | Concrete Washout | On site | 12/1/2022 | Pending | Yes | | |
|-------------------------|---|---|---|--------------------------------|-----------------|--|--|
| Current Condition: | Pending - 1.) Concrete waste related to construction on the north central portion of the site should be cleaned up and removed. 2.) A concrete washout should be installed to contain any washouts. 1.) Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23 | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | 2.) Calabretto Building Group was inform Calabretto Building Group was reminded | | r as weather conditions a | llow. Not done as of la | ast inspection. | | |
| WS 01 | Waste Storage Area | On site | 12/7/2022 | Active | No | | |
| Current Condition: | Active - Calabretto Building Group is storing building materials on site. A waste storage container was installed near the construction entrance (2/8/23). | | | | | | |
| WT 01 | Wattle | North East Corner | 11/30/2022 | Pending | Yes | | |
| | Wattles should be installed in front of dra Calabretto Building Group was informed treminded on 2/23/23, 4/21/23 | ŭ | ot done as of last inspection | on. Calabretto Building | g Group was | | |
| Certification Statement | "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man information submitted is, to the best of my penalties for submitting false information | athered and evaluated the rsons directly responsible , accurate, and complete | e information submitte e for gathering the info . I am aware that there | d. Based on my rmation, the | | | |
| spector Signature: | En Carlon | | | Reviewed By: | The Sol | | |