E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2011.160.006			
Inspector: Ethan Anderson					
Project Name:	Ridgeview Apartments CSW-202106011				1
For Week Ending:		8/26/2023 211 S 23RD ST - Plattsmouth, NE (Cass County)			
Project Location:	211				
Grading:		75%			
Sanitary Sewer:		5%			
Storm Sewer:		5%			
Paving:		0%			
Seeding:		0%			
Utilities:		0%			
Overall Development:		30%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Wee
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	8/23/2023	Sunny 96/76	10:10 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	1.59"				2:55 AM - 7:55 AM
	lat				
Complaints:	None				

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23). Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23). Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23).

porary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?
No, See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

Site was active during the inspection.

- Findings / Corrective Actions (Date):
 Findings / Corrective Actions (Date):
 1.) Some maintenance in BMP Section.
 2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection.
 Calabretto Building Group was reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenar
CE 01	Construction Entrance	North East Corner	12/1/2022	Active	Yes
Current Condition:	Fair Condition - 40% effective - Calabretto Building Group installed a construction entrance prior to the 1/18/23 inspection. Calabretto Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection. Trackout was observed during the inspection on 4/21/23. Calabretto Building Group placed more soil around the entrance prior to inspection on 6/14/23.				
	Rock should be installed on the construct Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23		t done as of last inspection	n. Calabretto Buildin	ig Group was ren
	511 572 1725, 572 1725, 1725/25, 57 15/25				
FT X	Fuel Tank	On site	4/26/2023	Active	No
Current Condition:	Good Condition - Calabretto Building Gro removed the fuel tank prior to inspection inspection on 6/21/23.				
MS 01	Material Storage	Near CE 01	11/23/2022	Active	No
Current Condition:	Active - Calabretto Building Group is stor entrance (2/8/23). Lumber and other con storage on site (3/29/23).				
PB 01	Portable Bathroom	Near CE 01	11/30/2022	Active	No
Current Condition:	Good Condition - Calabretto Building Gro moved and secured the portable toilet pri	ior to the inspection on 6/28	/23.		
RN 1 - RN 6 Current Condition:	Inlet Protection Pending - The inlet filter will be installed	RN 1 - RN 6	4/26/2023	Pending	No
	, and the second				1
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	No
Current Condition:	Pending - The inlet filter will be installed			raue.	
RN 13 - RN 18	Inlet Protection	Near RN 6	4/26/2023	Pending	No
Current Condition:	Pending - The inlet filter will be installed	once the inlet is installed ar	nd the inlet is at or below g	rade.	
RM 1 Current Condition:	Erosion Control Mat Pending -	RM 1	4/26/2023	Pending	Yes
RM 2	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat	to complete by 5/3/23. Not	done as of last inspection. 4/26/2023	Calabretto Building Pending	Group was rem
Current Condition:	Pending -				
	Erosion Matting should be installed. Calabretto Building Group was informed to complete by 5/3/23. Not done as of last inspection. Calabretto Building Group was remi on 5/24/23, 6/21/23, 7/20/23, 8/16/23				
RM 3	Erosion Control Mat	RM 3	4/26/2023	Pending	Yes
Current Condition:	Pending - Erosion Matting should be installed.				
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23				
ST 01	Silt Trap	South end of site	4/19/2023	Active	Yes
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. The area around and in the basin should be stabilized and repaired.				
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 4/26/23. No	t done as of last inspection	n. Calabretto Buildin	g Group was rer
ST 02	Silt Trap	East perimeter	4/19/2023	Active	Yes
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. The area around and in the basin should be stabilized.				
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23				•
SF 01 Current Condition:	Calabretto Building Group was informed	East perimeter	9/9/2022	Active	g Group was ren

SF 02	Silt Fence	Eastern Slope	12/1/2022	Pending	Yes	
Current Condition:	Pending -					
	Silt fence should be installed.					
	Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/		t done as of last inspection	on. Calabretto Buildi	ng Group was reminded	
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	No	
Current Condition:	Good Condition- No major signs of track					
	Group cleaned the entrance street prior to the inspection on 6/14/23.					
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No	
Current Condition:		Good Condition- E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection on 12/7/22. E&A inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection.				
WO 01	Concrete Washout	On site	12/1/2022	Pending	Yes	
Current Condition:	Pending -					
	Concrete waste related to construction A concrete washout should be install Calabretto Building Group was inform Calabretto Building Group was reminded 2.) Calabretto Building Group was reminded Calabretto Building Group was reminded Calabretto Building Group was reminded.	ed to contain any washouts. ned to complete by 1/25/23 o d on 2/23/23, 4/21/23, 5/24/23 ned to complete by 1/25/23 o	r as weather conditions a 3, 6/21/23, 7/20/23, 8/16/2 r as weather conditions a	llow. Not done as of 23 llow. Not done as of	last inspection.	
WS 01	Waste Storage Area	On site	12/7/2022	Active	No	
Current Condition:	Active - Calabretto Building Group is sto entrance (2/8/23).					
WT 01	Wattle	North East Corner	11/30/2022	Pending	Yes	
Current Condition:	Pending -					
	Wattles should be installed in front of drainage area. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23					
Certification Statement	"I certify, under penalty of law, that this of a system designed to assure that qualifit the person or persons who manage the submitted is, to the best of my knowledg submitting false information including the	ed personnel properly gather system or those persons dire ge and belief, true, accurate, a	ed and evaluated the info ctly responsible for gathe and complete. I am aware	rmation submitted. E ring the information, that there are signif	Based on my inquiry of the information	
Inspector Signature:	En Carlon			Reviewed By:	But Sel	