E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept. Ma	•			Engineering Ans	wers
	E&	A- P2011.160.006			
Inspector: Ethan Anderson					Stage
	-	Ridgeview Apartm CSW-20210601			1
Project Name:		9/2/2023			
For Week Ending:		68048			
Project Location:	211 S 23	RD ST - Plattsmouth, NE	(Cass County)		Storm Event Times
Grading:	75%	[			
	5%				
Sanitary Sewer: Storm Sewer:	5%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	30%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	0/20/0002	Supres 04/04	40.45 AM	
Wednesday: Thursday:	0.00"	8/30/2023	Sunny 81/61	12:45 AM	-
Friday:	0.00"				
Saturday:	0.00"				
-		l.			
Complaints:	None				
E&A hired as SWPPP inspector (11	the site have had a temporary or permanent cessat 1/21/22). Entire site active for grading as of	(11/23/2022). Removal of	concrete at entrance (11/	30/22). Retaining wall	
	related to footings active during inspection ( 3). Grading and soil placement at the entran		nd concrete work related	to apartment construc	uon acuve (2/01/23).
Which portion(s) (i.e. drainage basins) of	the site do not have grading, earthwork, or ground	disturbance scheduled in the r	next 14 days?		
Ground disturbance and earthwork	1/21/22). Entire site active for grading as of related to footings active during inspection ( a). Grading and soil placement at the entran	1/11/23). Some grading a			
What temporary or permanent stabilization Existing vegetation (11/23/2022).	n measures listed in this section are being implement	ented?			
Checklist Questions:					
Are receiving waters adjacent to	the project free of any significant signs o	of erosion or sediment th	nat would be associated	with the construction	on activity?
Create Corrective Action? No, See BMP Section					
prevent erosion.	ed or otherwise stabilized as required? L	ist inactive portions of th	ne project and if stabiliz	ation measure are a	dequate or needed to
No Create Corrective Action?					
No, See BMP and Findings Section					
Are waste materiale (concrete or	onstruction material, hazardous, etc.) bei	ng managad property?			
No		ing managed property?			
Create Corrective Action?					
No, See BMP Section					
No	adjacent streets being maintained adequa	ately?			
Create Corrective Action? No, See BMP Section					
Yes	truction activity adequately controlled on	the site?			
Create Corrective Action?					

## N/A

Comments: Comments:

Site was active during the inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance in BMP Section. 2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection. Calabretto Building Group was reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/23

Unique Name CE 01	Type Construction Entrance	Location North East Corner	Projected Install Date 12/1/2022	Status Active	Maintenar Yes		
Current Condition:	Fair Condition - 40% effective - Calabret						
	Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection. Trackout was observed during the inspection on 4/21/23. Calabretto Building Group placed more soil around the entrance prior to inspection on 6/14/23.						
	Rock should be installed on the construction entrance.						
	Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection. Calabretto Building Group was remin						
	on 5/24/23, 6/21/23, 7/20/23, 8/16/23						
FT X	Fuel Tank	On site	4/26/2023	Active	No		
Current Condition:	Good Condition - Calabretto Building Gro	oup installed a portable fuel	tank prior to the inspectior	n on 4/26/23. Calabr	retto Building Gro		
	removed the fuel tank prior to inspection	on 5/31/23. Calabretto Build	ling Group installed a dou	ble walled portable f	fuel tank prior to		
	inspection on 6/21/23.						
MS 01	Material Storage	Near CE 01	11/23/2022	Active	No		
Current Condition:	Active - Calabretto Building Group is stor						
	entrance (2/8/23). Lumber and other cor	nstruction materials moved o	n site in designated stora	ge areas (3/22/23). /	Additional lumber		
	storage on site (3/29/23).	1	1				
PB 01	Portable Bathroom	Near CE 01	11/30/2022	Active	No		
Current Condition:	Good Condition - Calabretto Building Gro			22 inspection. Calab	oretto Building Gro		
	moved and secured the portable toilet pr						
RN 1 - RN 6	Inlet Protection	RN 1 - RN 6	4/26/2023	Pending	No		
Current Condition:	Pending - The inlet filter will be installed	once the inlet is installed an	d the inlet is at or below g	rade.			
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	No		
Current Condition:	Pending - The inlet filter will be installed	once the inlet is installed an	d the inlet is at or below g	rade.			
RN 13 - RN 18	Inlet Protection	Near RN 6	4/26/2023	Pending	No		
Current Condition:	Pending - The inlet filter will be installed				INO		
	*		· · · · · · · · · · · · · · · · · · ·				
RM 1	Erosion Control Mat	RM 1	4/26/2023	Pending	Yes		
Current Condition:	Pending -						
	Erosion Matting should be installed.						
	Calabretto Building Group was informed	to complete by 5/3/23. Not a	one as of last inspection.	Calabretto Building	Group was remin		
	on 5/24/23, 6/21/23, 7/20/23, 8/16/23						
RM 2	Erosion Control Mat	RM 2	4/26/2023	Pending	Yes		
RM 2 Current Condition:		RM 2		Pending			
=	Erosion Control Mat Pending -	RM 2		Pending			
=	Erosion Control Mat	RM 2		Pending			
=	Erosion Control Mat Pending - Erosion Matting should be installed.	·	4/26/2023		Yes		
=	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed	·	4/26/2023		Yes		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not o	4/26/2023	Calabretto Building	Yes Group was remin		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat	·	4/26/2023		Yes		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not o	4/26/2023	Calabretto Building	Yes Group was remir		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending -	to complete by 5/3/23. Not o	4/26/2023	Calabretto Building	Yes Group was remir		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat	to complete by 5/3/23. Not o	4/26/2023	Calabretto Building	Yes Group was remin		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed.	to complete by 5/3/23. Not o	4/26/2023 done as of last inspection.	Calabretto Building	Yes Group was remin		
Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed	to complete by 5/3/23. Not o	4/26/2023 done as of last inspection.	Calabretto Building	Yes Group was remin		
Current Condition: RM 3 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not o	4/26/2023 done as of last inspection. 4/26/2023	Calabretto Building Pending Calabretto Building	Yes Group was remin Yes Group was remin		
Current Condition: RM 3 Current Condition: ST 01	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active	Yes Group was remin		
Current Condition: RM 3 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active	Yes Group was remin Yes Group was remin		
Current Condition: RM 3 Current Condition: ST 01	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Group	to complete by 5/3/23. Not o RM 3 to complete by 5/3/23. Not o South end of site up installed silt fence prior to	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active	Yes Group was remin Yes Group was remin		
Current Condition: RM 3 Current Condition: ST 01	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap	to complete by 5/3/23. Not o RM 3 to complete by 5/3/23. Not o South end of site up installed silt fence prior to	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active	Yes Group was remin Yes Group was remin		
Current Condition: RM 3 Current Condition: ST 01	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should	to complete by 5/3/23. Not o RM 3 to complete by 5/3/23. Not o South end of site up installed silt fence prior to be stabilized and repaired.	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Active 2.	Yes Group was remin Yes Group was remin Yes		
Current Condition: RM 3 Current Condition: ST 01	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed	to complete by 5/3/23. Not o RM 3 to complete by 5/3/23. Not o South end of site up installed silt fence prior to be stabilized and repaired.	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Active 2.	Yes Group was remin Yes Group was remin Yes		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2         done as of last inspectior	Calabretto Building Pending Calabretto Building Active 2. Calabretto Building	Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         done as of last inspection         4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active Active	Yes Group was remin Yes Group was remin Yes		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         done as of last inspection         4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active Active	Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         done as of last inspection         4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active Active	Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         done as of last inspection         4/19/2023	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active Active	Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized.	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active 2.	Yes Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized.	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Active 2.	Yes Group was remin Yes Group was remin Yes g Group was rem Yes		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not be stabilized. to complete by 4/26/23. Not	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         the inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         done as of last inspection	Calabretto Building Pending Calabretto Building Calabretto Building Active 2. Calabretto Building Calabretto Building	Group was remin Yes Group was remin Yes g Group was rem Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized. to complete by 4/26/23. Not	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         done as of last inspectior         4/19/2023         the inspection on 11/23/2         done as of last inspectior         9/9/2022	Calabretto Building Pending Calabretto Building Calabretto Building Active Calabretto Building Active Calabretto Building Active Active	Group was remin Yes Group was remin Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized. to complete by 4/26/23. Not	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         done as of last inspectior         4/19/2023         the inspection on 11/23/2         done as of last inspectior         9/9/2022	Calabretto Building Pending Calabretto Building Calabretto Building Active Calabretto Building Active Calabretto Building Active Active	Group was remir Yes Group was remir Yes g Group was rem Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Frap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Fence Fair Condition - Calabretto Building Grou	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized. to complete by 4/26/23. Not East perimeter up installed silt fence prior to pinstalled silt fence prior to	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2         done as of last inspectior         4/19/2023         the inspection on 11/23/2         done as of last inspectior         9/9/2022         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Calabretto Building Active Calabretto Building Active Calabretto Building Active Active	Group was remin Yes Group was remin Yes g Group was rem Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized. to complete by 4/26/23. Not East perimeter up installed silt fence prior to pinstalled silt fence prior to	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         the inspection on 11/23/2         done as of last inspectior         4/19/2023         the inspection on 11/23/2         done as of last inspectior         9/9/2022         the inspection on 11/23/2	Calabretto Building Pending Calabretto Building Calabretto Building Active Calabretto Building Active Calabretto Building Active Active	Group was remir Yes Group was remir Yes g Group was rem Yes g Group was rem		
Current Condition: RM 3 Current Condition: ST 01 Current Condition: ST 02 Current Condition:	Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Trap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Frap Fair Condition - Calabretto Building Grou The area around and in the basin should Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23 Silt Fence Fair Condition - Calabretto Building Grou	to complete by 5/3/23. Not of RM 3 to complete by 5/3/23. Not of South end of site up installed silt fence prior to be stabilized and repaired. to complete by 4/26/23. Not East perimeter up installed silt fence prior to be stabilized. to complete by 4/26/23. Not East perimeter up installed silt fence prior to set perimeter up installed silt fence prior to complete stabilized.	4/26/2023         done as of last inspection.         4/26/2023         done as of last inspection.         4/19/2023         done as of last inspection on 11/23/2         done as of last inspection         4/19/2023         the inspection on 11/23/2         done as of last inspectior         9/9/2022         the inspection on 11/23/2         done as of last inspectior         9/9/2022         the inspection on 11/23/2         primeter.	Calabretto Building Pending Calabretto Building Calabretto Building Active Calabretto Building Active Calabretto Building Active Active Calabretto Building Active Calabretto Building	Yes         Group was remin         Yes         Group was remin         Yes         g Group was remin		

	Silt Fence	Eastern Slope	12/1/2022	Pending	Yes		
Current Condition:	Pending -						
	Silt fence should be installed.						
	Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/2		t done as of last inspectio	n. Calabretto Building	g Group was remir		
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	No		
Current Condition:	Good Condition- No major signs of track off. Trackout was observed on the street during the inspection on 4/19/23. Calabretto Building Group cleaned the entrance street prior to the inspection on 6/14/23.						
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition- E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection on 12/7/22. E&A inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection.						
WO 01	Concrete Washout Pending -	On site	12/1/2022	Pending	Yes		
	1.) Calabretto Building Group was inform Calabretto Building Group was reminded 2.) Calabretto Building Group was inform Calabretto Building Group was reminded	l on 2/23/23, 4/21/23, 5/24/23 ned to complete by 1/25/23 or l on 2/23/23, 4/21/23, 5/24/23	8, 6/21/23, 7/20/23, 8/16/2 r as weather conditions a 8, 6/21/23, 7/20/23, 8/16/2	3 low. Not done as of la 3	ast inspection.		
WS 01	Waste Storage Area	On site	12/7/2022	Active	No		
Current Condition:	Active - Calabretto Building Group is storentrance (2/8/23).	ring building materials on site	e. A waste storage contai	ner was installed near	r the construction		
WT 01	Wattle	North East Corner	11/30/2022	Pending	Yes		
WT 01 Current Condition:	Pending - Wattles should be installed in front of dra Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/2	ainage area. to complete by 11/30/22. No 20/23, 8/16/23	t done as of last inspectic	n. Calabretto Building	g Group was remir		
	Pending - Wattles should be installed in front of dra Calabretto Building Group was informed	to complete by 11/30/22. No 20/23, 8/16/23 locument and all attachments ad personnel properly gathere system or those persons direc e and belief, true, accurate, a	t done as of last inspection were prepared under my ed and evaluated the info ttly responsible for gathe ind complete. I am aware	n. Calabretto Building direction or supervis mation submitted. Ba ing the information, th that there are signifo	g Group was remin ion in accordance ased on my inquiry he information		