E & A Consulting Group, Inc.
10909 Mill Valley Road, Suite 100
Omaha, NE 68154
tel 402.895.4700
fax 402.895.3599
www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E	&A- P2011.160.006				
Inspector: Ethan Anderson						Stage	
Project Name:	Ridgeview Apartments CSW-202106011						
For Week Ending:		68048					
Project Location:		211 S 23RD ST - Plattsmouth, NE (Cass County)					
Grading:		75%					
Sanitary Sewer: Storm Sewer:		5% 5%					
Paving:		0%					
Seeding: Utilities:		0% 0%					
Overall Development:		30%					
RAIN FALL AMOUNTS	Amount in tenths		Date inspected	Weather Conditions	Time		
Over days	0.00#					Week	
Sunday: Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"		10/11/2023	Sunny 77/52	12:45 PM		
Thursday:	0.18"			•		7:45 PM - 11:30 PM	
Friday:	0.02"						
Saturday:	0.00"						
Complaints:	None						
Construction Sequencing:							

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See BMP and Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No, See BMP Section

is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

Comments:

Site was active during the inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1.) Some maintenance in BMP Section.
- 2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection. Calabretto Building Group was reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23

CE 01	Туре	Location	Projected Install Date	Status	Maintena			
	Construction Entrance	North East Corner	12/1/2022	Active	Yes			
Current Condition:	Fair Condition - 40% effective - Calabretto Building Group installed a construction entrance prior to the 1/18/23 inspection. Calabrett Building Group added rock and extended the construction entrance prior to the 2/1/23 inspection. Trackout was observed during the							
	inspection on 4/21/23. Calabretto Building Group placed more soil around the entrance prior to inspection on 6/14/23.							
	mapes and on the state of the s							
	Rock should be installed on the construction entrance.							
	Calabanta Duildian Casus was informed to associate by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Calabanta Duildian Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was associated by AIOCIO2 Not done as of last increasing Casus was as of last increasing							
	Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection. Calabretto Building Group was rer on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23							
	0.1. 6/2 1/26, 6/2 1/26, 1/26/26, 6/16/26, 6							
FT X	Fuel Tank	On site	4/26/2023	Active	No			
Current Condition:	Good Condition - Calabretto Building G							
	removed the fuel tank prior to inspection on 5/31/23. Calabretto Building Group installed a double walled portable fuel tank prior to t							
FT 1	inspection on 6/21/23. Fuel Tank On site 9/27/2023 Active No							
Current Condition:	Good Condition - Calabretto Building G	-						
MS 01	Material Storage	Near CE 01	11/23/2022	Active	No			
Current Condition:	Active - Calabretto Building Group is sto							
	entrance (2/8/23). Lumber and other construction materials moved on site in designated storage areas (3/22/23). Additional lumber							
DD 04	storage on site (3/29/23).							
PB 01 Current Condition:	Portable Bathroom Good Condition - Calabretto Building G	Near CE 01	11/30/2022	Active	No Protto Building C			
Current Condition:	moved and secured the portable toilet i			zz irispection. Calat	retto building G			
RN 1 - RN 6	Inlet Protection	RN 1 - RN 6	4/26/2023	Pending	No			
Current Condition:	Pending - The inlet filter will be installed	once the inlet is installed and	the inlet is at or below gr	ade.	•			
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	No			
Current Condition:	Pending - The inlet filter will be installed	once the inlet is installed and	the inlet is at or below gr	ade.	•			
RN 13 - RN 18	Inlet Protection	Near RN 6	4/26/2023	Pending	No			
Current Condition:	Pending - The inlet filter will be installed				.,,,			
RM 1	Erosion Control Mat	RM 1	4/26/2023	Pending	Yes			
	Erosion Matting should be installed.							
	Calabretto Building Group was informed		done as of last inspection.	. Calabretto Building	Group was rem			
DM 2	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	9/14/23			<u> </u>			
RM 2	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat		done as of last inspection.	. Calabretto Building	Group was rem			
RM 2 Current Condition:	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	9/14/23			<u> </u>			
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat	9/14/23			<u> </u>			
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed.	0/14/23 RM 2	4/26/2023	Pending	Yes			
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed	9/14/23 RM 2	4/26/2023	Pending	Yes			
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed.	9/14/23 RM 2	4/26/2023	Pending	Yes			
Current Condition:	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	0/14/23 RM 2 d to complete by 5/3/23. Not 0	4/26/2023 done as of last inspection.	Pending Calabretto Building	Yes Group was rem			
Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending -	0/14/23 RM 2 d to complete by 5/3/23. Not 0	4/26/2023 done as of last inspection.	Pending Calabretto Building	Yes Group was rem			
Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Erosion Control Mat	0/14/23 RM 2 d to complete by 5/3/23. Not 0	4/26/2023 done as of last inspection.	Pending Calabretto Building	Yes Group was rem			
Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, § Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, § Erosion Control Mat Pending - Erosion Matting should be installed.	D/14/23 RM 2 d to complete by 5/3/23. Not 6 D/14/23 RM 3	done as of last inspection. 4/26/2023	Pending Calabretto Building Pending	Yes Group was rem			
Current Condition: RM 3 Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	RM 2 RM 2 RM 2	done as of last inspection. 4/26/2023 done as of last inspection.	Pending Calabretto Building Pending Calabretto Building	Group was rem Yes Group was rem			
RM 3 Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap	0/14/23 RM 2 d to complete by 5/3/23. Not 0/14/23 RM 3 d to complete by 5/3/23. Not 0/14/23 South end of site	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active	Yes Group was rem			
Current Condition: RM 3 Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	0/14/23 RM 2 d to complete by 5/3/23. Not 0/14/23 RM 3 d to complete by 5/3/23. Not 0/14/23 South end of site	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active	Group was rem Yes Group was rem			
RM 3 Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site out installed silt fence prior to	4/26/2023 done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active	Group was rem Yes Group was rem			
RM 3 Current Condition:	Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap Fair Condition - Calabretto Building Group was informe on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site rup installed silt fence prior to lid be stabilized and repaired.	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2	Pending Calabretto Building Pending Calabretto Building Active	Group was rem Yes Group was rem Yes			
RM 3 Current Condition:	Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8/21/23,	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site rup installed silt fence prior to lid be stabilized and repaired. In the complete by 4/26/23. Not of the complete by 4/26/23.	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2	Pending Calabretto Building Pending Calabretto Building Active	Group was rem Yes Group was rem Yes			
RM 3 Current Condition: ST 01 Current Condition:	Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site pup installed silt fence prior to lid be stabilized and repaired. d to complete by 4/26/23. Not of 3/14/23	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2	Pending Calabretto Building Pending Calabretto Building Active 2.	Group was rem Yes Group was rem Yes			
RM 3 Current Condition: ST 01 Current Condition:	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site purp installed silt fence prior to 1/14/23 d to complete by 4/26/23. Not 0/14/23 East perimeter	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active Calabretto Building Active	Group was rem Yes Group was rem Yes			
RM 3 Current Condition: ST 01 Current Condition:	Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 8/21/23, 7/20/23, 8/16/23, 8 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site purp installed silt fence prior to 1/14/23 d to complete by 4/26/23. Not 0/14/23 East perimeter	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active Calabretto Building Active	Group was rem Yes Group was rem Yes Group was rem			
RM 3 Current Condition: ST 01 Current Condition:	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site rup installed silt fence prior to 1/14/23 d to complete by 4/26/23. Not of 3/14/23 East perimeter rup installed silt fence prior to 1/14/23	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2 done as of last inspection. 4/19/2023	Pending Calabretto Building Pending Calabretto Building Active Calabretto Building Active	Group was rem Yes Group was rem Yes Group was rem			
RM 3 Current Condition: ST 01 Current Condition:	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Erosion Control Mat Pending - Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	RM 2 d to complete by 5/3/23. Not of 3/14/23 RM 3 d to complete by 5/3/23. Not of 3/14/23 South end of site pup installed silt fence prior to d be stabilized and repaired. d to complete by 4/26/23. Not 3/14/23 East perimeter pup installed silt fence prior to d be stabilized.	done as of last inspection. 4/26/2023 done as of last inspection. 4/19/2023 the inspection on 11/23/2 done as of last inspection 4/19/2023 the inspection on 11/23/2	Pending Calabretto Building Pending Calabretto Building Active Calabretto Building Active Active	Group was rem Yes Group was rem Yes Group was rem Yes			

Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22.						
	The silt fence needs to be repaired and ex	tended along the eastern p	perimeter.				
	Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23						
SF 02	Silt Fence	Eastern Slope	12/1/2022	Pending	Yes		
Current Condition:	Pending - Silt fence should be installed.						
	Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23						
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	No		
Current Condition:	Good Condition- No major signs of track off. Trackout was observed on the street during the inspection on 4/19/23. Calabretto Building Group cleaned the entrance street prior to the inspection on 6/14/23.						
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition- E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection on 12/7/22. E&A inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection.						
WO 01	Concrete Washout	On site	12/1/2022	Pending	Yes		
	1.) Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23 2.) Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23						
WS 01	Waste Storage Area	On site	12/7/2022	Active	No		
Current Condition:	Active - Calabretto Building Group is storing building materials on site. A waste storage container was installed near the construction entrance (2/8/23).						
WT 01	Wattle	North East Corner	11/30/2022	Pending	Yes		
Current Condition:	Pending - Wattles should be installed in front of drainage area. Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23						
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordation with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on ninquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
pector Signature:	En Carlon			Reviewed By:	to See		