E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dep	n. Manager				Linginicering Al	
		E	&A- P2011.160.006			
Inspector: Jason Wong						Stage
Project Name:		Ridgeview Apartments				
For Week Ending:						
Project Location:		211 S 23RD ST - Plattsmouth, NE (Cass County)				
						_
Grading:		75%				
Sanitary Sewer:		100%				
Storm Sewer:		80%	·			
Paving:		45%				
Seeding:		40%				
Utilities:		30%				
Overall Development:		45%				
RAIN FALL AMOUNTS	Amount in tenths		Date inspected	Weather Conditions	Time	Storm Event Duration
						Week
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.00"		10/17/2024	Sunny 66	12:10 PM	
Friday:	0.00"					
Saturday:	0.00"					
Complaints:	None					

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins (11/1/23). Grading in the center of the site (6/24/24). Concrete work related to apartments at the south end of the lot (9/25/24)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins (11/1/23). Grading in the center of the site (6/24/24). Concrete work related to apartments at the south end of the lot (9/25/24).

nt stabilization measures listed in this section are being impl

Existing vegetation (11/23/2022). Sod installation around the northeastern building and west side of adjacent basin (6/5/24). Sod installation around southwestern building (9/19/24).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

reate Corrective Action?

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed o prevent erosion.

reate Corrective Action?
o, See BMP and Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

lo, See BMP Section

re construction entrances and adjacent streets being maintained adequately?

reate Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

<u>.</u>
Yes
Create Corrective Action?
N/A
Comments:
Comments:
1.) Site was active for building construction during the most recent inspection.
Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):

 Findings / Corrective Actions (Date):

 1.) Some maintenance in BMP Section.

 2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection.

 Calabretto Building Group was reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23, 10/19/23, 11/2/23, 12/7/23, 1/31/24, 3/8/24, 4/4/24, 5/16/24, 6/20/24, 7/26/24, 8/29/24. 9/26/24

Unique Name	Туре	Location	Projected Install Date	Status	Maintena			
CE 01	Construction Entrance	North East Corner	ojootou motum zuto	Removed				
Current Condition:	Removed - Calabretto Building Grou	p paved construction entrance	prior to the inspection on	4/3/24.				
EM 1	Erosion Control Mat	EM 1	11/2/2023	Pending	Yes			
Current Condition:	Pending -							
	Erosion Matting should be installed when work is complete in the area. Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was rem							
EM 2	on 12/7/23 1/31/24 3/8/24 4/4/24 5		0/24 9/26/24 11/2/2023	Dan din a	Vaa			
Current Condition:	Erosion Control Mat	EM 2	11/2/2023	Pending	Yes			
Current Condition.	Pending - Erosion Matting should be installed when work is complete in the area. Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was rem							
EM 2	on 12/7/23 1/31/24 3/8/24 4/4/24 5			Daniella in	V			
EM 3 Current Condition:	Erosion Control Mat Pending -	EM 3	11/2/2023	Pending	Yes			
EM 4		Erosion Matting should be installed when work is complete in the area. Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was remon 12/7/23_1/31/24_3/8/24_4/4/24_5/16/24_6/20/24_7/26/24_8/29/24_9/26/26/26/26/26/26/26/26/26/26/26/26/26/						
Current Condition:	Pending -	EM 4	11/2/2023	Pending	Yes			
EM 5 Current Condition:	on 12/7/23 1/31/24 3/8/24 4/4/24 5 Erosion Control Mat Pending -	5/16/24 6/20/24 7/26/24 8/29 EM 5	0/24 9/26/24 11/2/2023	Pending	Yes			
	Erosion Matting should be installed when work is complete in the area. Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was remon 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/16/24. 6/20/24. 7/26/24. 8/29/24. 9/26/24							
				n. Calabretto Buildin	g Group was re			
EM 6				n. Calabretto Buildin Pending	g Group was re			
EM 6 Current Condition:	on 12/7/23, 1/31/24, 3/8/24, 4/4/24, 5 Erosion Control Mat Pending -	5/16/24, 6/20/24, 7/26/24, 8/29 EM 6	0/24 <u>9/26/24</u> 11/2/2023		• •			
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24, 5 Erosion Control Mat Pending - Erosion Matting should be installed w	5/16/24 6/20/24 7/26/24 8/29 EM 6 when work is complete in the a	0/24, 9/26/24 11/2/2023 area. lot done as of last inspectio	Pending	Yes			
	on 12/7/23 1/31/24 3/8/24 4/4/24 5 Erosion Control Mat Pending - Erosion Matting should be installed v	5/16/24 6/20/24 7/26/24 8/29 EM 6 when work is complete in the a	0/24, 9/26/24 11/2/2023 area. lot done as of last inspectio	Pending	Yes			
Current Condition:	on 12/7/23, 1/31/24, 3/8/24, 4/4/24, 5 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site	17/24 9/26/24 11/2/2023 Irea. Iot done as of last inspection	Pending n. Calabretto Buildin Removed	Yes			
Current Condition: FT X Current Condition: FT 1	on 12/7/23 1/31/24 3/8/24 4/4/24 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform on 12/7/23 1/31/24 3/8/24 4/4/24 E Fuel Tank	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site	17/24 9/26/24 11/2/2023 Irea. Iot done as of last inspection	Pending n. Calabretto Buildin Removed	Yes			
Current Condition: FT X Current Condition: FT 1 Current Condition:	on 12/7/23 1/31/24 3/8/24 4/4/24 5 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform on 12/7/23 1/31/24 3/8/24 4/4/24 5 Fuel Tank Removed - Calabretto Building Grou	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site On site On site	17/24, 9/26/24 11/2/2023 18 11/2/2023 18 11/2/2023 18 11/2/2023 18 11/2/2024	n. Calabretto Buildin Removed 3. Active	g Group was re			
FT X Current Condition: FT 1 Current Condition: FT 1 Current Condition: IF 1-3	on 12/7/23 1/31/24 3/8/24 4/4/24 5 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform on 12/7/23 1/31/24 3/8/24 4/4/24 5 Fuel Tank Removed - Calabretto Building Group Fuel Tank	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site On site On site	orea. lot done as of last inspection or 24 9/26/24 to the inspection on 11/22/2 3/7/2024 rtable fuel tanks prior to the	n. Calabretto Buildin Removed 3. Active	g Group was re			
Current Condition: FT X Current Condition: FT 1 Current Condition:	on 12/7/23 1/31/24 3/8/24 4/4/24 5 Erosion Control Mat Pending - Erosion Matting should be installed w Calabretto Building Group was inform on 12/7/23 1/34/24 3/8/24 4/4/24 5 Fuel Tank Removed - Calabretto Building Grou Fuel Tank Good Condition - Calabretto Building	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 Med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site On site On site Group re-installed the two po S 22nd St and 1st Ave In the street inlets.	orea. lot done as of last inspection on 11/22/2 10 the inspection on 11/22/2 10 the inspection on 11/22/2 10 the inspection on 11/22/2 10 11/2/2024 11/2/2024 11/2/2024 11/2/2024 11/2/2023	Pending n. Calabretto Buildin Removed 3. Active inspection on 3/6/2. Pending on. Calabretto Buildin	g Group was re			
FT X Current Condition: FT 1 Current Condition: FT 1 Current Condition: IF 1-3	on 12/7/23 1/31/24 3/8/24 4/4/24 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform on 12/7/23 1/31/24 3/8/24 4/4/24 E Fuel Tank Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Inlet Protection Pending - Inlet protection should be installed or Calabretto Building Group was inform	when work is complete in the a med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 Med to complete by 11/8/23. N 5/16/24 6/20/24 7/26/24 8/29 On site On site On site Group re-installed the two po S 22nd St and 1st Ave In the street inlets.	orea. lot done as of last inspection on 11/22/2 10 the inspection on 11/22/2 10 the inspection on 11/22/2 10 the inspection on 11/22/2 10 11/2/2024 11/2/2024 11/2/2024 11/2/2024 11/2/2023	Pending n. Calabretto Buildin Removed 3. Active inspection on 3/6/2. Pending on. Calabretto Buildin	g Group was re			
FT X Current Condition: FT 1 Current Condition: IF 1-3 Current Condition:	on 12/7/23 1/31/24 3/8/24 4/4/24 Erosion Control Mat Pending - Erosion Matting should be installed v Calabretto Building Group was inform on 12/7/23 1/31/24 3/8/24 4/4/24 F Fuel Tank Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Inlet Protection Pending - Inlet protection should be installed or Calabretto Building Group was inform terminded on 11/2/23 1/31/2	when work is complete in the a med to complete by 11/8/23. Note 1	10/24, 9/26/24 11/2/2023 10t done as of last inspection 2/24, 9/26/24 10t the inspection on 11/22/2 3/7/2024 10/18/2023 Not done as of last inspection 2/2/24, 7/26/24, 8/29/24, 9/2 11/23/2022 erials on site. A waste stora	Pending n. Calabretto Buildin Removed 3. Active inspection on 3/6/2 Pending on. Calabretto Buildin 6/24 Active ge container was ins	g Group was re No g Group was re No group was ng Group was No stalled near the			

Current Condition:	Fair Condition - Calabretto Building Grou					
	moved and secured the portable toilet p					
	to the 10/03/2024 inspection. As of 10/10/24 all portable toilets on site will be recorded in this BMP. Calabretto Building Group moved the portable toilet in the center of lot across the street prior 10/10/24 inspection but did not resecure it. Calabretto Building Group installed and secured a portable toilet on the south side of the site prior to 10/10/24 inspection. During the 10/17/24 inspection, E&A inspector					
	discovered that the portable toilet in	the center of the lot was co	overing RN 7.			
	1.) The portable toilet in the center of t 2.) The portable toilet in the center of			nlet.		
	1.) Calabretto Building Group was told to	complete by 10/17/24 insp	ection. Not done as of la	st inspection.		
RN 1 - RN 6	Inlet Protection	RN 1 - RN 6	4/26/2023	Pending	Yes	
Current Condition:	Pending - The inlet filter will be installed once the inlet is installed and the inlet is at or below grade. Calabretto Building Group installed inlets 4, 5, and 6 prior to the inspection on 10/18/23. Calabretto Building Group was in the process of installing the inlets during the inspection on 10/25/23.					
	Inlet protection should be installed. Calabretto Building Group was informed	I to complete by 10/25/23. N	ot done as of last inspecti	ion, Calabretto Buildi	ng Group was	
	reminded on 11/2/23 12/7/23 1/31/24	<u>3/8/24 4/4/24 5/16/24 6/20</u>			ig Group was	
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	Yes	
Current Condition:	Pending - The inlet filter will be installed process of installing the inlets during the Inlet protection should be installed.	inspection on 10/25/23.				
	Calabretto Building Group was informed on 12/7/23 1/31/24 3/8/24 4/4/24 5/16			n. Calabretto Building	g Group was reminded	
RN 13 - RN 18	Inlet Protection	Near RN 6	4/26/2023	Pending	No	
Current Condition:	Pending - The inlet filter will be installed process of installing the inlets during the to the inspection on 9/19/24, 9/26/24					
RM 1	Erosion Control Mat	RM 1	4/26/2023	Pending	Yes	
Current Condition:	Pending -			,		
DMO	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24	/14/23, 10/19/23, 11/2/23, 12	2/7/23, 1/31/24, 3/8/24, 4/	/4/24, 5/16/24, 6/20/2	4, 7/26/24, 8/29/24,	
RM 2 Current Condition:	Erosion Control Mat Pending -	RM 2	4/26/2023	Pending	Yes	
RM 3	Erosion Matting should be installed. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24 Erosion Control Mat			•		
Current Condition:	Removed - Erosion matting is no longer		VPPP as of the inspection			
ST 01	Silt Trap	South end of site	4/19/2023	Active	Yes	
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. Calabretto Building Group was in the process of installing the PCSMP riser and outfall during the inspection on 11/1/23. The area around and in the basin should be repaired and stabilized.					
	Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24	/14/23, 10/19/23, 11/2/23, 12	2/7/23, 1/31/24, 3/8/24, 4/	/4/24, 5/16/24, 6/20/2		
ST 02	Silt Trap	East perimeter	4/19/2023	Active		
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22. Calabretto Building Group was in the process of installing the PCSMP riser and outfall during the inspection on 11/1/23.					
		The second secon			Yes g Group was in the	
		nd outfall during the inspection p should be stabilized.	on on 11/1/23.	22. Calabretto Buildin	g Group was in the	
	process of installing the PCSMP riser are. The area around and in the basin/silt tra	nd outfall during the inspection p should be stabilized. It to complete by 4/26/23. No	on on 11/1/23. t done as of last inspectio	22. Calabretto Buildin on. Calabretto Buildin	g Group was in the	
SF 01	process of installing the PCSMP riser are The area around and in the basin/silt tra Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9	nd outfall during the inspection p should be stabilized. It to complete by 4/26/23. No	on on 11/1/23. t done as of last inspectio	22. Calabretto Buildin on. Calabretto Buildin	g Group was in the	
SF 01 Current Condition:	process of installing the PCSMP riser are The area around and in the basin/silt tra Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 9/26/24 Silt Fence Fair Condition - Calabretto Building Group	d outfall during the inspection p should be stabilized. I to complete by 4/26/23. No /14/23, 10/19/23, 11/2/23, 12 East perimeter up installed silt fence prior to	t done as of last inspectio 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/2	on. Calabretto Buildin 14/24, 5/16/24, 6/20/2	g Group was in the g Group was reminded 4, 7/26/24, 8/29/24,	
	process of installing the PCSMP riser are The area around and in the basin/silt tra Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24 Silt Fence Fair Condition - Calabretto Building Group The silt fence needs to be repaired, exte	nd outfall during the inspection p should be stabilized. It to complete by 4/26/23. No /14/23, 10/19/23, 11/2/23, 11 East perimeter up installed silt fence prior to ended and reinstalled along to the complete by 11/30/22. No	t done as of last inspection 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/24 the eastern perimeter. ot done as of last inspection	on. Calabretto Building Active Active Active Active Action. Calabretto Building	g Group was in the g Group was reminded 4, 7/26/24, 8/29/24, Yes	
	process of installing the PCSMP riser are The area around and in the basin/silt tra Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24 Silt Fence Fair Condition - Calabretto Building Group The silt fence needs to be repaired, external	nd outfall during the inspection p should be stabilized. It to complete by 4/26/23. No /14/23, 10/19/23, 11/2/23, 11 East perimeter up installed silt fence prior to ended and reinstalled along to the complete by 11/30/22. No	t done as of last inspection 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/24 the eastern perimeter. ot done as of last inspection	on. Calabretto Building Active Active Active Active Action. Calabretto Building	g Group was in the g Group was reminded 4, 7/26/24, 8/29/24, Yes	

Current Condition:	Pending -					
	Silt fence should be installed.					
	Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection. Calabretto Building Group was					
	reminded on 2/23/23, 4/21/23, 5/24/23,	, 6/21/23, 7/20/23, 8/16/23, 9/14	/23, 10/19/23, 11/2/23,	12/7/23, 1/31/24, 3/	8/24, 4/4/24, 5/16/24,	
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	Yes	
Current Condition:	Fair Condition - Track out was observe street prior to the inspection on 6/14/23 Streets should be cleaned.					
	Calabretto Building Group was informed to complete by 4/4/24. Not done as of last inspection. Calabretto Building Group was reminded on 5/16/24, 6/20/24, 7/26/24, 8/29/24, 9/26/24					
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No	
Current Condition:		Good Condition - E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection on 12/7/22. E&A inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection. E&A inspector reinstalled the SWPPP				
WO 01	Concrete Washout	On site	12/1/2022	Pending	Yes	
	 A concrete washout should be installed to contain any washouts. Concrete waste should be removed from the site. Calabretto Building Group was informed to complete by 1/25/23 or as weather conditions allow. Not done as of last inspection. Calabretto Building Group was reminded on 2/23/23, 4/21/23, 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23, 10/19/23, 11/2/23, 1/31/24, 3/8/24, 4/4/24, 5/16/24, 6/20/24, 7/26/24, 8/29/24, 9/26/24 Calabretto Building Group was informed to complete by 10/17/24. Not done as of last inspection. 					
WS 01	Waste Storage Area	On site	12/7/2022	Active	No	
Current Condition:	Good Condition - Calabretto Building G construction entrance (2/8/23). Lumbe Waste Storage Container was moved	r and other construction materia	als moved on site in des	signated storage are		
WT 01	Wattle	North East Corner		Removed		
Current Condition:	Removed - Calabretto Building Group pon 11/2/23.	paved the area above the drains	age and connected it to	existing storm inlets	prior to the inspection	
Certification Statement	"I certify, under penalty of law, that this with a system designed to assure that of inquiry of the person or persons who m information submitted is, to the best of penalties for submitting false information	qualified personnel properly gath anage the system or those pers my knowledge and belief, true, a	nered and evaluated the sons directly responsible accurate, and complete	e information submit e for gathering the in . I am aware that the	ted. Based on my iformation, the ere are significant	
spector Signature:	Jann e. Wreg			Reviewed By:	But Sur	