E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

E&A- P2011.160.006						
Inspector: Jason Wong	Ridgeview Apartments CSW-202106011				Stage	
Project Name:					1	
For Week Ending:		11/9/2024				
Project Location:	211 S	211 S 23RD ST - Plattsmouth, NE (Cass County)				
Grading:	75					
Sanitary Sewer:	100					
Storm Sewer:	80	1%				
Paving:	45	5%				
Seeding:	40					
Utilities:	30	***				
Overall Development:	45	5%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
					Week	
Sunday:	0.08"					
Monday:	0.52"				[15:55 to 23:55]	
Tuesday:	0.45"				[00:00 to 8:55]	
Wednesday:	0.00"					
Thursday:	0.00"	11/7/2024	Sunny 55	2:15 PM		
Friday:	0.00"					
Saturday:	0.16"					
Complaints:	None					

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins (11/1/23). Grading in the center of the site (6/24/24). Concrete work related to apartments at the south end of the lot (9/25/24)

# Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins (11/1/23). Grading in the center of the site (6/24/24). Concrete work related to apartments at the south end of the lot (9/25/24).

### nt stabilization measures listed in this section are being impl

Existing vegetation (11/23/2022). Sod installation around the northeastern building and west side of adjacent basin (6/5/24). Sod installation around southwestern building (9/19/24).

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

reate Corrective Action?

lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed o prevent erosion.

reate Corrective Action?
o, See BMP and Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

lo, See BMP Section

re construction entrances and adjacent streets being maintained adequately?

reate Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Yes	
Create Corrective Action?	
N/A	
Comments:	

### Comments:

1.) Site was active for building construction during the most recent inspection.

- Findings / Corrective Actions (Date):

  Findings / Corrective Actions (Date):

  1.) Some maintenance in BMP Section.

  2.) Disturbed areas of site should be stabilized with seed and matting. Calabretto Building Group was informed to complete by 4/26/23. Not done as of last inspection.

  Calabretto Building Group was reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/14/23, 10/19/23, 11/2/23, 12/7/23, 1/31/24, 3/8/24, 4/4/24, 5/16/24, 6/20/24, 7/26/24, 8/29/24. 10/24/24.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenar	
ČE 01	Construction Entrance	North East Corner		Removed		
Current Condition:	Removed - Calabretto Building Group					
EM 1	Erosion Control Mat	EM 1	11/2/2023	Pending	Yes	
Current Condition:	Pending -					
	Erosion Matting should be installed who Calabretto Building Group was information	ed to complete by 11/8/23. No	ot done as of last inspection	n. Calabretto Building	g Group was rer	
EM 2	on 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat	16/24 6/20/24 7/26/24 8/29/ EM 2	/ <u>24_9/26/24_10/24/24</u> 11/2/2023	Pending	Yes	
Current Condition:	Pending -	EIVI Z	11/2/2023	rending	162	
	Erosion Matting should be installed who Calabretto Building Group was informed to the control of	ed to complete by 11/8/23. No	ot done as of last inspection	n. Calabretto Buildinç	g Group was ren	
EMO	on 12/7/23 1/31/24 3/8/24 4/4/24 5/			Dending	V	
EM 3 Current Condition:	Erosion Control Mat	EM 3	11/2/2023	Pending	Yes	
Current Contaition.	Pending -					
	Erosion Matting should be installed when work is complete in the area.  Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was remin on 12/7/23 1/31/24 3/8/24 4/4/24 5/16/24 6/20/24 7/26/24 8/29/24 9/26/24 10/24/24					
EM 4	Erosion Control Mat	EM 4	11/2/2023	Pending	Yes	
Current Condition:	Pending -		11,2,2020	· · · · · · · · · · · · · · · · · · ·		
	Erosion Matting should be installed wh	nen work is complete in the ar	ea.			
- FM -	Calabretto Building Group was inform	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/	ot done as of last inspection /24_9/26/24_10/24/24		•	
EM 5 Current Condition:	Calabretto Building Group was informed	ed to complete by 11/8/23. No	ot done as of last inspection	n. Calabretto Building Pending	g Group was ren Yes	
•	Calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending -  Erosion Matting should be installed who calabretto Building Group was information.	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5	ot done as of last inspection 124 9/26/24 10/24/24 11/2/2023 ea. ot done as of last inspection	Pending	Yes	
Current Condition:	Calabretto Building Group was information 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat Pending - Erosion Matting should be installed who calabretto Building Group was information 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/ EM 5 nen work is complete in the ar	ot done as of last inspection 124 9/26/24 10/24/24 11/2/2023 ea. ot done as of last inspection 124 9/26/24 10/24/24	Pending  n. Calabretto Building	Yes  g Group was ren	
Current Condition:	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed wh Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5	ot done as of last inspection 124 9/26/24 10/24/24 11/2/2023 ea. ot done as of last inspection	Pending	Yes	
Current Condition:  EM 6  Current Condition:	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5  Then work is complete in the arrest to complete by 11/8/23. No 16/24. 6/20/24 7/26/24 8/29/EM 6  Then work is complete in the arrest to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/24 8	ot done as of last inspection (24. 9/26/24. 10/24/24. 11/2/2023)  ea. ot done as of last inspection (24. 9/26/24. 10/24/24. 11/2/2023)  ea. ot done as of last inspection (24. 9/26/24. 10/24/24. 11/2/2023)	Pending  n. Calabretto Building  Pending  n. Calabretto Building	Yes g Group was ren Yes	
Current Condition:  EM 6  Current Condition:	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed with Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed with Calabretto Building Group was information on 12/7/23 1/31/24 3/8/24 4/4/24 5/ Calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Fuel Tank	nen work is complete by 11/8/23. Note to complete by 11/8/23. Note to complete by 11/8/23. Note to complete in the arrow of the complete by 11/8/23. Note to complete by 11/8/24. 8/29/EM 6	ea.  11/2/2023	Pending  n. Calabretto Building  Pending  n. Calabretto Building  Removed	Yes g Group was ren Yes	
EM 6 Current Condition:  FT X Current Condition:	Calabretto Building Group was informann 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat Pending -  Erosion Matting should be installed who calabretto Building Group was informann 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat Pending -  Erosion Matting should be installed who calabretto Building Group was informann 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Matting Should be installed who calabretto Building Group was informann 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erel Tank Removed - Calabretto Building Group	the documplete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/EM 5  The men work is complete in the argument work is complete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/EM 6  The men work is complete in the argument work is complete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24. 6/20/24. 7/26/24. 8/29/24. 6/20/24.	ea.  11/2/2023	Pending  n. Calabretto Building  Pending  n. Calabretto Building  Removed  3.	yes  g Group was ren  Yes	
EM 6 Current Condition:  FT X Current Condition:  FT 1	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Fuel Tank Removed - Calabretto Building Group Fuel Tank	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5  Then work is complete in the arrival for the first the arrival for the first the arrival for the first	ea.  of done as of last inspection  11/2/2023  ea.  of done as of last inspection  12/4 9/26/24 10/24/24  11/2/2023  ea.  of done as of last inspection  11/2/2023  ea.  of done as of last inspection  12/4 9/26/24 10/24/24  of the inspection on 11/22/2  3/7/2024	Pending  1. Calabretto Building  Pending  1. Calabretto Building  Removed  3.  Active	Yes  G Group was ren  Yes  G Group was ren  No	
EM 6 Current Condition:  FT X Current Condition: FT 1 Current Condition:	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Matting should be installed who calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Fuel Tank  Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Group	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5  Then work is complete in the arrival for the full to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 6  Then work is complete in the arrival for the full tank prior to On site  Group re-installed the two por	ea.  of done as of last inspection  11/2/2023  ea.  of done as of last inspection  12/4 9/26/24 10/24/24  11/2/2023  ea.  of done as of last inspection  11/2/2023  ea.  of done as of last inspection  12/4 9/26/24 10/24/24  of the inspection on 11/22/2  3/7/2024	Pending  Pending  Pending  Calabretto Building  Removed  Active inspection on 3/6/24	Yes  G Group was ren  Yes  G Group was ren  No	
EM 6 Current Condition:  FT X Current Condition:  FT 1	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat Pending - Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Fuel Tank Removed - Calabretto Building Group Fuel Tank	nen work is complete in the arrest to complete by 11/8/23. No. 16/24. 6/20/24. 7/26/24. 8/29/EM 5  nen work is complete in the arrest to complete by 11/8/23. No. 16/24. 6/20/24. 7/26/24. 8/29/EM 6  nen work is complete in the arrest to complete by 11/8/23. No. 16/24. 6/20/24. 7/26/24. 8/29/On site removed the fuel tank prior to On site Group re-installed the two por	t done as of last inspection (24_9/26/24_10)/24/24 (11/24/24_11/2/2023 )  ea. ot done as of last inspection (24_9/26/24_10)/24/24 (11/2/2023 )  ea. ot done as of last inspection (24_9/26/24_10)/24/24 (11/24/24_11/2/2023 )  to done as of last inspection (24_9/26/24_10)/24/24 (11/24/24_10) (11/24/	Pending  Dending  Pending  Pending  Calabretto Building  Removed  Active inspection on 3/6/24  Removed	yes  g Group was ren  Yes  g Group was ren  No	
EM 6 Current Condition:  FT X Current Condition:  FT 1 Current Condition:  IF 1-3 Current Condition:	Calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Fuel Tank  Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Group Inlet Protection  Removed- As of 11/11/24 inlet filters	ed to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 5  Then work is complete in the arrest to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 6  Then work is complete in the arrest to complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 6/20/24 7/26/24 8/29/EM 6  The complete by 11/8/23. No 16/24 6/20/24 7/26/24 8/29/EM 6/20/24 8/29/EM 6/20/	ea.  ot done as of last inspection (24 9/26/24 10/24/24 11/2/2023  ea.  ot done as of last inspection (24 9/26/24 10/24/24 11/2/2023  ea.  ot done as of last inspection (24 9/26/24 10/24/24  ot done as of last inspection (24 9/26/24 10/24/24  ot the inspection on 11/22/2 3/7/2024  table fuel tanks prior to the  ause surronding area is for	Pending  Dending  Pending  Pending  Removed  Active inspection on 3/6/24 Removed ully paved or sodde	yes  g Group was ren  Yes  g Group was ren  No  a.	
EM 6 Current Condition:  FT X Current Condition:  FT 1 Current Condition:  IF 1-3 Current Condition:  MS 01	Calabretto Building Group was informan 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was information 12/7/23 1/31/24 3/8/24 4/4/24 5/ Fuel Tank  Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Group Inlet Protection  Removed- As of 11/11/24 inlet filters	nen work is complete in the arrest to complete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/EM 5  nen work is complete in the arrest to complete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/EM 6  nen work is complete in the arrest to complete by 11/8/23. No 16/24. 6/20/24. 7/26/24. 8/29/On site  on site  Group re-installed the two por S 22nd St and 1st Ave st are no longer needed because in the site of the site	ea.  of done as of last inspection (24. 9/26/24. 10/24/24. 11/2/2023  ea.  of done as of last inspection (24. 9/26/24. 10/24/24. 11/2/2023  ea.  of done as of last inspection (24. 9/26/24. 10/24/24. 11/24/2023  of the inspection on 11/22/2 3/7/2024  table fuel tanks prior to the (24. 9/26/24. 10/24/24. (25. 10/24/24. 10/24/24. (26. 10/24/24. 10	Pending  Pending  Pending  Pending  Calabretto Building  Removed  Active  Active  Active  Active  Active	yes  Group was ren  Yes  Group was ren  No  1.  No	
EM 6 Current Condition:  FT X Current Condition:  FT 1 Current Condition:  IF 1-3 Current Condition:	Calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Erosion Control Mat  Pending -  Erosion Matting should be installed who calabretto Building Group was informan 12/7/23. 1/31/24. 3/8/24. 4/4/24. 5/ Fuel Tank  Removed - Calabretto Building Group Fuel Tank Good Condition - Calabretto Building Group Inlet Protection  Removed- As of 11/11/24 inlet filters	nen work is complete in the arrest to complete by 11/8/23. Note 16/24. 6/20/24. 7/26/24. 8/29/EM 5  nen work is complete in the arrest to complete by 11/8/23. Note 16/24. 6/20/24. 7/26/24. 8/29/EM 6  nen work is complete in the arrest to complete by 11/8/23. Note 16/24. 6/20/24. 7/26/24. 8/29/On site  removed the fuel tank prior to On site  Group re-installed the two por S 22nd St and 1st Ave are no longer needed because of the storing building mate.	to done as of last inspection 1/24 9/26/24 10/24/24 11/2/2023  ea. ot done as of last inspection 1/24 9/26/24 10/24/24 11/2/2023  ea. ot done as of last inspection 1/24 9/26/24 10/24/24 11/2/2023  ea. ot done as of last inspection 11/22/2 3/7/2024 10/24/24 10/24/24 11/24/2	Pending  Pending  Pending  Pending  Calabretto Building  Removed  Active  Inspection on 3/6/24  Removed  Willy paved or sodde  Active  ge container was ins	yes  Group was ren  Yes  Group was ren  No  Lance Stalled near the	

Current Condition:	Fair Condition - Calabretto Building Group staked down the portable toilet prior to the 12/21/22 inspection. Calabretto Building Group moved and secured the portable toilet prior to the inspection on 6/28/23. Calabretto Building Group staked down the portable toilet prior to the 10/03/2024 inspection. As of 10/10/24 all portable toilets on site will be recorded in this BMP. Calabretto Building Group moved the portable toilet in the center of lot across the street prior 10/10/24 inspection but did not resecure it. Calabretto Building Group installed and secured a portable toilet on the south side of the site prior to 10/10/24 inspection. During the 10/17/24 inspection, E&A inspector discovered that the portable toilet in the center of the lot was covering RN 7. Calabretto Building Group moved the portable toilet in the center of the site prior to the 10/24/24 inspection. As of the 10/30/24 inspection, the portable toilet on the south side of the site was not secured.					
	<ol> <li>The portable toilet in the center of the site should be staked down.</li> <li>The portable toilet in the center of the site should be moved 50 feet away from any inlet.</li> <li>The portable toilet on the south side of the site should be staked down.</li> </ol>					
	1.) Calabretto Building Group was told to was reminded on 10/24/24, 10/31/24 2.) Calabretto Building Group was told to was reminded on 10/24/24, 10/31/24	complete by 10/24/24 inspe	ection. Not done as of the			
DNI4 DNI0	3.) Calabretto Building Group was inform					
RN 1 - RN 6 Current Condition:	Inlet Protection  Pending - The inlet filter will be installed inlets 4, 5, and 6 prior to the inspection of inspection on 10/25/23.  Inlet protection should be installed.					
	Calabretto Building Group was informed				ng Group was	
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	Yes	
Current Condition:	Pending - The inlet filter will be installed process of installing the inlets during the Inlet protection should be installed.	inspection on 10/25/23.				
	Calabretto Building Group was informed			n. Calabretto Buildin	g Group was reminded	
RN 13 - RN 18	on 12/7/23 1/31/24 3/8/24 4/4/24 5/16 Inlet Protection	Near RN 6	4/26/2023	Pending	No	
Current Condition:	Pending - The inlet filter will be installed process of installing the inlets during the to the inspection on 9/19/24, 9/26/24	once the inlet is installed and	the inlet is at or below gr	rade. Calabretto Buil	ding Group was in the	
RM 1	Erosion Control Mat	RM 1	4/26/2023	Pending	Yes	
	Erosion Matting should be installed.  Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/26/24, 10/24/24	/14/23, 10/19/23, 11/2/23, 12	2/7/23, 1/31/24, 3/8/24, 4/	4/24, 5/16/24, 6/20/2	24, 7/26/24, 8/29/24,	
RM 2 Current Condition:	Erosion Control Mat Pending -	RM 2	4/26/2023	Pending	Yes	
	Erosion Matting should be installed.  Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/28/24, 10/24/24	/14/23, 10/19/23, 11/2/23, 12		4/24, 5/16/24, 6/20/2		
RM 3 Current Condition:	Erosion Control Mat Removed - Erosion matting is no longer	RM 3	/DDD as of the inspection	Removed	J	
ST 01	Silt Trap	South end of site	4/19/2023	Active	Yes	
Current Condition:	Fair Condition - Calabretto Building Group rocess of installing the PCSMP riser and The area around and in the basin should Calabretto Building Group was informed	ip installed silt fence prior to ad outfall during the inspection do be repaired and stabilized.	n on 11/1/23.	n. Calabretto Buildin	g Group was reminded	
OT 00	on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9/9/26/24, 10/24/24.					
ST 02 Current Condition:	Silt Trap  Good Condition - Calabretto Building Gr process of installing the PCSMP riser ar existing vegetation.					
SF 01	Silt Fence	East perimeter	9/9/2022	Active	Yes	
Current Condition:	Fair Condition - Calabretto Building Group installed silt fence prior to the inspection on 11/23/22.  The silt fence needs to be repaired, extended and reinstalled along the eastern perimeter.					
	Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23,	to complete by 11/30/22. No	ot done as of last inspecti			
	6/20/24 7/26/24 8/29/24 9/26/24 10/2	4/24			5/2 f, 7/7/27, 5/10/24,	
SF 02	Silt Fence	Eastern Slope	12/1/2022	Pending	Yes	

Current Condition:	Pending -						
	Silt fence should be installed.						
	Sill refice stroute de installee.						
	Calabretto Building Group was informed						
	reminded on 2/23/23, 4/21/23, 5/24/23,		/23, 10/19/23, 11/2/23,	12/7/23, 1/31/24, 3/	8/24, 4/4/24, 5/16/24,		
STR	6/20/24 7/26/24 8/29/24 9/26/24 10/2 Streets	ADJ and Internal Streets	10/31/2022	Active	Yes		
Current Condition:	Fair Condition - Track out was observed						
	street prior to the inspection on 6/14/23.	street prior to the inspection on 6/14/23. Calabretto Building Group was cleaning the streets during the inspection on 2/7/24.					
	Streets should be cleaned.						
	Calabretto Building Group was informed to complete by 4/4/24. Not done as of last inspection. Calabretto Building Group was reminded on 5/16/24, 6/20/24, 7/26/24, 8/29/24, 9/26/24, 10/24/24.						
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition - E&A inspector installe inspector reinstalled the SWPPP sign no sign near the entrance of the site during	ear the entrance of the site duri					
WO 01	Concrete Washout	On site	12/1/2022	Pending	Yes		
WS 01	1. A concrete washout should be installed 2. Concrete washout should be removed for the concrete waste should be removed for the calabretto Building Group was inform Calabretto Building Group was reminded 1/31/24, 3/8/24, 4/4/24, 5/16/24, 6/20/24 (2. Calabretto Building Group was inform remined on 10/24/24.	ed to contain any washouts. rom the site.  ned to complete by 1/25/23 or a d on 2/23/23, 4/21/23, 5/24/23, 4, 7/26/24, 8/29/24, 9/26/24 10/10 to complete by 10/17/24. No	s weather conditions al 6/21/23, 7/20/23, 8/16/ 24/24. ot done as of the last in	low. Not done as of 23, 9/14/23, 10/19/2 spection. Calabretto	last inspection. 3, 11/2/23, 12/7/23, Building Group was		
Current Condition:	Waste Storage Area Good Condition - Calabretto Building Gr	On site	12/7/2022	Active	No		
Current Condition:	construction entrance (2/8/23). Lumber Waste Storage Container was moved to	and other construction materia	als moved on site in des				
WT 01	Wattle	North East Corner	_	Removed			
Current Condition:	Removed - Calabretto Building Group p on 11/2/23.	aved the area above the draina	age and connected it to	existing storm inlets	prior to the inspection		
Certification Statement	"I certify, under penalty of law, that this of with a system designed to assure that q inquiry of the person or persons who mainformation submitted is, to the best of n penalties for submitting false information	jualified personnel properly gath anage the system or those pers my knowledge and belief, true, a	nered and evaluated the sons directly responsible accurate, and complete	e information submit e for gathering the in . I am aware that the	ted. Based on my formation, the ere are significant		
spector Signature:	Jan e was			Reviewed By:	Pet Su		