E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Yes



				L & A CONSOL	ind droof, inc.
	hary A. Jilek, CPESC, CISEC Enginee ironmental Services Dept. Manager				
Environmental oct vides be	pt. manager	E&A - P2	018.228.001		
Inspector: Jason Brackett			<u> </u>		Stage
		Sevent	y Two Place		J.a.go
			0624-5346-GP1		1
Project Name:		CSW-	202004796		
For Week Ending:		1/:	22/2022		
Project Location:			apillion, Sarpy County, NE		68046
Project Location.		12101 3 /2110 3t, F	apilion, Sarpy County, NE		00040
Grading:	70%		<u> </u>		
Sanitary Sewer:	32%				
Storm Sewer:	15%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	21%				
Overall Development.	21/0	<u>'</u>			
	T	1			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Weel
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	1/18/2022	Mostly Sunny 55/13	1:50 PM	
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:	None.				
Construction Sequencing:					
	sins) of the site have had a temp	orary or permanent cess	ation of grading, earthwork, or grou	nd disturbance in the last	14 days?
			Grading ceased due to winter		
rtoagri graamig zogan (o/ 10/2			Grading source due to mine.	(1/0/22)	
Which portion(s) (i.e. drainage bas	sins) of the site do not have grad	ling, earthwork, or groun	d disturbance scheduled in the next	: 14 days?	
Rough grading began (6/15/2	1). Excavation for sanitary	installation (9/28/21).	Grading ceased due to winter	conditions (1/5/22).	
What temporary or permanent stal	bilization measures listed in this	s section are being imple	mented?		
Existing vegetation (6/15/21).	•				
Checklist Questions:					
	he project free of any significant	t signs of erosion or sedi	ment that would be associated with	the construction activity?	
No					
Create Corrective Action?					
No, see Findings section.					
Have disturbed areas been seeded	d or otherwise stabilized as requ	ired? List inactive portion	ons of the project and if stabilization	measure are adequate or	needed to prevent erosion.
Yes	·		• •		•
Create Corrective Action?					
N/A					
Are waste materials (concrete, con	nstruction material, hazardous,	etc.) being managed proj	perly?		
No Create Corrective Action?					
Create Corrective Action? No, see BMPs section.					
INO, SEE DIVIES SECTION.					
Are construction entrances and ac	diacent streets being maintained	I adequately?			
No	, Joney				
Create Corrective Action?					
No, see BMPs section.					

N/A

Comments

Comments:

The site was active for sanitary work during the most recent inspection.

*Due to snow cover as of the last inspection, not all BMPs could be observed in there entirety.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Sediment that has washed out beyond the property boundary at X16 and at the Ponderosa Drive culvert needs to be cleaned up and the upgradient area needs to be stabilized. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	Schram Road	7/8/2021	Active	Yes		
Current Condition:	Fair Condition - 50% Effective - An old farm entrance is in use on site as of the 7/8/21 inspection. DEJ added rock to the entrance prior to the 1/13/22 inspection.						
	Additional rock is neede	ed.					
	DEJ/Gene Graves were		by 1/25/22.				
D 1	Diversion	E of SB C	11/12/2021	Active	Yes		
Current Condition:	Fair Condition - DEJ installed the diversion prior to the 11/12/21 inspection. The diversion should be cleaned out in one location. DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection.						
D 2	Diversion	S of SB D	5/31/2021	Pending	Yes		
Current Condition:	Pending -	00.000	5,61,2321				
	 2.) Additional diversions should be built in the area with SB D to divert the water along the contours to the basin. 1.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21. 2.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21. 						
D 3	Diversion	N of SB D	5/31/2021	Pending	Yes		
Current Condition:	Pending -	IN OF OB B	0/01/2021	1 chaing	103		
	DEJ/Gene Graves were in reminded on 12/2/21.	nformed to complete by	11/2/21. Not done as of the la	ast inspection. DEJ/G	Gene Graves were		
D 4 Current Condition:	Diversion Pending -	E and SB B	9/7/2021	Pending	Yes		
	Pending - The diversion should be in	nstalled with SB B.	9/7/2021 ne as of the last inspection.				
	Pending - The diversion should be in DEJ was informed to com	nstalled with SB B.					
Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2	nstalled with SB B. uplete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr	ne as of the last inspection. D 5/31/2021 ading.	EJ/Gene Graves wer	re reminded on 10/15.		
D 5 Current Condition: D 5 Current Condition: D 6	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion	nstalled with SB B. plete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter	ne as of the last inspection. D 5/31/2021 ading. 1/18/2022	EJ/Gene Graves well Pending Active	re reminded on 10/15 No No		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection.	nstalled with SB B. pplete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter tion of the diversion a	ne as of the last inspection. D 5/31/2021 ading. 1/18/2022 ppears to have been installe	PEJ/Gene Graves well Pending Active d in the northwest of	re reminded on 10/15 No No Corner of the site pri		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace	nstalled with SB B. plete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter	ne as of the last inspection. D 5/31/2021 ading. 1/18/2022	EJ/Gene Graves well Pending Active	re reminded on 10/15 No No		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace Pending - The terrace should be ins	nstalled with SB B. plete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter tion of the diversion at the diversion at talled when the area rea	5/31/2021 ading. 1/18/2022 ppears to have been installed 5/31/2021 aches final grade.	Pending Active d in the northwest of Pending	No No Corner of the site pri		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition: ET 1 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace Pending - The terrace should be ins DEJ/Gene Graves were in reminded on 12/2/21.	nstalled with SB B. pplete by 9/7/21. Not do 21. Northwest Perimeter will be installed during graph western Perimeter tion of the diversion at N of SB D. talled when the area reachformed to complete by	5/31/2021 ading. 1/18/2022 ppears to have been installed 5/31/2021 aches final grade.	Pending Active d in the northwest of Pending Pending Active Dending	No No No Corner of the site pri		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition: ET 1 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace Pending - The terrace should be ins DEJ/Gene Graves were in reminded on 12/2/21. Erosion Control Terrace	nstalled with SB B. plete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter tion of the diversion at the diversion at talled when the area rea	5/31/2021 ading. 1/18/2022 ppears to have been installed 5/31/2021 aches final grade.	Pending Active d in the northwest of Pending	No No Corner of the site pri		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition: ET 1 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace Pending - The terrace should be ins DEJ/Gene Graves were in reminded on 12/2/21. Erosion Control Terrace Pending - The terrace should be ins	nstalled with SB B. pplete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter tion of the diversion at N of SB D talled when the area reachformed to complete by N of SB E talled when the area reachformed to the diversion and the diversion at N of SB E	5/31/2021 ading. 1/18/2022 ppears to have been installed 5/31/2021 aches final grade. 11/2/21. Not done as of the lace of the	Pending Active d in the northwest of Pending Pending Pending Ast inspection. DEJ/G	re reminded on 10/15. No No Corner of the site pri Yes Gene Graves were Yes		
D 5 Current Condition: D 6 Current Condition: D 6 Current Condition: ET 1 Current Condition:	Pending - The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2 Diversion Pending - The diversion w Diversion Good Condition - A port the 1/18/22 inspection. Erosion Control Terrace Pending - The terrace should be ins DEJ/Gene Graves were in reminded on 12/2/21. Erosion Control Terrace Pending - The terrace should be ins	nstalled with SB B. pplete by 9/7/21. Not do 21. Northwest Perimeter will be installed during gr Western Perimeter tion of the diversion at N of SB D talled when the area reachformed to complete by N of SB E talled when the area reachformed to the diversion and the diversion at N of SB E	ne as of the last inspection. D 5/31/2021 ading. 1/18/2022 ppears to have been installe 5/31/2021 aches final grade. 11/2/21. Not done as of the last inspection.	Pending Active d in the northwest of Pending Pending Pending Ast inspection. DEJ/G	re reminded on 10/15 No No Corner of the site pri Yes Gene Graves were Yes		

Current Condition:	Pending -							
	The terms of a data in	ralla d						
	The terrace should be ins	The terrace should be installed.						
	DEJ/Gene Graves were in reminded on 12/2/21.	DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21.						
ET 4	Erosion Control Terrace	East Central	5/31/2021	Pending	Yes			
Current Condition:	Pending -		<u>'</u>					
	The terrace should be ins	talled.						
	DEJ/Gene Graves were in	nformed to complete by	11/2/21. Not done as of the I	ast inspection. DEJ/G	Sene Graves were			
	reminded on 12/2/21.	, , , , , , , , , , , , , , , , , , , ,						
EM 1	Erosion Control Matting	Northwest Side	5/31/2021	Pending	No			
Current Condition:	Pending - The erosion cor	ntrol matting will be insta	alled within the seeding windo	w when the associate	d area reaches final grade			
EM 2	Erosion Control Matting	North-Central	5/31/2021	Pending	No			
Current Condition:			alled within the seeding windo		_			
	<u> </u>							
EM 3	Erosion Control Matting	Northeast Side	5/31/2021	Pending	No			
Current Condition:	Pending - The erosion cor	ntrol matting will be insta	alled within the seeding windo	w when the associate	d area reaches final grade			
EM 4	Erosion Control Matting	Southwest Corner	5/31/2021	Pending	No			
Current Condition:			alled within the seeding windo					
		-		_	-			
EM 5	Erosion Control Matting	West Side	5/31/2021	Pending	No			
Current Condition:	Pending - The erosion cor	ntroi matting will be insta	alled within the seeding windo	w when the associate	d area reaches final grade			
FT 1	Fuel Tank	SW Corner	5/18/2021	Active	Yes			
Current Condition:	Fair Condition - DEJ insta	lled a fuel tank on-site p	orior to the 5/18/21 inspection	DEJ installed a bern	around the tank prior to			
	the 9/7/21 inspection.							
	1.) The berm needs to be	robuilt on the couth aid	a of the final tents					
	2.) The stained soils and							
	2.) The standard sens and p	sanot flood to be clearle	a up and romovou.					
		e informed to complete	by 11/2/21. Not done as of the	ne last inspection. DE	J/Gene Graves were			
	reminded on 12/2/21.							
	2.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21.							
FT 2	Fuel Tank	Material Storage Area	10/6/2021	Active	Yes			
Current Condition:	Fair Condition - TAR insta	,						
Current Condition.	Fair Condition - TAB installed a fuel tank on site prior to the 10/6/21 inspection.							
	The plug in the secondary containment needs to be reinstalled.							
	TAB was informed to complete by 10/13/21. Not done as of the last inspection.							
	TAB was informed to com	plete by 10/13/21. Not	done as of the last inspection					
FT 3	Fuel Tank	Material Storage Area	12/21/2021	Active	No			
Current Condition:	Good Condition - RPL ins	talled a double walled fu	uel tank on site prior to the 12	/21/21 inspection.				
MS 1	Material Storage	On Site	9/14/2021	Active	No			
Current Condition:			ated along the west side of the	e site as of the 9/14/2	1 inspection. DEJ cleane			
	up the stained soils prior t							
PB X Current Condition:	Portable Bathroom	On Site	8/18/2021 om on site prior to the 8/18/21	Active	No			
Current Condition.		•	•	•				
	additional portable toilet prior to the 9/28/21 inspection, one of the toilets still needs to be secured. DEJ removed one of the portable toilets prior to the 10/26/21 inspection. DEJ stood up and secured the portable toilet prior to the 11/17/21 inspection.							
	1.	•	prior to the 12/21/21 inspection	•	•			
	prior to the 12/21/21 inspe	ection. DEJ removed or	ne of the portable toilets prior	to the 1/13/22 inspect	ion.			
SB A	Sediment Basin	X24	9/7/2021	Pending	Yes			
Current Condition:	Pending - The basin was	partially dug out prior to	the 12/1/21 inspection.					
	The basin should be installed.							
	The pasin should be lista	The Salar Charles of Middle Charles						
	DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21,							
	10/21/21, 10/29/21, 12/2/2	21.						
SB B	Sediment Basin	O24	9/7/2021	Pending	Yes			
Current Condition:	Pending - The basin had I	peen partially dug out pr	rior to the 9/14/21 inspection b	by DEJ, the inspector	will continue to monitor.			
	The begin charded by	llod						
	The basin should be installed.							
	DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21,							
	10/21/21, 10/29/21, 12/2/2				,			
CD C	Sediment Basin	H24	9/7/2021	Pending	Yes			
SB C	ecamient Baem		•		•			

Current Condition:	Pending - The basin was	dug out prior to the 11/1	2/21 inspection.				
	The basin should be installed. DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/1 10/21/21, 10/29/21, 12/2/21.						
SB D	Sediment Basin	H22	5/31/2021	Pending	Yes		
Current Condition:			dug out during the 11/4/21 ins		100		
	 Due to ground disturbance in the area, the basin should be installed. The existing area inlet in the location of the future riser should be wrapped with silt fence. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21. DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. 						
00.5	•						
SB E	Sediment Basin	D19	5/31/2021	Pending	Yes		
Current Condition:	Pending - The basin was partially dug out prior to the 12/1/21 inspection. Due to ground disturbance in the area, the basin should be installed. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21.						
SF 1	Silt fence	Northern/Western Perimeter	5/18/2021	Active	Yes		
Current Condition:	Fair Condition - The deve	eloper installed the silt fe	nce prior to the 5/18/21 inspe	ction. A diversion b	erm appears to have been		
	 The silt fence needs to be extended to the south and along the north side of the entrance. The silt fence should be extended to the north along the ground disturbance. Silt fence should be installed over the flared end sections at the area inlet outfall west of SB D. DEJ/Gene Graves were informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21. DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. 						
SF 2	Silt fence	Northeastern Perimeter	5/25/2021	Active	Yes		
Current Condition:	Fair Condition - The deve		nce prior to the 5/25/21 inspe	ction			
	 The silt fence is damaged/full and Y12 and needs to be maintained. The silt fence is damaged at U12 and needs to be repaired. DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21. DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 						
	8/27/21, 9/2/21, 10/15/21			·			
SF 3 Current Condition:	Silt fence	Southeast Corner	5/25/2021	Active	Yes		
	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection. Silt fence needs to be repaired at V25, X25, and AA25. DEJ/Gene Graves were informed to complete by 10/27/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/29/21, 12/2/21.						
SF 4 Current Condition:	Silt fence	Southwest Perimeter	5/18/2021 nce prior to the 5/18/21 inspe	Active	Yes		
	the Ponderosa Drive connection prior to the 10/13/21 inspection. Excavation spoils from sanitary excavation in the area of Ponderosa Drive damaged a small portion of the silt fence prior to the 1/18/22 inspection, the inspector will recommend repair when work is complete. 1.) The silt fence is ripped at G25, O25, and R25 and needs to be repaired. 2.) The silt fence around the Ponderosa Drive connection needs to be maintained. 3.) Additional silt fence should be installed in the high flow areas around Ponderosa Drive. 4.) The silt fence needs to be backfilled, cleaned out, and repaired in multiple locations. 1.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21. 2.) DEJ/Gene Graves were informed to complete by 10/20/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21. 3.) DEJ/Gene Graves were informed to complete by 10/20/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/21/21, 10/29/21, 12/2/21. 4.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21.						
STR	Streets	S 72nd Street	5/18/2021	Active	Yes		

Current Condition:	Fair Condition -					
	Trackout needs to be cleaned up.					
	DEJ/Gene Graves were	oy 1/18/22.				
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign in the southwest corner of the property during the 5/18/21 inspection.					
WO 1	Concrete Washout	On Site	5/31/2021	Pending	No	
Current Condition:	Pending - A concrete was	hout will be installed who	en paving begins on site.			
WS 1	Waste Storage	On Site	5/31/2021	Pending	No	
Current Condition:	Pending - Waste will be contained on site and in proper containment vessels.					
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Jule Show			Reviewed By:	Get Sol	