E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Engineering Answers** 

2:20 PM

Environmental Services De	pt. Manager				
		E&A - P201	8.228.001		
Inspector: Jason Brackett	Jason Brackett				Stage
•		Seventy	Two Place		
	PAP-20200624-5346-GP1				1
Project Name:					
For Week Ending:					
Project Location:			68046		
Grading:	70%				
Sanitary Sewer:	32%				
Storm Sewer:	15%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	21%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				

Mostly Sunny 60/29

Complaints: None.

0.00" 0.00"

0.00

0.03

0.27

0.00"

# Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

2/8/2022

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began (6/15/21). Excavation for sanitary installation (9/28/21). Grading ceased due to winter conditions (1/5/22). Excavation for utility connections along 72nd (2/8/22).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/15/21).

## Checklist Questions:

re receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Monday:

Tuesday:

Thursday:

Saturday:

Friday:

Wednesday:

Create Corrective Action?

No, see Findings section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

No, see Findings section.

re waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No, see BMPs section.

e construction entrances

Create Corrective Action?
No, see BMPs section.

Is dust as	ssociated with the construction activity adequately controlled on the site?
Yes	
Create C	orrective Action?
N/A	

### Comments:

### Comments:

The site was inactive during the most recent inspection.

# Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) Sediment that has washed out beyond the property boundary at X16 and at the Ponderosa Drive culvert needs to be cleaned up and the upgradient area needs to be stabilized. DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, **2/11/22.**
- 3) Off-site accumualtion of sediment along the northeast side of the site should be cleaned up and the area restabilized (unless the area will be farmed).

			1 - 1 - 1 - 1 - 1				
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	Schram Road	7/8/2021	Active	Yes		
Current Condition:	Fair Condition - 50% Effective - An old farm entrance is in use on site as of the 7/8/21 inspection. DEJ added rock to the entrance prior to the 1/13/22 inspection.  Additional rock is needed.  DEJ/Gene Graves were informed to complete by 1/25/22. Not done as of the last inspection. DEJ/Gene Graves were reminded on 2/11/22.						
D 1		F of CD C	11/12/2021	A ativo	Vaa		
Current Condition:	Fair Condition - DEJ insta The diversion should be c	Diversion E of SB C 11/12/2021 Active Yes  Fair Condition - DEJ installed the diversion prior to the 11/12/21 inspection.  The diversion should be cleaned out/redefined.					
	DEJ/Gene Graves were in reminded on 2/11/22.	formed to complete by	12/8/21. Not done as of the la	ast inspection. <b>DEJ/G</b>	iene Graves were		
D 2 Current Condition:	Diversion	S of SB D	5/31/2021	Pending	Yes		
	<ol> <li>The diversion should be installed with SB D.</li> <li>Additional diversions should be built in the area with SB D to divert the water along the contours to the basin.</li> <li>DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.</li> <li>DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were</li> </ol>						
D 3	reminded on 12/2/21, <b>2/1</b> 1  Diversion	N of SB D	5/31/2021	Pending	Yes		
Current Condition:	Pending -  The diversion should be in		5,6,7,252,	. S. a. a.			
DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last in reminded on 12/2/21, 2/11/22.							
			11/2/21. Not done as of the la	ast inspection. DEJ/G	ene Graves were		
D 4	reminded on 12/2/21, <b>2/1</b> 1 Diversion		11/2/21. Not done as of the la	Pending	ene Graves were		
Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in  DEJ was informed to com 10/21/21, 10/29/21, 12/2/2	E and SB B  estalled with SB B.  plete by 9/7/21. Not do 21, 2/11/22.	9/7/2021  ne as of the last inspection. D	Pending  EJ/Gene Graves wer	Yes e reminded on 10/15/2		
Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion	E and SB B  Installed with SB B.  Iplete by 9/7/21. Not do 21, 2/11/22.  Northwest Perimeter	9/7/2021  ne as of the last inspection. D  5/31/2021	Pending	Yes		
Current Condition:  D 5  Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion  Pending - The diversion w	E and SB B  Installed with SB B.  Installed by 9/7/21. Not do 21, 2/11/22.  Northwest Perimeter ill be installed during gr	9/7/2021  ne as of the last inspection. D  5/31/2021  ading.	Pending  PEJ/Gene Graves wer  Pending	Yes  e reminded on 10/15/2		
Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in  DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion  Pending - The diversion w Diversion	E and SB B  Installed with SB B.	9/7/2021  ne as of the last inspection. D  5/31/2021	Pending  PEJ/Gene Graves wer  Pending  Active	Yes reminded on 10/15/2 No		
D 5 Current Condition:  D 5 Current Condition: D 6	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in  DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion  Pending - The diversion w Diversion  Good Condition - A portio	E and SB B  Installed with SB B.	9/7/2021  ne as of the last inspection. E  5/31/2021  ading.  1/18/2022	Pending  PEJ/Gene Graves wer  Pending  Active	Yes reminded on 10/15/2 No		
D 5 Current Condition:  D 6 Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in  DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion  Pending - The diversion w Diversion  Good Condition - A portio 1/18/22 inspection.  Erosion Control Terrace  Pending -  The terrace should be ins	E and SB B  Installed with SB B. Installed with SB	9/7/2021  ne as of the last inspection. Description of the last inspection of the last inspection. Description of the last inspection of the	Pending PEJ/Gene Graves wer Pending Active e northwest corner of Pending	Per reminded on 10/15/2  No  No  the site prior to the		
D 5 Current Condition:  D 6 Current Condition:  D 6 Current Condition:	reminded on 12/2/21, 2/11  Diversion  Pending -  The diversion should be in  DEJ was informed to com 10/21/21, 10/29/21, 12/2/2  Diversion  Pending - The diversion w Diversion  Good Condition - A portio 1/18/22 inspection.  Erosion Control Terrace  Pending -  The terrace should be ins	E and SB B  Installed with SB B.  Installed during gr  Installed during gr  Installed during gr  Western Perimeter of the diversion appear  In of SB D  Installed when the area real of the diversion appear of the diversion appear.	9/7/2021  ne as of the last inspection. D  5/31/2021  ading.  1/18/2022  ars to have been installed in th  5/31/2021	Pending PEJ/Gene Graves wer Pending Active e northwest corner of Pending	Per reminded on 10/15/2  No  No  the site prior to the		

Current Condition:	Pending -						
	The terrace should be installed when the area reaches final grade.  DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.						
ET 3	Erosion Control Terrace	N of SB B	5/31/2021	Pending	Yes		
Current Condition:	Pending -	110.022	6/6 // 202 /	1 0.10.1.9	. 55		
	The terrace should be installed.  DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.						
ET 4	Erosion Control Terrace	East Central	5/31/2021	Pending	Yes		
Current Condition:	Pending -						
	The terrace should be installed.  DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were						
	reminded on 12/2/21, 2/11		7/2 / /2 2 2 /				
EM 1	Erosion Control Matting	Northwest Side	5/31/2021	Pending	No		
Current Condition:	Pending - The erosion cor	ntrol matting will be insta	alled within the seeding windo	w when the associate	d area reaches final grade.		
EM 2	Fracian Control Matting	North-Central	5/31/2021	Donding	l No		
Current Condition:	Erosion Control Matting		alled within the seeding windo	Pending	No		
Current Condition.	rending - The erosion con	Titloi matting will be insta	med within the seeding windo	w when the associate	u area reacries ililai graue.		
EM 3	Erosion Control Matting	Northeast Side	5/31/2021	Pending	Yes		
Current Condition:	Pending -	Tronsiduct Grad	6,6.,262.		1.00		
	The slope should be stabilized ASAP when work allows.  Gene Graves/DEJ were informed on 2/11/22.						
EM 4	Erosion Control Matting	Southwest Corner	5/31/2021	Pending	No		
Current Condition:	Pending - The erosion cor		alled within the seeding windo	w when the associate	d area reaches final grade.		
	-				_		
EM 5	Erosion Control Matting	West Side	5/31/2021	Pending	No		
Current Condition:	Pending - The erosion cor	ntrol matting will be insta	alled within the seeding windo	w when the associate	d area reaches final grade.		
FT 1	Fuel Tank	SW Corner	5/18/2021	Active	Yes		
Current Condition:			rior to the 5/18/21 inspection.				
	the 9/7/21 inspection.  1.) The berm needs to be rebuilt on the south side of the fuel tank.  2.) The stained soils and pallet need to be cleaned up and removed.  1.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.  2.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.						
FT 2	Fuel Tank	Material Storage Area	10/6/2021	Active	Yes		
Current Condition:	Fair Condition - TAB insta	ulled a fuel tank on site p	rior to the 10/6/21 inspection.				
	Fair Condition - TAB installed a fuel tank on site prior to the 10/6/21 inspection.  The plug in the secondary containment needs to be reinstalled.  TAB was informed to complete by 10/13/21. Not done as of the last inspection. <b>E&amp;A Construction Observer was reminded on 2/11/22.</b>						
		plete by 10/13/21. Not	done as of the last inspection.	E&A Construction	Observer was reminded		
FT 3		plete by 10/13/21. Not Material Storage Area	done as of the last inspection.	E&A Construction Active	Observer was reminded No		
FT 3 Current Condition:	on 2/11/22. Fuel Tank	Material Storage Area	12/21/2021	Active	l		
	on 2/11/22. Fuel Tank	Material Storage Area		Active	l		
Current Condition:	on 2/11/22.  Fuel Tank  Good Condition - RPL ins  Material Storage	Material Storage Area talled a double walled fu On Site storage is primarily loca	12/21/2021  el tank on site prior to the 12/ 9/14/2021  tted along the west side of the	Active 21/21 inspection. Active	No No		
Current Condition:  MS 1  Current Condition:	on 2/11/22.  Fuel Tank  Good Condition - RPL ins  Material Storage  Good Condition - Material up the stained soils prior t	Material Storage Area talled a double walled fu On Site storage is primarily loca o the 9/28/21 inspection	12/21/2021 el tank on site prior to the 12/ 9/14/2021 sted along the west side of the	Active 21/21 inspection. Active e site as of the 9/14/2	No No I inspection. DEJ cleaned		
Current Condition:  MS 1  Current Condition:  PB X	on 2/11/22.  Fuel Tank  Good Condition - RPL ins  Material Storage  Good Condition - Material up the stained soils prior t  Portable Bathroom	Material Storage Area talled a double walled fu On Site storage is primarily loca o the 9/28/21 inspection On Site	12/21/2021  el tank on site prior to the 12/ 9/14/2021  sted along the west side of the 12/ 8/18/2021	Active 21/21 inspection. Active e site as of the 9/14/2	No No 1 inspection. DEJ cleaned		
Current Condition:  MS 1  Current Condition:	on 2/11/22.  Fuel Tank  Good Condition - RPL ins  Material Storage  Good Condition - Material up the stained soils prior t  Portable Bathroom  Good Condition - DEJ ins additional portable toilet p portable toilets prior to the RPL installed an additional	Material Storage Area talled a double walled fu On Site storage is primarily loca to the 9/28/21 inspection On Site talled a portable bathroc rior to the 9/28/21 inspection. Deal portable toilet on site particular in the p	12/21/2021  el tank on site prior to the 12/9/14/2021  sted along the west side of the 12/9/18/2021  m on site prior to the 8/18/21 ction, one of the toilets still ne 12/9/18/21 stood up and secured the 12/21/21 inspection	Active 21/21 inspection. Active e site as of the 9/14/2  Active inspection. DEJ instated to be secured. Deportable toilet prior to m. RPL stood up and	No  No I inspection. DEJ cleaned  No alled and staked down an DEJ removed one of the the 11/17/21 inspection. secured the portable toilet		
Current Condition:  MS 1  Current Condition:  PB X	on 2/11/22.  Fuel Tank  Good Condition - RPL ins  Material Storage  Good Condition - Material up the stained soils prior t  Portable Bathroom  Good Condition - DEJ ins additional portable toilet p portable toilets prior to the RPL installed an additional	Material Storage Area talled a double walled fu On Site storage is primarily loca to the 9/28/21 inspection On Site talled a portable bathroc rior to the 9/28/21 inspection. Deal portable toilet on site particular in the p	12/21/2021 el tank on site prior to the 12/ 9/14/2021 sted along the west side of the . 8/18/2021 m on site prior to the 8/18/21 ction, one of the toilets still ne iEJ stood up and secured the	Active 21/21 inspection. Active e site as of the 9/14/2  Active inspection. DEJ instated to be secured. Deportable toilet prior to m. RPL stood up and	No  No I inspection. DEJ cleaned  No alled and staked down an DEJ removed one of the the 11/17/21 inspection. secured the portable toilet		

Current Condition:	Pending - The basin was partially dug out prior to the 12/1/21 inspection.						
	The basin should be installed.						
	DEJ was informed to com 10/21/21, 10/29/21, 12/2/		ne as of the last inspection. [	DEJ/Gene Graves wei	re reminded on 10/15/21,		
SB B	Sediment Basin	O24	9/7/2021	Pending	Yes		
Current Condition:	Pending - The basin had	been partially dug out pr	ior to the 9/14/21 inspection b	y DEJ, the inspector	will continue to monitor.		
	The basin should be installed.  DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22.						
SB C	Sediment Basin	H24	9/7/2021	Pending	Yes		
Current Condition:				rending	res		
Current Containon.	Pending - The basin was dug out prior to the 11/12/21 inspection.  The basin should be installed.  DEJ was informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22.						
SB D	Sediment Basin	H22	5/31/2021	Pending	Yes		
Current Condition:			dug out during the 11/4/21 ins		103		
	<ol> <li>1.) Due to ground disturbance in the area, the basin should be installed.</li> <li>2.) The existing area inlet in the location of the future riser should be wrapped with silt fence.</li> <li>1.) DEJ/Gene Graves were informed to complete by 11/2/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 12/2/21, 2/11/22.</li> <li>2.) DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. DEJ/Gene Graves were</li> </ol>						
SB E	reminded on 2/11/22. Sediment Basin	D19	5/31/2021	Pending	Yes		
Current Condition:	Pending - The basin was			rending	165		
SF 1	DEJ/Gene Graves were i reminded on 12/2/21, 2/1 Silt fence		11/2/21. Not done as of the la	Active	Gene Graves were Yes		
Current Condition:		Perimeter					
	Fair Condition - The developer installed the silt fence prior to the 5/18/21 inspection. A diversion berm appears to have been intentionally built in the northern section of the run prior to the 1/18/22 inspection, extending the silt fence is still recommended. Sudbeck installed wattles as an extension of the silt fence to the north prior to the 2/2/22 inspection.  1.) The silt fence needs to be extended to the south and along the north side of the entrance.  2.) Silt fence should be installed over the flared end sections at the area inlet outfall west of SB D.  3.) Silt fence should be reinstalled along 72nd Street when work allows.  1.) DEJ/Gene Graves were informed to complete by 9/7/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22.  2.) DEJ/Gene Graves were informed to complete by 12/8/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 2/11/22.  3.) DEJ/Gene Graves were informed to complete by 2/15/22.						
SF 2	Silt fence	Northeastern	5/25/2021	Active	Yes		
		Perimeter			165		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection.  1.) The silt fence is damaged/full and Y12 and needs to be maintained. 2.) The silt fence is damaged at U12 and needs to be repaired.  1.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22. 2.) DEJ was informed to complete by 7/17/21. Not done as of the last inspection. DEJ/Gene Graves were reminded on 8/27/21, 9/2/21, 10/15/21, 10/21/21, 10/29/21, 12/2/21, 2/11/22.						
SF 3	Silt fence	Southeast Corner	5/25/2021	Active	Yes		
Current Condition:	Fair Condition - The developer installed the silt fence prior to the 5/25/21 inspection.  Silt fence needs to be repaired at V25, X25, and AA25.						
	DEJ/Gene Graves were i reminded on 10/29/21, 12	2/2/21, <b>2/11/22</b> .	10/27/21. Not done as of the	last inspection. DEJ/	Gene Graves were		
SF 4	Silt fence	Southwest Perimeter	5/18/2021	Active	Yes		

Current Condition:	the Ponderosa Drive conr Ponderosa Drive damage	nce prior to the 5/18/21 insp /21 inspection. Excavation silt fence prior to the 1/18/22 nd Ponderosa Drive appear	spoils from sanitary exc inspection, the inspect	cavation in the area of or will recommend repair		
	<ol> <li>The silt fence is ripped at G25, O25, and R25 and needs to be repaired.</li> <li>The silt fence around the Ponderosa Drive connection needs to be maintained.</li> <li>Additional silt fence should be installed in the high flow areas around Ponderosa Drive.</li> <li>The silt fence needs to be backfilled, cleaned out, and repaired in multiple locations.</li> </ol>					
	8/27/21, 9/2/21, 10/15/21, 2.) DEJ/Gene Graves wereminded on 12/2/21, <b>2/1</b> <sup>2</sup> . 3.) DEJ/Gene Graves wereminded on 10/21/21, 10 4.) DEJ/Gene Graves were	, 10/21/21, 10/29/21, 12/ re informed to complete i	by 10/20/21. Not done as of	the last inspection. DE	J/Gene Graves were	
STR	reminded on 12/2/21, 2/11 Streets	S 72nd Street	5/18/2021	Active	No	
Current Condition:			during the most recent insp		INU	
SWPPP Sign	Misc/Other	S 72nd and Schram	5/18/2021	Active	No	
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign in the southwest corner of the property during the 5/18/21 inspection.					
WO 1	Concrete Washout	On Site	5/31/2021	Pending	No	
Current Condition:	Pending - A concrete was	hout will be installed who	en paving begins on site.			
WS 1	Waste Storage	On Site	5/31/2021	Pending	No	
Current Condition:			roper containment vessels.			
Certification Statement:	accordance with a system submitted. Based on my ingathering the information,	n designed to assure that nquiry of the person or p the information submitte	and all attachments were pre- t qualified personnel properly ersons who manage the system of my known abmitting false information in	y gathered and evaluate stem or those persons d rledge and belief, true, a	ed the information lirectly responsible for accurate, and complete. I	
Inspector Signature:	Jan Ca Mart			Reviewed By:	Gut Sol	